


AIR SCIENCES INC.

DENVER • PORTLAND

# Baseline Meteorological and Air Quality Data Report Resolution Copper Mining Project

**October 1 – December 31, 2013**

PREPARED FOR:
RESOLUTION COPPER
A MEMBER OF RIO TINTO GROUP

262-1
JANUARY 2014

# CONTENTS PAGE


1.0 Introduction ..... 1
1.1 Location ..... 1
1.2 Monitoring Program Description ..... 3
1.2.1 Meteorological Data ..... 3
1.2.2 $NO_2$ Data ..... 4
1.2.3 $SO_2$ Data ..... 4
1.2.4 $O_3$ Data ..... 5
1.2.5 PM Data ..... 5
2.0 Data Recovery Rates ..... 6
2.1 Data Loss ..... 6
2.1.1 Meteorological Data Loss ..... 6
2.1.2 $NO_2$ Data Loss ..... 7
2.1.3 $SO_2$ Data Loss ..... 7
2.1.4 $O_3$ Data Loss ..... 7
2.1.5 PM Data Loss ..... 7
2.2 Quality Control ..... 8
3.0 Meteorological Data Summary and Discussion ..... 10
3.1 Meteorological Data Summary ..... 10
3.2 Meteorological Data Discussion ..... 14
4.0 PM Data Summary and Discussion ..... 15
4.1 East Plant PM Data Summary ..... 15
4.2 West Plant PM Data Summary ..... 16
4.3 PM Data Discussion ..... 16
4.3.1 $PM_{10}$ ..... 16
4.3.2 $PM_{2.5}$ ..... 17
5.0 $NO_2$ Data Summary and Discussion ..... 18
5.1 $NO_2$ Data Summary ..... 18
5.2 $NO_2$ Data Discussion ..... 19
6.0 $SO_2$ Data Summary and Discussion ..... 20
6.1 $SO_2$ Data Summary ..... 20
6.2 $SO_2$ Data Discussion ..... 20
7.0 $O_3$ Data Summary and Discussion ..... 21
7.1 $O_3$ Data Summary ..... 21

7.2 $O_3$ Data Discussion....21

**Tables**

Table 1. Monitoring Station Locations....1
Table 2. Sensors and Heights....3
Table 3. Data Recovery Rates, East Plant and West Plant....6

**Figures**

Figure 1. Resolution Monitoring Stations Locations....2
Figure 2. Dates of Site Checks, Audits, and Calibrations....9
Figure 3. Example Schematic of Meteorological Data Sheets....11
Figure 4. East Plant Meteorological Data Summary....12
Figure 5. West Plant Meteorological Data Summary....13
Figure 6. East Plant Particulate Data....15
Figure 7. West Plant Particulate Data....16
Figure 8. $NO_2$ Maximum Hourly Concentration for Each Calendar Day....18
Figure 9. $NO_2$ Mean Hourly Concentrations....19
Figure 10. $SO_2$ Maximum Hourly Concentration for Each Calendar Day....20
Figure 11. $O_3$ Daily Rolling 8-Hour Maximum, 2013....21

**Appendices**

Appendix A: Frequency Distributions of Winds by Speed, Direction, and Stability
Appendix B: Monthly Wind Speed Frequencies and Instantaneous Daily Maximum Wind Speeds
Appendix C: Meteorological Data – Hourly
Appendix D: $PM_{10}$ and $PM_{2.5}$ Data – Hourly
Appendix E: $NO_2$, $SO_2$, $O_3$ Data – East Plant – Hourly
Appendix F: West Plant Meteorological Site Check Forms
Appendix G: West Plant $PM_{10}$ and $PM_{2.5}$ Site Check Forms and Flow Audits
Appendix H: East Plant Meteorological Site Check Forms
Appendix I: East Plant $PM_{10}$ and $PM_{2.5}$ Site Check Forms and Flow Audits
Appendix J: East Plant $SO_2$, $NO_x$, and $O_3$ Site Check and Audit Forms
Appendix K: Audits and Calibrations
Appendix L: CD

# 1.0 INTRODUCTION

This report summarizes the meteorological, nitrogen dioxide ($NO_2$), sulfur dioxide ($SO_2$), ozone ($O_3$), and particulate matter (PM) data collected at the Resolution Copper Project near Superior, Arizona for the fourth quarter, October 1 – December 31, 2013. Monitoring was performed in accordance with the *Resolution Copper Mining Monitoring Plan, November 2011* (approved by the Pinal County Air Quality Control District [PCAQCD] on November 15, 2011).

Resolution Copper Mining LLC (RCML) has implemented a meteorological and air quality monitoring program to support several efforts during the pre-feasibility and other mine development phases: environmental assessments, impact analyses, and documents required by the National Environmental Policy Act (NEPA); meteorological and air quality data to be processed and used as input for AERMOD (American Meteorological Society/Environmental Protection Agency Regulatory Model) dispersion modeling; and air quality baseline data and AERMOD analyses to be used to support RCML's application to the PCAQCD for air permit(s).

## 1.1 Location


The Resolution Copper Project is located near Superior, Arizona. Currently there are two meteorological and air quality stations. The East Plant station is located at the main project site, east of Superior. The West Plant station is located at RCML's facilities directly north of Superior, Arizona. The topography ranges from hilly to mountainous.

The monitoring station locations are shown in Figure 1 and listed by coordinates in Table 1.

**Table 1. Monitoring Station Locations**

| Station | Location | Latitude (Deg) | Longitude (Deg) | Elevation (ft) | Method of Determination |
|---|---|---|---|---|---|
| West Plant | 01S12E35NWSE | 33.2994 | -111.1021 | 2,949 | GPS |
| East Plant | 01S13E32SWNW | 33.3030 | -111.0676 | 4,199 | GPS |

**Figure 1. Resolution Monitoring Stations Locations**



## 1.2 Monitoring Program Description

### 1.2.1 Meteorological Data

Meteorological sensors and air quality instrumentation at the East Plant and West Plant stations are mounted on 10-meter, open-lattice towers or housed in climate-controlled insulated shelters, and are listed by height, from ground level, in Table 2.

**Table 2. Sensors and Heights**

| | | Height (m) | West Plant | East Plant |
|---|---|---|---|---|
| **AERMOD Meteorological Data** | Horizontal wind speed (meters per second [m/s]) | 10 | ✓ | ✓ |
| | Horizontal wind direction (degrees [°]) | 10 | ✓ | ✓ |
| | Horizontal wind direction standard deviation (sigma theta) | 10 | ✓ | ✓ |
| | Air temperature (degrees Celsius [°C]) | 2 | ✓ | ✓ |
| | Vertical temperature difference (ΔT, Delta T, [°C]) | 2,10 | ✓ | ✓ |
| | Relative humidity (percent [%]) | 2 | ✓ | ✓ |
| | Solar radiation (watts per square meter [$W/m^2$]) | 2 | ✓ | ✓ |
| | Barometric pressure (millimeters of mercury [mmHg]) | 1 | ✓ | ✓ |
| | Precipitation (inches [in]) | Ground | ✓ | ✓ |
| **Ambient Air Data** | FEM* Particulate matter less than 10 microns ($PM_{10}$) | 2,3 | ✓ | ✓ |
| | FEM* Particulate matter less than 2.5 microns ($PM_{2.5}$) | 2,3 | ✓ | ✓ |
| | Sulfur dioxide ($SO_2$) | 3 | | ✓ |
| | Ozone ($O_3$) | 3 | | ✓ |
| | Nitrogen dioxide ($NO_2$) | 3 | | ✓ |

*Federal Equivalent Method

The meteorological data are recorded by digital data acquisition systems equipped with broadband modems for data transfer. The meteorological parameters are sampled on-site at two-second intervals and are digitally processed into 15-minute averages. The 15-minute averages are transmitted to Air Sciences Inc. (Air Sciences) for quality assurance checks and are used as input for the calculation of one-hour averages.

Atmospheric stability is calculated using the Solar Radiation/Delta-T (SRDT) method (EPA-454/R-99-005, Table 6-7). Wind speed and solar radiation measurements are used for calculation of daytime atmospheric stability, and wind speed and delta temperature measurements are used for calculation of nighttime atmospheric stability.

Stability classes A, B, and C indicate the frequency of daytime low-speed winds, which are categorized as unstable or high-dispersion-potential winds with class A being the least stable. Stability classes E and F indicate the frequency of nighttime low-speed winds, which are categorized as stable or low-dispersion-potential winds with class E being the least stable. The D stability class is a mixture of daytime and nighttime winds, generally at higher speeds. This class is also referred to as neutral stability.

The frequency distribution of instantaneous winds by speed during each month of the quarter is collected at the monitoring stations. These winds can have a pronounced effect on the natural generation of airborne dust. The wind speed data are collected every two seconds and then binned based on wind speed classes to build a frequency distribution. The wind speed classes are:

- Wind speeds less than 5 meters per second (m/s) (11.2 miles per hour [mph])
- Wind speeds from 5 to 19 m/s, categorized in increments of 2 m/s
- Wind speeds greater than 19 m/s (42.5 mph)

The wind frequency distributions are compiled every eight hours and then converted to daily percentages. Appendix A contains the frequency distributions of winds by speed, direction, and stability. Appendix B includes monthly wind speed frequencies and instantaneous daily maximum wind speeds. Appendix C lists hourly meteorological data from October 1 through December 31, 2013.

Meteorological parameters are collected in support of air quality data. All meteorological sensors are audited and data undergo quality control procedures according to the guidelines outlined in the Quality Assurance Project Plan.

### 1.2.2 $NO_2$ Data

$NO_2$ is measured at the East Plant using the Teledyne T200 Chemiluminescence $NO_2$ Analyzer, which holds an Environmental Protection Agency (EPA) equivalency designation as a Reference Method (RFNA-1194-099). This instrument is designed to measure oxides of nitrogen ($NO_X$) (with nitrogen dioxide, $NO_2$, as an indicator) at trace levels in ambient air. The instrument is operated continuously to collect hourly NO, $NO_2$, and $NO_X$ concentrations. Data are transferred via FTP script every hour to the Air Sciences server and made available to authorized persons via a data web-portal. Appendix E lists hourly $NO_2$ data for the East Plant from October 1 through December 31, 2013.

Zero/span checks are run every morning, typically beginning at 1 a.m., and these data are invalidated. Level 1 zeros and spans are conducted by the site operator every two weeks or as needed. Second-party audits, adjustments, and general maintenance on the $NO_2$ monitor are performed according to the guidelines outlined in the Quality Assurance Project Plan.

### 1.2.3 $SO_2$ Data

$SO_2$ is measured at the East Plant using the Teledyne T100 UV Fluorescence $SO_2$ Analyzer, which holds an EPA designation as an Automated Equivalent Method (EQSA-0495-100). The instrument is operated continuously to collect hourly $SO_2$ concentrations. Data are transferred via FTP script every hour to the Air Sciences server and made available to authorized persons via a data web-portal. Appendix E lists hourly $SO_2$ data for the East Plant from October 1 through December 31, 2013.

Zero/span checks are run every night, typically beginning at midnight, and these data are invalidated. Level 1 zeros and spans are conducted by the site operator every two weeks or as needed. Second-party

audits, adjustments, and general maintenance on the $SO_2$ monitor are performed according to the guidelines outlined in the Quality Assurance Project Plan.

### 1.2.4 $O_3$ Data

$O_3$ is measured at the East Plant using the Teledyne T400 UV Absorption $O_3$ Analyzer, which holds an EPA designation as an Automated Equivalent Method (EQOA-0992-087). The instrument is operated continuously to collect hourly $O_3$ concentrations. Data are transferred via FTP script every hour to the Air Sciences server and made available to authorized persons via a data web-portal. Appendix E lists hourly and rolling 8-hour average $O_3$ data for the East Plant from October 1 through December 31, 2013.

Zero/span checks are run every morning, typically beginning at 2 a.m., and these data are invalidated. Level 1 zeros and spans are conducted by the site operator every two weeks or as needed. Second-party audits, adjustments, and general maintenance on the $O_3$ monitor are performed according to the guidelines outlined in the Quality Assurance Project Plan.

### 1.2.5 PM Data

$PM_{10}$ and $PM_{2.5}$ are measured at both the East Plant and West Plant using Met One Instruments' Beta Attenuation Monitors (BAM). At each site, one BAM is configured as a $PM_{2.5}$ Federal Equivalent Method (FEM), which holds the EPA designation (EQPM-0308-170), and the other BAM is configured as a $PM_{10}$ FEM, which holds the EPA designation (EQPM-0798-122). The instruments are operated continuously to collect hourly $PM_{2.5}$ and $PM_{10}$ concentrations. Data are transferred via FTP script every hour to the Air Sciences server and made available to authorized persons via a data web-portal. Appendix D lists hourly $PM_{2.5}$ and $PM_{10}$ data from October 1 through December 31, 2013.

The accuracy of the monitor is assessed through monthly audits of the flow rate by using a certified flow transfer standard.

Second-party audits, adjustments, and general maintenance on the PM monitors are performed according to the guidelines outlined in the Quality Assurance Project Plan.

# 2.0 DATA RECOVERY RATES

Data recovery rates for all parameters are presented in Table 3. Meteorological data recoveries are calculated by dividing the amount of valid hourly averages by the available hourly periods in the quarter. Air quality and particulate data recoveries are calculated by dividing the amount of valid 24-hour averages (for $PM_{10}$, $PM_{2.5}$), valid 24-hour maximum value (for $SO_2$, $NO_2$), or valid daily rolling 8-hour maximum ($O_3$) values by the number of days in the quarter. Particulate and air quality 24-hour averages or maximums are valid if greater than 75 percent of the hourly readings are valid for that day (at least 18 out of 24 hours).

**Table 3. Data Recovery Rates, East Plant and West Plant**
**October 1 – December 31, 2013**
**(percent)**

| | East Plant | | West Plant | | |
|---|---|---|---|---|---|
| **Parameter*** | **Recorded Observations** | **Recovery Rate** | **Recorded Observations** | **Recovery Rate** | **Minimum Required Recovery Rate** |
| Meteorological | | | | | |
| Wind speed (10 m) | 2,208 | 100 | 2,208 | 100 | 90 |
| Wind direction (10 m) | 2,208 | 100 | 2,208 | 100 | 90 |
| Temperature (2 m) | 2,208 | 100 | 2,208 | 100 | 90 |
| Delta temperature | 2,208 | 100 | 2,208 | 100 | 90 |
| Relative humidity | 2,208 | 100 | 2,208 | 100 | 90 |
| Barometric pressure | 2,208 | 100 | 2,208 | 100 | 90 |
| Precipitation | 2,208 | 100 | 2,208 | 100 | 90 |
| Solar radiation | 2,208 | 100 | 2,208 | 100 | 90 |
| $NO_2$ | 87 | 94.6 | -- | -- | 75 |
| $O_3$ | 91 | 98.9 | -- | -- | 75 |
| $SO_2$ | 91 | 98.9 | -- | -- | 75 |
| $PM_{10}$ | 92 | 100 | 90 | 97.8 | 75 |
| $PM_{2.5}$ | 90 | 97.8 | 90 | 97.8 | 75 |

*Meteorological parameters are observed hourly (2,208 hours in this period).
$NO_2$, $O_3$, $SO_2$, and PM parameters are observed every 24 hours (92 days in this period).

## 2.1 Data Loss

### 2.1.1 Meteorological Data Loss

#### 2.1.1.1 East Plant

No meteorological data were invalidated at the East Plant station for this quarter.

#### 2.1.1.2 West Plant

No meteorological data were invalidated at the West Plant station for this quarter.

### 2.1.2 $NO_2$ Data Loss

$NO_2$ 24-hour maximum data were invalidated for October 9, 2013, due to a calibration performed by Air Sciences. Data were also invalidated from December 27 through December 30, 2013, due to daily zero/span check results outside of accepted parameters.

Additional invalid hourly $NO_2$ data were due to daily zero/span checks, Level 1 zero/span checks, regularly scheduled maintenance, power outages, and internal instrument errors.

### 2.1.3 $SO_2$ Data Loss

$SO_2$ 24-hour maximum data were invalidated for October 9, 2013, due to a calibration performed by Air Sciences.

Additional invalid hourly $SO_2$ data were due to daily zero/span checks, Level 1 zero/span checks, regularly scheduled maintenance, power outages, and internal instrument errors.

### 2.1.4 $O_3$ Data Loss

$O_3$ rolling 8-hour maximum data were invalidated for October 9, 2013, due to a calibration performed by Air Sciences.

Additional invalid hourly $O_3$ data were due to daily zero/span checks, Level 1 zero/span checks, regularly scheduled maintenance, power outages, and internal instrument errors.

### 2.1.5 PM Data Loss

#### 2.1.5.1 East Plant

Hourly $PM_{10}$ data were invalidated on October 8, 2013, due to maintenance and a calibration performed by Air Sciences.

Hourly $PM_{2.5}$ data were invalidated on October 8, 2013, due to maintenance and a calibration performed by Air Sciences. From December 12 to December 13, 2013, 18 hours of $PM_{2.5}$ data are invalid due to a tape break error.

Additional invalid hourly PM data at the East Plant were due to monthly flow verifications, regularly scheduled maintenance, power outages, and internal instrument errors.

### 2.1.5.2 West Plant

Hourly $PM_{10}$ data were invalidated on October 8, 2013, due to maintenance and a calibration performed by Air Sciences.

Hourly $PM_{2.5}$ data were invalidated on October 8, 2013, due to maintenance and a calibration performed by Air Sciences. Tape break errors resulted in 14 hours of invalid $PM_{2.5}$ data from October 28 to October 29, 2013, and 8 hours of invalid $PM_{2.5}$ data on December 13, 2013.

Additional invalid hourly PM data at the West Plant were due to monthly flow verifications and regularly scheduled maintenance.


## 2.2 Quality Control

Quality assurance, equipment calibration, and audit procedures are conducted in accordance with the following documents:

- Quality Assurance Handbook for Air Pollution Measurement Systems, Volume II: Ambient Air Quality Monitoring Program (EPA-454/B-13-003, May 2013)
- Quality Assurance Handbook for Air Pollution Measurement Systems, Volume IV: Meteorological Measurements (EPA-454/B-08-002, March 2008)
- Transfer Standards for the Calibration of Ambient Air Monitoring Analyzers for Ozone (EPA-454/B-10-001, November 2010)
- Code of Federal Regulations (40 CFR Parts 50 and 58)
- Ambient Monitoring Guidelines for Prevention of Significant Deterioration (PSD) (EPA-450/4-87-007, May 1987)
- Meteorological Monitoring Guidance for Regulatory Modeling Applications (EPA-454/R-99-005, February 2000)

Audits and/or calibrations of meteorological instrumentation are required every six months. Audits and/or calibrations of the ambient air quality monitors and analyzers are required every three months. At the East and West Plant, Air Sciences performed calibrations of the particulate and air quality analyzers between October 8, and October 9, 2013. Site checks on the meteorological sensors, particulate instruments, and gas analyzers continue to be conducted on a weekly basis. Copies of the audit/calibration report, flow verifications, and site check forms can be found in Appendices F-K.

**Figure 2. Dates of Site Checks, Audits, and Calibrations**
**October 1- December 31, 2013**



# 3.0 METEOROLOGICAL DATA SUMMARY AND DISCUSSION

## 3.1 Meteorological Data Summary

Meteorological data from the fourth quarter have been compiled and summarized in graphical and tabular form. A schematic of meteorology summary sheets is shown in Figure 3. Meteorological summary sheets (Figure 4 and Figure 5) are comprised of the following:

**Wind Rose –** Graphically depicts the percentage of winds that come from each of the 16 directions for the reported period. Wind speeds are divided into six subcategories ranging from less than 0.5 m/s (the measurement threshold of the instrument) to greater than 11.75 m/ s.


**Wind Frequency Table –** A two-part table. The left part of the Wind Frequency Table shows the percentage of occurrence of winds for each of the 16 directions that occur in each of the six Wind Speed Class Intervals. The right part shows the percentage of occurrence of winds for each of the 16 directions that occur in each of the six Stability Classes.

**Meteorology Charts –** Graphically summarize recorded hourly meteorological parameters by month. Chart types include stock-ticker charts (with high, low, and average hourly values for each month) and bar charts.


**Instantaneous Wind Frequency and Maximum Chart –** Graphically summarizes instantaneous (two-second) wind speeds as a percentage of occurrences for each of the nine wind speed intervals and the magnitude, date, and time of the maximum instantaneous wind speed for each month.

**Figure 3. Example Schematic of Meteorological Data Sheets**

## Wind Rose





## Meteorology Charts




## Wind Frequency Tables


| | Speed Class Intervals (m/s) (percent of occurrence) | | | | | | | Mean | Stability Class | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed | A | B | C | D | E | F | All |
| N | 0.2 | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.5 | 1.9 | 0.0 | 0.1 | 0.1 | 0.1 | 0.0 | 0.2 | 0.5 |
| NNE | 0.0 | 0.2 | 0.5 | 1.8 | 2.1 | 0.9 | 5.5 | 7.4 | 0.0 | 0.2 | 0.6 | 4.7 | 0.0 | 0.1 | 5.6 |
| NE | 0.3 | 1.3 | 3.9 | 3.7 | 3.0 | 0.2 | 12.5 | 5.4 | 0.0 | 0.2 | 1.2 | 10.5 | 0.4 | 0.2 | 12.5 |
| ENE | 0.8 | 3.6 | 1.3 | 0.1 | 0.0 | 0.0 | 5.9 | 2.5 | 0.0 | 0.2 | 0.8 | 2.2 | 1.7 | 1.2 | 6.1 |
| E | 1.9 | 3.5 | 0.7 | 0.1 | 0.0 | 0.0 | 6.3 | 2.0 | 0.0 | 0.4 | 1.0 | 1.9 | 1.1 | 2.0 | 6.4 |
| ESE | 3.6 | 3.5 | 1.0 | 0.0 | 0.0 | 0.0 | 8.1 | 1.8 | 0.0 | 0.5 | 1.7 | 1.8 | 1.3 | 3.5 | 8.8 |
| SE | 6.0 | 2.0 | 0.4 | 0.0 | 0.0 | 0.0 | 8.4 | 1.3 | 0.0 | 0.5 | 0.4 | 0.8 | 1.0 | 6.6 | 9.3 |
| SSE | 7.3 | 1.7 | 0.5 | 0.0 | 0.0 | 0.0 | 9.6 | 1.2 | 0.0 | 0.3 | 0.5 | 1.0 | 0.5 | 8.0 | 10.2 |
| S | 3.6 | 1.9 | 1.7 | 0.5 | 0.0 | 0.0 | 7.8 | 2.2 | 0.1 | 0.4 | 1.5 | 2.0 | 0.4 | 3.8 | 8.3 |
| SSW | 1.4 | 3.4 | 1.7 | 0.8 | 0.1 | 0.0 | 7.3 | 2.8 | 0.0 | 1.0 | 1.5 | 3.1 | 0.7 | 1.0 | 7.3 |
| SW | 1.9 | 7.0 | 0.9 | 0.0 | 0.0 | 0.0 | 9.7 | 2.1 | 0.0 | 2.0 | 3.9 | 1.6 | 0.8 | 1.5 | 9.8 |
| WSW | 2.3 | 6.3 | 1.6 | 0.0 | 0.0 | 0.0 | 10.2 | 2.2 | 0.0 | 1.4 | 2.4 | 3.0 | 1.3 | 2.2 | 10.2 |
| W | 0.8 | 2.0 | 0.3 | 0.0 | 0.0 | 0.0 | 3.1 | 2.0 | 0.0 | 0.2 | 0.5 | 0.7 | 0.7 | 0.9 | 3.1 |
| WNW | 0.5 | 0.4 | 0.1 | 0.0 | 0.0 | 0.0 | 1.0 | 1.8 | 0.0 | 0.1 | 0.0 | 0.2 | 0.1 | 0.6 | 1.0 |
| NW | 0.2 | 0.5 | 0.0 | 0.0 | 0.0 | 0.0 | 0.7 | 1.7 | 0.0 | 0.1 | 0.0 | 0.0 | 0.2 | 0.2 | 0.7 |
| NNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.1 | 1.7 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.1 |
| All | 31.0 | 37.5 | 14.5 | 7.2 | 5.3 | 1.0 | 96.5 | 2.7 | 0.2 | 7.7 | 16.1 | 33.6 | 10.2 | 32.2 | 100.0 |

## Instantaneous Wind Frequency & Maximum Chart



# Figure 4: East Plant Meteorological Data Summary

Meteorological Data: October 1 - December 31, 2013




Calms (< 0.447 m/s): 1.8%
Mean wind speed: 3.6 m/s

Notes: Shown as direction from which wind is blowing.
Calms are winds with speeds less than 0.447 m/s.


**Wind Frequency Distribution**


Resolution Copper Mining LLC
East Plant
October 1 - December 31, 2013


AIR SCIENCES INC.
DENVER • PORTLAND


## Hourly Statistics














| Direction | Speed Class Intervals (m/s) (percent of occurrence) 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Mean Speed |
|---|---|---|---|---|---|---|---|---|
| N | 0.1 | 0.1 | 0.1 | 0.0 | 0.0 | 0.0 | 0.4 | 2.3 |
| NNE | 0.0 | 0.4 | 1.0 | 2.4 | 2.1 | 1.0 | 7.0 | 7.2 |
| NE | 0.2 | 1.2 | 5.8 | 8.0 | 6.3 | 0.7 | 22.1 | 6.0 |
| ENE | 0.5 | 2.7 | 2.9 | 1.4 | 0.4 | 0.0 | 7.8 | 3.7 |
| E | 1.8 | 2.8 | 1.5 | 0.3 | 0.3 | 0.0 | 6.7 | 2.7 |
| ESE | 2.3 | 3.6 | 1.0 | 0.0 | 0.0 | 0.0 | 6.8 | 2.0 |
| SE | 3.7 | 2.1 | 0.5 | 0.0 | 0.0 | 0.0 | 6.3 | 1.5 |
| SSE | 4.6 | 2.0 | 0.1 | 0.0 | 0.0 | 0.0 | 6.7 | 1.3 |
| S | 1.7 | 2.5 | 2.9 | 1.0 | 0.0 | 0.0 | 8.1 | 3.0 |
| SSW | 0.9 | 3.6 | 3.7 | 0.8 | 0.2 | 0.0 | 9.2 | 3.2 |
| SW | 1.3 | 4.1 | 0.4 | 0.0 | 0.0 | 0.0 | 5.8 | 2.1 |
| WSW | 1.5 | 4.6 | 1.4 | 0.0 | 0.0 | 0.0 | 7.5 | 2.3 |
| W | 1.0 | 1.8 | 0.0 | 0.0 | 0.0 | 0.0 | 2.9 | 1.8 |
| WNW | 0.2 | 0.3 | 0.1 | 0.0 | 0.0 | 0.0 | 0.6 | 2.0 |
| NW | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.2 | 0.9 |
| NNW | 0.1 | 0.1 | 0.0 | 0.0 | 0.0 | 0.0 | 0.3 | 1.3 |
| All | 20.1 | 31.7 | 21.5 | 14.0 | 9.2 | 1.7 | 98.2 | 3.6 |

| D | Stability Class A | B | C | D | E | F | All |
|---|---|---|---|---|---|---|---|
| N | 0.0 | 0.1 | 0.1 | 0.0 | 0.0 | 0.1 | 0.4 |
| N | 0.0 | 0.2 | 1.0 | 5.7 | 0.0 | 0.0 | 7.0 |
| N | 0.0 | 0.3 | 2.3 | 18.9 | 0.3 | 0.3 | 22.1 |
| E | 0.0 | 0.0 | 0.9 | 5.0 | 1.2 | 0.7 | 7.9 |
| E | 0.0 | 0.3 | 1.1 | 2.6 | 1.1 | 1.8 | 6.9 |
| E | 0.0 | 0.5 | 1.2 | 1.7 | 1.4 | 2.1 | 7.0 |
| S | 0.0 | 0.3 | 0.4 | 1.1 | 1.1 | 3.7 | 6.7 |
| S | 0.0 | 0.2 | 0.5 | 0.7 | 1.1 | 4.7 | 7.2 |
| S | 0.0 | 0.5 | 2.1 | 3.1 | 0.5 | 1.9 | 8.2 |
| S | 0.0 | 1.1 | 2.4 | 3.8 | 1.0 | 1.0 | 9.3 |
| S | 0.0 | 1.4 | 1.6 | 0.8 | 0.7 | 1.3 | 5.9 |
| W | 0.0 | 1.0 | 1.5 | 2.6 | 0.9 | 1.6 | 7.6 |
| W | 0.0 | 0.4 | 0.1 | 0.2 | 1.0 | 1.2 | 2.9 |
| W | 0.0 | 0.0 | 0.1 | 0.1 | 0.0 | 0.3 | 0.6 |
| N | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.2 | 0.2 |
| N | 0.0 | 0.0 | 0.0 | 0.0 | 0.1 | 0.1 | 0.3 |
| A | 0.3 | 6.5 | 15.5 | 46.3 | 10.4 | 21.1 | 100.0 |



# Figure 5: West Plant Meteorological Data Summary

Meteorological Data: October 1 - December 31, 2013




Notes: Shown as direction from which wind is blowing.
Calms are winds with speeds less than 0.447 m/s.

**Wind Frequency Distribution**


Resolution Copper Mining LLC
West Plant
October 1 - December 31, 2013


AIR SCIENCES INC.
DENVER • PORTLAND

| Direction | Speed Class Intervals (m/s) (percent of occurrence) 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Mean Speed |
|---|---|---|---|---|---|---|---|---|
| N | 2.9 | 1.0 | 0.8 | 0.1 | 0.0 | 0.0 | 4.9 | 1.8 |
| NNE | 2.8 | 2.2 | 1.3 | 0.6 | 0.4 | 0.3 | 7.7 | 2.9 |
| NE | 2.9 | 3.4 | 4.9 | 2.8 | 2.1 | 1.4 | 17.4 | 4.7 |
| ENE | 1.2 | 2.2 | 5.0 | 2.9 | 0.7 | 0.0 | 12.0 | 4.2 |
| E | 0.6 | 1.4 | 2.1 | 0.3 | 0.2 | 0.0 | 4.6 | 3.3 |
| ESE | 1.0 | 1.3 | 0.9 | 0.0 | 0.0 | 0.0 | 3.1 | 2.3 |
| SE | 0.7 | 1.0 | 0.6 | 0.0 | 0.0 | 0.0 | 2.4 | 2.3 |
| SSE | 0.9 | 1.0 | 1.2 | 0.1 | 0.0 | 0.0 | 3.1 | 2.6 |
| S | 0.8 | 1.7 | 0.5 | 0.4 | 0.0 | 0.0 | 3.4 | 2.7 |
| SSW | 1.1 | 1.8 | 1.5 | 0.9 | 0.2 | 0.0 | 5.4 | 3.3 |
| SW | 0.8 | 2.4 | 2.7 | 0.5 | 0.0 | 0.0 | 6.5 | 3.2 |
| WSW | 1.0 | 3.4 | 4.6 | 0.5 | 0.0 | 0.0 | 9.5 | 3.0 |
| W | 2.1 | 2.4 | 1.2 | 0.1 | 0.0 | 0.0 | 5.8 | 2.1 |
| WNW | 2.6 | 1.0 | 0.4 | 0.0 | 0.0 | 0.0 | 4.0 | 1.5 |
| NW | 2.3 | 0.7 | 0.3 | 0.0 | 0.0 | 0.0 | 3.3 | 1.4 |
| NNW | 2.3 | 1.3 | 0.6 | 0.0 | 0.0 | 0.0 | 4.2 | 1.7 |
| All | 26.0 | 28.1 | 28.5 | 9.2 | 3.7 | 1.7 | 97.3 | 3.1 |

| D | Stability Class A | B | C | D | E | F | All |
|---|---|---|---|---|---|---|---|
| N | 0.0 | 0.0 | 0.4 | 0.8 | 0.7 | 3.2 | 5.2 |
| N | 0.0 | 0.1 | 0.5 | 2.6 | 1.0 | 3.8 | 8.1 |
| N | 0.0 | 0.3 | 1.4 | 10.3 | 1.9 | 3.8 | 17.7 |
| E | 0.0 | 0.2 | 2.1 | 7.9 | 0.9 | 1.1 | 12.1 |
| E | 0.0 | 0.1 | 1.1 | 2.2 | 0.4 | 0.8 | 4.7 |
| E | 0.0 | 0.2 | 1.1 | 0.8 | 0.4 | 0.7 | 3.2 |
| S | 0.0 | 0.2 | 1.2 | 0.4 | 0.4 | 0.2 | 2.4 |
| S | 0.1 | 0.6 | 1.3 | 0.7 | 0.4 | 0.1 | 3.2 |
| S | 0.1 | 0.9 | 1.2 | 0.7 | 0.4 | 0.2 | 3.4 |
| S | 0.1 | 1.0 | 1.5 | 2.1 | 0.5 | 0.2 | 5.4 |
| S | 0.0 | 0.8 | 2.5 | 2.5 | 0.4 | 0.3 | 6.5 |
| W | 0.1 | 1.3 | 3.1 | 3.8 | 0.7 | 0.6 | 9.6 |
| W | 0.0 | 0.4 | 1.0 | 1.7 | 1.5 | 1.3 | 6.0 |
| W | 0.0 | 0.0 | 0.1 | 0.9 | 1.2 | 2.0 | 4.2 |
| N | 0.0 | 0.0 | 0.1 | 0.4 | 0.7 | 2.6 | 3.8 |
| N | 0.0 | 0.1 | 0.5 | 0.6 | 0.9 | 2.5 | 4.6 |
| A | 0.5 | 6.2 | 19.3 | 38.4 | 12.4 | 23.3 | 100.0 |

## Hourly Statistics



## 3.2 Meteorological Data Discussion


The meteorological data collected at the East and the West Plant sites for the fourth quarter of 2013 met all data recovery objectives.

# 4.0 PM DATA SUMMARY AND DISCUSSION

## 4.1 East Plant PM Data Summary

Figure 6 presents the $PM_{10}$ and $PM_{2.5}$ data collected at the East Plant site for 2013, and compares the data to the $PM_{10}$ and $PM_{2.5}$ NAAQS. The second-high 24-hour average for $PM_{10}$, and the 98th percentile for $PM_{2.5}$ are labeled. The daily mean value for $PM_{10}$ and $PM_{2.5}$ are shown in the lower-right corner.


**Figure 6. East Plant Particulate Data**



## 4.2 West Plant PM Data Summary

Figure 7 presents the $PM_{10}$ and $PM_{2.5}$ data collected at the West Plant site for 2013, and compares the data to the $PM_{10}$ and $PM_{2.5}$ NAAQS. The second-high 24-hour average for $PM_{10}$, and the 98th percentile for $PM_{2.5}$ are labeled. The daily mean value for $PM_{10}$ and $PM_{2.5}$ are shown in the lower-right corner.

**Figure 7. West Plant Particulate Data**




## 4.3 PM Data Discussion

### 4.3.1 $PM_{10}$

The National Ambient Air Quality Standard (NAAQS) for $PM_{10}$ is 150 µg/m³ for a 24-hour average concentration. The standard is met when the expected number of days per calendar year with a 24-hour average concentration above 150 µg/m³ is equal to or less than one (second-high value).

As shown in Figure 6 and Figure 7, the second-high $PM_{10}$ concentrations recorded at the East and West Plants are 109.0 µg/m³ and 134.2 µg/m³, respectively. Both the East and West Plants' second-high values are below the NAAQS of 150 µg/m³.

Actual comparison to the NAAQS requires three calendar years of monitoring data, which have not been obtained at this time.

### 4.3.2 $PM_{2.5}$

The annual primary and secondary $PM_{2.5}$ standards are met when the annual arithmetic mean concentration is less than or equal to 12.0 $\mu g/m^3$. The 24-hour primary and secondary $PM_{2.5}$ standards are met when the 98th percentile 24-hour concentration is less than or equal to 35 $\mu g/m^3$.

As shown in Figure 6 and Figure 7, arithmetic mean concentrations for the East and West Plants are 5.2 and 3.1 $\mu g/m^3$, respectively. Both the East and West Plants' arithmetic mean values are below the NAAQS of 12 $\mu g/m^3$.

Figure 6 and Figure 7 also show the $98^{th}$ percentile concentrations at the East and West Plants, which were 14.8 and 12.6 $\mu g/m^3$, respectively. The $98^{th}$ percentiles of both the East and West Plants' 24-hour concentrations are also below 35 $\mu g/m^3$.

Actual comparison to the NAAQS requires three calendar years of monitoring data, which have not been obtained at this time.

# 5.0 $NO_2$ DATA SUMMARY AND DISCUSSION

## 5.1 $NO_2$ Data Summary

Figure 8 and Figure 9 present the $NO_2$ maximum hourly concentrations for each calendar day, and hourly data collected at the East Plant site for 2013. Figure 8 shows the 98th percentile compared to the one-hour $NO_2$ standard. Figure 9 shows the mean hourly $NO_2$ concentration compared with the annual $NO_2$ standard.

**Figure 8. $NO_2$ Maximum Hourly Concentration for Each Calendar Day**





**Figure 9. $NO_2$ Mean Hourly Concentrations**




## 5.2 $NO_2$ Data Discussion

The level of the annual NAAQS for oxides of nitrogen is 53 parts per billion (ppb), measured in the ambient air as $NO_2$. The annual NAAQS is met when the annual average concentration in a calendar year is less than or equal to 53 ppb.

The level of the 1-hour NAAQS for oxides of nitrogen is 100 ppb, measured in the ambient air as $NO_2$. The 1-hour NAAQS is met when the three-year average of the annual 98th percentile of the daily maximum 1-hour average concentration is less than or equal to 100 ppb.

As shown in Figure 8, the 98$^{th}$ percentile of the daily maximum 1-hour average $NO_2$ concentration for 2013 is 11.6 ppb, which is less than the NAAQS 1-hour primary standard of 100. As shown in Figure 9, the 2013 hourly $NO_2$ average is -0.4 ppb, which is below the annual $NO_2$ NAAQS of 53 ppb.


Actual comparison to the NAAQS requires three calendar years of monitoring data, which have not been obtained at this time.

# 6.0 $SO_2$ DATA SUMMARY AND DISCUSSION

## 6.1 $SO_2$ Data Summary

Figure 10 presents the maximum hourly $SO_2$ concentrations for each calendar day collected at the East Plant site for 2013, and it shows the 99th percentile (labeled) compared to the one-hour $SO_2$ standard.

**Figure 10. $SO_2$ Maximum Hourly Concentration for Each Calendar Day**




## 6.2 $SO_2$ Data Discussion

The level of the primary 1-hour NAAQS for oxides of sulfur is 75 ppb measured in the ambient air as sulfur dioxide ($SO_2$). The 1-hour primary standard is met at an ambient air quality monitoring site when the three-year average of the annual (99th percentile) daily maximum 1-hour average concentrations is less than or equal to 75 ppb.

As shown in Figure 10, the 99th percentile 1-hour maximum concentration for 2013 is 11.8 ppb, which is below the annual $SO_2$ NAAQS of 75 ppb.


Actual comparison to the NAAQS requires three calendar years of monitoring data, which have not been obtained at this time.

# 7.0 $O_3$ DATA SUMMARY AND DISCUSSION

## 7.1 $O_3$ Data Summary

Figure 11 presents the daily rolling 8-hour maximum $O_3$ data collected at the East Plant site for 2013, and it shows the first-highest rolling 8-hour average compared to the eight-hour $O_3$ standard.

**Figure 11. $O_3$ Daily Rolling 8-Hour Maximum, 2013**




## 7.2 $O_3$ Data Discussion

The level of the primary and secondary 8-hour NAAQS for ozone is 0.075 parts per million, daily maximum average. The 8-hour primary and secondary standard is met at an ambient air quality monitoring site when the three-year average of the annual fourth-highest daily maximum 8-hour average $O_3$ concentration is less than or equal to 0.075 ppm.

Figure 11 shows that the averaged fourth-high maximum recorded at the East Plant is 0.064 ppm. This concentration is below the NAAQS 8-hour $O_3$ standard of 0.075 ppm.

Parts of Pinal County and adjacent Maricopa County have been designated as non-attainment areas for 8-hour ozone by the Arizona Department of Environmental Quality (ADEQ).

Actual comparison to the NAAQS requires three calendar years of monitoring data, which have not been obtained at this time.

# Appendix A: Frequency Distributions of Winds by Speed, Direction, and Stability

# Frequency of Winds By Direction and Speed - 10m
## Stability Class A
## East Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| ENE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| E | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| ESE | 16.7 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 16.7 | 1.5 |
| SE | 0.0 | 16.7 | 0.0 | 0.0 | 0.0 | 0.0 | 16.7 | 1.8 |
| SSE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| S | 0.0 | 16.7 | 0.0 | 0.0 | 0.0 | 0.0 | 16.7 | 1.9 |
| SSW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| SW | 0.0 | 16.7 | 0.0 | 0.0 | 0.0 | 0.0 | 16.7 | 1.5 |
| WSW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| W | 0.0 | 16.7 | 0.0 | 0.0 | 0.0 | 0.0 | 16.7 | 1.6 |
| WNW | 0.0 | 16.7 | 0.0 | 0.0 | 0.0 | 0.0 | 16.7 | 1.9 |
| NW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| All | 16.7 | 83.3 | 0.0 | 0.0 | 0.0 | 0.0 | 100.0 | 1.7 |

Calms (< 0.447 m/s): 0.0%

Mean wind speed: 1.7 m/s

Percent Occurence for this Stability Class: 0.3%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class B
## East Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.7 | 0.7 | 0.0 | 0.0 | 0.0 | 1.4 | 3.7 |
| NNE | 0.0 | 1.4 | 1.4 | 0.0 | 0.0 | 0.0 | 2.8 | 3.5 |
| NE | 0.0 | 4.2 | 0.7 | 0.0 | 0.0 | 0.0 | 4.9 | 2.2 |
| ENE | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 0.0 | 0.7 | 2.0 |
| E | 0.7 | 1.4 | 2.1 | 0.0 | 0.0 | 0.0 | 4.2 | 3.4 |
| ESE | 2.8 | 1.4 | 3.5 | 0.0 | 0.0 | 0.0 | 7.7 | 2.5 |
| SE | 0.0 | 2.1 | 2.8 | 0.0 | 0.0 | 0.0 | 4.9 | 2.8 |
| SSE | 0.0 | 2.8 | 0.0 | 0.0 | 0.0 | 0.0 | 2.8 | 1.9 |
| S | 0.7 | 4.2 | 3.5 | 0.0 | 0.0 | 0.0 | 8.4 | 3.0 |
| SSW | 0.0 | 9.8 | 7.7 | 0.0 | 0.0 | 0.0 | 17.5 | 2.9 |
| SW | 0.0 | 22.4 | 0.0 | 0.0 | 0.0 | 0.0 | 22.4 | 2.3 |
| WSW | 1.4 | 12.6 | 2.1 | 0.0 | 0.0 | 0.0 | 16.1 | 2.4 |
| W | 0.7 | 4.9 | 0.0 | 0.0 | 0.0 | 0.0 | 5.6 | 2.3 |
| WNW | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 0.0 | 0.7 | 1.9 |
| NW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| All | 6.3 | 69.2 | 24.5 | 0.0 | 0.0 | 0.0 | 100.0 | 2.6 |

Calms (< 0.447 m/s): 0.0%

Mean wind speed: 2.6 m/s

Percent Occurence for this Stability Class: 6.5%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class C
## East Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.3 | 0.3 | 0.0 | 0.0 | 0.0 | 0.6 | 3.0 |
| NNE | 0.0 | 0.9 | 3.8 | 2.0 | 0.0 | 0.0 | 6.7 | 4.4 |
| NE | 0.0 | 1.8 | 12.9 | 0.3 | 0.0 | 0.0 | 14.9 | 4.0 |
| ENE | 0.6 | 1.5 | 3.5 | 0.3 | 0.0 | 0.0 | 5.8 | 3.3 |
| E | 2.3 | 2.6 | 2.0 | 0.3 | 0.0 | 0.0 | 7.3 | 2.5 |
| ESE | 1.2 | 4.1 | 2.3 | 0.0 | 0.0 | 0.0 | 7.6 | 2.6 |
| SE | 0.0 | 2.6 | 0.0 | 0.0 | 0.0 | 0.0 | 2.6 | 2.3 |
| SSE | 0.6 | 2.0 | 0.9 | 0.0 | 0.0 | 0.0 | 3.5 | 2.4 |
| S | 0.3 | 3.2 | 8.5 | 1.5 | 0.0 | 0.0 | 13.5 | 3.6 |
| SSW | 0.3 | 7.0 | 7.6 | 0.6 | 0.0 | 0.0 | 15.5 | 3.1 |
| SW | 0.0 | 9.1 | 1.5 | 0.0 | 0.0 | 0.0 | 10.5 | 2.5 |
| WSW | 0.3 | 7.9 | 1.5 | 0.0 | 0.0 | 0.0 | 9.6 | 2.5 |
| W | 0.0 | 0.9 | 0.0 | 0.0 | 0.0 | 0.0 | 0.9 | 2.5 |
| WNW | 0.0 | 0.6 | 0.0 | 0.0 | 0.0 | 0.0 | 0.6 | 2.4 |
| NW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNW | 0.0 | 0.3 | 0.0 | 0.0 | 0.0 | 0.0 | 0.3 | 1.6 |
| All | 5.6 | 44.7 | 44.7 | 5.0 | 0.0 | 0.0 | 100.0 | 3.1 |

Calms (< 0.447 m/s): 0.0%

Mean wind speed: 3.1 m/s

Percent Occurence for this Stability Class: 15.5%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class D
## East Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.0 | 0.1 | 0.0 | 0.0 | 0.0 | 0.1 | 3.0 |
| NNE | 0.0 | 0.3 | 0.8 | 4.4 | 4.6 | 2.3 | 12.3 | 7.9 |
| NE | 0.1 | 0.7 | 8.0 | 17.0 | 13.5 | 1.5 | 40.8 | 6.5 |
| ENE | 0.3 | 1.9 | 5.0 | 2.9 | 0.8 | 0.0 | 10.9 | 4.4 |
| E | 0.7 | 1.4 | 2.3 | 0.6 | 0.6 | 0.0 | 5.6 | 3.8 |
| ESE | 0.6 | 2.3 | 0.8 | 0.1 | 0.0 | 0.0 | 3.7 | 2.5 |
| SE | 1.1 | 0.5 | 0.7 | 0.0 | 0.0 | 0.0 | 2.3 | 2.0 |
| SSE | 0.3 | 1.2 | 0.0 | 0.0 | 0.0 | 0.0 | 1.5 | 2.3 |
| S | 0.0 | 2.3 | 2.6 | 1.8 | 0.0 | 0.0 | 6.7 | 3.9 |
| SSW | 0.2 | 2.2 | 3.9 | 1.6 | 0.4 | 0.0 | 8.2 | 4.0 |
| SW | 0.1 | 1.2 | 0.4 | 0.0 | 0.0 | 0.0 | 1.7 | 2.4 |
| WSW | 0.2 | 3.1 | 2.3 | 0.0 | 0.0 | 0.0 | 5.6 | 2.9 |
| W | 0.0 | 0.4 | 0.1 | 0.0 | 0.0 | 0.0 | 0.5 | 2.7 |
| WNW | 0.0 | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 0.2 | 3.6 |
| NW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| All | 3.5 | 17.2 | 27.2 | 28.4 | 19.9 | 3.7 | 99.9 | 5.3 |

Calms (< 0.447 m/s): 0.1%

Mean wind speed: 5.3 m/s

Percent Occurence for this Stability Class: 46.3%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class E
## East Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNE | 0.0 | 0.0 | 0.0 | 0.4 | 0.0 | 0.0 | 0.4 | 6.9 |
| NE | 0.0 | 2.2 | 0.0 | 0.4 | 0.0 | 0.0 | 2.6 | 2.6 |
| ENE | 0.4 | 10.4 | 0.9 | 0.0 | 0.0 | 0.0 | 11.7 | 2.4 |
| E | 3.0 | 7.4 | 0.0 | 0.0 | 0.0 | 0.0 | 10.4 | 1.9 |
| ESE | 2.6 | 9.6 | 0.0 | 0.0 | 0.0 | 0.0 | 12.2 | 1.9 |
| SE | 4.8 | 5.7 | 0.0 | 0.0 | 0.0 | 0.0 | 10.4 | 1.6 |
| SSE | 5.7 | 4.3 | 0.0 | 0.0 | 0.0 | 0.0 | 10.0 | 1.5 |
| S | 0.4 | 3.0 | 0.9 | 0.0 | 0.0 | 0.0 | 4.3 | 2.3 |
| SSW | 0.4 | 7.0 | 1.7 | 0.0 | 0.0 | 0.0 | 9.1 | 2.3 |
| SW | 1.7 | 4.8 | 0.0 | 0.0 | 0.0 | 0.0 | 6.5 | 1.8 |
| WSW | 3.0 | 5.7 | 0.0 | 0.0 | 0.0 | 0.0 | 8.7 | 1.8 |
| W | 1.7 | 7.4 | 0.0 | 0.0 | 0.0 | 0.0 | 9.1 | 2.0 |
| WNW | 0.0 | 0.4 | 0.0 | 0.0 | 0.0 | 0.0 | 0.4 | 2.0 |
| NW | 0.4 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.4 | 1.3 |
| NNW | 0.4 | 0.9 | 0.0 | 0.0 | 0.0 | 0.0 | 1.3 | 1.6 |
| All | 24.8 | 68.7 | 3.5 | 0.9 | 0.0 | 0.0 | 97.8 | 1.9 |

Calms (< 0.447 m/s): 2.2%

Mean wind speed: 1.9 m/s

Percent Occurence for this Stability Class: 10.4%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class F
## East Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.6 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.6 | 0.7 |
| NNE | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.2 | 0.5 |
| NE | 0.9 | 0.4 | 0.0 | 0.0 | 0.0 | 0.0 | 1.3 | 1.1 |
| ENE | 0.9 | 2.2 | 0.0 | 0.0 | 0.0 | 0.0 | 3.0 | 1.5 |
| E | 3.4 | 4.1 | 0.0 | 0.0 | 0.0 | 0.0 | 7.5 | 1.5 |
| ESE | 6.2 | 3.9 | 0.0 | 0.0 | 0.0 | 0.0 | 10.1 | 1.3 |
| SE | 12.7 | 3.2 | 0.0 | 0.0 | 0.0 | 0.0 | 15.9 | 1.1 |
| SSE | 17.8 | 2.6 | 0.0 | 0.0 | 0.0 | 0.0 | 20.4 | 0.9 |
| S | 7.3 | 1.5 | 0.0 | 0.0 | 0.0 | 0.0 | 8.8 | 1.1 |
| SSW | 3.4 | 0.9 | 0.0 | 0.0 | 0.0 | 0.0 | 4.3 | 1.1 |
| SW | 4.9 | 0.6 | 0.0 | 0.0 | 0.0 | 0.0 | 5.6 | 1.1 |
| WSW | 4.7 | 2.4 | 0.0 | 0.0 | 0.0 | 0.0 | 7.1 | 1.3 |
| W | 3.9 | 1.5 | 0.0 | 0.0 | 0.0 | 0.0 | 5.4 | 1.3 |
| WNW | 0.9 | 0.4 | 0.0 | 0.0 | 0.0 | 0.0 | 1.3 | 1.4 |
| NW | 0.6 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.6 | 0.7 |
| NNW | 0.4 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.4 | 0.9 |
| All | 69.0 | 23.7 | 0.0 | 0.0 | 0.0 | 0.0 | 92.7 | 1.1 |

Calms (< 0.447 m/s): 7.3%

Mean wind speed: 1.1 m/s

Percent Occurence for this Stability Class: 21.1%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class A
## West Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| ENE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| E | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| ESE | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| SE | 0.0 | 9.1 | 0.0 | 0.0 | 0.0 | 0.0 | 9.1 | 2.0 |
| SSE | 0.0 | 18.2 | 0.0 | 0.0 | 0.0 | 0.0 | 18.2 | 1.6 |
| S | 0.0 | 27.3 | 0.0 | 0.0 | 0.0 | 0.0 | 27.3 | 1.7 |
| SSW | 0.0 | 18.2 | 0.0 | 0.0 | 0.0 | 0.0 | 18.2 | 1.7 |
| SW | 0.0 | 9.1 | 0.0 | 0.0 | 0.0 | 0.0 | 9.1 | 1.7 |
| WSW | 0.0 | 18.2 | 0.0 | 0.0 | 0.0 | 0.0 | 18.2 | 1.6 |
| W | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| WNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| All | 0.0 | 100.0 | 0.0 | 0.0 | 0.0 | 0.0 | 100.0 | 1.7 |

Calms (< 0.447 m/s): 0.0%

Mean wind speed: 1.7 m/s

Percent Occurence for this Stability Class: 0.5%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class B
## West Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 0.7 | 3.2 |
| NNE | 0.0 | 1.5 | 0.0 | 0.0 | 0.0 | 0.0 | 1.5 | 1.7 |
| NE | 0.0 | 1.5 | 2.9 | 0.0 | 0.0 | 0.0 | 4.4 | 3.7 |
| ENE | 0.0 | 2.2 | 1.5 | 0.0 | 0.0 | 0.0 | 3.6 | 2.7 |
| E | 0.0 | 1.5 | 0.7 | 0.0 | 0.0 | 0.0 | 2.2 | 3.0 |
| ESE | 0.0 | 2.9 | 0.0 | 0.0 | 0.0 | 0.0 | 2.9 | 2.2 |
| SE | 0.0 | 2.2 | 1.5 | 0.0 | 0.0 | 0.0 | 3.6 | 2.8 |
| SSE | 2.9 | 3.6 | 2.9 | 0.0 | 0.0 | 0.0 | 9.5 | 2.2 |
| S | 5.8 | 6.6 | 1.5 | 0.0 | 0.0 | 0.0 | 13.9 | 2.0 |
| SSW | 8.0 | 3.6 | 3.6 | 0.0 | 0.0 | 0.0 | 15.3 | 2.1 |
| SW | 1.5 | 6.6 | 5.1 | 0.0 | 0.0 | 0.0 | 13.1 | 2.9 |
| WSW | 0.7 | 8.8 | 11.7 | 0.0 | 0.0 | 0.0 | 21.2 | 3.1 |
| W | 0.7 | 4.4 | 1.5 | 0.0 | 0.0 | 0.0 | 6.6 | 2.4 |
| WNW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NW | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 |
| NNW | 0.0 | 0.7 | 0.7 | 0.0 | 0.0 | 0.0 | 1.5 | 2.4 |
| All | 19.7 | 46.0 | 34.3 | 0.0 | 0.0 | 0.0 | 100.0 | 2.6 |

Calms (< 0.447 m/s): 0.0%

Mean wind speed: 2.6 m/s

Percent Occurence for this Stability Class: 6.2%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class C
## West Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.0 | 0.5 | 1.6 | 0.0 | 0.0 | 0.0 | 2.1 | 3.7 |
| NNE | 0.0 | 1.2 | 1.4 | 0.0 | 0.0 | 0.0 | 2.6 | 3.3 |
| NE | 0.0 | 1.9 | 4.9 | 0.5 | 0.0 | 0.0 | 7.3 | 3.8 |
| ENE | 0.2 | 4.5 | 5.6 | 0.5 | 0.0 | 0.0 | 10.8 | 3.4 |
| E | 0.0 | 2.1 | 3.8 | 0.0 | 0.0 | 0.0 | 5.9 | 3.5 |
| ESE | 0.5 | 3.1 | 2.1 | 0.0 | 0.0 | 0.0 | 5.6 | 2.8 |
| SE | 1.4 | 2.8 | 1.9 | 0.0 | 0.0 | 0.0 | 6.1 | 2.4 |
| SSE | 1.4 | 2.1 | 3.1 | 0.2 | 0.0 | 0.0 | 6.8 | 2.9 |
| S | 0.7 | 4.0 | 0.9 | 0.5 | 0.0 | 0.0 | 6.1 | 2.7 |
| SSW | 0.2 | 3.1 | 3.8 | 0.9 | 0.0 | 0.0 | 8.0 | 3.5 |
| SW | 0.2 | 4.2 | 8.0 | 0.7 | 0.0 | 0.0 | 13.1 | 3.6 |
| WSW | 0.2 | 4.7 | 11.3 | 0.0 | 0.0 | 0.0 | 16.2 | 3.3 |
| W | 0.2 | 2.6 | 2.6 | 0.0 | 0.0 | 0.0 | 5.4 | 2.9 |
| WNW | 0.0 | 0.7 | 0.0 | 0.0 | 0.0 | 0.0 | 0.7 | 2.4 |
| NW | 0.2 | 0.0 | 0.2 | 0.0 | 0.0 | 0.0 | 0.5 | 2.6 |
| NNW | 0.0 | 1.4 | 1.4 | 0.0 | 0.0 | 0.0 | 2.8 | 3.2 |
| All | 5.4 | 38.7 | 52.6 | 3.3 | 0.0 | 0.0 | 100.0 | 3.2 |

Calms (< 0.447 m/s): 0.0%

Mean wind speed: 3.2 m/s

Percent Occurence for this Stability Class: 19.3%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class D
## West Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 0.1 | 0.5 | 1.2 | 0.4 | 0.0 | 0.0 | 2.1 | 3.6 |
| NNE | 0.2 | 0.7 | 2.5 | 1.7 | 1.1 | 0.7 | 6.8 | 5.6 |
| NE | 0.2 | 2.0 | 8.5 | 7.0 | 5.4 | 3.7 | 26.8 | 6.4 |
| ENE | 0.2 | 1.9 | 9.3 | 7.1 | 1.9 | 0.1 | 20.5 | 4.9 |
| E | 0.1 | 0.9 | 3.4 | 0.7 | 0.6 | 0.0 | 5.8 | 4.2 |
| ESE | 0.4 | 0.6 | 1.2 | 0.0 | 0.0 | 0.0 | 2.1 | 2.8 |
| SE | 0.1 | 0.5 | 0.5 | 0.0 | 0.0 | 0.0 | 1.1 | 2.6 |
| SSE | 0.2 | 0.2 | 1.1 | 0.2 | 0.0 | 0.0 | 1.8 | 3.5 |
| S | 0.0 | 0.4 | 0.5 | 0.8 | 0.1 | 0.0 | 1.8 | 4.7 |
| SSW | 0.5 | 1.4 | 1.4 | 1.8 | 0.5 | 0.0 | 5.5 | 4.4 |
| SW | 0.5 | 2.7 | 2.1 | 1.1 | 0.1 | 0.0 | 6.5 | 3.4 |
| WSW | 0.9 | 3.2 | 4.5 | 1.2 | 0.0 | 0.0 | 9.8 | 3.3 |
| W | 0.5 | 2.1 | 1.5 | 0.2 | 0.0 | 0.0 | 4.4 | 2.8 |
| WNW | 0.1 | 1.2 | 0.9 | 0.0 | 0.0 | 0.0 | 2.2 | 2.8 |
| NW | 0.0 | 0.5 | 0.6 | 0.0 | 0.0 | 0.0 | 1.1 | 3.3 |
| NNW | 0.1 | 0.7 | 0.6 | 0.1 | 0.0 | 0.0 | 1.5 | 3.1 |
| All | 4.3 | 19.5 | 39.8 | 22.2 | 9.7 | 4.5 | 99.9 | 4.7 |

Calms (< 0.447 m/s): 0.1%

Mean wind speed: 4.7 m/s

Percent Occurence for this Stability Class: 38.4%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class E
## West Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 1.8 | 4.0 | 0.0 | 0.0 | 0.0 | 0.0 | 5.9 | 1.8 |
| NNE | 1.1 | 6.2 | 0.7 | 0.0 | 0.0 | 0.0 | 8.1 | 2.2 |
| NE | 1.5 | 9.9 | 4.0 | 0.0 | 0.0 | 0.0 | 15.4 | 2.7 |
| ENE | 0.7 | 3.3 | 2.2 | 0.7 | 0.0 | 0.0 | 7.0 | 3.1 |
| E | 1.1 | 1.8 | 0.0 | 0.0 | 0.0 | 0.0 | 2.9 | 1.6 |
| ESE | 2.2 | 0.7 | 0.4 | 0.0 | 0.0 | 0.0 | 3.3 | 1.7 |
| SE | 2.2 | 0.7 | 0.0 | 0.0 | 0.0 | 0.0 | 2.9 | 1.4 |
| SSE | 1.5 | 1.1 | 0.0 | 0.0 | 0.0 | 0.0 | 2.6 | 1.6 |
| S | 1.8 | 1.5 | 0.0 | 0.0 | 0.0 | 0.0 | 3.3 | 1.5 |
| SSW | 1.5 | 2.6 | 0.0 | 0.0 | 0.0 | 0.0 | 4.0 | 1.6 |
| SW | 2.2 | 0.7 | 0.0 | 0.0 | 0.0 | 0.0 | 2.9 | 1.1 |
| WSW | 2.2 | 3.3 | 0.0 | 0.0 | 0.0 | 0.0 | 5.5 | 1.6 |
| W | 5.5 | 7.0 | 0.0 | 0.0 | 0.0 | 0.0 | 12.5 | 1.6 |
| WNW | 7.3 | 2.2 | 0.0 | 0.0 | 0.0 | 0.0 | 9.5 | 1.2 |
| NW | 2.9 | 2.6 | 0.0 | 0.0 | 0.0 | 0.0 | 5.5 | 1.4 |
| NNW | 3.3 | 3.3 | 0.4 | 0.0 | 0.0 | 0.0 | 7.0 | 1.7 |
| All | 38.8 | 50.9 | 7.7 | 0.7 | 0.0 | 0.0 | 98.2 | 1.9 |

Calms (< 0.447 m/s): 1.8%

Mean wind speed: 1.9 m/s

Percent Occurence for this Stability Class: 12.4%

# Frequency of Winds By Direction and Speed - 10m
## Stability Class F
## West Plant, Resolution
## 10/01/13 - 12/31/13
## (percent of occurrence)

| | Speed Class Intervals (m/s) | | | | | | | Mean |
|---|---|---|---|---|---|---|---|---|
| Direction | 0.5 <1.5 | 1.5 <3 | 3 <5 | 5 <7 | 7 <10 | >=10 | All | Speed |
| N | 11.5 | 1.0 | 0.0 | 0.0 | 0.0 | 0.0 | 12.5 | 0.9 |
| NNE | 11.1 | 3.7 | 0.0 | 0.0 | 0.0 | 0.0 | 14.8 | 1.2 |
| NE | 11.5 | 3.9 | 0.0 | 0.0 | 0.0 | 0.0 | 15.4 | 1.2 |
| ENE | 4.1 | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 4.3 | 1.0 |
| E | 1.9 | 1.2 | 0.0 | 0.0 | 0.0 | 0.0 | 3.1 | 1.3 |
| ESE | 1.9 | 0.8 | 0.0 | 0.0 | 0.0 | 0.0 | 2.7 | 1.2 |
| SE | 0.4 | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.6 | 1.4 |
| SSE | 0.6 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.6 | 1.2 |
| S | 0.2 | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 0.4 | 1.3 |
| SSW | 0.8 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.8 | 0.8 |
| SW | 1.0 | 0.2 | 0.0 | 0.0 | 0.0 | 0.0 | 1.2 | 1.0 |
| WSW | 1.4 | 1.0 | 0.0 | 0.0 | 0.0 | 0.0 | 2.3 | 1.1 |
| W | 5.1 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 5.1 | 0.8 |
| WNW | 7.2 | 0.8 | 0.0 | 0.0 | 0.0 | 0.0 | 8.0 | 1.0 |
| NW | 8.0 | 1.0 | 0.0 | 0.0 | 0.0 | 0.0 | 8.9 | 1.0 |
| NNW | 8.0 | 1.2 | 0.0 | 0.0 | 0.0 | 0.0 | 9.1 | 0.9 |
| All | 74.5 | 15.2 | 0.0 | 0.0 | 0.0 | 0.0 | 89.7 | 1.0 |

Calms (< 0.447 m/s): 10.3%

Mean wind speed: 1.0 m/s

Percent Occurence for this Stability Class: 23.3%

# Appendix B: Monthly Wind Speed Frequencies and Instantaneous Daily Maximum Wind Speeds

Average Frequency Distribution of Wind Speeds - 10m
Resolution - East Plant
Oct-13

| | Wind Speed Interval (percent) | | | | | | | | | Max Gust | Time of |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Day | <5 | 5 <7 | 7 <9 | 9 <11 | 11 <13 | 13 <15 | 15 <17 | 17 <19 | >19 | (m/s) | Gust |
| 1 | 98.60 | 1.30 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.57 | 14:19 |
| 2 | 98.93 | 1.00 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.81 | 16:25 |
| 3 | 94.83 | 4.27 | 0.83 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.83 | 11:34 |
| 4 | 88.00 | 4.90 | 2.60 | 2.07 | 1.63 | 0.73 | 0.07 | 0.00 | 0.00 | 17.60 | 22:59 |
| 5 | 13.80 | 20.37 | 18.93 | 18.40 | 15.90 | 9.10 | 3.00 | 0.50 | 0.03 | 21.20 | 4:28 |
| 6 | 45.83 | 12.73 | 17.77 | 14.53 | 6.33 | 2.10 | 0.57 | 0.13 | 0.00 | 21.10 | 0:39 |
| 7 | 75.47 | 16.37 | 7.30 | 0.87 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.10 | 6:07 |
| 8 | 81.90 | 13.83 | 3.63 | 0.53 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 13.10 | 12:08 |
| 9 | 73.57 | 17.80 | 6.10 | 1.97 | 0.47 | 0.10 | 0.00 | 0.00 | 0.00 | 16.50 | 14:14 |
| 10 | 88.73 | 7.27 | 2.70 | 0.93 | 0.27 | 0.07 | 0.00 | 0.00 | 0.00 | 16.30 | 4:19 |
| 11 | 99.93 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 6.09 | 12:15 |
| 12 | 94.50 | 5.10 | 0.40 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.81 | 9:59 |
| 13 | 87.33 | 9.23 | 2.70 | 0.63 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 14.00 | 11:37 |
| 14 | 98.80 | 1.17 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.14 | 13:46 |
| 15 | 98.60 | 1.37 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.65 | 14:18 |
| 16 | 86.97 | 9.03 | 3.57 | 0.43 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.80 | 8:37 |
| 17 | 98.50 | 1.47 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.99 | 13:46 |
| 18 | 88.73 | 9.67 | 1.47 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.60 | 23:58 |
| 19 | 80.17 | 12.00 | 6.73 | 1.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.90 | 2:22 |
| 20 | 99.23 | 0.77 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.94 | 16:19 |
| 21 | 99.30 | 0.67 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.70 | 15:20 |
| 22 | 71.43 | 17.50 | 10.03 | 1.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.40 | 3:59 |
| 23 | 70.63 | 17.30 | 10.40 | 1.63 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.00 | 8:42 |
| 24 | 94.73 | 4.87 | 0.40 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.91 | 9:50 |
| 25 | 98.00 | 1.87 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.76 | 14:13 |
| 26 | 72.33 | 17.60 | 8.97 | 1.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.20 | 10:30 |
| 27 | 83.57 | 14.80 | 1.60 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.20 | 0:26 |
| 28 | 71.30 | 20.87 | 6.10 | 1.53 | 0.17 | 0.00 | 0.00 | 0.00 | 0.00 | 13.60 | 13:01 |
| 29 | 84.77 | 10.97 | 3.67 | 0.57 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 14.90 | 12:32 |
| 30 | 97.13 | 2.63 | 0.23 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.11 | 15:13 |
| 31 | 96.17 | 3.80 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.09 | 15:49 |
| All | 84.90 | 8.47 | 3.76 | 1.53 | 0.81 | 0.39 | 0.12 | 0.02 | 0.00 | 21.20 | 4:28 |

Average Frequency Distribution of Wind Speeds - 10m
Resolution - East Plant
Nov-13

| | Wind Speed Interval (percent) | | | | | | | | | Max Gust | Time of |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Day | <5 | 5 <7 | 7 <9 | 9 <11 | 11 <13 | 13 <15 | 15 <17 | 17 <19 | >19 | (m/s) | Gust |
| 1 | 83.53 | 12.73 | 3.50 | 0.23 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.80 | 9:21 |
| 2 | 62.67 | 19.13 | 13.63 | 4.27 | 0.27 | 0.00 | 0.00 | 0.00 | 0.00 | 12.90 | 6:42 |
| 3 | 94.37 | 4.73 | 0.83 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 12.00 | 13:36 |
| 4 | 94.37 | 4.90 | 0.70 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.50 | 22:22 |
| 5 | 91.13 | 5.50 | 2.87 | 0.43 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.10 | 23:48 |
| 6 | 34.67 | 28.57 | 23.30 | 11.07 | 2.23 | 0.13 | 0.00 | 0.00 | 0.00 | 15.50 | 3:59 |
| 7 | 43.17 | 20.13 | 21.27 | 12.40 | 2.97 | 0.10 | 0.00 | 0.00 | 0.00 | 14.40 | 0:59 |
| 8 | 89.17 | 10.23 | 0.60 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.86 | 6:35 |
| 9 | 99.73 | 0.27 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.73 | 13:36 |
| 10 | 89.20 | 10.47 | 0.33 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.94 | 10:40 |
| 11 | 66.07 | 22.00 | 10.30 | 1.60 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 11.70 | 23:43 |
| 12 | 44.70 | 30.63 | 17.80 | 5.77 | 1.10 | 0.03 | 0.00 | 0.00 | 0.00 | 14.00 | 10:18 |
| 13 | 19.83 | 24.87 | 27.17 | 21.00 | 6.67 | 0.40 | 0.00 | 0.00 | 0.00 | 14.80 | 1:31 |
| 14 | 83.90 | 11.60 | 4.03 | 0.47 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.10 | 8:20 |
| 15 | 68.90 | 19.27 | 8.07 | 3.00 | 0.63 | 0.10 | 0.00 | 0.00 | 0.00 | 15.30 | 15:10 |
| 16 | 92.63 | 6.43 | 0.80 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.40 | 15:36 |
| 17 | 98.07 | 1.83 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.22 | 11:44 |
| 18 | 98.10 | 1.90 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 6.96 | 10:30 |
| 19 | 98.43 | 1.53 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.47 | 13:09 |
| 20 | 99.03 | 0.87 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.04 | 13:11 |
| 21 | 98.57 | 1.37 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.35 | 12:51 |
| 22 | 90.73 | 8.20 | 1.03 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.10 | 13:54 |
| 23 | 47.77 | 38.30 | 12.70 | 1.20 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 11.90 | 12:10 |
| 24 | 38.00 | 45.70 | 15.57 | 0.70 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.70 | 20:43 |
| 25 | 91.77 | 6.33 | 1.93 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.93 | 2:46 |
| 26 | 33.27 | 32.07 | 23.93 | 10.00 | 0.73 | 0.00 | 0.00 | 0.00 | 0.00 | 12.90 | 14:04 |
| 27 | 18.70 | 30.67 | 26.13 | 17.00 | 6.90 | 0.53 | 0.00 | 0.00 | 0.00 | 15.10 | 10:05 |
| 28 | 45.73 | 26.60 | 20.10 | 6.80 | 0.70 | 0.00 | 0.00 | 0.00 | 0.00 | 13.50 | 4:32 |
| 29 | 93.57 | 6.03 | 0.40 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.50 | 6:00 |
| 30 | 97.77 | 2.17 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.58 | 6:51 |
| All | 73.58 | 14.50 | 7.91 | 3.21 | 0.74 | 0.04 | 0.00 | 0.00 | 0.00 | 15.51 | 3:59 |

Average Frequency Distribution of Wind Speeds - 10m
Resolution - East Plant
Dec-13

| | Wind Speed Interval (percent) | | | | | | | | | Max Gust | Time of |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Day | <5 | 5 <7 | 7 <9 | 9 <11 | 11 <13 | 13 <15 | 15 <17 | 17 <19 | >19 | (m/s) | Gust |
| 1 | 98.20 | 1.80 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.12 | 11:29 |
| 2 | 99.97 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 5.89 | 13:10 |
| 3 | 92.13 | 6.90 | 0.93 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.30 | 14:49 |
| 4 | 89.57 | 7.30 | 2.37 | 0.63 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 16.40 | 9:26 |
| 5 | 98.17 | 1.70 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.01 | 17:08 |
| 6 | 100.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 5.27 | 16:45 |
| 7 | 85.73 | 9.07 | 3.63 | 1.23 | 0.30 | 0.07 | 0.00 | 0.00 | 0.00 | 14.70 | 23:45 |
| 8 | 74.43 | 11.23 | 7.70 | 4.47 | 1.73 | 0.37 | 0.07 | 0.00 | 0.00 | 18.00 | 1:57 |
| 9 | 59.93 | 19.13 | 12.90 | 6.10 | 1.73 | 0.20 | 0.00 | 0.00 | 0.00 | 16.10 | 21:04 |
| 10 | 32.93 | 25.23 | 21.47 | 13.63 | 5.47 | 1.23 | 0.10 | 0.00 | 0.00 | 16.50 | 10:01 |
| 11 | 14.50 | 33.13 | 33.40 | 15.60 | 3.20 | 0.17 | 0.00 | 0.00 | 0.00 | 15.40 | 5:32 |
| 12 | 38.57 | 21.37 | 22.27 | 14.10 | 3.60 | 0.13 | 0.00 | 0.00 | 0.00 | 14.50 | 9:47 |
| 13 | 99.77 | 0.20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.37 | 14:29 |
| 14 | 31.43 | 22.43 | 24.30 | 15.17 | 5.50 | 1.00 | 0.17 | 0.00 | 0.00 | 18.30 | 10:37 |
| 15 | 31.47 | 29.93 | 24.50 | 11.50 | 2.40 | 0.20 | 0.00 | 0.00 | 0.00 | 15.10 | 10:07 |
| 16 | 45.23 | 19.73 | 20.90 | 10.77 | 3.07 | 0.30 | 0.00 | 0.00 | 0.00 | 14.80 | 11:12 |
| 17 | 67.30 | 22.27 | 8.57 | 1.73 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 12.60 | 9:15 |
| 18 | 67.30 | 21.27 | 10.40 | 1.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.10 | 8:11 |
| 19 | 64.63 | 26.73 | 7.73 | 0.87 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 13.10 | 2:55 |
| 20 | 94.87 | 4.63 | 0.50 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.73 | 7:06 |
| 21 | 90.70 | 7.83 | 1.33 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.60 | 6:06 |
| 22 | 99.17 | 0.83 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.12 | 10:51 |
| 23 | 30.43 | 27.17 | 20.23 | 14.53 | 6.43 | 1.13 | 0.07 | 0.00 | 0.00 | 16.00 | 10:13 |
| 24 | 48.70 | 29.10 | 15.53 | 5.30 | 1.23 | 0.13 | 0.00 | 0.00 | 0.00 | 15.60 | 23:39 |
| 25 | 19.07 | 16.50 | 18.83 | 15.73 | 10.57 | 7.77 | 6.43 | 3.53 | 1.53 | 24.00 | 3:18 |
| 26 | 16.53 | 15.97 | 18.63 | 22.90 | 17.93 | 6.70 | 1.20 | 0.07 | 0.00 | 18.40 | 9:58 |
| 27 | 21.57 | 26.90 | 26.70 | 18.40 | 5.90 | 0.50 | 0.00 | 0.00 | 0.00 | 15.60 | 8:26 |
| 28 | 72.37 | 17.53 | 8.50 | 1.57 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 11.80 | 2:13 |
| 29 | 51.20 | 16.30 | 16.97 | 11.57 | 3.50 | 0.47 | 0.07 | 0.00 | 0.00 | 17.00 | 9:55 |
| 30 | 93.47 | 4.83 | 1.40 | 0.33 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.40 | 0:09 |
| 31 | 82.40 | 13.53 | 3.90 | 0.17 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.40 | 8:20 |
| All | 64.89 | 14.86 | 10.77 | 6.05 | 2.35 | 0.66 | 0.26 | 0.12 | 0.05 | 23.96 | 3:18 |

Average Frequency Distribution of Wind Speeds - 10m
Resolution - West Plant
Oct-13

| | Wind Speed Interval (percent) | | | | | | | | | Max Gust | Time of |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Day | <5 | 5 <7 | 7 <9 | 9 <11 | 11 <13 | 13 <15 | 15 <17 | 17 <19 | >19 | (m/s) | Gust |
| 1 | 96.17 | 3.70 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.50 | 12:21 |
| 2 | 95.67 | 4.07 | 0.27 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.91 | 13:16 |
| 3 | 87.23 | 10.67 | 2.00 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.20 | 12:37 |
| 4 | 81.73 | 11.03 | 3.10 | 1.97 | 1.33 | 0.60 | 0.20 | 0.03 | 0.00 | 18.70 | 22:57 |
| 5 | 39.13 | 15.40 | 16.67 | 14.00 | 8.70 | 4.13 | 1.60 | 0.33 | 0.03 | 21.20 | 5:27 |
| 6 | 66.20 | 15.77 | 7.60 | 5.53 | 3.47 | 1.17 | 0.23 | 0.00 | 0.00 | 18.20 | 8:01 |
| 7 | 81.90 | 12.07 | 4.53 | 1.10 | 0.23 | 0.07 | 0.00 | 0.00 | 0.00 | 15.90 | 9:25 |
| 8 | 78.33 | 16.97 | 4.37 | 0.33 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.90 | 12:18 |
| 9 | 63.17 | 16.60 | 12.57 | 6.13 | 1.40 | 0.13 | 0.00 | 0.00 | 0.00 | 15.70 | 15:42 |
| 10 | 85.53 | 11.23 | 2.53 | 0.57 | 0.13 | 0.03 | 0.00 | 0.00 | 0.00 | 14.90 | 4:00 |
| 11 | 94.77 | 5.00 | 0.23 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.73 | 12:56 |
| 12 | 90.23 | 8.43 | 1.27 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 12.80 | 9:04 |
| 13 | 81.90 | 13.87 | 3.83 | 0.40 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.70 | 10:59 |
| 14 | 95.47 | 4.33 | 0.20 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.60 | 13:16 |
| 15 | 91.70 | 7.97 | 0.37 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.40 | 12:25 |
| 16 | 94.60 | 4.73 | 0.63 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.20 | 6:54 |
| 17 | 94.83 | 5.03 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.20 | 12:20 |
| 18 | 96.93 | 3.03 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.83 | 14:37 |
| 19 | 98.83 | 1.17 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.12 | 11:45 |
| 20 | 98.47 | 1.50 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.55 | 14:44 |
| 21 | 97.20 | 2.80 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.17 | 14:54 |
| 22 | 72.63 | 18.27 | 7.07 | 1.77 | 0.27 | 0.00 | 0.00 | 0.00 | 0.00 | 13.40 | 9:13 |
| 23 | 68.43 | 16.90 | 8.97 | 4.13 | 1.27 | 0.27 | 0.03 | 0.00 | 0.00 | 18.30 | 9:26 |
| 24 | 87.10 | 9.33 | 2.43 | 0.97 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 13.60 | 9:51 |
| 25 | 97.03 | 2.87 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.04 | 14:29 |
| 26 | 73.37 | 10.13 | 10.07 | 5.50 | 0.87 | 0.03 | 0.00 | 0.00 | 0.00 | 14.00 | 10:22 |
| 27 | 75.60 | 17.30 | 5.33 | 1.53 | 0.23 | 0.00 | 0.00 | 0.00 | 0.00 | 13.40 | 0:54 |
| 28 | 67.83 | 22.47 | 8.47 | 1.17 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.00 | 11:29 |
| 29 | 77.70 | 17.40 | 4.53 | 0.37 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.80 | 13:21 |
| 30 | 93.83 | 5.93 | 0.23 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.60 | 12:25 |
| 31 | 88.80 | 10.37 | 0.83 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.40 | 4:43 |
| All | 84.27 | 9.88 | 3.50 | 1.47 | 0.58 | 0.21 | 0.07 | 0.01 | 0.00 | 21.20 | 5:27 |

Average Frequency Distribution of Wind Speeds - 10m
Resolution - West Plant
Nov-13

| | Wind Speed Interval (percent) | | | | | | | | | Max Gust | Time of |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Day | <5 | 5 <7 | 7 <9 | 9 <11 | 11 <13 | 13 <15 | 15 <17 | 17 <19 | >19 | (m/s) | Gust |
| 1 | 95.83 | 3.63 | 0.50 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.37 | 7:02 |
| 2 | 58.90 | 19.80 | 12.27 | 5.83 | 2.37 | 0.77 | 0.13 | 0.00 | 0.00 | 17.60 | 8:35 |
| 3 | 82.90 | 14.60 | 2.40 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.80 | 13:48 |
| 4 | 82.70 | 15.33 | 1.87 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 12.50 | 22:05 |
| 5 | 95.20 | 4.63 | 0.17 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.91 | 14:43 |
| 6 | 77.90 | 12.60 | 6.13 | 2.60 | 0.67 | 0.07 | 0.00 | 0.00 | 0.00 | 14.60 | 19:56 |
| 7 | 56.83 | 20.27 | 11.73 | 6.97 | 3.20 | 0.87 | 0.13 | 0.00 | 0.00 | 18.60 | 5:09 |
| 8 | 91.30 | 6.93 | 1.60 | 0.17 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.20 | 2:47 |
| 9 | 97.57 | 2.40 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.99 | 4:32 |
| 10 | 93.20 | 6.60 | 0.17 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.19 | 18:22 |
| 11 | 83.60 | 12.20 | 3.83 | 0.37 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.80 | 11:47 |
| 12 | 66.20 | 21.30 | 8.67 | 2.90 | 0.77 | 0.17 | 0.03 | 0.00 | 0.00 | 19.70 | 23:54 |
| 13 | 36.53 | 20.37 | 13.53 | 10.37 | 8.50 | 6.33 | 3.03 | 1.03 | 0.33 | 24.00 | 4:26 |
| 14 | 80.47 | 14.53 | 4.70 | 0.27 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.50 | 7:22 |
| 15 | 72.97 | 17.50 | 8.03 | 1.37 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 12.90 | 19:02 |
| 16 | 90.93 | 8.50 | 0.53 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.50 | 15:13 |
| 17 | 98.77 | 1.23 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.58 | 11:33 |
| 18 | 98.33 | 1.67 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.37 | 5:10 |
| 19 | 93.70 | 5.97 | 0.33 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.11 | 13:17 |
| 20 | 97.70 | 2.30 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.53 | 12:55 |
| 21 | 95.57 | 3.93 | 0.50 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.40 | 22:21 |
| 22 | 84.47 | 8.10 | 3.97 | 2.17 | 1.00 | 0.27 | 0.03 | 0.00 | 0.00 | 17.20 | 4:20 |
| 23 | 58.20 | 14.30 | 11.53 | 8.00 | 4.77 | 2.23 | 0.77 | 0.13 | 0.03 | 23.20 | 12:24 |
| 24 | 51.57 | 30.20 | 13.90 | 3.47 | 0.73 | 0.10 | 0.00 | 0.00 | 0.00 | 15.60 | 5:29 |
| 25 | 84.60 | 8.83 | 4.73 | 1.77 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 13.10 | 23:17 |
| 26 | 56.60 | 22.17 | 11.47 | 5.50 | 3.33 | 0.93 | 0.10 | 0.00 | 0.00 | 16.30 | 7:20 |
| 27 | 34.13 | 20.87 | 20.00 | 14.00 | 6.43 | 2.63 | 1.27 | 0.43 | 0.20 | 25.00 | 1:55 |
| 28 | 57.63 | 22.13 | 12.87 | 5.47 | 1.53 | 0.33 | 0.03 | 0.00 | 0.00 | 17.30 | 2:35 |
| 29 | 83.07 | 12.13 | 4.20 | 0.57 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 12.50 | 9:24 |
| 30 | 99.63 | 0.33 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.94 | 11:17 |
| All | 78.57 | 11.85 | 5.32 | 2.40 | 1.12 | 0.49 | 0.18 | 0.05 | 0.02 | 25.04 | 1:55 |

Average Frequency Distribution of Wind Speeds - 10m
Resolution - West Plant
Dec-13

| | Wind Speed Interval (percent) | | | | | | | | | Max Gust | Time of |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Day | <5 | 5 <7 | 7 <9 | 9 <11 | 11 <13 | 13 <15 | 15 <17 | 17 <19 | >19 | (m/s) | Gust |
| 1 | 99.47 | 0.53 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 6.14 | 11:37 |
| 2 | 99.13 | 0.87 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 6.96 | 2:55 |
| 3 | 96.50 | 3.47 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.73 | 13:19 |
| 4 | 82.97 | 12.00 | 4.30 | 0.67 | 0.07 | 0.00 | 0.00 | 0.00 | 0.00 | 12.70 | 10:39 |
| 5 | 95.87 | 4.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.42 | 14:49 |
| 6 | 99.87 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 6.20 | 15:07 |
| 7 | 94.43 | 5.47 | 0.13 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.16 | 12:37 |
| 8 | 87.67 | 11.23 | 1.07 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 10.00 | 0:56 |
| 9 | 95.20 | 4.43 | 0.40 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 8.70 | 14:54 |
| 10 | 55.13 | 25.13 | 12.80 | 5.23 | 1.43 | 0.23 | 0.03 | 0.00 | 0.00 | 17.00 | 9:23 |
| 11 | 67.47 | 20.33 | 9.17 | 2.57 | 0.47 | 0.07 | 0.00 | 0.00 | 0.00 | 19.60 | 20:52 |
| 12 | 75.37 | 15.50 | 6.17 | 2.23 | 0.63 | 0.10 | 0.00 | 0.00 | 0.00 | 15.60 | 2:00 |
| 13 | 99.90 | 0.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 5.84 | 13:16 |
| 14 | 85.30 | 6.93 | 4.23 | 2.07 | 0.97 | 0.37 | 0.10 | 0.03 | 0.00 | 20.30 | 10:42 |
| 15 | 66.77 | 16.47 | 10.47 | 4.70 | 1.33 | 0.27 | 0.03 | 0.00 | 0.00 | 16.20 | 5:23 |
| 16 | 74.33 | 13.50 | 8.37 | 3.03 | 0.73 | 0.07 | 0.00 | 0.00 | 0.00 | 16.60 | 2:43 |
| 17 | 61.67 | 22.70 | 12.30 | 2.90 | 0.43 | 0.00 | 0.00 | 0.00 | 0.00 | 13.90 | 12:29 |
| 18 | 87.20 | 10.50 | 2.00 | 0.27 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.60 | 5:44 |
| 19 | 79.17 | 16.60 | 3.83 | 0.40 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.70 | 14:13 |
| 20 | 93.43 | 5.87 | 0.70 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 9.73 | 5:11 |
| 21 | 96.90 | 3.10 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.27 | 13:35 |
| 22 | 98.97 | 1.03 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.32 | 23:52 |
| 23 | 69.33 | 16.13 | 9.67 | 3.77 | 0.97 | 0.17 | 0.00 | 0.00 | 0.00 | 15.40 | 3:31 |
| 24 | 71.77 | 12.13 | 8.37 | 4.60 | 2.03 | 0.83 | 0.23 | 0.03 | 0.00 | 19.80 | 23:17 |
| 25 | 36.47 | 14.53 | 11.13 | 9.57 | 9.03 | 7.77 | 5.87 | 3.37 | 2.27 | 25.60 | 3:02 |
| 26 | 37.23 | 12.73 | 8.43 | 8.03 | 8.60 | 8.43 | 7.87 | 5.20 | 3.43 | 25.20 | 3:45 |
| 27 | 52.30 | 13.30 | 11.30 | 10.67 | 8.27 | 3.53 | 0.57 | 0.07 | 0.00 | 18.80 | 8:13 |
| 28 | 98.50 | 1.50 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 7.94 | 7:02 |
| 29 | 92.13 | 6.47 | 1.17 | 0.23 | 0.03 | 0.00 | 0.00 | 0.00 | 0.00 | 12.10 | 21:00 |
| 30 | 99.60 | 0.40 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 6.35 | 13:47 |
| 31 | 92.37 | 7.33 | 0.23 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 0.00 | 11.20 | 12:08 |
| All | 82.01 | 9.18 | 4.08 | 1.97 | 1.13 | 0.70 | 0.47 | 0.28 | 0.18 | 25.65 | 3:02 |

# Appendix C: Meteorological Data – Hourly

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, WS_ms_10m"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.0 | 0.8 | 0.4 | 0.9 | 0.7 | 0.9 | 0.7 | 0.5 | 0.7 | 1.8 | 2.2 | 2.4 | 2.5 | 2.7 | 2.7 | 2.5 | 2.0 | 1.8 | 1.2 | 0.2 | 0.7 | 0.8 | 0.5 | 0.2 | 1.3 | 2.7 | 0.2 |
| 2 | 0.6 | 1.2 | 0.8 | 1.7 | 1.0 | 0.8 | 0.5 | 0.4 | 1.5 | 2.6 | 2.3 | 2.2 | 2.4 | 2.4 | 2.5 | 2.4 | 2.4 | 1.9 | 1.2 | 1.0 | 0.5 | 0.6 | 0.7 | 0.5 | 1.4 | 2.6 | 0.4 |
| 3 | 0.8 | 1.0 | 1.1 | 0.5 | 0.7 | 0.9 | 1.2 | 2.1 | 3.1 | 2.9 | 3.2 | 2.3 | 4.0 | 3.5 | 2.9 | 3.1 | 3.2 | 2.3 | 1.7 | 1.4 | 1.2 | 1.3 | 2.1 | 2.7 | 2.0 | 4.0 | 0.5 |
| 4 | 1.8 | 2.3 | 2.1 | 0.8 | 0.4 | 0.3 | 0.6 | 0.7 | 1.5 | 1.9 | 2.6 | 2.5 | 2.7 | 3.2 | 3.4 | 3.1 | 2.5 | 2.5 | 1.6 | 2.4 | 2.1 | 3.0 | 7.7 | 11.0 | 2.6 | 11.0 | 0.3 |
| 5 | 10.6 | 11.8 | 12.7 | 12.1 | 12.7 | 11.5 | 11.6 | 11.3 | 10.7 | 10.4 | 10.2 | 8.6 | 7.1 | 5.5 | 5.2 | 5.6 | 5.7 | 5.9 | 4.6 | 7.4 | 6.3 | 6.4 | 7.9 | 10.3 | 8.8 | 12.7 | 4.6 |
| 6 | 12.4 | 8.6 | 7.4 | 8.7 | 8.3 | 7.5 | 8.1 | 8.4 | 9.1 | 10.7 | 8.8 | 8.8 | 6.9 | 3.9 | 2.0 | 2.2 | 3.4 | 4.0 | 2.3 | 1.8 | 1.2 | 1.7 | 1.8 | 1.9 | 5.8 | 12.4 | 1.2 |
| 7 | 3.2 | 3.6 | 3.4 | 3.2 | 4.7 | 5.2 | 6.8 | 6.1 | 7.1 | 6.3 | 5.1 | 5.0 | 3.7 | 2.4 | 2.7 | 2.3 | 2.0 | 2.5 | 2.3 | 1.1 | 0.9 | 0.9 | 0.6 | 0.4 | 3.4 | 7.1 | 0.4 |
| 8 | 1.7 | 1.7 | 1.2 | 0.8 | 1.2 | 0.8 | 0.7 | 1.2 | 1.4 | 2.7 | 3.5 | 2.6 | 4.1 | 4.8 | 4.0 | 4.0 | 4.0 | 4.1 | 4.5 | 4.0 | 4.8 | 4.6 | 4.4 | 4.5 | 3.0 | 4.8 | 0.7 |
| 9 | 4.2 | 3.8 | 3.5 | 4.0 | 2.7 | 1.4 | 1.1 | 2.1 | 4.0 | 4.7 | 5.0 | 6.8 | 5.6 | 5.1 | 5.5 | 5.3 | 4.8 | 4.0 | 2.9 | 3.6 | 3.7 | 3.3 | 3.4 | 2.8 | 3.9 | 6.8 | 1.1 |
| 10 | 1.8 | 2.7 | 4.5 | 5.2 | 5.1 | 4.1 | 5.9 | 2.6 | 2.1 | 2.1 | 1.8 | 1.6 | 2.0 | 3.2 | 2.6 | 2.2 | 1.5 | 1.1 | 0.6 | 1.0 | 1.0 | 1.1 | 1.5 | 1.1 | 2.4 | 5.9 | 0.6 |
| 11 | 1.0 | 1.6 | 1.5 | 1.8 | 1.9 | 1.7 | 1.6 | 1.6 | 2.2 | 1.6 | 1.6 | 2.5 | 2.8 | 2.3 | 2.2 | 2.5 | 2.6 | 2.5 | 1.6 | 0.9 | 1.5 | 1.4 | 1.6 | 1.9 | 1.9 | 2.8 | 0.9 |
| 12 | 1.9 | 1.7 | 1.9 | 2.1 | 2.3 | 2.0 | 1.8 | 2.8 | 3.4 | 4.1 | 4.5 | 4.1 | 3.8 | 3.1 | 2.2 | 2.6 | 2.7 | 2.8 | 3.2 | 2.4 | 0.9 | 0.8 | 1.2 | 1.0 | 2.5 | 4.5 | 0.8 |
| 13 | 0.5 | 0.5 | 0.5 | 0.6 | 0.7 | 0.6 | 0.4 | 1.8 | 4.0 | 4.3 | 4.9 | 6.7 | 3.5 | 3.7 | 3.3 | 3.8 | 3.9 | 3.3 | 2.2 | 1.2 | 2.2 | 1.4 | 0.9 | 0.8 | 2.3 | 6.7 | 0.4 |
| 14 | 1.1 | 0.3 | 0.3 | 0.7 | 0.5 | 0.4 | 0.6 | 0.7 | 0.8 | 1.7 | 2.4 | 2.3 | 2.6 | 2.7 | 2.6 | 3.0 | 2.2 | 1.8 | 1.3 | 1.2 | 0.6 | 0.5 | 0.7 | 1.4 | 1.4 | 3.0 | 0.3 |
| 15 | 1.1 | 1.4 | 1.3 | 1.3 | 0.8 | 0.9 | 1.2 | 0.9 | 0.8 | 2.2 | 2.3 | 2.6 | 2.0 | 2.5 | 2.8 | 2.5 | 2.3 | 1.9 | 1.3 | 1.4 | 1.8 | 1.4 | 1.5 | 0.6 | 1.6 | 2.8 | 0.6 |
| 16 | 0.6 | 0.5 | 1.0 | 1.7 | 1.8 | 2.9 | 4.0 | 4.3 | 6.9 | 5.7 | 5.1 | 2.6 | 2.3 | 1.9 | 2.5 | 2.3 | 2.9 | 2.6 | 3.4 | 3.9 | 2.7 | 1.6 | 0.9 | 1.2 | 2.7 | 6.9 | 0.5 |
| 17 | 1.7 | 1.3 | 1.6 | 1.9 | 1.7 | 1.9 | 2.1 | 2.0 | 2.9 | 1.7 | 2.6 | 2.7 | 2.4 | 2.7 | 2.6 | 2.5 | 3.2 | 2.6 | 3.4 | 3.0 | 1.7 | 1.4 | 2.4 | 2.2 | 2.3 | 3.4 | 1.3 |
| 18 | 1.1 | 0.9 | 1.2 | 0.8 | 0.7 | 0.8 | 1.3 | 1.5 | 3.8 | 4.6 | 5.7 | 4.3 | 2.8 | 2.9 | 3.1 | 3.2 | 4.0 | 3.4 | 2.7 | 2.6 | 0.8 | 1.7 | 1.3 | 3.9 | 2.5 | 5.7 | 0.7 |
| 19 | 3.8 | 4.1 | 7.4 | 3.1 | 3.8 | 2.4 | 2.9 | 2.9 | 4.6 | 6.7 | 6.4 | 5.3 | 2.7 | 1.8 | 2.3 | 2.2 | 2.4 | 2.9 | 3.6 | 2.7 | 1.3 | 1.0 | 1.1 | 0.7 | 3.2 | 7.4 | 0.7 |
| 20 | 1.2 | 1.6 | 1.7 | 1.7 | 1.6 | 0.8 | 0.9 | 1.0 | 0.6 | 2.3 | 2.4 | 2.7 | 2.6 | 2.5 | 1.9 | 2.5 | 2.4 | 2.2 | 1.8 | 1.9 | 1.3 | 0.8 | 0.8 | 1.1 | 1.7 | 2.7 | 0.6 |
| 21 | 1.6 | 0.7 | 0.5 | 0.7 | 0.6 | 0.6 | 1.0 | 1.1 | 1.2 | 1.4 | 2.3 | 2.3 | 2.8 | 2.7 | 2.5 | 2.8 | 1.8 | 2.2 | 3.0 | 1.7 | 0.9 | 1.2 | 2.0 | 1.8 | 1.6 | 3.0 | 0.5 |
| 22 | 2.0 | 2.5 | 5.2 | 4.2 | 3.9 | 5.2 | 3.9 | 4.8 | 6.4 | 6.6 | 6.5 | 6.8 | 6.2 | 3.4 | 2.2 | 2.4 | 1.8 | 3.5 | 2.9 | 2.3 | 2.3 | 2.0 | 2.4 | 2.8 | 3.8 | 6.8 | 1.8 |
| 23 | 3.2 | 3.2 | 3.4 | 4.0 | 4.7 | 6.0 | 5.7 | 5.7 | 6.8 | 7.4 | 7.6 | 6.6 | 4.5 | 3.1 | 2.4 | 2.5 | 2.2 | 1.1 | 2.0 | 1.9 | 1.6 | 1.5 | 1.3 | 1.5 | 3.7 | 7.6 | 1.1 |
| 24 | 2.1 | 1.6 | 1.3 | 1.3 | 1.3 | 1.8 | 1.9 | 2.7 | 3.4 | 4.4 | 4.9 | 3.8 | 3.3 | 2.7 | 2.1 | 3.0 | 2.4 | 1.5 | 1.5 | 1.1 | 0.5 | 0.6 | 0.8 | 0.4 | 2.1 | 4.9 | 0.4 |
| 25 | 1.6 | 0.8 | 1.3 | 1.2 | 0.7 | 0.9 | 1.2 | 0.9 | 0.6 | 1.3 | 2.7 | 3.1 | 2.7 | 2.6 | 2.9 | 2.9 | 2.5 | 2.9 | 2.8 | 2.3 | 1.8 | 1.3 | 1.4 | 1.6 | 1.8 | 3.1 | 0.6 |
| 26 | 1.7 | 2.2 | 2.6 | 4.7 | 6.3 | 5.9 | 3.0 | 4.1 | 5.1 | 5.9 | 6.8 | 6.5 | 6.0 | 4.5 | 4.1 | 2.6 | 2.1 | 1.9 | 1.6 | 0.7 | 1.2 | 2.5 | 2.4 | 2.7 | 3.6 | 6.8 | 0.7 |
| 27 | 4.3 | 4.6 | 3.8 | 3.4 | 3.2 | 3.6 | 3.6 | 3.7 | 4.0 | 5.0 | 4.8 | 3.9 | 3.5 | 3.9 | 3.6 | 3.8 | 2.4 | 3.9 | 1.8 | 1.6 | 1.4 | 0.7 | 1.6 | 3.2 | 3.3 | 5.0 | 0.7 |
| 28 | 3.9 | 4.2 | 4.1 | 3.3 | 4.1 | 2.9 | 4.0 | 4.3 | 4.1 | 5.2 | 4.0 | 5.8 | 4.9 | 4.6 | 4.2 | 3.5 | 2.8 | 4.5 | 3.9 | 4.7 | 3.6 | 3.6 | 5.2 | 6.3 | 4.2 | 6.3 | 2.8 |
| 29 | 4.6 | 2.7 | 2.9 | 3.0 | 1.9 | 1.5 | 1.7 | 1.3 | 4.3 | 5.2 | 5.1 | 4.9 | 5.4 | 3.8 | 2.6 | 2.4 | 2.9 | 4.0 | 2.2 | 1.7 | 1.4 | 0.6 | 0.7 | 0.5 | 2.8 | 5.4 | 0.5 |
| 30 | 0.6 | 0.6 | 0.3 | 0.5 | 0.7 | 0.3 | 0.3 | 1.5 | 1.7 | 1.8 | 2.0 | 2.6 | 2.8 | 3.4 | 3.0 | 3.3 | 2.8 | 2.0 | 1.8 | 2.2 | 1.2 | 1.9 | 1.6 | 1.2 | 1.7 | 3.4 | 0.3 |
| 31 | 1.4 | 1.6 | 1.4 | 1.4 | 1.3 | 1.1 | 1.0 | 1.7 | 2.6 | 2.9 | 1.9 | 2.7 | 2.5 | 3.0 | 3.0 | 3.7 | 3.5 | 4.0 | 4.4 | 3.1 | 2.3 | 2.3 | 2.1 | 1.1 | 2.3 | 4.4 | 1.0 |
| Avg | 2.6 | 2.5 | 2.7 | 2.6 | 2.6 | 2.5 | 2.6 | 2.8 | 3.6 | 4.1 | 4.2 | 4.1 | 3.6 | 3.2 | 3.0 | 3.0 | 2.8 | 2.8 | 2.4 | 2.2 | 1.8 | 1.7 | 2.1 | 2.4 | 2.8 | -- | -- |
| Max | 12.4 | 11.8 | 12.7 | 12.1 | 12.7 | 11.5 | 11.6 | 11.3 | 10.7 | 10.7 | 10.2 | 8.8 | 7.1 | 5.5 | 5.5 | 5.6 | 5.7 | 5.9 | 4.6 | 7.4 | 6.3 | 6.4 | 7.9 | 11.0 | -- | 12.7 | -- |
| Min | 0.5 | 0.3 | 0.3 | 0.5 | 0.4 | 0.3 | 0.3 | 0.4 | 0.6 | 1.3 | 1.6 | 1.6 | 2.0 | 1.8 | 1.9 | 2.2 | 1.5 | 1.1 | 0.6 | 0.2 | 0.5 | 0.5 | 0.5 | 0.2 | -- | -- | 0.2 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, WS_ms_10m"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.4 | 0.7 | 1.1 | 1.2 | 1.7 | 1.7 | 2.0 | 3.5 | 4.5 | 5.3 | 6.2 | 5.5 | 5.0 | 4.7 | 4.1 | 2.7 | 2.6 | 2.8 | 1.5 | 1.5 | 2.6 | 2.3 | 2.2 | 3.4 | 2.9 | 6.2 | 0.7 |
| 2 | 2.5 | 2.3 | 2.9 | 5.2 | 5.5 | 6.4 | 8.3 | 6.5 | 7.0 | 7.0 | 6.8 | 7.1 | 5.8 | 4.8 | 3.6 | 3.4 | 2.7 | 2.3 | 1.6 | 1.6 | 1.6 | 1.2 | 2.5 | 4.2 | 4.3 | 8.3 | 1.2 |
| 3 | 2.1 | 3.4 | 3.4 | 2.4 | 2.3 | 1.8 | 1.4 | 0.8 | 1.5 | 3.5 | 3.5 | 3.5 | 3.6 | 4.4 | 3.1 | 3.0 | 2.3 | 1.4 | 0.9 | 0.6 | 1.2 | 1.1 | 0.9 | 1.0 | 2.2 | 4.4 | 0.6 |
| 4 | 1.0 | 0.9 | 1.0 | 0.9 | 1.1 | 1.5 | 1.2 | 1.1 | 1.0 | 3.3 | 3.8 | 4.2 | 3.1 | 3.2 | 3.3 | 2.4 | 2.5 | 2.4 | 1.1 | 1.4 | 1.4 | 1.5 | 3.3 | 2.7 | 2.1 | 4.2 | 0.9 |
| 5 | 1.0 | 1.2 | 1.1 | 1.0 | 0.7 | 0.6 | 1.5 | 1.4 | 1.6 | 2.0 | 2.4 | 3.1 | 2.6 | 2.4 | 2.5 | 2.3 | 2.4 | 2.4 | 3.4 | 1.4 | 3.0 | 3.1 | 5.8 | 7.1 | 2.3 | 7.1 | 0.6 |
| 6 | 5.6 | 2.7 | 4.6 | 7.9 | 6.3 | 7.4 | 4.4 | 5.5 | 6.8 | 6.9 | 7.1 | 7.9 | 7.3 | 5.9 | 5.3 | 4.9 | 5.0 | 4.3 | 4.3 | 4.4 | 8.1 | 8.4 | 8.3 | 8.0 | 6.1 | 8.4 | 2.7 |
| 7 | 8.3 | 8.1 | 7.3 | 8.2 | 8.3 | 6.0 | 6.3 | 6.4 | 8.5 | 8.6 | 7.6 | 7.3 | 8.1 | 7.5 | 5.4 | 4.8 | 4.2 | 3.1 | 2.4 | 2.4 | 2.4 | 2.3 | 2.3 | 2.7 | 5.8 | 8.6 | 2.3 |
| 8 | 3.1 | 3.3 | 3.2 | 3.9 | 5.0 | 4.7 | 4.5 | 3.6 | 4.7 | 4.2 | 4.1 | 3.3 | 1.9 | 2.5 | 1.9 | 2.9 | 2.2 | 1.6 | 1.6 | 0.5 | 0.8 | 0.6 | 0.6 | 0.6 | 2.7 | 5.0 | 0.5 |
| 9 | 0.3 | 0.7 | 0.7 | 1.4 | 1.8 | 1.8 | 1.8 | 1.8 | 2.3 | 2.0 | 1.4 | 1.5 | 2.3 | 2.3 | 2.5 | 1.8 | 1.9 | 2.7 | 2.7 | 0.7 | 1.4 | 1.6 | 1.2 | 1.2 | 1.7 | 2.7 | 0.3 |
| 10 | 1.7 | 1.8 | 1.7 | 1.9 | 2.0 | 2.1 | 3.1 | 3.2 | 3.2 | 3.4 | 4.7 | 5.1 | 4.9 | 3.6 | 4.1 | 3.6 | 4.4 | 4.3 | 4.1 | 1.8 | 1.8 | 1.9 | 2.1 | 2.1 | 3.0 | 5.1 | 1.7 |
| 11 | 2.2 | 2.7 | 2.7 | 2.8 | 2.2 | 2.7 | 3.1 | 3.7 | 5.1 | 6.6 | 7.1 | 7.0 | 5.8 | 5.6 | 4.7 | 4.6 | 4.2 | 2.1 | 1.1 | 2.9 | 3.8 | 2.8 | 6.4 | 6.7 | 4.1 | 7.1 | 1.1 |
| 12 | 7.3 | 5.0 | 3.8 | 3.6 | 3.9 | 5.5 | 6.6 | 7.8 | 6.6 | 6.8 | 8.6 | 7.3 | 6.3 | 5.0 | 5.3 | 4.4 | 4.8 | 4.7 | 4.2 | 4.3 | 5.0 | 4.0 | 5.4 | 6.6 | 5.5 | 8.6 | 3.6 |
| 13 | 7.6 | 9.9 | 8.9 | 7.4 | 8.1 | 8.6 | 8.3 | 7.5 | 9.0 | 9.3 | 9.2 | 9.7 | 9.1 | 8.6 | 7.9 | 7.2 | 6.8 | 5.3 | 4.5 | 5.9 | 5.8 | 4.0 | 4.0 | 3.6 | 7.3 | 9.9 | 3.6 |
| 14 | 3.7 | 3.5 | 3.9 | 3.4 | 4.4 | 5.7 | 3.9 | 3.6 | 6.5 | 6.5 | 3.9 | 2.4 | 1.5 | 2.5 | 2.3 | 2.3 | 1.9 | 2.6 | 2.1 | 0.9 | 0.6 | 0.7 | 0.5 | 0.4 | 2.9 | 6.5 | 0.4 |
| 15 | 0.6 | 0.3 | 0.5 | 0.9 | 0.6 | 0.8 | 0.9 | 2.8 | 4.4 | 4.0 | 4.4 | 6.0 | 5.9 | 5.1 | 5.7 | 6.3 | 5.3 | 5.8 | 6.3 | 4.5 | 4.2 | 4.2 | 4.9 | 4.4 | 3.7 | 6.3 | 0.3 |
| 16 | 3.4 | 2.3 | 2.6 | 2.5 | 2.7 | 3.1 | 3.5 | 3.5 | 2.3 | 2.3 | 2.3 | 2.6 | 2.6 | 3.1 | 3.0 | 3.7 | 3.0 | 1.9 | 2.1 | 1.5 | 1.4 | 0.9 | 0.5 | 0.6 | 2.4 | 3.7 | 0.5 |
| 17 | 0.8 | 0.8 | 0.4 | 0.6 | 0.8 | 0.5 | 2.1 | 1.9 | 1.0 | 3.3 | 3.1 | 3.6 | 3.2 | 2.4 | 1.9 | 1.7 | 0.8 | 1.3 | 1.5 | 1.6 | 2.0 | 1.8 | 1.6 | 1.7 | 1.7 | 3.6 | 0.4 |
| 18 | 1.6 | 2.1 | 2.2 | 2.3 | 2.3 | 2.5 | 2.0 | 2.1 | 3.0 | 3.3 | 4.4 | 3.0 | 2.1 | 2.7 | 2.9 | 2.3 | 2.1 | 3.1 | 2.9 | 1.3 | 1.3 | 0.8 | 1.6 | 1.1 | 2.3 | 4.4 | 0.8 |
| 19 | 1.5 | 0.3 | 0.6 | 0.6 | 0.9 | 1.0 | 1.1 | 1.0 | 0.9 | 1.9 | 2.2 | 2.9 | 3.5 | 2.7 | 2.2 | 2.7 | 1.7 | 1.6 | 0.9 | 1.2 | 1.4 | 0.7 | 0.5 | 0.5 | 1.4 | 3.5 | 0.3 |
| 20 | 0.4 | 0.6 | 0.8 | 0.5 | 0.8 | 0.7 | 0.9 | 0.8 | 1.2 | 1.2 | 1.6 | 1.9 | 2.4 | 2.9 | 2.5 | 1.8 | 2.8 | 2.2 | 1.4 | 1.0 | 1.5 | 1.5 | 1.0 | 0.4 | 1.4 | 2.9 | 0.4 |
| 21 | 1.0 | 1.9 | 1.2 | 1.3 | 1.1 | 0.6 | 0.8 | 1.0 | 0.7 | 2.6 | 3.2 | 3.2 | 4.0 | 1.9 | 1.7 | 1.9 | 1.1 | 1.8 | 1.2 | 1.0 | 1.7 | 2.0 | 1.9 | 1.8 | 1.7 | 4.0 | 0.6 |
| 22 | 2.5 | 2.9 | 2.0 | 3.0 | 2.8 | 3.6 | 2.8 | 3.0 | 3.4 | 4.4 | 3.8 | 3.7 | 3.4 | 4.4 | 4.6 | 2.2 | 1.0 | 1.6 | 1.9 | 1.9 | 1.3 | 1.6 | 1.8 | 2.2 | 2.7 | 4.6 | 1.0 |
| 23 | 2.2 | 3.4 | 5.0 | 4.8 | 4.9 | 4.8 | 3.9 | 3.9 | 4.2 | 4.7 | 5.4 | 5.0 | 6.8 | 5.5 | 4.6 | 5.4 | 6.0 | 6.9 | 5.8 | 5.4 | 5.8 | 5.7 | 6.2 | 6.2 | 5.1 | 6.9 | 2.2 |
| 24 | 6.0 | 5.8 | 6.1 | 6.3 | 6.3 | 5.5 | 5.3 | 5.9 | 5.1 | 5.8 | 5.8 | 5.8 | 6.2 | 6.2 | 5.2 | 5.2 | 4.6 | 3.7 | 4.7 | 5.1 | 7.0 | 5.6 | 3.6 | 3.0 | 5.4 | 7.0 | 3.0 |
| 25 | 2.5 | 2.5 | 4.7 | 2.8 | 3.0 | 2.5 | 1.6 | 1.9 | 2.6 | 2.8 | 2.5 | 2.4 | 1.5 | 2.6 | 1.9 | 4.2 | 3.8 | 1.9 | 1.8 | 5.1 | 2.0 | 1.7 | 2.4 | 4.8 | 2.7 | 5.1 | 1.5 |
| 26 | 5.2 | 8.1 | 5.6 | 5.9 | 7.2 | 6.3 | 5.4 | 4.7 | 6.4 | 8.3 | 8.1 | 8.2 | 6.9 | 6.8 | 8.1 | 5.4 | 5.3 | 4.5 | 3.2 | 4.8 | 6.1 | 5.0 | 4.8 | 5.8 | 6.1 | 8.3 | 3.2 |
| 27 | 6.5 | 6.6 | 8.4 | 6.0 | 6.9 | 6.3 | 6.4 | 7.1 | 9.0 | 9.4 | 9.2 | 9.8 | 10.6 | 9.7 | 8.3 | 7.8 | 6.0 | 6.1 | 6.1 | 6.0 | 5.1 | 6.1 | 4.9 | 5.1 | 7.2 | 10.6 | 4.9 |
| 28 | 6.2 | 6.5 | 7.1 | 7.9 | 7.9 | 6.1 | 7.7 | 7.5 | 7.1 | 6.7 | 6.0 | 6.6 | 6.8 | 5.9 | 4.2 | 3.4 | 3.9 | 3.4 | 2.9 | 4.6 | 3.8 | 2.5 | 3.1 | 2.5 | 5.4 | 7.9 | 2.5 |
| 29 | 2.1 | 2.3 | 2.8 | 2.7 | 3.0 | 3.5 | 5.2 | 4.0 | 4.6 | 4.1 | 3.1 | 2.7 | 3.3 | 2.8 | 2.1 | 1.9 | 1.3 | 1.9 | 2.0 | 1.7 | 1.7 | 1.2 | 1.0 | 1.4 | 2.6 | 5.2 | 1.0 |
| 30 | 1.4 | 1.6 | 1.5 | 1.8 | 1.9 | 2.9 | 3.4 | 2.7 | 3.0 | 3.6 | 3.3 | 3.9 | 3.5 | 2.9 | 3.4 | 2.8 | 1.3 | 1.2 | 1.1 | 1.2 | 1.3 | 1.3 | 1.4 | 1.1 | 2.2 | 3.9 | 1.1 |
| Avg | 3.1 | 3.1 | 3.3 | 3.4 | 3.5 | 3.6 | 3.6 | 3.7 | 4.2 | 4.8 | 4.8 | 4.9 | 4.7 | 4.3 | 4.0 | 3.6 | 3.3 | 3.0 | 2.7 | 2.6 | 2.9 | 2.6 | 2.9 | 3.1 | 3.6 | -- | -- |
| Max | 8.3 | 9.9 | 8.9 | 8.2 | 8.3 | 8.6 | 8.3 | 7.8 | 9.0 | 9.4 | 9.2 | 9.8 | 10.6 | 9.7 | 8.3 | 7.8 | 6.8 | 6.9 | 6.3 | 6.0 | 8.1 | 8.4 | 8.3 | 8.0 | -- | 10.6 | -- |
| Min | 0.3 | 0.3 | 0.4 | 0.5 | 0.6 | 0.5 | 0.8 | 0.8 | 0.7 | 1.2 | 1.4 | 1.5 | 1.5 | 1.9 | 1.7 | 1.7 | 0.8 | 1.2 | 0.9 | 0.5 | 0.6 | 0.6 | 0.5 | 0.4 | -- | -- | 0.3 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, WS_ms_10m"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.3 | 1.8 | 2.0 | 2.6 | 2.3 | 2.2 | 2.3 | 2.9 | 2.1 | 2.7 | 3.5 | 3.5 | 3.9 | 1.7 | 1.6 | 1.5 | 0.6 | 1.4 | 1.3 | 1.7 | 2.2 | 2.2 | 2.3 | 1.9 | 2.1 | 3.9 | 0.6 |
| 2 | 2.2 | 2.4 | 2.2 | 2.4 | 2.5 | 2.3 | 1.9 | 2.2 | 1.4 | 0.9 | 2.0 | 2.4 | 2.7 | 2.6 | 2.1 | 2.5 | 2.2 | 2.0 | 1.0 | 0.4 | 0.4 | 0.5 | 0.5 | 0.7 | 1.8 | 2.7 | 0.4 |
| 3 | 0.1 | 0.5 | 0.7 | 0.3 | 0.4 | 1.1 | 0.8 | 1.8 | 0.8 | 1.4 | 2.4 | 3.1 | 3.6 | 3.5 | 4.5 | 4.1 | 3.3 | 2.4 | 2.5 | 3.5 | 3.8 | 2.6 | 3.4 | 3.8 | 2.3 | 4.5 | 0.1 |
| 4 | 2.1 | 1.9 | 2.4 | 2.7 | 2.0 | 1.4 | 3.6 | 3.8 | 4.2 | 5.8 | 4.4 | 2.9 | 2.5 | 2.7 | 2.7 | 2.6 | 1.7 | 0.9 | 1.3 | 1.8 | 1.7 | 1.7 | 3.7 | 2.7 | 2.6 | 5.8 | 0.9 |
| 5 | 3.1 | 1.8 | 1.0 | 1.3 | 1.5 | 1.4 | 1.5 | 1.5 | 1.6 | 1.7 | 1.9 | 2.1 | 2.0 | 2.5 | 2.5 | 2.8 | 2.1 | 1.7 | 1.7 | 2.8 | 2.0 | 2.3 | 1.9 | 0.9 | 1.9 | 3.1 | 0.9 |
| 6 | 1.1 | 1.3 | 0.8 | 1.1 | 0.5 | 0.8 | 0.7 | 0.5 | 0.7 | 1.6 | 1.6 | 1.7 | 1.6 | 1.8 | 2.0 | 1.8 | 2.2 | 3.4 | 2.0 | 0.7 | 1.1 | 0.9 | 0.8 | 0.4 | 1.3 | 3.4 | 0.4 |
| 7 | 0.4 | 0.5 | 0.4 | 0.6 | 0.5 | 0.5 | 0.5 | 0.4 | 0.6 | 1.5 | 2.5 | 2.6 | 3.7 | 2.5 | 3.8 | 3.1 | 3.1 | 1.1 | 2.0 | 2.0 | 5.2 | 5.1 | 6.7 | 6.5 | 2.3 | 6.7 | 0.4 |
| 8 | 8.4 | 8.1 | 8.1 | 7.6 | 6.7 | 5.1 | 4.5 | 2.2 | 2.2 | 1.6 | 2.5 | 2.1 | 2.3 | 2.8 | 3.7 | 3.7 | 2.9 | 2.5 | 1.7 | 1.9 | 1.3 | 1.4 | 1.6 | 1.9 | 3.6 | 8.4 | 1.3 |
| 9 | 2.1 | 1.2 | 0.9 | 0.3 | 0.4 | 0.3 | 0.4 | 0.4 | 0.8 | 2.4 | 4.6 | 5.3 | 4.3 | 4.4 | 6.0 | 5.8 | 5.7 | 5.2 | 8.3 | 8.6 | 7.7 | 8.2 | 7.1 | 7.0 | 4.1 | 8.6 | 0.3 |
| 10 | 7.1 | 6.4 | 5.5 | 5.7 | 6.1 | 6.2 | 8.2 | 8.8 | 9.4 | 9.9 | 9.8 | 8.0 | 8.2 | 9.2 | 8.1 | 6.6 | 6.1 | 4.1 | 5.0 | 3.8 | 4.1 | 4.3 | 3.8 | 4.1 | 6.6 | 9.9 | 3.8 |
| 11 | 4.2 | 6.8 | 7.8 | 8.4 | 8.5 | 9.4 | 8.8 | 8.5 | 7.9 | 7.2 | 7.1 | 6.5 | 6.6 | 6.0 | 6.7 | 6.3 | 6.2 | 6.2 | 6.5 | 7.4 | 5.2 | 6.8 | 8.4 | 8.6 | 7.2 | 9.4 | 4.2 |
| 12 | 9.2 | 8.3 | 8.3 | 8.1 | 8.8 | 9.2 | 8.9 | 8.2 | 7.4 | 9.0 | 8.1 | 6.8 | 5.5 | 5.1 | 5.6 | 4.8 | 5.2 | 2.9 | 1.6 | 1.2 | 1.1 | 1.2 | 1.2 | 1.3 | 5.7 | 9.2 | 1.1 |
| 13 | 0.8 | 1.7 | 0.8 | 0.5 | 0.7 | 1.2 | 0.6 | 1.2 | 0.9 | 1.1 | 1.6 | 2.5 | 2.5 | 2.5 | 2.4 | 1.9 | 1.7 | 1.7 | 1.2 | 1.1 | 1.9 | 0.8 | 1.0 | 0.7 | 1.4 | 2.5 | 0.5 |
| 14 | 0.7 | 1.4 | 1.7 | 1.3 | 6.9 | 7.8 | 8.9 | 9.5 | 7.7 | 8.8 | 10.7 | 8.7 | 7.3 | 6.5 | 6.7 | 6.4 | 5.6 | 6.4 | 8.2 | 6.0 | 7.8 | 4.5 | 6.9 | 6.5 | 6.4 | 10.7 | 0.7 |
| 15 | 7.1 | 5.6 | 7.2 | 9.2 | 8.3 | 7.6 | 6.8 | 6.8 | 7.4 | 7.4 | 8.7 | 7.2 | 6.6 | 5.2 | 4.5 | 4.3 | 3.2 | 3.1 | 4.5 | 6.7 | 6.3 | 5.3 | 6.3 | 6.3 | 6.3 | 9.2 | 3.1 |
| 16 | 7.2 | 6.4 | 8.9 | 7.9 | 6.8 | 7.1 | 6.8 | 6.4 | 7.2 | 6.7 | 8.2 | 9.9 | 8.9 | 6.1 | 5.3 | 4.3 | 2.1 | 2.2 | 2.2 | 3.1 | 3.0 | 2.8 | 2.9 | 2.7 | 5.6 | 9.9 | 2.1 |
| 17 | 4.0 | 5.1 | 4.6 | 5.2 | 3.8 | 4.0 | 3.5 | 4.4 | 5.0 | 5.5 | 5.9 | 6.7 | 5.5 | 5.5 | 5.7 | 4.7 | 4.0 | 2.9 | 3.1 | 3.6 | 3.2 | 3.6 | 2.9 | 3.4 | 4.4 | 6.7 | 2.9 |
| 18 | 3.6 | 4.7 | 6.3 | 6.0 | 6.5 | 6.4 | 5.9 | 5.8 | 6.8 | 5.2 | 4.8 | 5.1 | 4.1 | 3.0 | 2.6 | 2.3 | 1.8 | 1.2 | 0.6 | 0.3 | 1.0 | 1.0 | 0.4 | 1.8 | 3.6 | 6.8 | 0.3 |
| 19 | 4.0 | 4.9 | 6.0 | 6.1 | 4.9 | 5.1 | 5.4 | 5.1 | 5.6 | 5.8 | 5.5 | 5.8 | 5.0 | 4.4 | 4.0 | 2.9 | 4.0 | 2.8 | 2.4 | 2.5 | 2.7 | 2.6 | 3.1 | 3.0 | 4.3 | 6.1 | 2.4 |
| 20 | 3.2 | 1.2 | 1.3 | 0.9 | 1.0 | 3.9 | 4.3 | 3.2 | 2.2 | 1.4 | 1.8 | 2.5 | 1.5 | 1.8 | 2.2 | 3.1 | 2.3 | 2.5 | 3.0 | 3.2 | 2.3 | 2.2 | 1.9 | 3.5 | 2.3 | 4.3 | 0.9 |
| 21 | 3.9 | 1.8 | 2.2 | 2.6 | 3.0 | 2.2 | 3.7 | 4.0 | 4.3 | 4.4 | 3.7 | 2.4 | 2.6 | 2.9 | 2.7 | 1.6 | 1.0 | 1.4 | 1.3 | 0.9 | 1.4 | 1.3 | 2.2 | 1.0 | 2.4 | 4.4 | 0.9 |
| 22 | 1.1 | 0.8 | 0.7 | 0.4 | 0.4 | 0.6 | 1.1 | 1.4 | 1.0 | 1.4 | 3.5 | 2.3 | 2.6 | 2.4 | 2.4 | 2.4 | 2.2 | 2.8 | 2.3 | 0.6 | 0.9 | 1.0 | 1.4 | 2.3 | 1.6 | 3.5 | 0.4 |
| 23 | 3.3 | 4.1 | 5.1 | 5.8 | 6.5 | 7.3 | 6.6 | 8.5 | 9.9 | 10.4 | 9.9 | 10.0 | 8.7 | 8.3 | 5.6 | 4.4 | 5.4 | 4.1 | 3.4 | 4.2 | 5.6 | 8.2 | 8.0 | 7.1 | 6.7 | 10.4 | 3.3 |
| 24 | 6.8 | 5.5 | 6.1 | 6.7 | 8.2 | 8.6 | 5.4 | 4.9 | 5.5 | 6.1 | 6.7 | 6.5 | 6.1 | 5.3 | 4.7 | 4.6 | 1.5 | 0.8 | 1.3 | 2.6 | 3.5 | 3.8 | 4.5 | 7.0 | 5.1 | 8.6 | 0.8 |
| 25 | 10.7 | 13.3 | 14.7 | 15.7 | 15.1 | 15.1 | 13.4 | 8.4 | 8.2 | 9.1 | 8.6 | 7.7 | 7.5 | 7.2 | 6.9 | 4.3 | 2.8 | 2.1 | 4.7 | 6.1 | 6.5 | 7.5 | 10.3 | 10.1 | 9.0 | 15.7 | 2.1 |
| 26 | 10.7 | 10.6 | 10.6 | 9.9 | 10.4 | 9.8 | 11.3 | 11.1 | 10.3 | 11.2 | 11.6 | 10.6 | 10.1 | 9.3 | 7.5 | 5.9 | 5.7 | 4.2 | 4.1 | 4.1 | 5.3 | 6.4 | 8.7 | 7.4 | 8.6 | 11.6 | 4.1 |
| 27 | 8.1 | 5.0 | 6.8 | 7.0 | 9.8 | 8.0 | 7.5 | 9.0 | 10.0 | 9.5 | 8.6 | 9.5 | 9.2 | 8.6 | 5.8 | 6.7 | 6.3 | 7.2 | 6.2 | 4.5 | 4.3 | 4.9 | 5.0 | 4.0 | 7.1 | 10.0 | 4.0 |
| 28 | 5.3 | 7.8 | 6.0 | 6.5 | 5.9 | 6.7 | 4.7 | 4.2 | 4.1 | 4.4 | 5.2 | 3.8 | 2.7 | 2.0 | 0.9 | 1.3 | 1.7 | 2.0 | 1.4 | 1.1 | 0.8 | 0.9 | 0.8 | 0.7 | 3.4 | 7.8 | 0.7 |
| 29 | 0.8 | 0.9 | 1.0 | 1.6 | 1.7 | 2.1 | 2.7 | 3.0 | 5.2 | 9.1 | 9.5 | 9.7 | 8.0 | 7.7 | 6.8 | 4.7 | 5.0 | 3.4 | 4.6 | 7.8 | 9.1 | 8.6 | 4.8 | 6.1 | 5.2 | 9.7 | 0.8 |
| 30 | 6.2 | 3.4 | 3.8 | 2.8 | 3.1 | 3.4 | 3.1 | 2.5 | 2.6 | 3.5 | 3.7 | 3.7 | 2.5 | 2.9 | 3.2 | 3.0 | 3.5 | 2.0 | 1.0 | 1.2 | 1.9 | 2.2 | 2.4 | 3.6 | 3.0 | 6.2 | 1.0 |
| 31 | 2.6 | 2.5 | 2.2 | 2.8 | 2.6 | 2.6 | 4.7 | 4.6 | 5.0 | 5.4 | 5.8 | 6.0 | 5.3 | 4.1 | 2.6 | 1.8 | 1.8 | 1.0 | 1.2 | 1.5 | 1.3 | 1.4 | 1.8 | 1.7 | 3.0 | 6.0 | 1.0 |
| Avg | 4.2 | 4.1 | 4.4 | 4.5 | 4.7 | 4.8 | 4.8 | 4.7 | 4.8 | 5.2 | 5.6 | 5.4 | 5.0 | 4.5 | 4.2 | 3.7 | 3.3 | 2.8 | 3.0 | 3.1 | 3.4 | 3.4 | 3.8 | 3.8 | 4.2 | -- | -- |
| Max | 10.7 | 13.3 | 14.7 | 15.7 | 15.1 | 15.1 | 13.4 | 11.1 | 10.3 | 11.2 | 11.6 | 10.6 | 10.1 | 9.3 | 8.1 | 6.7 | 6.3 | 7.2 | 8.3 | 8.6 | 9.1 | 8.6 | 10.3 | 10.1 | -- | 15.7 | -- |
| Min | 0.1 | 0.5 | 0.4 | 0.3 | 0.4 | 0.3 | 0.4 | 0.4 | 0.6 | 0.9 | 1.6 | 1.7 | 1.5 | 1.7 | 0.9 | 1.3 | 0.6 | 0.8 | 0.6 | 0.3 | 0.4 | 0.5 | 0.4 | 0.4 | -- | -- | 0.1 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, WD_10m"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 265 | 160 | 151 | 150 | 165 | 157 | 167 | 126 | 103 | 234 | 232 | 214 | 194 | 228 | 257 | 256 | 206 | 184 | 153 | 110 | 136 | 181 | 154 | 158 | 179 | 265 | 103 |
| 2 | 144 | 206 | 158 | 245 | 196 | 146 | 113 | 129 | 149 | 228 | 228 | 183 | 255 | 265 | 265 | 280 | 257 | 206 | 163 | 161 | 10 | 156 | 168 | 140 | 191 | 280 | 10 |
| 3 | 123 | 172 | 159 | 113 | 112 | 161 | 137 | 164 | 175 | 174 | 199 | 211 | 198 | 206 | 178 | 159 | 178 | 136 | 110 | 67 | 167 | 191 | 181 | 214 | 164 | 214 | 67 |
| 4 | 205 | 210 | 220 | 318 | 138 | 83 | 126 | 114 | 101 | 195 | 209 | 216 | 263 | 249 | 204 | 200 | 239 | 251 | 235 | 273 | 265 | 1 | 21 | 23 | 219 | 318 | 1 |
| 5 | 22 | 24 | 24 | 21 | 22 | 20 | 23 | 22 | 25 | 25 | 27 | 37 | 22 | 21 | 29 | 21 | 29 | 41 | 51 | 34 | 66 | 71 | 48 | 36 | 32 | 71 | 20 |
| 6 | 23 | 42 | 40 | 34 | 37 | 43 | 40 | 41 | 40 | 33 | 34 | 40 | 42 | 50 | 172 | 131 | 45 | 20 | 51 | 57 | 92 | 114 | 89 | 81 | 54 | 172 | 20 |
| 7 | 56 | 58 | 58 | 49 | 42 | 37 | 39 | 47 | 39 | 40 | 77 | 96 | 104 | 131 | 162 | 206 | 232 | 250 | 265 | 154 | 148 | 146 | 171 | 220 | 97 | 265 | 37 |
| 8 | 230 | 256 | 231 | 141 | 156 | 141 | 155 | 123 | 78 | 131 | 203 | 199 | 192 | 194 | 195 | 192 | 172 | 195 | 196 | 193 | 194 | 193 | 203 | 210 | 184 | 256 | 78 |
| 9 | 203 | 191 | 185 | 176 | 159 | 144 | 130 | 125 | 157 | 175 | 180 | 187 | 182 | 179 | 187 | 179 | 180 | 178 | 175 | 183 | 185 | 210 | 215 | 211 | 178 | 215 | 125 |
| 10 | 164 | 196 | 200 | 198 | 188 | 192 | 186 | 122 | 213 | 190 | 177 | 170 | 202 | 217 | 183 | 215 | 181 | 183 | 213 | 117 | 171 | 139 | 150 | 167 | 181 | 217 | 117 |
| 11 | 137 | 128 | 145 | 133 | 92 | 98 | 139 | 117 | 65 | 49 | 265 | 231 | 242 | 269 | 250 | 251 | 248 | 241 | 279 | 143 | 176 | 155 | 130 | 127 | 166 | 279 | 49 |
| 12 | 134 | 149 | 114 | 105 | 109 | 102 | 93 | 60 | 50 | 80 | 103 | 123 | 141 | 141 | 181 | 244 | 243 | 245 | 249 | 251 | 161 | 185 | 199 | 171 | 146 | 251 | 50 |
| 13 | 137 | 149 | 143 | 121 | 116 | 81 | 100 | 159 | 178 | 185 | 177 | 189 | 192 | 202 | 205 | 192 | 183 | 178 | 146 | 252 | 265 | 221 | 249 | 337 | 176 | 337 | 81 |
| 14 | 271 | 250 | 192 | 166 | 164 | 155 | 140 | 137 | 100 | 187 | 237 | 220 | 258 | 242 | 243 | 203 | 199 | 216 | 191 | 284 | 280 | 38 | 107 | 166 | 201 | 284 | 38 |
| 15 | 137 | 152 | 147 | 142 | 112 | 150 | 152 | 141 | 94 | 267 | 241 | 230 | 267 | 188 | 263 | 197 | 161 | 242 | 236 | 240 | 263 | 297 | 285 | 211 | 202 | 297 | 94 |
| 16 | 198 | 157 | 134 | 114 | 119 | 64 | 76 | 60 | 29 | 37 | 29 | 356 | 41 | 170 | 223 | 252 | 255 | 242 | 254 | 253 | 256 | 258 | 316 | 172 | 188 | 356 | 29 |
| 17 | 171 | 152 | 111 | 112 | 97 | 102 | 105 | 106 | 75 | 98 | 229 | 226 | 225 | 228 | 221 | 242 | 225 | 259 | 248 | 256 | 256 | 258 | 249 | 252 | 200 | 259 | 75 |
| 18 | 253 | 111 | 144 | 158 | 155 | 157 | 163 | 137 | 56 | 54 | 29 | 31 | 11 | 260 | 233 | 224 | 247 | 247 | 258 | 249 | 143 | 103 | 131 | 60 | 157 | 260 | 11 |
| 19 | 58 | 68 | 34 | 99 | 130 | 108 | 107 | 108 | 58 | 36 | 32 | 30 | 86 | 127 | 258 | 235 | 223 | 262 | 251 | 253 | 278 | 265 | 235 | 157 | 109 | 278 | 30 |
| 20 | 181 | 180 | 163 | 161 | 156 | 146 | 122 | 138 | 91 | 241 | 230 | 246 | 232 | 239 | 230 | 211 | 191 | 150 | 182 | 239 | 249 | 241 | 145 | 354 | 192 | 354 | 91 |
| 21 | 274 | 150 | 161 | 166 | 150 | 151 | 151 | 120 | 83 | 107 | 51 | 160 | 233 | 231 | 247 | 219 | 228 | 249 | 252 | 253 | 168 | 114 | 83 | 87 | 171 | 274 | 51 |
| 22 | 125 | 109 | 47 | 54 | 61 | 43 | 49 | 47 | 40 | 39 | 36 | 29 | 30 | 68 | 138 | 133 | 104 | 32 | 41 | 58 | 65 | 88 | 68 | 67 | 64 | 138 | 29 |
| 23 | 62 | 61 | 49 | 48 | 41 | 38 | 41 | 44 | 41 | 36 | 30 | 37 | 86 | 120 | 127 | 114 | 115 | 95 | 48 | 49 | 62 | 74 | 89 | 95 | 66 | 127 | 30 |
| 24 | 83 | 68 | 114 | 102 | 96 | 81 | 73 | 68 | 57 | 94 | 104 | 114 | 128 | 156 | 224 | 256 | 252 | 244 | 251 | 271 | 126 | 141 | 168 | 247 | 127 | 271 | 57 |
| 25 | 236 | 208 | 254 | 252 | 186 | 183 | 153 | 142 | 99 | 255 | 233 | 246 | 249 | 228 | 216 | 213 | 242 | 254 | 246 | 249 | 242 | 215 | 102 | 85 | 218 | 255 | 85 |
| 26 | 154 | 143 | 95 | 45 | 21 | 33 | 97 | 89 | 66 | 46 | 39 | 47 | 34 | 38 | 25 | 19 | 17 | 259 | 257 | 162 | 124 | 67 | 71 | 73 | 63 | 259 | 17 |
| 27 | 53 | 44 | 53 | 64 | 65 | 60 | 49 | 54 | 54 | 44 | 84 | 106 | 125 | 176 | 185 | 206 | 176 | 205 | 198 | 240 | 229 | 268 | 154 | 192 | 117 | 268 | 44 |
| 28 | 182 | 178 | 181 | 184 | 176 | 173 | 173 | 179 | 184 | 185 | 181 | 205 | 194 | 200 | 190 | 188 | 191 | 198 | 180 | 176 | 181 | 181 | 181 | 182 | 184 | 205 | 173 |
| 29 | 178 | 188 | 190 | 203 | 186 | 201 | 198 | 153 | 175 | 184 | 186 | 186 | 193 | 188 | 162 | 195 | 113 | 285 | 273 | 259 | 284 | 230 | 226 | 116 | 196 | 285 | 113 |
| 30 | 10 | 155 | 317 | 182 | 166 | 147 | 168 | 226 | 227 | 232 | 229 | 224 | 209 | 210 | 200 | 233 | 231 | 213 | 194 | 265 | 248 | 267 | 249 | 257 | 221 | 317 | 10 |
| 31 | 268 | 296 | 171 | 159 | 121 | 91 | 96 | 106 | 72 | 54 | 231 | 235 | 246 | 216 | 237 | 252 | 249 | 247 | 252 | 259 | 267 | 268 | 270 | 196 | 227 | 296 | 54 |
| Avg | 160 | 151 | 141 | 130 | 125 | 114 | 117 | 110 | 86 | 111 | 184 | 185 | 198 | 199 | 209 | 213 | 208 | 224 | 221 | 226 | 201 | 184 | 163 | 155 | 166 | -- | -- |
| Max | 274 | 296 | 317 | 318 | 196 | 201 | 198 | 226 | 227 | 267 | 265 | 356 | 267 | 269 | 265 | 280 | 257 | 285 | 279 | 284 | 284 | 297 | 316 | 354 | -- | 356 | -- |
| Min | 10 | 24 | 24 | 21 | 21 | 20 | 23 | 22 | 25 | 25 | 27 | 29 | 11 | 21 | 25 | 19 | 17 | 20 | 41 | 34 | 10 | 1 | 21 | 23 | -- | -- | 1 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, WD_10m"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 253 | 172 | 183 | 158 | 162 | 135 | 78 | 92 | 87 | 55 | 37 | 35 | 28 | 6 | 36 | 289 | 247 | 254 | 338 | 99 | 85 | 94 | 83 | 55 | 80 | 338 | 6 |
| 2 | 85 | 116 | 67 | 46 | 46 | 41 | 33 | 47 | 45 | 43 | 73 | 83 | 93 | 100 | 109 | 109 | 108 | 113 | 68 | 109 | 45 | 171 | 231 | 128 | 82 | 231 | 33 |
| 3 | 134 | 145 | 130 | 58 | 101 | 108 | 71 | 117 | 80 | 112 | 101 | 176 | 198 | 197 | 206 | 195 | 163 | 121 | 148 | 176 | 238 | 194 | 172 | 162 | 146 | 238 | 58 |
| 4 | 161 | 150 | 138 | 115 | 103 | 95 | 90 | 71 | 67 | 151 | 178 | 180 | 200 | 190 | 186 | 220 | 192 | 205 | 160 | 214 | 237 | 246 | 210 | 271 | 171 | 271 | 67 |
| 5 | 156 | 147 | 163 | 175 | 165 | 155 | 216 | 235 | 336 | 295 | 246 | 239 | 232 | 257 | 251 | 208 | 232 | 246 | 253 | 331 | 21 | 55 | 33 | 28 | 229 | 336 | 21 |
| 6 | 33 | 100 | 64 | 38 | 46 | 42 | 63 | 51 | 43 | 40 | 41 | 31 | 39 | 32 | 33 | 34 | 34 | 51 | 85 | 53 | 31 | 30 | 35 | 37 | 45 | 100 | 30 |
| 7 | 41 | 40 | 40 | 41 | 41 | 54 | 48 | 49 | 42 | 43 | 66 | 79 | 90 | 97 | 110 | 108 | 95 | 83 | 61 | 70 | 63 | 66 | 80 | 71 | 66 | 110 | 40 |
| 8 | 66 | 64 | 65 | 45 | 38 | 43 | 41 | 48 | 42 | 42 | 37 | 36 | 292 | 210 | 284 | 202 | 218 | 221 | 248 | 248 | 176 | 158 | 170 | 154 | 79 | 292 | 36 |
| 9 | 147 | 148 | 155 | 165 | 138 | 126 | 133 | 129 | 99 | 72 | 101 | 236 | 256 | 256 | 255 | 228 | 246 | 249 | 250 | 142 | 150 | 140 | 139 | 123 | 164 | 256 | 72 |
| 10 | 160 | 173 | 156 | 143 | 133 | 127 | 113 | 106 | 96 | 70 | 42 | 33 | 29 | 17 | 19 | 10 | 23 | 24 | 35 | 87 | 125 | 119 | 103 | 112 | 86 | 173 | 10 |
| 11 | 113 | 99 | 95 | 101 | 109 | 101 | 88 | 71 | 48 | 40 | 35 | 31 | 31 | 23 | 35 | 44 | 25 | 37 | 98 | 60 | 74 | 89 | 28 | 28 | 62 | 113 | 23 |
| 12 | 23 | 41 | 55 | 57 | 54 | 44 | 41 | 36 | 46 | 45 | 41 | 82 | 98 | 90 | 68 | 76 | 100 | 86 | 75 | 60 | 57 | 58 | 56 | 54 | 60 | 100 | 23 |
| 13 | 45 | 40 | 43 | 46 | 44 | 40 | 41 | 40 | 40 | 37 | 37 | 39 | 39 | 37 | 37 | 29 | 24 | 31 | 42 | 34 | 35 | 44 | 46 | 50 | 39 | 50 | 24 |
| 14 | 55 | 64 | 47 | 51 | 40 | 36 | 49 | 55 | 33 | 32 | 40 | 53 | 105 | 240 | 227 | 204 | 243 | 246 | 242 | 53 | 149 | 165 | 140 | 156 | 78 | 246 | 32 |
| 15 | 153 | 139 | 171 | 85 | 67 | 83 | 89 | 147 | 178 | 178 | 182 | 186 | 180 | 194 | 185 | 197 | 194 | 193 | 194 | 187 | 203 | 200 | 200 | 194 | 171 | 203 | 67 |
| 16 | 196 | 192 | 199 | 182 | 189 | 206 | 206 | 205 | 198 | 176 | 171 | 208 | 177 | 193 | 199 | 184 | 177 | 162 | 267 | 251 | 280 | 215 | 14 | 272 | 203 | 280 | 14 |
| 17 | 260 | 252 | 89 | 317 | 98 | 136 | 173 | 182 | 133 | 180 | 192 | 192 | 188 | 208 | 208 | 225 | 236 | 246 | 78 | 95 | 100 | 112 | 101 | 92 | 166 | 317 | 78 |
| 18 | 119 | 111 | 113 | 95 | 104 | 102 | 117 | 100 | 62 | 57 | 35 | 41 | 27 | 137 | 221 | 246 | 257 | 256 | 251 | 126 | 156 | 232 | 270 | 263 | 124 | 270 | 27 |
| 19 | 271 | 139 | 131 | 153 | 139 | 136 | 142 | 100 | 101 | 120 | 111 | 183 | 184 | 238 | 224 | 214 | 188 | 196 | 225 | 240 | 258 | 190 | 228 | 148 | 176 | 271 | 100 |
| 20 | 136 | 168 | 220 | 138 | 180 | 153 | 119 | 123 | 99 | 114 | 135 | 204 | 197 | 180 | 213 | 211 | 206 | 204 | 167 | 240 | 245 | 224 | 218 | 132 | 177 | 245 | 99 |
| 21 | 200 | 195 | 183 | 178 | 173 | 125 | 124 | 89 | 73 | 105 | 172 | 173 | 172 | 197 | 237 | 241 | 253 | 238 | 221 | 201 | 131 | 77 | 86 | 117 | 167 | 253 | 73 |
| 22 | 84 | 80 | 81 | 72 | 108 | 144 | 164 | 154 | 138 | 238 | 241 | 247 | 250 | 241 | 251 | 259 | 45 | 247 | 227 | 271 | 312 | 270 | 340 | 213 | 218 | 340 | 45 |
| 23 | 74 | 88 | 86 | 93 | 61 | 44 | 59 | 48 | 52 | 46 | 45 | 40 | 43 | 57 | 57 | 53 | 45 | 33 | 42 | 42 | 36 | 40 | 36 | 36 | 52 | 93 | 33 |
| 24 | 39 | 43 | 39 | 36 | 35 | 39 | 41 | 34 | 40 | 35 | 35 | 34 | 29 | 31 | 33 | 28 | 35 | 42 | 39 | 39 | 29 | 34 | 46 | 56 | 37 | 56 | 28 |
| 25 | 74 | 66 | 42 | 74 | 107 | 125 | 105 | 106 | 108 | 83 | 65 | 53 | 262 | 238 | 243 | 24 | 31 | 41 | 72 | 36 | 80 | 90 | 100 | 84 | 76 | 262 | 24 |
| 26 | 69 | 35 | 50 | 38 | 33 | 35 | 42 | 46 | 47 | 39 | 38 | 37 | 43 | 65 | 40 | 63 | 69 | 66 | 61 | 63 | 65 | 71 | 61 | 56 | 51 | 71 | 33 |
| 27 | 71 | 50 | 43 | 53 | 56 | 56 | 52 | 48 | 41 | 41 | 41 | 38 | 36 | 37 | 39 | 37 | 35 | 40 | 40 | 38 | 41 | 38 | 47 | 46 | 44 | 71 | 35 |
| 28 | 37 | 41 | 37 | 34 | 33 | 46 | 37 | 38 | 40 | 39 | 41 | 36 | 27 | 27 | 54 | 44 | 26 | 46 | 53 | 37 | 46 | 62 | 51 | 63 | 41 | 63 | 26 |
| 29 | 68 | 64 | 57 | 55 | 55 | 44 | 38 | 43 | 42 | 41 | 51 | 63 | 110 | 119 | 110 | 158 | 89 | 22 | 71 | 88 | 105 | 177 | 122 | 114 | 77 | 177 | 22 |
| 30 | 112 | 109 | 93 | 73 | 73 | 60 | 57 | 63 | 55 | 43 | 45 | 40 | 37 | 33 | 33 | 42 | 78 | 85 | 132 | 134 | 138 | 139 | 130 | 120 | 79 | 139 | 33 |
| Avg | 98 | 104 | 95 | 82 | 87 | 87 | 82 | 80 | 67 | 65 | 68 | 70 | 87 | 135 | 153 | 163 | 108 | 108 | 96 | 86 | 87 | 116 | 89 | 95 | 87 | -- | -- |
| Max | 271 | 252 | 220 | 317 | 189 | 206 | 216 | 235 | 336 | 295 | 246 | 247 | 292 | 257 | 284 | 289 | 257 | 256 | 338 | 331 | 312 | 270 | 340 | 272 | -- | 340 | -- |
| Min | 23 | 35 | 37 | 34 | 33 | 35 | 33 | 34 | 33 | 32 | 35 | 31 | 27 | 6 | 19 | 10 | 23 | 22 | 35 | 34 | 21 | 30 | 14 | 28 | -- | -- | 6 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, WD_10m"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 115 | 146 | 143 | 110 | 119 | 133 | 125 | 104 | 108 | 84 | 63 | 46 | 39 | 37 | 159 | 237 | 169 | 126 | 126 | 131 | 128 | 110 | 84 | 110 | 113 | 237 | 37 |
| 2 | 139 | 151 | 136 | 159 | 168 | 166 | 170 | 161 | 152 | 96 | 231 | 227 | 234 | 225 | 235 | 241 | 246 | 232 | 210 | 265 | 142 | 134 | 127 | 90 | 181 | 265 | 90 |
| 3 | 89 | 242 | 143 | 85 | 73 | 133 | 160 | 171 | 85 | 116 | 161 | 194 | 198 | 202 | 204 | 200 | 194 | 198 | 205 | 203 | 202 | 202 | 179 | 176 | 172 | 242 | 73 |
| 4 | 189 | 190 | 194 | 199 | 205 | 190 | 195 | 192 | 194 | 194 | 178 | 168 | 117 | 169 | 44 | 243 | 245 | 259 | 260 | 230 | 189 | 187 | 205 | 215 | 199 | 260 | 44 |
| 5 | 215 | 227 | 222 | 232 | 230 | 210 | 210 | 213 | 208 | 219 | 206 | 198 | 220 | 224 | 187 | 212 | 173 | 164 | 205 | 259 | 257 | 258 | 262 | 282 | 220 | 282 | 164 |
| 6 | 252 | 267 | 223 | 224 | 207 | 101 | 166 | 126 | 107 | 84 | 138 | 159 | 211 | 246 | 244 | 264 | 221 | 258 | 257 | 165 | 161 | 130 | 134 | 236 | 195 | 267 | 84 |
| 7 | 156 | 133 | 194 | 127 | 163 | 145 | 132 | 109 | 90 | 109 | 212 | 206 | 189 | 199 | 204 | 194 | 192 | 158 | 213 | 197 | 201 | 196 | 200 | 198 | 174 | 213 | 90 |
| 8 | 203 | 201 | 200 | 199 | 201 | 202 | 191 | 111 | 149 | 92 | 165 | 146 | 141 | 180 | 202 | 203 | 174 | 174 | 156 | 222 | 262 | 217 | 226 | 219 | 187 | 262 | 92 |
| 9 | 226 | 221 | 275 | 215 | 182 | 147 | 45 | 124 | 123 | 79 | 29 | 30 | 39 | 28 | 31 | 41 | 54 | 43 | 34 | 36 | 36 | 40 | 46 | 47 | 55 | 275 | 28 |
| 10 | 46 | 45 | 49 | 51 | 46 | 48 | 42 | 39 | 35 | 34 | 32 | 36 | 37 | 35 | 38 | 37 | 37 | 54 | 45 | 59 | 75 | 48 | 56 | 68 | 45 | 75 | 32 |
| 11 | 49 | 37 | 34 | 33 | 34 | 31 | 33 | 34 | 35 | 38 | 40 | 41 | 39 | 38 | 31 | 33 | 33 | 39 | 38 | 35 | 43 | 40 | 35 | 35 | 37 | 49 | 31 |
| 12 | 32 | 34 | 34 | 34 | 32 | 30 | 33 | 36 | 37 | 37 | 36 | 28 | 65 | 54 | 23 | 20 | 25 | 54 | 116 | 159 | 159 | 172 | 196 | 266 | 47 | 266 | 20 |
| 13 | 170 | 238 | 201 | 167 | 155 | 234 | 151 | 254 | 142 | 204 | 178 | 228 | 231 | 229 | 233 | 213 | 213 | 218 | 264 | 230 | 259 | 186 | 223 | 176 | 209 | 264 | 142 |
| 14 | 147 | 127 | 118 | 126 | 32 | 32 | 32 | 27 | 36 | 36 | 38 | 43 | 45 | 46 | 50 | 52 | 51 | 45 | 27 | 32 | 33 | 50 | 33 | 36 | 50 | 147 | 27 |
| 15 | 36 | 39 | 40 | 39 | 38 | 57 | 65 | 59 | 51 | 52 | 41 | 56 | 58 | 56 | 60 | 51 | 73 | 83 | 95 | 79 | 90 | 69 | 52 | 45 | 58 | 95 | 36 |
| 16 | 39 | 45 | 44 | 76 | 75 | 77 | 53 | 74 | 77 | 65 | 44 | 34 | 35 | 42 | 45 | 49 | 54 | 54 | 107 | 105 | 115 | 116 | 113 | 88 | 67 | 116 | 34 |
| 17 | 53 | 47 | 50 | 55 | 71 | 86 | 119 | 112 | 56 | 53 | 49 | 43 | 50 | 44 | 41 | 41 | 54 | 90 | 83 | 98 | 86 | 84 | 78 | 56 | 66 | 119 | 41 |
| 18 | 49 | 42 | 37 | 38 | 37 | 38 | 40 | 41 | 37 | 42 | 47 | 42 | 47 | 62 | 79 | 106 | 138 | 111 | 114 | 189 | 137 | 138 | 125 | 175 | 74 | 189 | 37 |
| 19 | 185 | 186 | 201 | 207 | 192 | 189 | 181 | 174 | 179 | 183 | 188 | 193 | 186 | 184 | 194 | 191 | 191 | 170 | 212 | 239 | 197 | 210 | 206 | 223 | 194 | 239 | 170 |
| 20 | 224 | 158 | 90 | 34 | 58 | 191 | 198 | 287 | 90 | 97 | 108 | 119 | 104 | 225 | 257 | 265 | 244 | 258 | 252 | 253 | 219 | 207 | 201 | 211 | 199 | 287 | 34 |
| 21 | 208 | 209 | 173 | 177 | 190 | 198 | 196 | 204 | 206 | 204 | 208 | 173 | 168 | 199 | 190 | 139 | 193 | 257 | 183 | 74 | 263 | 268 | 267 | 345 | 201 | 345 | 74 |
| 22 | 46 | 258 | 158 | 136 | 167 | 162 | 138 | 158 | 125 | 81 | 58 | 48 | 235 | 219 | 224 | 230 | 233 | 249 | 264 | 105 | 154 | 146 | 96 | 84 | 157 | 264 | 46 |
| 23 | 71 | 55 | 84 | 58 | 72 | 71 | 87 | 49 | 38 | 38 | 39 | 39 | 42 | 41 | 45 | 52 | 38 | 49 | 63 | 68 | 45 | 33 | 34 | 36 | 52 | 87 | 33 |
| 24 | 40 | 47 | 45 | 41 | 35 | 34 | 46 | 49 | 47 | 42 | 36 | 35 | 34 | 31 | 30 | 24 | 69 | 89 | 101 | 79 | 74 | 64 | 63 | 35 | 49 | 101 | 24 |
| 25 | 32 | 25 | 26 | 25 | 22 | 24 | 29 | 92 | 79 | 42 | 43 | 44 | 47 | 46 | 41 | 64 | 67 | 66 | 81 | 77 | 65 | 46 | 37 | 36 | 48 | 92 | 22 |
| 26 | 37 | 38 | 40 | 43 | 38 | 35 | 31 | 31 | 41 | 41 | 37 | 37 | 40 | 37 | 30 | 28 | 42 | 61 | 88 | 84 | 45 | 43 | 26 | 44 | 42 | 88 | 26 |
| 27 | 33 | 73 | 70 | 62 | 37 | 39 | 42 | 39 | 39 | 37 | 36 | 33 | 27 | 28 | 46 | 26 | 29 | 35 | 40 | 79 | 56 | 46 | 43 | 52 | 43 | 79 | 26 |
| 28 | 41 | 31 | 37 | 34 | 36 | 32 | 43 | 44 | 48 | 50 | 43 | 47 | 38 | 116 | 102 | 122 | 153 | 234 | 255 | 91 | 164 | 142 | 147 | 142 | 74 | 255 | 31 |
| 29 | 115 | 143 | 136 | 168 | 163 | 149 | 101 | 76 | 68 | 26 | 20 | 24 | 20 | 22 | 18 | 23 | 26 | 40 | 36 | 24 | 22 | 22 | 65 | 31 | 56 | 168 | 18 |
| 30 | 37 | 64 | 60 | 103 | 121 | 121 | 124 | 123 | 118 | 101 | 55 | 51 | 10 | 233 | 243 | 247 | 250 | 294 | 155 | 132 | 64 | 60 | 83 | 106 | 97 | 294 | 10 |
| 31 | 112 | 100 | 95 | 64 | 62 | 69 | 46 | 42 | 41 | 42 | 44 | 38 | 37 | 34 | 26 | 39 | 52 | 97 | 131 | 114 | 108 | 134 | 142 | 88 | 72 | 142 | 26 |
| Avg | 91 | 101 | 101 | 94 | 94 | 103 | 99 | 90 | 84 | 71 | 67 | 64 | 62 | 70 | 61 | 61 | 113 | 102 | 131 | 116 | 118 | 113 | 106 | 85 | 91 | -- | -- |
| Max | 252 | 267 | 275 | 232 | 230 | 234 | 210 | 287 | 208 | 219 | 231 | 228 | 235 | 246 | 257 | 265 | 250 | 294 | 264 | 265 | 263 | 268 | 267 | 345 | -- | 345 | -- |
| Min | 32 | 25 | 26 | 25 | 22 | 24 | 29 | 27 | 35 | 26 | 20 | 24 | 10 | 22 | 18 | 20 | 25 | 35 | 27 | 24 | 22 | 22 | 26 | 31 | -- | -- | 10 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, DeltaTemp_C"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.94 | 1.25 | 0.77 | 0.79 | 1.25 | 1.19 | 1.06 | 0.41 | -0.68 | -0.57 | -0.96 | -1.20 | -1.22 | -1.21 | -1.10 | -0.95 | -0.61 | -0.13 | 0.26 | 0.66 | 0.65 | 0.87 | 1.18 | 0.92 | 0.15 | 1.25 | -1.22 |
| 2 | 0.88 | 0.80 | 1.13 | 1.30 | 1.15 | 0.84 | 0.60 | -0.19 | -0.66 | -0.75 | -0.98 | -1.40 | -1.19 | -1.31 | -1.19 | -0.95 | -0.62 | -0.14 | 0.19 | 0.19 | 0.46 | 0.70 | 0.55 | 0.53 | 0.00 | 1.30 | -1.40 |
| 3 | 0.96 | 0.79 | 0.61 | 0.65 | 0.66 | 0.77 | 0.81 | 0.00 | -0.65 | -1.14 | -1.09 | -1.06 | -1.35 | -1.13 | -1.09 | -0.93 | -0.60 | -0.11 | 0.16 | 0.23 | 0.20 | 0.21 | 0.18 | 0.22 | -0.11 | 0.96 | -1.35 |
| 4 | 0.18 | 0.19 | 0.27 | 0.44 | 0.41 | 0.46 | 0.68 | -0.20 | -0.78 | -0.84 | -1.10 | -1.16 | -1.09 | -1.18 | -1.06 | -0.85 | -0.55 | -0.12 | 0.11 | 0.08 | 0.18 | 0.35 | 0.23 | 0.11 | -0.22 | 0.68 | -1.18 |
| 5 | 0.11 | 0.09 | 0.09 | 0.09 | 0.09 | 0.12 | 0.09 | -0.24 | -0.58 | -0.90 | -1.16 | -1.40 | -1.58 | -1.51 | -1.46 | -1.20 | -0.69 | -0.03 | 0.21 | 0.24 | 0.17 | 0.15 | 0.19 | 0.19 | -0.37 | 0.24 | -1.58 |
| 6 | 0.17 | 0.19 | 0.24 | 0.22 | 0.22 | 0.22 | 0.17 | -0.30 | -0.67 | -0.95 | -1.25 | -1.41 | -1.53 | -1.71 | -1.32 | -1.23 | -0.74 | 0.11 | 0.57 | 0.52 | 0.70 | 0.77 | 0.65 | 0.60 | -0.24 | 0.77 | -1.71 |
| 7 | 0.51 | 0.38 | 0.42 | 0.45 | 0.40 | 0.45 | 0.28 | -0.27 | -0.63 | -1.11 | -1.12 | -1.26 | -1.41 | -1.51 | -1.06 | -1.05 | -0.26 | -0.03 | 0.09 | 0.70 | 0.61 | 0.70 | 0.78 | 1.20 | -0.11 | 1.20 | -1.51 |
| 8 | 1.02 | 0.64 | 0.85 | 0.87 | 1.04 | 1.04 | 0.96 | -0.08 | -0.73 | -1.02 | -1.13 | -1.11 | -1.12 | -1.05 | -0.96 | -0.85 | -0.48 | -0.05 | 0.14 | 0.22 | 0.20 | 0.21 | 0.23 | 0.24 | -0.04 | 1.04 | -1.13 |
| 9 | 0.29 | 0.38 | 0.46 | 0.33 | 0.35 | 0.45 | 0.36 | -0.30 | -0.60 | -0.93 | -1.18 | -1.19 | -1.09 | -1.09 | -0.90 | -0.69 | -0.31 | -0.11 | -0.06 | -0.04 | -0.02 | -0.03 | -0.01 | -0.01 | -0.25 | 0.46 | -1.19 |
| 10 | -0.10 | -0.14 | -0.16 | -0.15 | -0.14 | -0.14 | -0.14 | -0.23 | -0.14 | -0.16 | -0.29 | -0.38 | 0.39 | -0.68 | -0.85 | -0.79 | -0.69 | -0.13 | 0.24 | 0.52 | 0.58 | 0.59 | 0.62 | 0.78 | -0.07 | 0.78 | -0.85 |
| 11 | 0.83 | 0.62 | 0.88 | 0.58 | 0.22 | 0.33 | 0.40 | -0.41 | -0.69 | -1.26 | -0.83 | -1.03 | -1.12 | -0.97 | -0.90 | -0.72 | -0.54 | -0.08 | 0.19 | 0.63 | 0.63 | 0.75 | 0.71 | 0.70 | -0.05 | 0.88 | -1.26 |
| 12 | 0.70 | 0.77 | 0.49 | 0.42 | 0.44 | 0.46 | 0.75 | -0.17 | -0.72 | -1.06 | -1.18 | -1.31 | -1.46 | -1.33 | -1.12 | -0.79 | -0.47 | -0.07 | 0.08 | 0.30 | 0.76 | 0.76 | 1.58 | 1.07 | -0.05 | 1.58 | -1.46 |
| 13 | 0.73 | 0.44 | 0.46 | 0.65 | 0.69 | 0.78 | 0.75 | 0.24 | -0.39 | -0.80 | -1.13 | -1.14 | -1.02 | -1.07 | -0.98 | -0.68 | -0.40 | -0.04 | 0.16 | 0.17 | 0.15 | 0.25 | 0.28 | 0.51 | -0.06 | 0.78 | -1.14 |
| 14 | 0.33 | 0.30 | 0.90 | 0.67 | 0.59 | 0.88 | 0.63 | -0.20 | -0.58 | -0.69 | -0.75 | -1.00 | -1.12 | -1.00 | -0.91 | -0.92 | -0.54 | -0.04 | 0.20 | 0.50 | 0.71 | 0.61 | 0.68 | 1.05 | 0.01 | 1.05 | -1.12 |
| 15 | 0.60 | 0.71 | 1.04 | 0.71 | 0.45 | 0.70 | 0.66 | -0.05 | -0.70 | -0.58 | -0.86 | -0.95 | -1.09 | -1.10 | -0.95 | -0.78 | -0.50 | -0.02 | 0.12 | 0.18 | 0.19 | 0.26 | 0.24 | 0.83 | -0.04 | 1.04 | -1.10 |
| 16 | 0.95 | 0.86 | 0.83 | 0.61 | 0.47 | 0.40 | 0.23 | -0.25 | -0.63 | -1.11 | -1.59 | -1.58 | -1.57 | -1.33 | -1.10 | -0.80 | -0.45 | -0.05 | 0.03 | 0.05 | 0.13 | 0.50 | 0.73 | 0.81 | -0.16 | 0.95 | -1.59 |
| 17 | 1.19 | 0.87 | 0.62 | 0.61 | 0.51 | 0.53 | 0.35 | -0.33 | -0.69 | -0.91 | -0.80 | -0.98 | -1.11 | -1.09 | -1.06 | -0.85 | -0.50 | -0.05 | 0.04 | 0.09 | 0.27 | 0.35 | 0.25 | 0.20 | -0.10 | 1.19 | -1.11 |
| 18 | 0.47 | 0.82 | 0.95 | 0.83 | 1.32 | 0.94 | 0.83 | 0.13 | -0.73 | -1.11 | -1.39 | -1.71 | -1.56 | -1.11 | -1.01 | -0.84 | -0.37 | 0.01 | 0.14 | 0.42 | 0.93 | 0.91 | 0.49 | 0.59 | 0.00 | 1.32 | -1.71 |
| 19 | 0.45 | 0.47 | 0.43 | 0.34 | 0.47 | 0.50 | 0.36 | -0.15 | -0.61 | -1.05 | -1.42 | -1.70 | -1.68 | -1.44 | -0.96 | -0.76 | -0.48 | 0.01 | 0.07 | 0.23 | 1.02 | 1.80 | 0.88 | 1.10 | -0.09 | 1.80 | -1.70 |
| 20 | 1.24 | 0.93 | 0.86 | 1.37 | 1.09 | 0.66 | 0.40 | 0.11 | -0.60 | -0.48 | -0.77 | -0.80 | -1.05 | -0.98 | -1.01 | -0.92 | -0.40 | 0.07 | 0.20 | 0.42 | 0.56 | 0.94 | 0.76 | 0.95 | 0.15 | 1.37 | -1.05 |
| 21 | 0.68 | 1.08 | 0.79 | 0.83 | 0.83 | 1.15 | 1.11 | -0.01 | -0.77 | -0.95 | -1.51 | -1.33 | -1.06 | -1.10 | -0.88 | -0.85 | -0.44 | 0.02 | 0.10 | 0.36 | 0.81 | 0.69 | 0.67 | 0.45 | 0.03 | 1.15 | -1.51 |
| 22 | 0.45 | 0.43 | 0.53 | 0.41 | 0.41 | 0.37 | 0.34 | -0.17 | -0.64 | -1.02 | -1.27 | -1.40 | -1.48 | -1.42 | -1.21 | -1.03 | -0.51 | 0.31 | 0.57 | 0.47 | 0.57 | 0.65 | 0.66 | 0.60 | -0.14 | 0.66 | -1.48 |
| 23 | 0.54 | 0.38 | 0.41 | 0.38 | 0.44 | 0.39 | 0.31 | -0.14 | -0.58 | -0.97 | -1.17 | -1.42 | -1.24 | -1.28 | -1.19 | -0.82 | -0.36 | 0.28 | 0.51 | 0.59 | 0.57 | 0.60 | 0.49 | 0.56 | -0.11 | 0.60 | -1.42 |
| 24 | 0.74 | 0.71 | 0.37 | 0.46 | 0.40 | 0.68 | 0.66 | -0.12 | -0.68 | -0.87 | -0.92 | -1.06 | -1.39 | -1.11 | -0.71 | -0.45 | -0.11 | 0.05 | 0.23 | 0.41 | 1.04 | 1.02 | 0.92 | 0.86 | 0.05 | 1.04 | -1.39 |
| 25 | 1.28 | 0.87 | 0.97 | 1.04 | 1.40 | 1.12 | 0.72 | 0.18 | -0.56 | -0.66 | -0.83 | -0.84 | -0.99 | -1.04 | -0.93 | -0.65 | -0.38 | 0.03 | 0.10 | 0.21 | 0.92 | 1.02 | 0.94 | 0.53 | 0.19 | 1.40 | -1.04 |
| 26 | 0.78 | 0.68 | 0.39 | 0.51 | 0.45 | 0.45 | 0.27 | -0.17 | -0.60 | -0.97 | -1.23 | -1.36 | -1.58 | -1.53 | -1.35 | -0.84 | -0.39 | 0.15 | 0.46 | 0.43 | 0.83 | 0.47 | 0.38 | 0.34 | -0.14 | 0.83 | -1.58 |
| 27 | 0.36 | 0.34 | 0.36 | 0.27 | 0.28 | 0.30 | 0.30 | -0.14 | -0.67 | -1.09 | -1.16 | -1.27 | -1.35 | -1.30 | -1.01 | -0.68 | -0.33 | 0.10 | 0.21 | 0.24 | 0.18 | 0.20 | 0.40 | 0.40 | -0.21 | 0.40 | -1.35 |
| 28 | 0.41 | 0.31 | 0.24 | 0.26 | 0.19 | 0.21 | 0.19 | 0.03 | -0.21 | -0.45 | -0.86 | -1.00 | -1.09 | -0.80 | -0.47 | -0.32 | -0.13 | -0.01 | 0.02 | 0.03 | 0.09 | 0.13 | 0.12 | 0.09 | -0.13 | 0.41 | -1.09 |
| 29 | 0.09 | 0.14 | 0.20 | 0.19 | 0.38 | 0.60 | 0.66 | 0.01 | -0.46 | -0.80 | -1.08 | -1.11 | -1.06 | -0.83 | -0.35 | -0.40 | -0.24 | -0.09 | 0.02 | 0.09 | 0.16 | 0.23 | 0.65 | 0.50 | -0.10 | 0.66 | -1.11 |
| 30 | 0.60 | 0.59 | 0.94 | 0.75 | 0.44 | 0.74 | 0.54 | 0.49 | -0.32 | -0.71 | -0.85 | -1.02 | -1.05 | -1.16 | -1.10 | -0.66 | -0.34 | 0.02 | 0.12 | 0.11 | 0.24 | 0.29 | 0.24 | 0.26 | -0.04 | 0.94 | -1.16 |
| 31 | 0.37 | 0.43 | 0.98 | 0.85 | 0.57 | 0.58 | 0.50 | -0.22 | -0.68 | -1.23 | -0.85 | -0.96 | -1.07 | -1.13 | -0.88 | -0.55 | -0.23 | 0.00 | 0.02 | 0.08 | 0.18 | 0.24 | 0.41 | 0.92 | -0.07 | 0.98 | -1.23 |
| Avg | 0.60 | 0.56 | 0.59 | 0.57 | 0.56 | 0.59 | 0.51 | -0.09 | -0.60 | -0.88 | -1.06 | -1.18 | -1.20 | -1.18 | -1.00 | -0.80 | -0.44 | -0.01 | 0.18 | 0.30 | 0.47 | 0.55 | 0.55 | 0.58 | -0.08 | -- | -- |
| Max | 1.28 | 1.25 | 1.13 | 1.37 | 1.40 | 1.19 | 1.11 | 0.49 | -0.14 | -0.16 | -0.29 | -0.38 | 0.39 | -0.68 | -0.35 | -0.32 | -0.11 | 0.31 | 0.57 | 0.70 | 1.04 | 1.80 | 1.58 | 1.20 | -- | 1.80 | -- |
| Min | -0.10 | -0.14 | -0.16 | -0.15 | -0.14 | -0.14 | -0.14 | -0.41 | -0.78 | -1.26 | -1.59 | -1.71 | -1.68 | -1.71 | -1.46 | -1.23 | -0.74 | -0.14 | -0.06 | -0.04 | -0.02 | -0.03 | -0.01 | -0.01 | -- | -- | -1.71 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, DeltaTemp_C"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.83 | 0.70 | 0.70 | 0.88 | 1.10 | 0.60 | 0.41 | -0.03 | -0.50 | -0.89 | -1.24 | -1.40 | -1.56 | -1.24 | -1.29 | -0.95 | -0.28 | 0.09 | 0.49 | 0.75 | 0.50 | 0.45 | 0.49 | 0.42 | -0.04 | 1.10 | -1.56 |
| 2 | 0.47 | 0.68 | 0.41 | 0.38 | 0.35 | 0.35 | 0.35 | -0.05 | -0.48 | -0.82 | -0.92 | -0.90 | -1.05 | -1.08 | -0.87 | -0.50 | -0.15 | 0.46 | 0.70 | 0.83 | 0.91 | 0.80 | 0.33 | 0.21 | 0.02 | 0.91 | -1.08 |
| 3 | 0.36 | 0.26 | 0.17 | 0.21 | 0.11 | 0.24 | 0.28 | -0.08 | -0.48 | -0.86 | -0.93 | -1.19 | -0.96 | -0.94 | -0.68 | -0.68 | -0.27 | 0.12 | 0.36 | 0.66 | 0.63 | 0.96 | 0.75 | 0.85 | -0.05 | 0.96 | -1.19 |
| 4 | 0.82 | 0.64 | 0.67 | 0.94 | 0.59 | 0.85 | 0.67 | -0.11 | -0.86 | -0.97 | -1.14 | -1.26 | -1.01 | -1.02 | -0.85 | -0.46 | -0.19 | -0.03 | 0.11 | 0.14 | 0.11 | 0.07 | -0.05 | 0.09 | -0.09 | 0.94 | -1.26 |
| 5 | 0.25 | 0.37 | 0.35 | 0.44 | 0.40 | 0.36 | 0.60 | 0.14 | -0.41 | -0.83 | -0.84 | -0.89 | -0.80 | -0.47 | -0.50 | -0.45 | -0.35 | 0.00 | 0.04 | 0.18 | 0.45 | 0.32 | 0.27 | 0.24 | -0.05 | 0.60 | -0.89 |
| 6 | 0.36 | 0.29 | 0.23 | 0.27 | 0.23 | 0.25 | 0.26 | -0.03 | -0.44 | -0.83 | -1.02 | -1.14 | -1.27 | -1.30 | -1.06 | -0.72 | -0.12 | 0.37 | 0.28 | 0.38 | 0.35 | 0.30 | 0.30 | 0.29 | -0.16 | 0.38 | -1.30 |
| 7 | 0.27 | 0.26 | 0.28 | 0.26 | 0.25 | 0.24 | 0.26 | -0.07 | -0.42 | -0.70 | -0.85 | -0.88 | -0.88 | -0.82 | -0.80 | -0.53 | -0.07 | 0.33 | 0.46 | 0.60 | 0.71 | 0.74 | 0.65 | 0.56 | -0.01 | 0.74 | -0.88 |
| 8 | 0.42 | 0.41 | 0.32 | 0.40 | 0.41 | 0.36 | 0.37 | -0.06 | -0.68 | -0.76 | -1.39 | -1.55 | -1.35 | -1.00 | -0.94 | -0.90 | -0.31 | 0.11 | 0.17 | 0.68 | 0.79 | 0.71 | 0.88 | 1.08 | -0.08 | 1.08 | -1.55 |
| 9 | 0.95 | 0.87 | 0.74 | 0.94 | 0.90 | 0.80 | 0.69 | 0.25 | -0.61 | -1.14 | -1.15 | -0.87 | -0.84 | -0.94 | -0.91 | -0.71 | -0.28 | 0.08 | 0.22 | 0.66 | 0.80 | 0.78 | 1.29 | 1.02 | 0.15 | 1.29 | -1.15 |
| 10 | 1.19 | 1.04 | 1.22 | 0.87 | 0.51 | 0.54 | 0.30 | 0.00 | -0.06 | -0.45 | -0.74 | -1.07 | -1.31 | -1.05 | -1.16 | -0.57 | 0.04 | 0.31 | 0.40 | 0.53 | 0.59 | 0.67 | 0.59 | 0.64 | 0.13 | 1.22 | -1.31 |
| 11 | 0.59 | 0.37 | 0.26 | 0.32 | 0.64 | 0.67 | 0.47 | 0.10 | -0.43 | -0.81 | -1.05 | -1.17 | -1.33 | -1.22 | -1.07 | -0.70 | -0.04 | 0.85 | 0.56 | 0.52 | 0.46 | 0.43 | 0.43 | 0.37 | -0.03 | 0.85 | -1.33 |
| 12 | 0.37 | 0.40 | 0.31 | 0.41 | 0.40 | 0.37 | 0.34 | 0.06 | -0.40 | -0.75 | -0.84 | -0.78 | -0.91 | -0.88 | -0.49 | -0.39 | -0.13 | 0.09 | 0.17 | 0.15 | 0.14 | 0.13 | 0.11 | 0.11 | -0.08 | 0.41 | -0.91 |
| 13 | 0.09 | 0.04 | 0.03 | 0.01 | 0.00 | 0.06 | 0.09 | -0.05 | -0.49 | -0.80 | -0.99 | -1.11 | -1.18 | -1.11 | -0.92 | -0.64 | -0.18 | 0.15 | 0.19 | 0.23 | 0.22 | 0.25 | 0.23 | 0.23 | -0.24 | 0.25 | -1.18 |
| 14 | 0.18 | 0.16 | 0.19 | 0.20 | 0.24 | 0.23 | 0.22 | -0.07 | -0.50 | -0.89 | -1.36 | -1.48 | -1.27 | -0.88 | -0.88 | -0.72 | -0.23 | 0.08 | 0.49 | 0.83 | 0.93 | 0.76 | 0.76 | 0.84 | -0.09 | 0.93 | -1.48 |
| 15 | 0.62 | 0.68 | 0.29 | 0.72 | 0.55 | 0.44 | 0.41 | 0.39 | 0.01 | -0.35 | -0.50 | -0.78 | -0.59 | -0.55 | -0.39 | -0.30 | 0.04 | 0.02 | 0.04 | 0.29 | 0.15 | 0.04 | -0.02 | -0.05 | 0.05 | 0.72 | -0.78 |
| 16 | -0.07 | -0.07 | -0.06 | -0.08 | -0.07 | -0.08 | -0.10 | -0.13 | -0.13 | -0.18 | -0.37 | -0.34 | -0.54 | -0.48 | -0.54 | -0.49 | -0.16 | 0.07 | 0.12 | 0.15 | 0.13 | 0.18 | 0.37 | 0.21 | -0.11 | 0.37 | -0.54 |
| 17 | 0.13 | 0.19 | 0.19 | 0.20 | 0.27 | 0.49 | 0.53 | 0.14 | -0.27 | -0.63 | -0.89 | -1.11 | -1.06 | -0.99 | -0.93 | -0.56 | -0.23 | 0.29 | 0.38 | 0.29 | 0.40 | 0.43 | 0.44 | 0.41 | -0.08 | 0.53 | -1.11 |
| 18 | 0.51 | 0.37 | 0.32 | 0.18 | 0.22 | 0.28 | 0.52 | 0.16 | -0.26 | -0.44 | -1.15 | -1.22 | -1.51 | -0.85 | -0.63 | -0.62 | -0.14 | 0.06 | 0.12 | 0.58 | 0.84 | 0.99 | 0.58 | 0.95 | -0.01 | 0.99 | -1.51 |
| 19 | 1.15 | 1.10 | 1.05 | 0.68 | 0.89 | 0.70 | 0.66 | 0.38 | -0.32 | -0.75 | -1.01 | -1.12 | -1.17 | -0.95 | -0.85 | -0.72 | -0.19 | 0.09 | 0.16 | 0.14 | 0.22 | 0.62 | 0.95 | 0.51 | 0.09 | 1.15 | -1.17 |
| 20 | 0.56 | 0.63 | 0.77 | 0.86 | 0.53 | 0.39 | 0.35 | 0.22 | -0.21 | -0.61 | -0.85 | -0.97 | -0.80 | -0.53 | -0.51 | -0.29 | -0.15 | -0.08 | -0.06 | -0.03 | -0.03 | -0.02 | 0.01 | 0.04 | -0.03 | 0.86 | -0.97 |
| 21 | 0.27 | 0.27 | 0.38 | 0.26 | 0.18 | 0.10 | 0.20 | 0.15 | -0.27 | -0.29 | -0.62 | -0.79 | -1.13 | -0.68 | -0.40 | -0.29 | -0.12 | 0.07 | 0.05 | 0.34 | 0.25 | 0.08 | 0.01 | -0.03 | -0.09 | 0.38 | -1.13 |
| 22 | -0.11 | -0.06 | 0.08 | 0.10 | 0.23 | 0.31 | 0.22 | 0.11 | -0.04 | -0.10 | -0.12 | -0.15 | -0.11 | -0.12 | -0.11 | -0.12 | -0.20 | -0.08 | -0.09 | 0.00 | -0.04 | -0.07 | -0.11 | -0.13 | -0.03 | 0.31 | -0.20 |
| 23 | -0.12 | -0.08 | 0.07 | 0.27 | 0.18 | 0.14 | 0.01 | 0.00 | -0.11 | -0.05 | -0.03 | 0.00 | -0.10 | -0.08 | -0.14 | -0.33 | -0.07 | 0.14 | 0.00 | 0.00 | 0.03 | 0.01 | -0.01 | -0.02 | -0.01 | 0.27 | -0.33 |
| 24 | -0.03 | -0.03 | -0.03 | -0.03 | -0.02 | 0.01 | 0.03 | -0.01 | -0.11 | -0.28 | -0.43 | -0.51 | -0.34 | -0.39 | -0.47 | -0.43 | -0.03 | 0.16 | 0.20 | 0.23 | 0.21 | 0.23 | 0.25 | 0.22 | -0.07 | 0.25 | -0.51 |
| 25 | 0.24 | 0.28 | 0.22 | 0.16 | 0.19 | 0.33 | 0.37 | 0.05 | -0.48 | -0.71 | -1.03 | -1.19 | -0.85 | -0.77 | -0.82 | -0.61 | -0.01 | 0.37 | 0.36 | 0.41 | 0.36 | 0.43 | 0.42 | 0.27 | -0.08 | 0.43 | -1.19 |
| 26 | 0.28 | 0.35 | 0.33 | 0.37 | 0.36 | 0.34 | 0.28 | 0.10 | -0.32 | -0.56 | -0.74 | -0.90 | -0.91 | -0.80 | -0.59 | -0.36 | 0.04 | 0.21 | 0.23 | 0.23 | 0.23 | 0.28 | 0.25 | 0.22 | -0.05 | 0.37 | -0.91 |
| 27 | 0.23 | 0.23 | 0.21 | 0.17 | 0.16 | 0.17 | 0.14 | 0.11 | -0.10 | -0.33 | -0.38 | -0.43 | -0.41 | -0.38 | -0.35 | -0.35 | 0.04 | 0.18 | 0.27 | 0.28 | 0.30 | 0.25 | 0.19 | 0.25 | 0.02 | 0.30 | -0.43 |
| 28 | 0.31 | 0.26 | 0.25 | 0.27 | 0.29 | 0.26 | 0.25 | 0.07 | -0.32 | -0.64 | -0.93 | -1.12 | -1.06 | -1.00 | -0.83 | -0.60 | 0.11 | 0.34 | 0.32 | 0.42 | 0.41 | 0.41 | 0.44 | 0.37 | -0.07 | 0.44 | -1.12 |
| 29 | 0.45 | 0.44 | 0.43 | 0.38 | 0.32 | 0.35 | 0.41 | 0.21 | -0.33 | -0.72 | -1.09 | -1.25 | -1.06 | -0.99 | -0.80 | -0.66 | -0.13 | 0.38 | 0.42 | 0.54 | 0.56 | 0.87 | 0.93 | 0.77 | 0.02 | 0.93 | -1.25 |
| 30 | 0.78 | 0.69 | 0.76 | 0.61 | 0.45 | 0.41 | 0.43 | 0.32 | -0.06 | -0.42 | -0.57 | -0.62 | -0.75 | -0.78 | -0.56 | -0.28 | 0.15 | 0.44 | 0.58 | 0.76 | 0.75 | 0.92 | 0.87 | 0.77 | 0.24 | 0.92 | -0.78 |
| Avg | 0.41 | 0.39 | 0.37 | 0.39 | 0.36 | 0.35 | 0.33 | 0.07 | -0.34 | -0.62 | -0.84 | -0.94 | -0.94 | -0.81 | -0.71 | -0.53 | -0.12 | 0.19 | 0.26 | 0.39 | 0.41 | 0.43 | 0.42 | 0.39 | -0.03 | -- | -- |
| Max | 1.19 | 1.10 | 1.22 | 0.94 | 1.10 | 0.85 | 0.69 | 0.39 | 0.01 | -0.05 | -0.03 | 0.00 | -0.10 | -0.08 | -0.11 | -0.12 | 0.15 | 0.85 | 0.70 | 0.83 | 0.93 | 0.99 | 1.29 | 1.08 | -- | 1.29 | -- |
| Min | -0.12 | -0.08 | -0.06 | -0.08 | -0.07 | -0.08 | -0.10 | -0.13 | -0.86 | -1.14 | -1.39 | -1.55 | -1.56 | -1.30 | -1.29 | -0.95 | -0.35 | -0.08 | -0.09 | -0.03 | -0.04 | -0.07 | -0.11 | -0.13 | -- | -- | -1.56 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, DeltaTemp_C"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.85 | 0.74 | 0.60 | 0.36 | 0.41 | 0.52 | 0.49 | 0.16 | -0.32 | -0.57 | -0.89 | -1.16 | -1.42 | -1.04 | -0.59 | -0.33 | 0.11 | 0.59 | 0.71 | 0.50 | 0.56 | 0.52 | 0.52 | 0.70 | 0.08 | 0.85 | -1.42 |
| 2 | 0.70 | 0.79 | 0.59 | 0.93 | 0.98 | 1.20 | 0.93 | 1.00 | -0.17 | -0.59 | -0.46 | -0.65 | -0.70 | -0.61 | -0.54 | -0.43 | -0.04 | 0.19 | 0.43 | 0.72 | 0.72 | 0.75 | 0.99 | 1.19 | 0.33 | 1.20 | -0.70 |
| 3 | 1.08 | 0.87 | 0.60 | 0.65 | 0.76 | 1.23 | 1.01 | 1.14 | -0.38 | -0.66 | -0.77 | -0.88 | -1.00 | -0.78 | -0.69 | -0.50 | -0.11 | 0.29 | 0.57 | 0.37 | 0.28 | 0.32 | 0.43 | 0.24 | 0.17 | 1.23 | -1.00 |
| 4 | 0.26 | 0.33 | 0.55 | 0.39 | 0.26 | 0.23 | 0.18 | 0.07 | -0.07 | -0.29 | -0.21 | -0.14 | -0.23 | -0.19 | -0.21 | -0.11 | -0.03 | -0.04 | -0.01 | -0.09 | -0.09 | 0.00 | -0.08 | -0.08 | 0.02 | 0.55 | -0.29 |
| 5 | -0.07 | -0.02 | -0.01 | 0.01 | -0.01 | 0.00 | 0.02 | 0.02 | -0.23 | -0.41 | -0.76 | -0.64 | -0.90 | -0.75 | -0.67 | -0.55 | -0.20 | 0.03 | 0.08 | 0.04 | 0.08 | 0.07 | 0.10 | 0.20 | -0.19 | 0.20 | -0.90 |
| 6 | 0.26 | 0.21 | 0.33 | 0.31 | 0.61 | 0.59 | 0.54 | 0.82 | -0.34 | -0.83 | -0.94 | -0.89 | -1.03 | -0.79 | -0.81 | -0.51 | -0.24 | 0.01 | 0.18 | 0.57 | 0.72 | 0.35 | 0.50 | 0.62 | 0.01 | 0.82 | -1.03 |
| 7 | 0.63 | 0.74 | 0.70 | 0.88 | 0.47 | 0.55 | 0.60 | 0.38 | -0.28 | -0.78 | -0.65 | -0.88 | -1.08 | -0.74 | -0.80 | -0.54 | -0.18 | 0.18 | 0.28 | 0.00 | 0.00 | -0.04 | -0.06 | -0.08 | -0.03 | 0.88 | -1.08 |
| 8 | -0.08 | -0.04 | -0.03 | -0.02 | 0.00 | -0.01 | -0.04 | -0.09 | -0.15 | -0.55 | -0.36 | -0.46 | -0.40 | -0.27 | -0.41 | -0.33 | -0.11 | -0.01 | -0.02 | -0.04 | 0.01 | 0.06 | 0.09 | 0.00 | -0.14 | 0.09 | -0.55 |
| 9 | 0.04 | 0.14 | 0.21 | 0.55 | 0.59 | 0.76 | 0.66 | 0.69 | -0.24 | -0.78 | -1.05 | -1.22 | -1.25 | -1.16 | -0.85 | -0.48 | -0.04 | 0.25 | 0.22 | 0.21 | 0.20 | 0.20 | 0.18 | 0.20 | -0.08 | 0.76 | -1.25 |
| 10 | 0.21 | 0.22 | 0.21 | 0.20 | 0.21 | 0.21 | 0.19 | 0.13 | -0.02 | -0.31 | -0.44 | -0.60 | -0.64 | -0.55 | -0.54 | -0.31 | 0.03 | 0.20 | 0.29 | 0.27 | 0.24 | 0.32 | 0.30 | 0.28 | 0.00 | 0.32 | -0.64 |
| 11 | 0.28 | 0.29 | 0.26 | 0.23 | 0.21 | 0.21 | 0.23 | 0.16 | -0.20 | -0.56 | -0.75 | -0.95 | -1.02 | -1.00 | -0.70 | -0.39 | 0.06 | 0.28 | 0.32 | 0.34 | 0.34 | 0.35 | 0.28 | 0.27 | -0.06 | 0.35 | -1.02 |
| 12 | 0.26 | 0.26 | 0.28 | 0.27 | 0.22 | 0.23 | 0.24 | 0.15 | -0.23 | -0.52 | -0.76 | -0.91 | -1.00 | -1.17 | -1.13 | -0.32 | 0.03 | 0.11 | 0.30 | 0.47 | 0.69 | 0.53 | 0.47 | 0.37 | -0.05 | 0.69 | -1.17 |
| 13 | 0.72 | 0.40 | 0.65 | 0.99 | 0.68 | 0.85 | 0.67 | 0.69 | -0.03 | -0.39 | -0.78 | -0.74 | -0.73 | -0.86 | -0.70 | -0.65 | -0.18 | 0.09 | 0.19 | 0.69 | 0.33 | 0.75 | 1.22 | 0.90 | 0.20 | 1.22 | -0.86 |
| 14 | 0.97 | 0.82 | 0.54 | 0.65 | 0.54 | 0.38 | 0.34 | 0.23 | -0.18 | -0.46 | -0.62 | -0.79 | -0.88 | -0.79 | -0.63 | -0.34 | 0.03 | 0.27 | 0.27 | 0.31 | 0.27 | 0.25 | 0.31 | 0.31 | 0.08 | 0.97 | -0.88 |
| 15 | 0.31 | 0.32 | 0.28 | 0.23 | 0.23 | 0.23 | 0.23 | 0.13 | -0.17 | -0.42 | -0.62 | -0.84 | -0.83 | -0.80 | -0.67 | -0.42 | 0.06 | 0.34 | 0.28 | 0.21 | 0.21 | 0.25 | 0.28 | 0.30 | -0.04 | 0.34 | -0.84 |
| 16 | 0.28 | 0.26 | 0.25 | 0.19 | 0.19 | 0.19 | 0.24 | 0.16 | -0.12 | -0.40 | -0.65 | -0.69 | -0.69 | -0.66 | -0.42 | -0.13 | 0.18 | 0.52 | 0.54 | 0.51 | 0.53 | 0.63 | 0.60 | 0.49 | 0.08 | 0.63 | -0.69 |
| 17 | 0.42 | 0.43 | 0.44 | 0.39 | 0.38 | 0.34 | 0.42 | 0.46 | -0.06 | -0.41 | -0.68 | -0.88 | -0.90 | -0.83 | -0.64 | -0.36 | 0.06 | 0.29 | 0.35 | 0.46 | 0.49 | 0.39 | 0.40 | 0.36 | 0.05 | 0.49 | -0.90 |
| 18 | 0.39 | 0.42 | 0.41 | 0.41 | 0.38 | 0.31 | 0.26 | 0.21 | 0.05 | -0.02 | -0.54 | -0.70 | -0.57 | -0.74 | -0.86 | -0.20 | 0.18 | 0.85 | 0.51 | 0.55 | 0.79 | 1.17 | 0.68 | 1.03 | 0.21 | 1.17 | -0.86 |
| 19 | 0.72 | 0.46 | 0.25 | 0.23 | 0.32 | 0.30 | 0.29 | 0.25 | -0.06 | -0.43 | -0.72 | -0.82 | -0.99 | -0.91 | -0.77 | -0.52 | -0.17 | 0.01 | 0.08 | 0.03 | -0.08 | -0.09 | -0.11 | -0.07 | -0.12 | 0.72 | -0.99 |
| 20 | -0.04 | -0.03 | -0.06 | 0.13 | 0.11 | -0.02 | -0.02 | 0.04 | -0.08 | -0.19 | -0.36 | -0.56 | -0.70 | -0.24 | -0.19 | -0.14 | -0.08 | 0.02 | 0.00 | -0.08 | -0.06 | -0.06 | -0.06 | -0.07 | -0.11 | 0.13 | -0.70 |
| 21 | -0.07 | -0.05 | -0.06 | -0.05 | -0.04 | -0.06 | -0.05 | -0.07 | -0.08 | -0.10 | -0.12 | -0.13 | -0.25 | -0.05 | -0.02 | -0.20 | -0.13 | 0.17 | 0.28 | 0.25 | 0.08 | 0.25 | 0.17 | 0.46 | 0.00 | 0.46 | -0.25 |
| 22 | 0.57 | 0.93 | 0.86 | 0.67 | 0.69 | 0.78 | 1.10 | 0.67 | -0.02 | -0.61 | -0.82 | -1.05 | -0.73 | -0.76 | -0.62 | -0.51 | -0.17 | 0.06 | 0.11 | 0.51 | 0.49 | 0.75 | 0.74 | 0.56 | 0.18 | 1.10 | -1.05 |
| 23 | 0.37 | 0.32 | 0.27 | 0.33 | 0.25 | 0.25 | 0.25 | 0.26 | -0.05 | -0.32 | -0.52 | -0.61 | -0.66 | -0.61 | -0.60 | -0.36 | 0.15 | 0.34 | 0.34 | 0.36 | 0.39 | 0.39 | 0.39 | 0.40 | 0.06 | 0.40 | -0.66 |
| 24 | 0.38 | 0.35 | 0.34 | 0.36 | 0.35 | 0.33 | 0.34 | 0.29 | -0.14 | -0.49 | -0.68 | -0.88 | -0.95 | -1.01 | -0.80 | -0.44 | 0.00 | 0.88 | 0.53 | 0.40 | 0.49 | 0.52 | 0.63 | 0.55 | 0.06 | 0.88 | -1.01 |
| 25 | 0.36 | 0.31 | 0.30 | 0.27 | 0.24 | 0.22 | 0.27 | 0.14 | -0.15 | -0.42 | -0.58 | -0.78 | -0.74 | -0.71 | -0.57 | -0.37 | 0.08 | 0.53 | 0.35 | 0.24 | 0.23 | 0.26 | 0.28 | 0.28 | 0.00 | 0.53 | -0.78 |
| 26 | 0.26 | 0.24 | 0.22 | 0.22 | 0.21 | 0.22 | 0.22 | 0.15 | -0.14 | -0.42 | -0.60 | -0.71 | -0.73 | -0.69 | -0.56 | -0.37 | 0.06 | 0.32 | 0.32 | 0.29 | 0.37 | 0.40 | 0.38 | 0.29 | 0.00 | 0.40 | -0.73 |
| 27 | 0.31 | 0.28 | 0.25 | 0.24 | 0.31 | 0.30 | 0.29 | 0.22 | -0.11 | -0.42 | -0.63 | -0.74 | -0.73 | -0.70 | -0.65 | -0.36 | 0.09 | 0.36 | 0.38 | 0.25 | 0.41 | 0.40 | 0.42 | 0.43 | 0.03 | 0.43 | -0.74 |
| 28 | 0.41 | 0.34 | 0.37 | 0.35 | 0.39 | 0.36 | 0.34 | 0.26 | -0.15 | -0.55 | -0.79 | -1.03 | -1.20 | -0.85 | -0.56 | -0.41 | -0.05 | 0.20 | 0.44 | 0.48 | 0.67 | 0.63 | 0.79 | 0.81 | 0.05 | 0.81 | -1.20 |
| 29 | 0.77 | 0.78 | 0.87 | 1.00 | 0.94 | 0.81 | 0.43 | 0.26 | -0.08 | -0.27 | -0.48 | -0.67 | -0.77 | -0.77 | -0.63 | -0.50 | 0.06 | 0.47 | 0.50 | 0.33 | 0.27 | 0.27 | 0.29 | 0.35 | 0.18 | 1.00 | -0.77 |
| 30 | 0.31 | 0.28 | 0.34 | 0.39 | 0.49 | 0.44 | 0.34 | 0.35 | -0.25 | -0.61 | -0.82 | -1.06 | -1.08 | -0.73 | -0.54 | -0.33 | -0.06 | 0.47 | 0.74 | 0.91 | 0.81 | 0.68 | 0.66 | 0.46 | 0.09 | 0.91 | -1.08 |
| 31 | 0.58 | 0.61 | 0.67 | 0.46 | 0.39 | 0.40 | 0.37 | 0.31 | -0.16 | -0.54 | -0.85 | -1.00 | -1.16 | -1.22 | -1.10 | -0.83 | -0.12 | 0.83 | 0.89 | 0.75 | 0.95 | 1.16 | 0.85 | 0.69 | 0.12 | 1.16 | -1.22 |
| Avg | 0.40 | 0.39 | 0.37 | 0.39 | 0.38 | 0.40 | 0.37 | 0.31 | -0.15 | -0.46 | -0.64 | -0.78 | -0.84 | -0.74 | -0.63 | -0.39 | -0.02 | 0.29 | 0.34 | 0.35 | 0.37 | 0.40 | 0.41 | 0.40 | 0.04 | -- | -- |
| Max | 1.08 | 0.93 | 0.87 | 1.00 | 0.98 | 1.23 | 1.10 | 1.14 | 0.05 | -0.02 | -0.12 | -0.13 | -0.23 | -0.05 | -0.02 | -0.11 | 0.18 | 0.88 | 0.89 | 0.91 | 0.95 | 1.17 | 1.22 | 1.19 | -- | 1.23 | -- |
| Min | -0.08 | -0.05 | -0.06 | -0.05 | -0.04 | -0.06 | -0.05 | -0.09 | -0.38 | -0.83 | -1.05 | -1.22 | -1.42 | -1.22 | -1.13 | -0.83 | -0.24 | -0.04 | -0.02 | -0.09 | -0.09 | -0.09 | -0.11 | -0.08 | -- | -- | -1.42 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, Temp_2m_C"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 20.9 | 18.6 | 18.6 | 17.7 | 17.4 | 17.1 | 17.3 | 18.5 | 21.8 | 23.3 | 24.4 | 25.5 | 26.2 | 26.5 | 26.6 | 26.3 | 25.8 | 24.9 | 23.7 | 22.9 | 21.4 | 20.7 | 20.0 | 20.2 | 21.9 | 26.6 | 17.1 |
| 2 | 19.1 | 19.7 | 18.0 | 18.8 | 17.5 | 16.7 | 16.4 | 18.1 | 21.3 | 22.1 | 23.2 | 24.2 | 24.7 | 25.5 | 25.6 | 25.5 | 25.0 | 24.0 | 23.0 | 22.5 | 21.9 | 20.0 | 19.8 | 19.0 | 21.3 | 25.6 | 16.4 |
| 3 | 18.5 | 18.8 | 18.6 | 17.5 | 16.5 | 16.1 | 16.2 | 18.1 | 19.9 | 21.5 | 22.7 | 23.7 | 24.5 | 24.6 | 25.2 | 25.3 | 25.0 | 24.0 | 22.8 | 22.1 | 21.8 | 21.2 | 20.3 | 19.7 | 21.0 | 25.3 | 16.1 |
| 4 | 18.9 | 18.1 | 17.2 | 16.3 | 15.1 | 14.8 | 14.2 | 16.0 | 18.5 | 20.0 | 20.9 | 21.9 | 22.5 | 22.7 | 22.8 | 22.6 | 22.0 | 20.9 | 19.9 | 19.4 | 18.9 | 17.1 | 16.1 | 15.1 | 18.8 | 22.8 | 14.2 |
| 5 | 14.1 | 13.4 | 13.0 | 12.2 | 11.6 | 11.3 | 11.6 | 12.1 | 13.0 | 14.6 | 16.5 | 18.8 | 20.5 | 21.3 | 22.1 | 21.7 | 20.9 | 19.5 | 18.0 | 17.4 | 16.8 | 16.4 | 16.4 | 16.3 | 16.2 | 22.1 | 11.3 |
| 6 | 16.0 | 15.3 | 14.5 | 14.1 | 13.6 | 13.7 | 14.2 | 15.2 | 16.2 | 17.4 | 19.7 | 21.7 | 23.5 | 25.1 | 25.6 | 25.9 | 25.3 | 23.5 | 21.7 | 20.2 | 18.7 | 18.3 | 18.6 | 17.8 | 19.0 | 25.9 | 13.6 |
| 7 | 18.1 | 17.5 | 17.1 | 16.8 | 16.5 | 16.4 | 16.5 | 17.6 | 19.7 | 22.3 | 24.2 | 25.4 | 26.9 | 27.8 | 27.6 | 27.7 | 26.1 | 25.1 | 24.6 | 23.0 | 21.6 | 21.1 | 21.1 | 21.0 | 21.7 | 27.8 | 16.4 |
| 8 | 21.4 | 22.1 | 20.6 | 18.3 | 17.8 | 16.9 | 17.1 | 18.5 | 20.9 | 23.2 | 23.9 | 24.5 | 24.8 | 24.7 | 24.9 | 24.9 | 24.3 | 23.3 | 22.6 | 22.1 | 21.8 | 21.3 | 20.6 | 19.3 | 21.7 | 24.9 | 16.9 |
| 9 | 18.7 | 18.7 | 18.7 | 18.3 | 17.5 | 17.0 | 17.0 | 18.3 | 20.2 | 21.4 | 22.6 | 23.3 | 23.9 | 24.7 | 24.7 | 24.6 | 23.2 | 21.3 | 19.7 | 18.4 | 17.3 | 16.1 | 15.0 | 14.2 | 19.8 | 24.7 | 14.2 |
| 10 | 13.2 | 12.5 | 12.1 | 12.1 | 11.4 | 10.4 | 10.5 | 7.4 | 6.8 | 6.9 | 7.2 | 7.5 | 8.6 | 10.7 | 11.8 | 12.2 | 12.3 | 11.5 | 10.9 | 9.6 | 8.9 | 8.4 | 8.0 | 8.1 | 10.0 | 13.2 | 6.8 |
| 11 | 8.3 | 7.7 | 7.9 | 7.1 | 6.9 | 6.2 | 6.0 | 8.1 | 11.9 | 14.2 | 15.2 | 16.0 | 16.9 | 17.1 | 17.6 | 17.9 | 17.7 | 16.6 | 15.7 | 14.0 | 13.1 | 12.8 | 12.2 | 12.1 | 12.5 | 17.9 | 6.0 |
| 12 | 12.0 | 11.8 | 11.4 | 11.1 | 10.8 | 10.6 | 11.7 | 14.2 | 16.4 | 18.8 | 20.0 | 21.3 | 22.2 | 22.8 | 23.1 | 22.4 | 21.7 | 20.6 | 19.6 | 18.9 | 17.1 | 16.2 | 16.3 | 16.1 | 17.0 | 23.1 | 10.6 |
| 13 | 15.5 | 15.5 | 15.3 | 14.9 | 14.9 | 14.5 | 14.7 | 16.8 | 18.5 | 19.3 | 20.2 | 21.0 | 21.6 | 22.0 | 22.2 | 21.9 | 21.6 | 20.6 | 19.7 | 18.8 | 18.5 | 18.1 | 17.5 | 16.7 | 18.3 | 22.2 | 14.5 |
| 14 | 16.2 | 15.5 | 14.3 | 12.8 | 12.8 | 12.1 | 11.8 | 13.3 | 16.0 | 17.6 | 18.2 | 19.3 | 19.9 | 20.4 | 20.5 | 20.5 | 19.9 | 18.6 | 17.6 | 17.1 | 16.4 | 16.2 | 14.6 | 13.7 | 16.5 | 20.5 | 11.8 |
| 15 | 13.3 | 12.7 | 12.3 | 11.8 | 11.8 | 10.8 | 11.1 | 12.9 | 16.7 | 18.3 | 19.2 | 19.8 | 20.4 | 20.5 | 20.3 | 20.1 | 19.5 | 18.1 | 17.3 | 16.7 | 16.3 | 16.0 | 15.9 | 14.2 | 16.1 | 20.5 | 10.8 |
| 16 | 13.6 | 12.5 | 11.4 | 10.5 | 10.4 | 11.2 | 10.9 | 12.1 | 14.1 | 15.7 | 17.3 | 18.5 | 19.7 | 20.4 | 20.3 | 20.1 | 19.3 | 18.2 | 17.0 | 16.3 | 16.0 | 15.3 | 14.6 | 13.1 | 15.4 | 20.4 | 10.4 |
| 17 | 12.3 | 12.2 | 11.8 | 11.7 | 10.7 | 10.2 | 10.3 | 11.8 | 15.2 | 17.4 | 18.2 | 19.0 | 19.8 | 20.1 | 20.4 | 20.4 | 19.6 | 18.3 | 17.2 | 16.6 | 16.3 | 16.1 | 16.1 | 15.9 | 15.7 | 20.4 | 10.2 |
| 18 | 14.9 | 14.2 | 13.2 | 12.8 | 11.6 | 11.3 | 11.6 | 12.6 | 15.9 | 17.7 | 19.2 | 20.8 | 21.8 | 21.8 | 21.8 | 21.6 | 20.7 | 19.4 | 18.6 | 17.6 | 16.0 | 15.8 | 15.2 | 15.8 | 16.7 | 21.8 | 11.3 |
| 19 | 15.8 | 15.1 | 15.7 | 13.7 | 12.5 | 13.1 | 12.6 | 14.1 | 17.0 | 18.3 | 19.9 | 21.4 | 22.9 | 23.7 | 23.5 | 23.3 | 22.8 | 21.2 | 20.1 | 19.2 | 17.8 | 17.0 | 17.9 | 15.9 | 18.1 | 23.7 | 12.5 |
| 20 | 15.5 | 15.4 | 14.7 | 13.6 | 12.9 | 12.9 | 12.7 | 13.0 | 16.9 | 18.9 | 20.0 | 20.6 | 21.7 | 21.9 | 22.2 | 22.0 | 21.2 | 20.1 | 19.1 | 18.4 | 18.0 | 16.7 | 16.0 | 16.5 | 17.5 | 22.2 | 12.7 |
| 21 | 17.5 | 15.2 | 15.1 | 14.7 | 14.2 | 13.5 | 12.8 | 13.6 | 16.9 | 19.8 | 21.7 | 22.5 | 22.8 | 23.5 | 23.4 | 23.2 | 22.5 | 21.3 | 20.4 | 19.3 | 17.2 | 16.6 | 17.0 | 17.3 | 18.4 | 23.5 | 12.8 |
| 22 | 16.3 | 15.8 | 17.5 | 17.0 | 16.0 | 15.5 | 14.9 | 16.1 | 17.9 | 19.0 | 20.7 | 22.2 | 23.5 | 24.8 | 25.4 | 25.3 | 24.6 | 22.5 | 20.6 | 19.9 | 18.8 | 18.0 | 17.8 | 17.5 | 19.5 | 25.4 | 14.9 |
| 23 | 17.2 | 16.6 | 16.3 | 16.1 | 16.1 | 16.2 | 16.0 | 17.1 | 18.8 | 20.4 | 22.0 | 24.2 | 25.4 | 26.4 | 26.6 | 26.3 | 25.6 | 24.4 | 22.3 | 21.7 | 21.2 | 20.0 | 19.0 | 18.0 | 20.6 | 26.6 | 16.0 |
| 24 | 18.9 | 19.3 | 17.3 | 16.3 | 16.1 | 16.2 | 16.0 | 17.8 | 20.5 | 22.4 | 23.3 | 24.1 | 25.7 | 26.0 | 25.4 | 24.5 | 23.2 | 22.4 | 21.9 | 21.5 | 20.1 | 18.9 | 18.3 | 18.5 | 20.6 | 26.0 | 16.0 |
| 25 | 18.4 | 18.7 | 18.4 | 18.4 | 16.2 | 15.9 | 14.8 | 15.6 | 18.7 | 21.2 | 21.7 | 22.2 | 22.8 | 23.2 | 23.2 | 22.8 | 22.0 | 20.9 | 20.3 | 19.7 | 19.0 | 17.1 | 17.4 | 17.4 | 19.4 | 23.2 | 14.8 |
| 26 | 16.7 | 16.8 | 16.1 | 16.8 | 17.7 | 17.1 | 14.8 | 16.0 | 18.4 | 20.0 | 21.2 | 22.6 | 23.9 | 24.5 | 24.9 | 24.5 | 24.0 | 22.6 | 21.5 | 19.9 | 18.3 | 18.5 | 18.1 | 17.7 | 19.7 | 24.9 | 14.8 |
| 27 | 17.9 | 17.4 | 16.6 | 16.0 | 15.6 | 15.2 | 14.8 | 16.0 | 18.2 | 20.4 | 21.9 | 23.3 | 24.3 | 25.1 | 25.2 | 24.4 | 23.5 | 22.4 | 21.0 | 20.2 | 19.8 | 19.2 | 19.0 | 18.8 | 19.8 | 25.2 | 14.8 |
| 28 | 18.2 | 17.8 | 17.4 | 16.7 | 16.2 | 15.8 | 15.7 | 16.0 | 16.4 | 17.7 | 18.5 | 19.0 | 20.0 | 20.2 | 19.8 | 19.5 | 19.0 | 18.6 | 17.9 | 17.1 | 16.6 | 16.4 | 16.3 | 16.1 | 17.6 | 20.2 | 15.7 |
| 29 | 15.8 | 15.3 | 14.9 | 14.3 | 13.5 | 12.9 | 12.9 | 14.0 | 15.9 | 16.5 | 17.6 | 18.6 | 19.0 | 18.5 | 16.4 | 15.1 | 13.8 | 12.7 | 12.3 | 12.0 | 11.6 | 11.2 | 10.4 | 9.5 | 14.4 | 19.0 | 9.5 |
| 30 | 9.4 | 8.9 | 8.6 | 8.5 | 7.8 | 7.9 | 7.6 | 8.6 | 9.8 | 11.0 | 11.4 | 12.4 | 12.9 | 13.5 | 13.8 | 13.4 | 13.0 | 12.2 | 11.6 | 11.5 | 10.9 | 11.0 | 11.0 | 10.9 | 10.7 | 13.8 | 7.6 |
| 31 | 10.6 | 10.1 | 7.4 | 7.5 | 7.1 | 6.8 | 6.3 | 7.9 | 11.5 | 13.8 | 14.4 | 15.1 | 16.0 | 16.3 | 16.6 | 16.3 | 15.6 | 14.4 | 13.5 | 13.0 | 12.7 | 12.5 | 12.6 | 11.3 | 12.0 | 16.6 | 6.3 |
| Avg | 15.9 | 15.4 | 14.9 | 14.3 | 13.8 | 13.4 | 13.3 | 14.4 | 16.8 | 18.4 | 19.6 | 20.7 | 21.6 | 22.1 | 22.2 | 22.0 | 21.3 | 20.1 | 19.1 | 18.3 | 17.4 | 16.8 | 16.4 | 15.9 | 17.7 | -- | -- |
| Max | 21.4 | 22.1 | 20.6 | 18.8 | 17.8 | 17.1 | 17.3 | 18.5 | 21.8 | 23.3 | 24.4 | 25.5 | 26.9 | 27.8 | 27.6 | 27.7 | 26.1 | 25.1 | 24.6 | 23.0 | 21.9 | 21.3 | 21.1 | 21.0 | -- | 27.8 | -- |
| Min | 8.3 | 7.7 | 7.4 | 7.1 | 6.9 | 6.2 | 6.0 | 7.4 | 6.8 | 6.9 | 7.2 | 7.5 | 8.6 | 10.7 | 11.8 | 12.2 | 12.3 | 11.5 | 10.9 | 9.6 | 8.9 | 8.4 | 8.0 | 8.1 | -- | -- | 6.0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, Temp_2m_C"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 11.3 | 10.2 | 9.6 | 9.6 | 8.5 | 9.1 | 8.5 | 10.4 | 13.2 | 15.8 | 16.9 | 18.2 | 19.7 | 20.3 | 21.3 | 21.0 | 19.1 | 17.7 | 16.3 | 14.8 | 15.6 | 14.7 | 14.7 | 15.3 | 14.7 | 21.3 | 8.5 |
| 2 | 14.3 | 13.3 | 13.0 | 13.8 | 13.6 | 13.1 | 13.4 | 14.1 | 16.1 | 18.2 | 20.1 | 21.2 | 22.2 | 22.7 | 23.1 | 22.8 | 22.3 | 20.9 | 19.0 | 18.1 | 17.7 | 18.3 | 18.0 | 16.6 | 17.7 | 23.1 | 13.0 |
| 3 | 15.5 | 15.6 | 15.2 | 13.5 | 13.7 | 13.0 | 12.9 | 13.6 | 14.8 | 16.5 | 17.3 | 19.4 | 19.7 | 20.2 | 19.8 | 19.8 | 19.1 | 18.1 | 17.2 | 16.2 | 15.1 | 14.2 | 13.1 | 13.3 | 16.1 | 20.2 | 12.9 |
| 4 | 13.0 | 12.6 | 11.8 | 11.6 | 12.1 | 11.5 | 11.4 | 12.3 | 14.5 | 16.6 | 17.7 | 18.5 | 18.9 | 19.3 | 19.2 | 18.5 | 17.9 | 17.5 | 16.8 | 16.0 | 15.7 | 15.5 | 12.8 | 10.1 | 15.1 | 19.3 | 10.1 |
| 5 | 9.3 | 9.0 | 8.2 | 8.4 | 9.1 | 9.5 | 10.3 | 10.2 | 10.5 | 11.8 | 12.6 | 13.3 | 13.8 | 13.5 | 14.0 | 14.3 | 14.5 | 13.5 | 13.0 | 12.4 | 11.4 | 10.9 | 10.4 | 9.7 | 11.4 | 14.5 | 8.2 |
| 6 | 8.7 | 7.7 | 8.1 | 8.2 | 7.9 | 7.9 | 7.2 | 8.7 | 10.2 | 11.6 | 12.9 | 14.4 | 16.2 | 17.8 | 18.6 | 18.6 | 17.5 | 15.8 | 14.6 | 14.1 | 14.6 | 14.2 | 13.6 | 13.2 | 12.6 | 18.6 | 7.2 |
| 7 | 12.7 | 12.4 | 12.0 | 11.8 | 11.6 | 11.1 | 11.0 | 11.5 | 13.2 | 15.4 | 17.4 | 18.7 | 19.6 | 20.1 | 20.7 | 20.5 | 19.6 | 17.9 | 15.9 | 15.5 | 14.6 | 14.4 | 13.8 | 13.5 | 15.2 | 20.7 | 11.0 |
| 8 | 13.5 | 13.3 | 13.1 | 13.1 | 13.3 | 13.2 | 12.9 | 13.5 | 15.4 | 16.0 | 18.8 | 20.4 | 21.5 | 21.5 | 21.6 | 21.5 | 20.5 | 19.1 | 18.5 | 17.6 | 15.9 | 15.7 | 15.3 | 14.5 | 16.7 | 21.6 | 12.9 |
| 9 | 14.8 | 14.2 | 14.3 | 13.0 | 11.6 | 11.8 | 11.3 | 12.0 | 15.6 | 18.8 | 20.7 | 21.2 | 21.4 | 21.8 | 21.9 | 21.9 | 21.0 | 19.7 | 19.0 | 17.0 | 15.1 | 14.9 | 15.1 | 15.8 | 16.8 | 21.9 | 11.3 |
| 10 | 14.7 | 14.0 | 13.3 | 13.0 | 12.9 | 12.6 | 12.9 | 13.4 | 14.0 | 17.2 | 18.8 | 20.5 | 22.1 | 22.6 | 23.0 | 22.5 | 21.3 | 20.5 | 19.7 | 17.5 | 16.3 | 16.1 | 16.5 | 15.9 | 17.1 | 23.0 | 12.6 |
| 11 | 15.3 | 15.3 | 14.8 | 14.3 | 14.1 | 14.2 | 14.5 | 16.1 | 18.3 | 19.5 | 20.7 | 22.4 | 24.0 | 24.7 | 25.2 | 24.8 | 23.5 | 22.0 | 20.1 | 18.9 | 19.4 | 18.4 | 19.3 | 19.0 | 19.1 | 25.2 | 14.1 |
| 12 | 18.8 | 18.5 | 17.4 | 17.0 | 16.6 | 17.0 | 16.9 | 17.2 | 18.7 | 21.1 | 22.0 | 23.1 | 23.6 | 24.1 | 23.3 | 22.8 | 22.0 | 20.6 | 19.3 | 17.7 | 16.9 | 16.0 | 15.3 | 14.8 | 19.2 | 24.1 | 14.8 |
| 13 | 14.4 | 13.7 | 13.2 | 12.7 | 12.1 | 11.4 | 10.9 | 11.3 | 13.1 | 14.6 | 15.6 | 16.9 | 17.8 | 18.3 | 18.3 | 17.8 | 16.6 | 15.3 | 14.4 | 13.9 | 13.4 | 13.1 | 12.9 | 12.4 | 14.3 | 18.3 | 10.9 |
| 14 | 12.1 | 11.7 | 11.2 | 11.0 | 10.9 | 11.0 | 11.0 | 11.5 | 12.8 | 14.5 | 17.1 | 19.3 | 20.5 | 20.5 | 21.1 | 20.9 | 19.6 | 18.3 | 17.2 | 15.8 | 14.7 | 14.8 | 14.1 | 14.1 | 15.2 | 21.1 | 10.9 |
| 15 | 13.7 | 13.6 | 13.5 | 13.4 | 13.2 | 12.9 | 12.7 | 13.7 | 15.6 | 16.4 | 16.9 | 18.2 | 18.3 | 18.8 | 18.6 | 18.5 | 17.1 | 17.0 | 16.9 | 14.3 | 14.4 | 13.7 | 12.9 | 12.4 | 15.3 | 18.8 | 12.4 |
| 16 | 12.0 | 11.7 | 11.7 | 11.6 | 11.3 | 10.9 | 10.5 | 10.0 | 9.9 | 10.1 | 10.8 | 11.2 | 12.4 | 12.9 | 13.7 | 13.9 | 13.4 | 12.6 | 12.2 | 11.9 | 11.9 | 11.8 | 11.2 | 11.2 | 11.7 | 13.9 | 9.9 |
| 17 | 11.3 | 11.0 | 10.8 | 10.7 | 9.8 | 9.8 | 10.1 | 11.0 | 11.7 | 12.8 | 13.7 | 14.9 | 15.5 | 16.3 | 16.8 | 16.7 | 16.3 | 15.2 | 13.4 | 12.3 | 12.7 | 12.5 | 13.0 | 13.0 | 13.0 | 16.8 | 9.8 |
| 18 | 12.2 | 11.2 | 10.6 | 10.7 | 10.8 | 10.9 | 11.0 | 12.1 | 14.2 | 14.8 | 16.8 | 18.4 | 19.7 | 19.5 | 19.4 | 19.2 | 18.3 | 17.4 | 16.7 | 14.7 | 13.7 | 14.7 | 15.4 | 14.5 | 14.9 | 19.7 | 10.6 |
| 19 | 14.5 | 12.9 | 13.0 | 12.5 | 11.4 | 10.7 | 10.1 | 10.2 | 12.3 | 15.3 | 17.4 | 18.6 | 19.0 | 18.6 | 18.3 | 18.0 | 17.1 | 16.0 | 15.1 | 14.9 | 14.7 | 13.3 | 12.7 | 12.0 | 14.5 | 19.0 | 10.1 |
| 20 | 11.7 | 11.2 | 11.5 | 10.9 | 11.7 | 11.7 | 11.2 | 11.8 | 12.5 | 14.0 | 15.6 | 16.1 | 15.9 | 15.1 | 14.8 | 14.3 | 14.0 | 13.8 | 13.6 | 13.5 | 13.4 | 13.2 | 12.9 | 12.9 | 13.2 | 16.1 | 10.9 |
| 21 | 12.7 | 12.7 | 12.3 | 12.5 | 12.5 | 12.0 | 12.0 | 11.9 | 12.6 | 13.5 | 14.6 | 15.1 | 16.0 | 16.1 | 15.4 | 15.0 | 14.6 | 14.2 | 13.9 | 13.0 | 12.2 | 10.9 | 10.5 | 10.6 | 13.2 | 16.1 | 10.5 |
| 22 | 10.7 | 10.4 | 10.6 | 10.9 | 11.5 | 12.9 | 12.2 | 11.7 | 11.3 | 9.7 | 8.1 | 7.5 | 7.4 | 7.2 | 6.9 | 6.9 | 7.5 | 7.5 | 7.4 | 7.4 | 7.6 | 7.3 | 7.3 | 6.6 | 8.9 | 12.9 | 6.6 |
| 23 | 6.6 | 6.2 | 5.5 | 5.0 | 4.3 | 3.9 | 3.8 | 3.5 | 3.2 | 3.4 | 3.2 | 2.8 | 2.0 | 2.8 | 2.9 | 3.9 | 2.9 | 3.0 | 2.9 | 3.0 | 2.8 | 2.6 | 2.8 | 2.7 | 3.6 | 6.6 | 2.0 |
| 24 | 2.4 | 2.3 | 2.1 | 1.8 | 1.6 | 1.3 | 1.3 | 1.1 | 1.0 | 1.5 | 2.2 | 2.8 | 2.5 | 2.7 | 3.6 | 4.3 | 3.8 | 3.0 | 2.9 | 2.8 | 2.8 | 2.5 | 2.3 | 2.2 | 2.4 | 4.3 | 1.0 |
| 25 | 2.1 | 1.9 | 1.7 | 1.4 | 1.3 | 1.7 | 1.2 | 1.3 | 3.6 | 5.8 | 7.8 | 9.4 | 10.0 | 10.0 | 10.4 | 10.7 | 10.0 | 8.6 | 7.5 | 7.3 | 6.7 | 6.1 | 6.3 | 6.4 | 5.8 | 10.7 | 1.2 |
| 26 | 6.4 | 6.7 | 6.7 | 6.7 | 6.7 | 6.3 | 5.6 | 5.6 | 6.8 | 8.2 | 9.5 | 10.2 | 11.4 | 12.2 | 12.0 | 12.5 | 11.5 | 9.7 | 8.8 | 8.8 | 8.5 | 8.0 | 7.2 | 6.7 | 8.4 | 12.5 | 5.6 |
| 27 | 6.8 | 6.6 | 6.7 | 6.3 | 6.2 | 6.1 | 6.2 | 6.1 | 6.9 | 8.3 | 8.9 | 9.3 | 9.8 | 10.1 | 10.2 | 10.5 | 9.6 | 8.9 | 8.0 | 7.3 | 6.9 | 6.9 | 6.3 | 6.0 | 7.7 | 10.5 | 6.0 |
| 28 | 5.8 | 5.4 | 5.0 | 5.5 | 5.5 | 5.2 | 5.0 | 5.1 | 6.5 | 8.0 | 9.6 | 11.1 | 12.3 | 13.3 | 14.4 | 14.3 | 13.0 | 11.1 | 10.3 | 10.4 | 10.4 | 10.0 | 10.1 | 9.7 | 9.1 | 14.4 | 5.0 |
| 29 | 9.5 | 9.3 | 9.0 | 8.6 | 8.5 | 8.2 | 8.4 | 8.7 | 10.2 | 11.9 | 14.2 | 15.6 | 16.3 | 16.9 | 16.9 | 17.0 | 16.0 | 14.1 | 12.9 | 12.5 | 11.6 | 11.5 | 10.4 | 9.9 | 12.0 | 17.0 | 8.2 |
| 30 | 10.2 | 9.8 | 9.8 | 10.5 | 10.5 | 10.6 | 10.5 | 10.6 | 11.5 | 12.9 | 13.6 | 14.5 | 15.2 | 16.1 | 16.0 | 15.4 | 14.4 | 12.7 | 11.9 | 11.5 | 11.2 | 11.1 | 11.2 | 11.4 | 12.2 | 16.1 | 9.8 |
| Avg | 11.2 | 10.8 | 10.5 | 10.3 | 10.2 | 10.0 | 9.9 | 10.3 | 11.7 | 13.1 | 14.4 | 15.4 | 16.2 | 16.5 | 16.7 | 16.6 | 15.8 | 14.7 | 13.8 | 13.0 | 12.6 | 12.2 | 11.9 | 11.5 | 12.9 | -- | -- |
| Max | 18.8 | 18.5 | 17.4 | 17.0 | 16.6 | 17.0 | 16.9 | 17.2 | 18.7 | 21.1 | 22.0 | 23.1 | 24.0 | 24.7 | 25.2 | 24.8 | 23.5 | 22.0 | 20.1 | 18.9 | 19.4 | 18.4 | 19.3 | 19.0 | -- | 25.2 | -- |
| Min | 2.1 | 1.9 | 1.7 | 1.4 | 1.3 | 1.3 | 1.2 | 1.1 | 1.0 | 1.5 | 2.2 | 2.8 | 2.0 | 2.7 | 2.9 | 3.9 | 2.9 | 3.0 | 2.9 | 2.8 | 2.8 | 2.5 | 2.3 | 2.2 | -- | -- | 1.0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, Temp_2m_C"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 10.9 | 9.0 | 8.9 | 8.6 | 7.8 | 7.6 | 7.5 | 7.4 | 9.7 | 12.7 | 14.0 | 15.1 | 16.7 | 17.3 | 16.7 | 15.7 | 14.9 | 12.7 | 12.0 | 10.9 | 10.5 | 10.2 | 9.9 | 9.5 | 11.5 | 17.3 | 7.4 |
| 2 | 8.4 | 7.8 | 7.1 | 6.3 | 6.1 | 6.5 | 6.5 | 6.3 | 8.9 | 12.0 | 13.8 | 14.0 | 14.6 | 14.8 | 14.8 | 14.7 | 13.7 | 12.3 | 11.2 | 10.6 | 10.1 | 9.7 | 9.4 | 9.6 | 10.4 | 14.8 | 6.1 |
| 3 | 9.9 | 10.7 | 10.2 | 9.3 | 9.0 | 9.0 | 8.8 | 9.3 | 10.1 | 12.1 | 13.5 | 14.3 | 15.1 | 15.5 | 15.5 | 15.3 | 14.6 | 13.6 | 13.2 | 13.6 | 13.2 | 12.7 | 12.3 | 12.2 | 12.2 | 15.5 | 8.8 |
| 4 | 11.8 | 11.6 | 11.0 | 11.0 | 10.3 | 9.4 | 9.2 | 9.1 | 9.3 | 9.9 | 9.8 | 9.2 | 9.6 | 9.0 | 6.9 | 5.8 | 6.0 | 5.8 | 5.9 | 5.1 | 4.8 | 4.6 | 4.4 | 4.2 | 8.1 | 11.8 | 4.2 |
| 5 | 3.8 | 3.7 | 3.5 | 3.6 | 3.4 | 3.2 | 2.8 | 2.5 | 2.9 | 3.2 | 4.3 | 4.4 | 4.9 | 5.1 | 5.1 | 4.7 | 3.8 | 3.0 | 2.5 | 2.1 | 1.6 | 1.3 | 1.1 | 0.8 | 3.2 | 5.1 | 0.8 |
| 6 | 0.4 | 0.4 | 0.4 | 0.3 | -0.4 | -2.3 | -1.7 | -2.3 | -0.4 | 1.9 | 3.3 | 3.8 | 4.9 | 5.0 | 5.5 | 5.3 | 4.6 | 3.3 | 2.4 | 1.3 | 0.5 | 0.6 | 0.4 | 1.3 | 1.6 | 5.5 | -2.3 |
| 7 | 0.6 | 0.1 | 0.3 | -0.6 | -0.4 | -0.4 | -0.7 | -0.5 | 1.0 | 3.4 | 4.6 | 5.5 | 6.2 | 6.2 | 6.2 | 5.9 | 4.9 | 3.9 | 3.9 | 4.2 | 4.8 | 4.8 | 4.6 | 4.3 | 3.0 | 6.2 | -0.7 |
| 8 | 4.1 | 3.5 | 3.4 | 3.3 | 3.2 | 3.2 | 3.2 | 3.0 | 2.9 | 4.0 | 4.2 | 4.7 | 4.9 | 4.8 | 5.4 | 5.5 | 4.9 | 4.4 | 4.2 | 3.8 | 3.4 | 3.0 | 2.7 | 2.5 | 3.8 | 5.5 | 2.5 |
| 9 | 1.9 | 1.0 | 0.7 | -0.1 | -0.8 | -1.1 | -1.6 | -1.7 | -0.4 | 2.3 | 3.3 | 3.9 | 4.8 | 5.6 | 5.5 | 5.3 | 4.3 | 2.6 | 1.7 | 1.1 | 0.6 | 0.5 | 0.5 | 0.5 | 1.7 | 5.6 | -1.7 |
| 10 | 0.4 | 0.5 | 0.5 | 0.5 | 0.6 | 0.5 | 0.4 | 0.8 | 1.2 | 2.2 | 3.3 | 5.0 | 6.3 | 7.0 | 7.5 | 7.3 | 7.2 | 6.5 | 6.1 | 6.0 | 5.8 | 5.8 | 5.8 | 5.4 | 3.9 | 7.5 | 0.4 |
| 11 | 5.6 | 5.6 | 5.4 | 5.4 | 5.3 | 5.3 | 5.2 | 5.4 | 6.3 | 7.5 | 8.7 | 10.6 | 11.8 | 13.0 | 13.5 | 13.2 | 12.2 | 10.9 | 10.6 | 11.1 | 10.5 | 10.3 | 10.1 | 9.9 | 8.9 | 13.5 | 5.2 |
| 12 | 9.6 | 9.2 | 9.2 | 9.0 | 9.1 | 8.9 | 8.7 | 8.6 | 9.0 | 9.9 | 11.3 | 13.5 | 14.8 | 15.1 | 14.2 | 13.1 | 11.6 | 10.5 | 9.7 | 8.6 | 7.4 | 7.3 | 6.9 | 7.7 | 10.1 | 15.1 | 6.9 |
| 13 | 6.0 | 6.1 | 5.1 | 4.6 | 4.5 | 3.9 | 3.7 | 4.5 | 4.8 | 7.6 | 8.9 | 9.2 | 9.7 | 10.3 | 10.3 | 10.3 | 9.3 | 8.0 | 7.5 | 6.3 | 6.8 | 5.4 | 4.1 | 4.6 | 6.7 | 10.3 | 3.7 |
| 14 | 4.6 | 4.0 | 4.2 | 3.7 | 6.1 | 5.9 | 5.7 | 5.7 | 6.2 | 7.0 | 8.1 | 9.7 | 11.0 | 12.1 | 12.9 | 12.6 | 11.5 | 10.0 | 9.1 | 8.4 | 7.9 | 7.2 | 7.2 | 6.5 | 7.8 | 12.9 | 3.7 |
| 15 | 6.3 | 5.7 | 5.7 | 5.3 | 4.4 | 4.4 | 5.0 | 6.1 | 7.8 | 9.9 | 11.7 | 12.7 | 13.9 | 15.4 | 16.0 | 15.7 | 14.8 | 13.4 | 12.7 | 12.2 | 11.4 | 11.6 | 10.6 | 10.3 | 10.1 | 16.0 | 4.4 |
| 16 | 10.4 | 10.3 | 9.3 | 9.4 | 9.4 | 9.3 | 9.9 | 10.0 | 11.0 | 12.9 | 13.8 | 14.7 | 16.1 | 17.4 | 17.9 | 17.6 | 16.4 | 14.5 | 13.5 | 13.7 | 14.0 | 13.5 | 13.3 | 13.3 | 13.0 | 17.9 | 9.3 |
| 17 | 13.3 | 13.6 | 13.7 | 13.7 | 13.1 | 12.4 | 11.2 | 11.7 | 13.8 | 15.1 | 15.7 | 16.4 | 17.6 | 18.5 | 19.0 | 18.8 | 17.7 | 16.3 | 15.3 | 15.0 | 14.7 | 14.6 | 14.5 | 14.3 | 15.0 | 19.0 | 11.2 |
| 18 | 14.1 | 13.8 | 13.7 | 13.3 | 13.0 | 12.5 | 12.1 | 11.9 | 12.3 | 12.4 | 14.5 | 15.0 | 15.3 | 16.5 | 18.8 | 18.2 | 17.2 | 16.0 | 15.2 | 15.0 | 13.9 | 13.9 | 13.7 | 13.8 | 14.4 | 18.8 | 11.9 |
| 19 | 14.3 | 13.7 | 12.5 | 11.6 | 11.3 | 11.0 | 10.6 | 10.4 | 11.1 | 11.8 | 12.8 | 13.3 | 14.1 | 14.4 | 14.6 | 14.4 | 13.3 | 11.8 | 10.3 | 9.6 | 9.0 | 8.3 | 7.9 | 7.7 | 11.7 | 14.6 | 7.7 |
| 20 | 7.5 | 7.4 | 7.2 | 7.1 | 7.6 | 5.7 | 4.0 | 3.1 | 3.3 | 4.1 | 5.2 | 5.1 | 6.1 | 5.7 | 5.6 | 5.2 | 4.6 | 4.7 | 4.5 | 4.3 | 4.1 | 4.1 | 4.1 | 4.2 | 5.2 | 7.6 | 3.1 |
| 21 | 3.7 | 4.0 | 4.1 | 4.0 | 3.8 | 3.6 | 3.3 | 2.8 | 2.4 | 2.3 | 2.3 | 2.3 | 2.7 | 2.8 | 3.2 | 3.8 | 3.9 | 3.6 | 3.8 | 3.9 | 4.1 | 3.7 | 3.9 | 3.0 | 3.4 | 4.1 | 2.3 |
| 22 | 2.7 | 2.6 | 2.0 | 2.1 | 1.6 | 1.7 | 1.2 | 1.1 | 2.7 | 5.6 | 7.4 | 8.3 | 8.0 | 8.5 | 8.5 | 8.2 | 7.4 | 6.3 | 5.9 | 4.8 | 4.0 | 4.0 | 3.9 | 4.0 | 4.7 | 8.5 | 1.1 |
| 23 | 4.2 | 3.5 | 3.9 | 3.8 | 3.8 | 4.2 | 4.2 | 4.6 | 5.4 | 6.7 | 7.7 | 8.9 | 10.2 | 11.0 | 11.9 | 12.0 | 11.0 | 9.3 | 8.3 | 8.2 | 8.6 | 8.4 | 8.1 | 8.2 | 7.3 | 12.0 | 3.5 |
| 24 | 7.9 | 7.3 | 7.1 | 6.9 | 6.7 | 6.5 | 6.1 | 6.3 | 7.3 | 8.6 | 9.8 | 10.7 | 11.5 | 12.3 | 12.9 | 12.8 | 12.6 | 11.0 | 9.5 | 9.3 | 8.5 | 8.3 | 8.0 | 9.4 | 9.1 | 12.9 | 6.1 |
| 25 | 9.8 | 9.9 | 9.7 | 9.0 | 8.0 | 7.3 | 7.5 | 6.3 | 6.4 | 7.5 | 8.9 | 10.3 | 11.7 | 12.6 | 13.2 | 13.3 | 12.7 | 10.8 | 9.7 | 9.3 | 8.4 | 7.5 | 7.3 | 7.4 | 9.3 | 13.3 | 6.3 |
| 26 | 7.2 | 6.8 | 6.4 | 6.2 | 5.8 | 5.6 | 5.6 | 5.5 | 6.4 | 7.5 | 8.1 | 9.2 | 10.6 | 11.4 | 12.1 | 12.2 | 11.7 | 10.2 | 10.3 | 9.9 | 9.3 | 9.0 | 9.3 | 8.7 | 8.5 | 12.2 | 5.5 |
| 27 | 8.4 | 8.1 | 7.8 | 7.1 | 7.4 | 7.1 | 6.7 | 6.6 | 7.6 | 9.0 | 10.6 | 11.6 | 12.3 | 12.9 | 13.8 | 13.2 | 12.4 | 11.2 | 10.3 | 9.1 | 8.9 | 9.0 | 8.3 | 7.7 | 9.5 | 13.8 | 6.6 |
| 28 | 7.5 | 7.8 | 7.4 | 7.0 | 6.5 | 6.7 | 6.4 | 6.3 | 6.9 | 8.5 | 9.4 | 10.9 | 12.3 | 12.9 | 13.0 | 12.7 | 11.7 | 10.7 | 9.8 | 8.5 | 8.4 | 7.9 | 7.9 | 7.1 | 8.9 | 13.0 | 6.3 |
| 29 | 7.2 | 6.3 | 6.1 | 4.3 | 4.4 | 3.8 | 4.1 | 4.8 | 7.0 | 9.2 | 9.7 | 10.4 | 11.5 | 12.2 | 12.8 | 13.0 | 12.2 | 10.7 | 10.2 | 9.6 | 8.9 | 8.5 | 7.8 | 7.9 | 8.4 | 13.0 | 3.8 |
| 30 | 7.2 | 7.0 | 6.7 | 5.4 | 4.3 | 4.1 | 3.3 | 3.6 | 5.4 | 7.8 | 10.0 | 11.5 | 13.3 | 13.7 | 12.8 | 12.8 | 11.9 | 11.2 | 9.6 | 8.5 | 8.7 | 8.7 | 7.7 | 7.9 | 8.5 | 13.7 | 3.3 |
| 31 | 7.6 | 7.3 | 7.3 | 8.2 | 7.5 | 7.2 | 7.2 | 7.1 | 8.1 | 9.3 | 10.8 | 12.1 | 13.1 | 14.4 | 15.4 | 15.5 | 14.3 | 11.5 | 9.8 | 9.6 | 9.8 | 9.1 | 7.9 | 9.2 | 10.0 | 15.5 | 7.1 |
| Avg | 7.0 | 6.7 | 6.5 | 6.1 | 5.9 | 5.6 | 5.4 | 5.4 | 6.3 | 7.9 | 9.0 | 9.9 | 10.8 | 11.4 | 11.7 | 11.4 | 10.6 | 9.4 | 8.7 | 8.2 | 7.8 | 7.5 | 7.2 | 7.2 | 8.1 | -- | -- |
| Max | 14.3 | 13.8 | 13.7 | 13.7 | 13.1 | 12.5 | 12.1 | 11.9 | 13.8 | 15.1 | 15.7 | 16.4 | 17.6 | 18.5 | 19.0 | 18.8 | 17.7 | 16.3 | 15.3 | 15.0 | 14.7 | 14.6 | 14.5 | 14.3 | -- | 19.0 | -- |
| Min | 0.4 | 0.1 | 0.3 | -0.6 | -0.8 | -2.3 | -1.7 | -2.3 | -0.4 | 1.9 | 2.3 | 2.3 | 2.7 | 2.8 | 3.2 | 3.8 | 3.8 | 2.6 | 1.7 | 1.1 | 0.5 | 0.5 | 0.4 | 0.5 | -- | -- | -2.3 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, SR_Wm2_2m"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 40 | 258 | 488 | 683 | 821 | 891 | 888 | 822 | 690 | 507 | 287 | 65 | 0 | 0 | 0 | 0 | 0 | 0 | 268 | 891 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 36 | 248 | 476 | 669 | 802 | 871 | 871 | 807 | 675 | 495 | 278 | 61 | 0 | 0 | 0 | 0 | 0 | 0 | 262 | 871 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 37 | 254 | 489 | 678 | 812 | 876 | 876 | 797 | 666 | 487 | 272 | 57 | 0 | 0 | 0 | 0 | 0 | 0 | 263 | 876 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 32 | 238 | 464 | 653 | 792 | 860 | 858 | 792 | 661 | 480 | 262 | 54 | 0 | 0 | 0 | 0 | 0 | 0 | 256 | 860 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 37 | 262 | 499 | 701 | 842 | 911 | 902 | 829 | 690 | 502 | 279 | 53 | 0 | 0 | 0 | 0 | 0 | 0 | 271 | 911 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 35 | 256 | 489 | 686 | 822 | 891 | 889 | 817 | 675 | 489 | 267 | 47 | 0 | 0 | 0 | 0 | 0 | 0 | 265 | 891 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 34 | 252 | 468 | 687 | 781 | 830 | 840 | 767 | 518 | 451 | 124 | 38 | 0 | 0 | 0 | 0 | 0 | 0 | 241 | 840 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 27 | 228 | 455 | 647 | 782 | 850 | 849 | 781 | 638 | 464 | 249 | 41 | 0 | 0 | 0 | 0 | 0 | 0 | 250 | 850 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 29 | 233 | 454 | 647 | 789 | 851 | 788 | 778 | 598 | 447 | 162 | 33 | 0 | 0 | 0 | 0 | 0 | 0 | 242 | 851 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 9 | 22 | 59 | 173 | 316 | 552 | 626 | 570 | 468 | 250 | 36 | 0 | 0 | 0 | 0 | 0 | 0 | 128 | 626 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 26 | 232 | 460 | 650 | 784 | 854 | 850 | 779 | 641 | 458 | 240 | 34 | 0 | 0 | 0 | 0 | 0 | 0 | 250 | 854 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 24 | 225 | 451 | 643 | 780 | 844 | 841 | 772 | 631 | 447 | 231 | 31 | 0 | 0 | 0 | 0 | 0 | 0 | 247 | 844 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 20 | 212 | 443 | 633 | 767 | 838 | 831 | 764 | 628 | 446 | 230 | 30 | 0 | 0 | 0 | 0 | 0 | 0 | 243 | 838 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 22 | 213 | 435 | 626 | 768 | 832 | 828 | 764 | 629 | 443 | 224 | 28 | 0 | 0 | 0 | 0 | 0 | 0 | 242 | 832 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 20 | 210 | 434 | 626 | 763 | 828 | 823 | 756 | 620 | 435 | 219 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 240 | 828 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 20 | 216 | 444 | 635 | 770 | 836 | 833 | 759 | 621 | 435 | 218 | 24 | 0 | 0 | 0 | 0 | 0 | 0 | 242 | 836 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 20 | 215 | 443 | 631 | 765 | 828 | 824 | 754 | 615 | 428 | 212 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 240 | 828 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 17 | 204 | 431 | 625 | 767 | 834 | 827 | 756 | 613 | 427 | 210 | 21 | 0 | 0 | 0 | 0 | 0 | 0 | 239 | 834 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 19 | 214 | 443 | 634 | 769 | 834 | 825 | 748 | 611 | 422 | 203 | 18 | 0 | 0 | 0 | 0 | 0 | 0 | 239 | 834 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 16 | 200 | 423 | 616 | 751 | 818 | 813 | 742 | 602 | 418 | 202 | 16 | 0 | 0 | 0 | 0 | 0 | 0 | 234 | 818 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 15 | 192 | 418 | 606 | 739 | 804 | 797 | 725 | 588 | 406 | 188 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 229 | 804 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 192 | 419 | 608 | 742 | 807 | 800 | 728 | 588 | 403 | 181 | 13 | 0 | 0 | 0 | 0 | 0 | 0 | 229 | 807 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 185 | 405 | 592 | 724 | 786 | 780 | 708 | 566 | 383 | 175 | 18 | 0 | 0 | 0 | 0 | 0 | 0 | 222 | 786 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 11 | 188 | 376 | 531 | 579 | 610 | 762 | 542 | 466 | 273 | 83 | 16 | 0 | 0 | 0 | 0 | 0 | 0 | 185 | 762 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 10 | 176 | 395 | 580 | 716 | 783 | 779 | 707 | 571 | 387 | 161 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 220 | 783 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 10 | 178 | 401 | 587 | 720 | 777 | 777 | 706 | 560 | 261 | 158 | 11 | 0 | 0 | 0 | 0 | 0 | 0 | 214 | 777 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 168 | 392 | 578 | 712 | 781 | 770 | 693 | 536 | 372 | 153 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 215 | 781 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 10 | 95 | 197 | 387 | 639 | 777 | 751 | 537 | 301 | 180 | 75 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 165 | 777 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 166 | 386 | 570 | 700 | 765 | 759 | 551 | 144 | 186 | 68 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 180 | 765 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 98 | 292 | 526 | 587 | 765 | 766 | 691 | 546 | 365 | 143 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 200 | 766 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 163 | 384 | 569 | 697 | 764 | 759 | 688 | 549 | 364 | 142 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 212 | 764 | 0 |
| Avg | 0 | 0 | 0 | 0 | 0 | 0 | 20 | 199 | 412 | 599 | 731 | 803 | 810 | 732 | 581 | 411 | 198 | 28 | 0 | 0 | 0 | 0 | 0 | 0 | 230 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 0 | 0 | 40 | 262 | 499 | 701 | 842 | 911 | 902 | 829 | 690 | 507 | 287 | 65 | 0 | 0 | 0 | 0 | 0 | 0 | -- | 911 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 9 | 22 | 59 | 173 | 316 | 552 | 537 | 144 | 180 | 68 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, SR_Wm2_2m"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 163 | 385 | 573 | 705 | 772 | 768 | 690 | 550 | 360 | 140 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 213 | 772 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 162 | 385 | 574 | 708 | 774 | 766 | 685 | 488 | 276 | 148 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 207 | 774 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 78 | 219 | 473 | 491 | 691 | 601 | 655 | 387 | 344 | 130 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 170 | 691 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 139 | 353 | 540 | 670 | 736 | 612 | 654 | 434 | 242 | 67 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 186 | 736 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 106 | 270 | 453 | 748 | 834 | 378 | 266 | 373 | 171 | 170 | 8 | 0 | 0 | 0 | 0 | 0 | 0 | 157 | 834 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 150 | 374 | 563 | 695 | 760 | 752 | 675 | 538 | 351 | 129 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 208 | 760 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 145 | 368 | 557 | 691 | 760 | 755 | 680 | 537 | 350 | 127 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 207 | 760 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 138 | 346 | 377 | 658 | 717 | 708 | 637 | 502 | 329 | 110 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 189 | 717 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 126 | 339 | 519 | 646 | 708 | 706 | 634 | 502 | 323 | 109 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 192 | 708 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 81 | 138 | 380 | 398 | 557 | 602 | 411 | 484 | 222 | 68 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 139 | 602 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 116 | 324 | 502 | 630 | 696 | 696 | 623 | 490 | 316 | 105 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 188 | 696 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 117 | 330 | 518 | 606 | 631 | 667 | 544 | 281 | 233 | 84 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 167 | 667 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 82 | 319 | 498 | 629 | 692 | 688 | 632 | 488 | 312 | 102 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 185 | 692 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 104 | 315 | 493 | 621 | 688 | 682 | 613 | 485 | 309 | 100 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 184 | 688 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 20 | 91 | 261 | 300 | 475 | 363 | 346 | 213 | 177 | 35 | 2 | 0 | 2 | 0 | 0 | 0 | 0 | 95 | 475 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 10 | 34 | 89 | 193 | 269 | 349 | 406 | 386 | 281 | 101 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 88 | 406 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 54 | 157 | 383 | 535 | 678 | 571 | 626 | 460 | 298 | 89 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 160 | 678 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 107 | 150 | 267 | 588 | 484 | 696 | 347 | 393 | 302 | 87 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 143 | 696 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 53 | 261 | 392 | 557 | 672 | 668 | 584 | 460 | 286 | 89 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 168 | 672 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 44 | 116 | 295 | 426 | 516 | 540 | 274 | 264 | 119 | 23 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 109 | 540 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 41 | 110 | 151 | 298 | 400 | 548 | 338 | 195 | 130 | 51 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 94 | 548 | 0 |
| 22 | 0 | 0 | 0 | 0 | 1 | 2 | 0 | 2 | 15 | 23 | 51 | 122 | 71 | 76 | 83 | 65 | 40 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 23 | 122 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 45 | 48 | 45 | 28 | 45 | 61 | 128 | 281 | 57 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 31 | 281 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 64 | 160 | 239 | 223 | 170 | 204 | 260 | 210 | 53 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 66 | 260 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 82 | 283 | 461 | 589 | 655 | 656 | 595 | 465 | 291 | 76 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 173 | 656 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 80 | 283 | 463 | 592 | 659 | 658 | 593 | 466 | 294 | 78 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 174 | 659 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 37 | 185 | 319 | 332 | 355 | 335 | 316 | 268 | 257 | 49 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 102 | 355 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 77 | 281 | 462 | 591 | 657 | 655 | 589 | 462 | 288 | 76 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 172 | 657 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 60 | 262 | 419 | 584 | 649 | 654 | 579 | 459 | 278 | 79 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 168 | 654 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 31 | 170 | 307 | 382 | 356 | 398 | 356 | 269 | 173 | 49 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 104 | 398 | 0 |
| Avg | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 81 | 232 | 384 | 507 | 574 | 558 | 490 | 392 | 262 | 87 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 149 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 1 | 2 | 6 | 163 | 385 | 574 | 748 | 834 | 768 | 690 | 550 | 360 | 170 | 8 | 0 | 2 | 0 | 0 | 0 | 0 | -- | 834 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 15 | 23 | 45 | 28 | 45 | 61 | 83 | 65 | 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, SR_Wm2_2m"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 55 | 263 | 427 | 580 | 643 | 674 | 507 | 317 | 221 | 80 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 157 | 674 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 54 | 257 | 441 | 568 | 633 | 619 | 455 | 357 | 304 | 74 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 157 | 633 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 44 | 239 | 418 | 539 | 641 | 644 | 573 | 460 | 289 | 84 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 164 | 644 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 48 | 168 | 331 | 169 | 70 | 141 | 96 | 29 | 19 | 23 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 46 | 331 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 17 | 162 | 316 | 538 | 490 | 630 | 523 | 464 | 299 | 80 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 147 | 630 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 55 | 254 | 438 | 570 | 642 | 646 | 584 | 459 | 288 | 86 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 168 | 646 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 54 | 249 | 434 | 567 | 638 | 643 | 582 | 458 | 286 | 87 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 167 | 643 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 127 | 331 | 291 | 297 | 226 | 202 | 354 | 206 | 53 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 87 | 354 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 51 | 251 | 439 | 571 | 646 | 655 | 594 | 471 | 300 | 89 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 169 | 655 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 15 | 78 | 286 | 352 | 431 | 436 | 394 | 348 | 221 | 94 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 111 | 436 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 46 | 233 | 416 | 547 | 617 | 623 | 563 | 446 | 281 | 87 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 161 | 623 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 41 | 226 | 406 | 537 | 607 | 661 | 595 | 476 | 135 | 33 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 155 | 661 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 38 | 218 | 393 | 531 | 607 | 617 | 560 | 440 | 274 | 86 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 157 | 617 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 45 | 236 | 421 | 559 | 632 | 639 | 583 | 465 | 294 | 94 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 165 | 639 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 43 | 231 | 414 | 548 | 621 | 629 | 571 | 453 | 285 | 91 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 162 | 629 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 40 | 218 | 411 | 542 | 596 | 599 | 517 | 369 | 200 | 61 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 148 | 599 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 43 | 228 | 414 | 554 | 632 | 617 | 568 | 458 | 281 | 90 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 162 | 632 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 10 | 115 | 179 | 414 | 456 | 336 | 449 | 474 | 192 | 50 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 112 | 474 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 35 | 217 | 400 | 536 | 614 | 620 | 577 | 436 | 272 | 93 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 159 | 620 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 55 | 158 | 230 | 254 | 398 | 69 | 85 | 65 | 19 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 56 | 398 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 12 | 41 | 65 | 117 | 203 | 122 | 166 | 133 | 76 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 39 | 203 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 31 | 209 | 397 | 540 | 617 | 627 | 568 | 377 | 287 | 101 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 157 | 627 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 35 | 220 | 409 | 550 | 628 | 640 | 585 | 465 | 298 | 105 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 164 | 640 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 34 | 219 | 405 | 545 | 623 | 634 | 577 | 460 | 296 | 102 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 162 | 634 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 34 | 224 | 416 | 556 | 633 | 646 | 591 | 474 | 304 | 108 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 166 | 646 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 31 | 217 | 407 | 550 | 631 | 645 | 592 | 475 | 307 | 113 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 166 | 645 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 29 | 211 | 399 | 542 | 625 | 638 | 585 | 470 | 307 | 115 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 163 | 638 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 30 | 187 | 362 | 493 | 559 | 524 | 483 | 372 | 195 | 84 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 137 | 559 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 25 | 203 | 390 | 532 | 613 | 630 | 578 | 467 | 303 | 115 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 161 | 630 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 27 | 207 | 400 | 545 | 627 | 640 | 588 | 475 | 308 | 119 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 164 | 640 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 27 | 206 | 397 | 540 | 622 | 638 | 587 | 472 | 305 | 116 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 163 | 638 | 0 |
| Avg | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 34 | 198 | 371 | 490 | 550 | 565 | 497 | 403 | 250 | 84 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 144 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 55 | 263 | 441 | 580 | 646 | 674 | 595 | 476 | 308 | 119 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | -- | 674 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 12 | 41 | 65 | 70 | 141 | 69 | 29 | 19 | 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, RH_Percent"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 17 | 20 | 20 | 21 | 21 | 22 | 22 | 21 | 17 | 14 | 13 | 14 | 14 | 15 | 14 | 15 | 16 | 16 | 17 | 18 | 20 | 21 | 23 | 23 | 18 | 23 | 13 |
| 2 | 25 | 25 | 28 | 29 | 31 | 35 | 34 | 28 | 28 | 30 | 27 | 26 | 24 | 23 | 22 | 22 | 23 | 24 | 27 | 26 | 27 | 30 | 30 | 31 | 27 | 35 | 22 |
| 3 | 31 | 31 | 33 | 36 | 39 | 42 | 45 | 42 | 38 | 28 | 20 | 22 | 23 | 26 | 25 | 24 | 22 | 20 | 21 | 21 | 21 | 22 | 29 | 35 | 29 | 45 | 20 |
| 4 | 42 | 43 | 50 | 51 | 55 | 54 | 53 | 42 | 34 | 29 | 25 | 22 | 22 | 22 | 22 | 20 | 21 | 18 | 16 | 13 | 11 | 16 | 15 | 14 | 30 | 55 | 11 |
| 5 | 15 | 15 | 16 | 17 | 19 | 19 | 16 | 15 | 15 | 13 | 11 | 10 | 9 | 8 | 8 | 8 | 9 | 10 | 12 | 14 | 16 | 16 | 16 | 16 | 13 | 19 | 8 |
| 6 | 16 | 15 | 17 | 17 | 19 | 19 | 18 | 17 | 17 | 16 | 13 | 12 | 10 | 8 | 8 | 7 | 8 | 10 | 12 | 13 | 14 | 14 | 13 | 15 | 14 | 19 | 7 |
| 7 | 14 | 14 | 15 | 15 | 16 | 17 | 17 | 16 | 15 | 12 | 10 | 10 | 10 | 10 | 10 | 10 | 10 | 9 | 10 | 11 | 12 | 13 | 13 | 14 | 13 | 17 | 9 |
| 8 | 13 | 12 | 13 | 16 | 17 | 18 | 18 | 16 | 15 | 12 | 11 | 11 | 14 | 16 | 14 | 12 | 12 | 13 | 14 | 14 | 15 | 16 | 18 | 20 | 15 | 20 | 11 |
| 9 | 18 | 18 | 18 | 21 | 25 | 26 | 27 | 25 | 22 | 21 | 19 | 18 | 16 | 15 | 15 | 14 | 19 | 26 | 31 | 35 | 37 | 45 | 53 | 58 | 26 | 58 | 14 |
| 10 | 65 | 74 | 79 | 80 | 79 | 79 | 76 | 92 | 95 | 96 | 96 | 92 | 74 | 60 | 54 | 47 | 47 | 48 | 54 | 61 | 64 | 61 | 63 | 60 | 71 | 96 | 47 |
| 11 | 56 | 65 | 61 | 65 | 68 | 72 | 70 | 59 | 43 | 36 | 26 | 25 | 25 | 29 | 29 | 27 | 27 | 29 | 31 | 36 | 39 | 38 | 41 | 41 | 43 | 72 | 25 |
| 12 | 40 | 40 | 41 | 40 | 40 | 40 | 35 | 29 | 26 | 24 | 24 | 23 | 21 | 18 | 18 | 20 | 21 | 24 | 26 | 27 | 32 | 34 | 34 | 34 | 30 | 41 | 18 |
| 13 | 36 | 36 | 36 | 38 | 38 | 39 | 38 | 34 | 32 | 33 | 33 | 33 | 29 | 25 | 23 | 20 | 18 | 19 | 21 | 26 | 27 | 28 | 29 | 31 | 30 | 39 | 18 |
| 14 | 32 | 36 | 41 | 45 | 46 | 50 | 51 | 45 | 38 | 36 | 32 | 29 | 27 | 22 | 21 | 21 | 19 | 18 | 19 | 20 | 23 | 24 | 27 | 27 | 31 | 51 | 18 |
| 15 | 26 | 28 | 29 | 30 | 30 | 33 | 32 | 28 | 22 | 20 | 18 | 19 | 18 | 19 | 19 | 18 | 18 | 20 | 21 | 23 | 23 | 23 | 22 | 25 | 23 | 33 | 18 |
| 16 | 26 | 27 | 29 | 31 | 32 | 33 | 35 | 33 | 30 | 28 | 25 | 17 | 14 | 14 | 15 | 16 | 19 | 20 | 22 | 23 | 24 | 25 | 27 | 29 | 25 | 35 | 14 |
| 17 | 30 | 30 | 29 | 28 | 29 | 30 | 29 | 25 | 20 | 17 | 17 | 17 | 16 | 16 | 15 | 15 | 17 | 19 | 21 | 21 | 22 | 22 | 22 | 23 | 22 | 30 | 15 |
| 18 | 24 | 25 | 27 | 28 | 30 | 31 | 29 | 28 | 23 | 18 | 13 | 11 | 10 | 11 | 12 | 13 | 14 | 16 | 17 | 18 | 20 | 15 | 15 | 14 | 19 | 31 | 10 |
| 19 | 14 | 15 | 14 | 17 | 19 | 17 | 18 | 16 | 13 | 12 | 10 | 9 | 7 | 6 | 6 | 7 | 8 | 9 | 9 | 10 | 11 | 12 | 11 | 12 | 12 | 19 | 6 |
| 20 | 12 | 12 | 13 | 15 | 16 | 16 | 16 | 16 | 12 | 10 | 10 | 10 | 10 | 10 | 10 | 10 | 10 | 11 | 13 | 14 | 15 | 17 | 17 | 16 | 13 | 17 | 10 |
| 21 | 14 | 17 | 17 | 17 | 18 | 19 | 20 | 18 | 15 | 12 | 11 | 9 | 10 | 9 | 8 | 8 | 9 | 10 | 11 | 13 | 15 | 16 | 14 | 13 | 14 | 20 | 8 |
| 22 | 14 | 16 | 14 | 15 | 16 | 16 | 20 | 22 | 22 | 20 | 19 | 17 | 15 | 12 | 8 | 8 | 9 | 11 | 12 | 11 | 13 | 16 | 16 | 17 | 15 | 22 | 8 |
| 23 | 18 | 20 | 21 | 21 | 22 | 22 | 23 | 21 | 19 | 18 | 16 | 14 | 12 | 11 | 10 | 10 | 10 | 12 | 15 | 15 | 14 | 17 | 19 | 22 | 17 | 23 | 10 |
| 24 | 22 | 23 | 27 | 29 | 30 | 29 | 30 | 26 | 22 | 20 | 19 | 17 | 14 | 13 | 13 | 13 | 13 | 13 | 14 | 14 | 15 | 16 | 17 | 16 | 19 | 30 | 13 |
| 25 | 16 | 16 | 16 | 16 | 19 | 19 | 21 | 20 | 16 | 13 | 13 | 14 | 15 | 14 | 14 | 14 | 15 | 17 | 16 | 16 | 17 | 19 | 19 | 21 | 16 | 21 | 13 |
| 26 | 27 | 29 | 31 | 32 | 30 | 32 | 36 | 33 | 29 | 26 | 24 | 21 | 17 | 15 | 14 | 14 | 14 | 17 | 20 | 22 | 24 | 23 | 24 | 25 | 24 | 36 | 14 |
| 27 | 25 | 25 | 25 | 27 | 29 | 30 | 32 | 30 | 27 | 24 | 21 | 18 | 16 | 13 | 12 | 12 | 13 | 14 | 16 | 19 | 19 | 20 | 19 | 18 | 21 | 32 | 12 |
| 28 | 20 | 21 | 24 | 26 | 30 | 30 | 28 | 26 | 26 | 24 | 23 | 23 | 21 | 21 | 20 | 21 | 23 | 27 | 31 | 35 | 37 | 35 | 34 | 35 | 27 | 37 | 20 |
| 29 | 36 | 37 | 40 | 42 | 49 | 52 | 49 | 40 | 34 | 32 | 29 | 27 | 27 | 30 | 43 | 51 | 51 | 50 | 47 | 48 | 50 | 51 | 54 | 56 | 43 | 56 | 27 |
| 30 | 57 | 57 | 58 | 57 | 59 | 60 | 61 | 55 | 50 | 45 | 45 | 40 | 36 | 31 | 31 | 30 | 30 | 33 | 34 | 35 | 37 | 38 | 38 | 38 | 44 | 61 | 30 |
| 31 | 39 | 39 | 45 | 44 | 45 | 46 | 48 | 42 | 34 | 29 | 25 | 24 | 21 | 21 | 21 | 22 | 24 | 27 | 28 | 29 | 30 | 31 | 31 | 32 | 32 | 48 | 21 |
| Avg | 27 | 28 | 30 | 31 | 33 | 34 | 34 | 31 | 27 | 25 | 23 | 21 | 19 | 18 | 18 | 18 | 18 | 20 | 21 | 23 | 24 | 25 | 26 | 27 | 25 | -- | -- |
| Max | 65 | 74 | 79 | 80 | 79 | 79 | 76 | 92 | 95 | 96 | 96 | 92 | 74 | 60 | 54 | 51 | 51 | 50 | 54 | 61 | 64 | 61 | 63 | 60 | -- | 96 | -- |
| Min | 12 | 12 | 13 | 15 | 16 | 16 | 16 | 15 | 12 | 10 | 10 | 9 | 7 | 6 | 6 | 7 | 8 | 9 | 9 | 10 | 11 | 12 | 11 | 12 | -- | -- | 6 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, RH_Percent"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 32 | 34 | 35 | 35 | 39 | 37 | 38 | 31 | 26 | 22 | 21 | 19 | 16 | 15 | 14 | 15 | 18 | 21 | 23 | 24 | 22 | 21 | 20 | 18 | 25 | 39 | 14 |
| 2 | 20 | 21 | 22 | 20 | 21 | 21 | 20 | 19 | 16 | 14 | 11 | 10 | 9 | 9 | 9 | 9 | 9 | 10 | 12 | 14 | 14 | 14 | 16 | 27 | 15 | 27 | 9 |
| 3 | 31 | 31 | 36 | 43 | 49 | 62 | 62 | 58 | 54 | 47 | 45 | 33 | 32 | 32 | 33 | 30 | 29 | 30 | 30 | 31 | 33 | 35 | 38 | 37 | 39 | 62 | 29 |
| 4 | 37 | 38 | 39 | 39 | 40 | 43 | 45 | 41 | 38 | 39 | 38 | 34 | 31 | 31 | 32 | 34 | 35 | 35 | 36 | 38 | 38 | 36 | 52 | 80 | 40 | 80 | 31 |
| 5 | 86 | 85 | 86 | 84 | 80 | 77 | 66 | 67 | 67 | 64 | 58 | 55 | 54 | 55 | 53 | 52 | 49 | 52 | 52 | 54 | 44 | 33 | 31 | 29 | 60 | 86 | 29 |
| 6 | 26 | 21 | 15 | 13 | 13 | 12 | 13 | 11 | 9 | 9 | 8 | 8 | 7 | 5 | 3 | 4 | 6 | 7 | 8 | 11 | 13 | 13 | 14 | 14 | 11 | 26 | 3 |
| 7 | 15 | 16 | 17 | 18 | 17 | 18 | 16 | 16 | 15 | 12 | 8 | 6 | 6 | 5 | 6 | 6 | 8 | 10 | 11 | 13 | 16 | 18 | 20 | 23 | 13 | 23 | 5 |
| 8 | 25 | 27 | 28 | 28 | 28 | 27 | 27 | 26 | 24 | 24 | 21 | 19 | 17 | 18 | 18 | 18 | 20 | 24 | 27 | 29 | 31 | 32 | 33 | 34 | 25 | 34 | 17 |
| 9 | 34 | 34 | 33 | 34 | 38 | 38 | 39 | 35 | 28 | 23 | 18 | 17 | 18 | 18 | 18 | 17 | 19 | 22 | 23 | 26 | 29 | 29 | 29 | 27 | 27 | 39 | 17 |
| 10 | 29 | 31 | 33 | 33 | 33 | 33 | 32 | 31 | 30 | 24 | 22 | 20 | 19 | 18 | 18 | 18 | 19 | 20 | 21 | 25 | 27 | 28 | 27 | 29 | 26 | 33 | 18 |
| 11 | 30 | 30 | 31 | 32 | 32 | 32 | 31 | 28 | 25 | 24 | 22 | 21 | 20 | 19 | 17 | 17 | 19 | 22 | 25 | 25 | 19 | 20 | 18 | 18 | 24 | 32 | 17 |
| 12 | 17 | 15 | 16 | 17 | 18 | 19 | 20 | 20 | 18 | 16 | 15 | 17 | 18 | 20 | 22 | 24 | 26 | 29 | 30 | 35 | 37 | 38 | 38 | 39 | 24 | 39 | 15 |
| 13 | 41 | 44 | 48 | 52 | 55 | 58 | 60 | 58 | 53 | 48 | 45 | 43 | 42 | 40 | 40 | 41 | 43 | 46 | 49 | 51 | 52 | 53 | 54 | 55 | 49 | 60 | 40 |
| 14 | 56 | 58 | 59 | 60 | 60 | 60 | 60 | 57 | 53 | 49 | 42 | 35 | 30 | 30 | 26 | 27 | 32 | 36 | 39 | 43 | 45 | 45 | 45 | 43 | 45 | 60 | 26 |
| 15 | 44 | 44 | 44 | 46 | 47 | 47 | 47 | 49 | 51 | 49 | 48 | 41 | 40 | 38 | 40 | 42 | 53 | 52 | 50 | 69 | 66 | 69 | 76 | 82 | 51 | 82 | 38 |
| 16 | 86 | 88 | 87 | 87 | 88 | 90 | 91 | 93 | 94 | 91 | 85 | 78 | 68 | 60 | 53 | 51 | 52 | 55 | 56 | 57 | 57 | 57 | 59 | 61 | 73 | 94 | 51 |
| 17 | 60 | 62 | 64 | 66 | 70 | 73 | 72 | 68 | 64 | 63 | 59 | 52 | 46 | 42 | 40 | 35 | 40 | 47 | 51 | 54 | 51 | 51 | 49 | 49 | 55 | 73 | 35 |
| 18 | 52 | 56 | 57 | 56 | 55 | 55 | 54 | 49 | 43 | 42 | 38 | 36 | 32 | 35 | 33 | 33 | 36 | 41 | 45 | 50 | 52 | 48 | 48 | 51 | 46 | 57 | 32 |
| 19 | 52 | 54 | 55 | 57 | 60 | 62 | 64 | 62 | 53 | 45 | 40 | 34 | 34 | 36 | 36 | 35 | 34 | 35 | 43 | 46 | 45 | 49 | 50 | 53 | 47 | 64 | 34 |
| 20 | 55 | 56 | 58 | 59 | 58 | 59 | 61 | 58 | 55 | 48 | 43 | 42 | 42 | 43 | 46 | 49 | 46 | 48 | 50 | 51 | 52 | 52 | 52 | 52 | 51 | 61 | 42 |
| 21 | 52 | 53 | 54 | 54 | 55 | 56 | 56 | 56 | 54 | 51 | 48 | 45 | 43 | 40 | 43 | 46 | 47 | 49 | 50 | 63 | 70 | 85 | 90 | 92 | 56 | 92 | 40 |
| 22 | 95 | 96 | 95 | 93 | 88 | 77 | 84 | 90 | 95 | 96 | 97 | 97 | 98 | 98 | 98 | 98 | 98 | 99 | 99 | 99 | 99 | 99 | 99 | 99 | 95 | 99 | 77 |
| 23 | 99 | 99 | 99 | 95 | 94 | 95 | 94 | 95 | 95 | 94 | 94 | 94 | 95 | 93 | 93 | 89 | 89 | 88 | 90 | 92 | 93 | 93 | 92 | 91 | 93 | 99 | 88 |
| 24 | 92 | 91 | 90 | 89 | 91 | 94 | 92 | 91 | 92 | 90 | 88 | 86 | 88 | 88 | 85 | 80 | 81 | 82 | 81 | 79 | 79 | 80 | 81 | 81 | 86 | 94 | 79 |
| 25 | 80 | 81 | 81 | 84 | 85 | 83 | 85 | 83 | 75 | 69 | 60 | 53 | 47 | 54 | 55 | 50 | 51 | 55 | 58 | 56 | 59 | 61 | 60 | 60 | 66 | 85 | 47 |
| 26 | 59 | 57 | 56 | 55 | 55 | 56 | 61 | 65 | 61 | 57 | 52 | 50 | 43 | 39 | 38 | 31 | 30 | 35 | 37 | 37 | 40 | 42 | 45 | 47 | 48 | 65 | 30 |
| 27 | 46 | 46 | 44 | 45 | 45 | 44 | 43 | 44 | 42 | 37 | 36 | 34 | 32 | 32 | 32 | 30 | 31 | 32 | 35 | 37 | 38 | 38 | 42 | 43 | 39 | 46 | 30 |
| 28 | 43 | 44 | 46 | 43 | 42 | 42 | 43 | 44 | 40 | 37 | 35 | 33 | 32 | 30 | 27 | 28 | 31 | 34 | 37 | 36 | 37 | 39 | 39 | 40 | 38 | 46 | 27 |
| 29 | 42 | 43 | 44 | 46 | 46 | 47 | 45 | 44 | 40 | 38 | 36 | 34 | 35 | 33 | 32 | 31 | 33 | 38 | 41 | 42 | 46 | 47 | 51 | 52 | 41 | 52 | 31 |
| 30 | 50 | 51 | 52 | 50 | 50 | 50 | 50 | 50 | 47 | 44 | 44 | 42 | 41 | 39 | 39 | 42 | 45 | 51 | 52 | 52 | 52 | 51 | 50 | 50 | 48 | 52 | 39 |
| Avg | 49 | 50 | 51 | 51 | 52 | 52 | 52 | 51 | 49 | 46 | 43 | 40 | 38 | 37 | 37 | 36 | 38 | 40 | 42 | 45 | 45 | 46 | 47 | 49 | 45 | -- | -- |
| Max | 99 | 99 | 99 | 95 | 94 | 95 | 94 | 95 | 95 | 96 | 97 | 97 | 98 | 98 | 98 | 98 | 98 | 99 | 99 | 99 | 99 | 99 | 99 | 99 | -- | 99 | -- |
| Min | 15 | 15 | 15 | 13 | 13 | 12 | 13 | 11 | 9 | 9 | 8 | 6 | 6 | 5 | 3 | 4 | 6 | 7 | 8 | 11 | 13 | 13 | 14 | 14 | -- | -- | 3 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, RH_Percent"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 51 | 60 | 62 | 63 | 65 | 65 | 64 | 63 | 53 | 44 | 40 | 38 | 34 | 31 | 33 | 41 | 40 | 38 | 38 | 43 | 44 | 43 | 42 | 44 | 47 | 65 | 31 |
| 2 | 48 | 49 | 49 | 51 | 49 | 48 | 50 | 51 | 42 | 32 | 27 | 28 | 30 | 32 | 33 | 35 | 39 | 46 | 51 | 53 | 52 | 49 | 49 | 48 | 43 | 53 | 27 |
| 3 | 45 | 43 | 46 | 50 | 50 | 49 | 49 | 50 | 45 | 40 | 31 | 28 | 24 | 20 | 22 | 22 | 29 | 35 | 35 | 37 | 43 | 47 | 49 | 48 | 39 | 50 | 20 |
| 4 | 39 | 34 | 37 | 41 | 48 | 54 | 52 | 50 | 52 | 54 | 59 | 66 | 64 | 72 | 88 | 93 | 89 | 88 | 82 | 91 | 91 | 84 | 89 | 91 | 67 | 93 | 34 |
| 5 | 86 | 74 | 75 | 63 | 66 | 71 | 73 | 71 | 70 | 65 | 52 | 44 | 40 | 38 | 36 | 39 | 43 | 47 | 47 | 44 | 44 | 45 | 46 | 48 | 55 | 86 | 36 |
| 6 | 48 | 46 | 42 | 43 | 46 | 59 | 57 | 57 | 48 | 42 | 35 | 32 | 29 | 26 | 25 | 26 | 31 | 37 | 41 | 46 | 48 | 47 | 47 | 43 | 42 | 59 | 25 |
| 7 | 45 | 45 | 44 | 46 | 44 | 45 | 45 | 41 | 39 | 38 | 34 | 32 | 31 | 29 | 32 | 35 | 41 | 46 | 48 | 47 | 51 | 58 | 68 | 78 | 44 | 78 | 29 |
| 8 | 83 | 92 | 91 | 92 | 92 | 92 | 93 | 94 | 95 | 82 | 71 | 66 | 67 | 66 | 62 | 58 | 61 | 62 | 62 | 58 | 57 | 57 | 55 | 50 | 73 | 95 | 50 |
| 9 | 47 | 53 | 55 | 59 | 61 | 61 | 63 | 60 | 51 | 41 | 44 | 38 | 29 | 25 | 21 | 18 | 17 | 18 | 20 | 21 | 20 | 19 | 19 | 20 | 37 | 63 | 17 |
| 10 | 21 | 21 | 21 | 20 | 20 | 19 | 19 | 19 | 20 | 21 | 20 | 20 | 19 | 18 | 18 | 18 | 18 | 20 | 21 | 21 | 21 | 21 | 21 | 22 | 20 | 22 | 18 |
| 11 | 21 | 21 | 21 | 22 | 22 | 22 | 22 | 22 | 21 | 20 | 20 | 18 | 18 | 19 | 21 | 21 | 23 | 24 | 25 | 26 | 25 | 24 | 25 | 25 | 22 | 26 | 18 |
| 12 | 24 | 23 | 24 | 26 | 28 | 29 | 29 | 29 | 29 | 29 | 29 | 28 | 30 | 35 | 42 | 47 | 54 | 59 | 61 | 65 | 68 | 68 | 68 | 54 | 41 | 68 | 23 |
| 13 | 61 | 57 | 58 | 57 | 57 | 60 | 60 | 52 | 51 | 39 | 38 | 35 | 34 | 34 | 34 | 35 | 38 | 41 | 43 | 47 | 44 | 50 | 55 | 54 | 47 | 61 | 34 |
| 14 | 54 | 58 | 57 | 58 | 38 | 37 | 36 | 35 | 34 | 32 | 29 | 26 | 24 | 22 | 19 | 18 | 19 | 20 | 22 | 24 | 26 | 27 | 27 | 29 | 32 | 58 | 18 |
| 15 | 30 | 32 | 32 | 34 | 36 | 37 | 34 | 29 | 24 | 20 | 18 | 18 | 18 | 17 | 16 | 17 | 18 | 21 | 22 | 22 | 23 | 23 | 24 | 25 | 24 | 37 | 16 |
| 16 | 24 | 24 | 27 | 26 | 26 | 27 | 26 | 24 | 22 | 20 | 20 | 19 | 16 | 15 | 15 | 16 | 19 | 22 | 24 | 23 | 21 | 22 | 23 | 23 | 22 | 27 | 15 |
| 17 | 22 | 20 | 19 | 19 | 19 | 19 | 22 | 21 | 18 | 17 | 18 | 17 | 16 | 16 | 14 | 14 | 14 | 16 | 17 | 18 | 18 | 20 | 21 | 22 | 18 | 22 | 14 |
| 18 | 23 | 24 | 24 | 24 | 25 | 25 | 25 | 26 | 25 | 26 | 23 | 23 | 22 | 21 | 17 | 16 | 18 | 20 | 22 | 22 | 24 | 23 | 24 | 24 | 23 | 26 | 16 |
| 19 | 24 | 26 | 30 | 31 | 31 | 32 | 32 | 32 | 31 | 30 | 27 | 24 | 22 | 21 | 20 | 20 | 26 | 33 | 44 | 55 | 63 | 69 | 71 | 75 | 36 | 75 | 20 |
| 20 | 78 | 80 | 80 | 81 | 71 | 87 | 91 | 92 | 91 | 88 | 82 | 88 | 80 | 81 | 76 | 84 | 93 | 85 | 86 | 92 | 96 | 97 | 97 | 98 | 86 | 98 | 71 |
| 21 | 98 | 98 | 98 | 98 | 98 | 99 | 99 | 99 | 99 | 99 | 99 | 99 | 98 | 91 | 84 | 78 | 77 | 72 | 67 | 70 | 65 | 70 | 68 | 73 | 87 | 99 | 65 |
| 22 | 75 | 74 | 78 | 78 | 80 | 80 | 82 | 80 | 69 | 59 | 46 | 42 | 53 | 51 | 54 | 57 | 64 | 73 | 79 | 83 | 86 | 83 | 79 | 73 | 70 | 86 | 42 |
| 23 | 71 | 75 | 66 | 63 | 52 | 44 | 42 | 39 | 38 | 38 | 36 | 32 | 28 | 25 | 24 | 24 | 26 | 31 | 34 | 34 | 35 | 38 | 38 | 36 | 40 | 75 | 24 |
| 24 | 36 | 36 | 36 | 35 | 36 | 36 | 37 | 35 | 33 | 31 | 29 | 28 | 28 | 27 | 27 | 26 | 28 | 32 | 35 | 34 | 37 | 38 | 38 | 35 | 33 | 38 | 26 |
| 25 | 33 | 29 | 24 | 20 | 22 | 25 | 20 | 25 | 28 | 28 | 26 | 24 | 22 | 20 | 17 | 17 | 18 | 21 | 24 | 27 | 25 | 24 | 24 | 25 | 24 | 33 | 17 |
| 26 | 28 | 30 | 32 | 33 | 35 | 38 | 40 | 37 | 39 | 38 | 39 | 35 | 28 | 26 | 23 | 22 | 21 | 28 | 27 | 27 | 26 | 20 | 17 | 19 | 30 | 40 | 17 |
| 27 | 20 | 20 | 20 | 22 | 22 | 26 | 24 | 24 | 27 | 29 | 27 | 24 | 22 | 21 | 19 | 19 | 20 | 21 | 22 | 24 | 25 | 25 | 28 | 30 | 23 | 30 | 19 |
| 28 | 29 | 28 | 28 | 29 | 31 | 31 | 32 | 33 | 32 | 30 | 29 | 26 | 24 | 19 | 19 | 21 | 24 | 27 | 33 | 36 | 36 | 38 | 36 | 37 | 30 | 38 | 19 |
| 29 | 35 | 36 | 37 | 42 | 40 | 46 | 46 | 43 | 35 | 29 | 28 | 27 | 25 | 24 | 22 | 22 | 23 | 26 | 27 | 27 | 28 | 28 | 29 | 26 | 31 | 46 | 22 |
| 30 | 25 | 26 | 26 | 29 | 33 | 33 | 35 | 33 | 28 | 24 | 22 | 20 | 15 | 16 | 23 | 22 | 26 | 30 | 33 | 29 | 25 | 24 | 26 | 27 | 26 | 35 | 15 |
| 31 | 24 | 24 | 26 | 26 | 26 | 29 | 33 | 34 | 32 | 31 | 29 | 27 | 25 | 23 | 21 | 21 | 24 | 31 | 33 | 32 | 30 | 30 | 32 | 28 | 28 | 34 | 21 |
| Avg | 44 | 44 | 44 | 45 | 44 | 46 | 46 | 45 | 42 | 39 | 36 | 35 | 33 | 32 | 32 | 32 | 35 | 38 | 40 | 41 | 42 | 42 | 43 | 43 | 40 | -- | -- |
| Max | 98 | 98 | 98 | 98 | 98 | 99 | 99 | 99 | 99 | 99 | 99 | 99 | 98 | 91 | 88 | 93 | 93 | 88 | 86 | 92 | 96 | 97 | 97 | 98 | -- | 99 | -- |
| Min | 20 | 20 | 19 | 19 | 19 | 19 | 19 | 19 | 18 | 17 | 18 | 17 | 15 | 15 | 14 | 14 | 14 | 16 | 17 | 18 | 18 | 19 | 17 | 19 | -- | -- | 14 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, Precip_Inches"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Total | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.095 | 0.06 | 0.008 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.163 | 0.095 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.095 | 0.06 | 0.008 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.163 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.095 | 0.06 | 0.008 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | 0.095 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, Precip_Inches"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Total | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.016 | 0.016 | 0.016 | 0 |
| 5 | 0 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0 | 0.071 | 0 | 0 | 0 | 0 | 0.075 | 0.071 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.056 | 0.004 | 0.095 | 0.159 | 0.095 | 0 |
| 22 | 0.084 | 0.11 | 0 | 0.016 | 0.004 | 0 | 0.138 | 0.24 | 0.272 | 0.123 | 0.103 | 0.02 | 0.13 | 0.071 | 0.008 | 0.02 | 0 | 0.04 | 0.067 | 0.012 | 0 | 0 | 0.036 | 0.056 | 1.55 | 0.272 | 0 |
| 23 | 0.028 | 0.111 | 0.068 | 0.088 | 0.044 | 0.08 | 0.064 | 0.138 | 0.068 | 0.052 | 0.142 | 0.228 | 0.075 | 0.04 | 0 | 0 | 0 | 0 | 0 | 0.012 | 0.004 | 0 | 0 | 0 | 1.24 | 0.228 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0.04 | 0.004 | 0 | 0.004 | 0.004 | 0 | 0 | 0 | 0 | 0.008 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.06 | 0.04 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 0.112 | 0.225 | 0.068 | 0.104 | 0.088 | 0.084 | 0.202 | 0.382 | 0.344 | 0.175 | 0.245 | 0.248 | 0.205 | 0.119 | 0.008 | 0.02 | 0.004 | 0.04 | 0.067 | 0.095 | 0.008 | 0.056 | 0.04 | 0.167 | 3.11 | -- | -- |
| Max | 0.084 | 0.111 | 0.068 | 0.088 | 0.044 | 0.08 | 0.138 | 0.24 | 0.272 | 0.123 | 0.142 | 0.228 | 0.13 | 0.071 | 0.008 | 0.02 | 0.004 | 0.04 | 0.067 | 0.071 | 0.004 | 0.056 | 0.036 | 0.095 | -- | 0.272 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, Precip_Inches"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Total | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 | 0.004 | 0.016 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.02 | 0.016 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0.229 | 0.28 | 0.122 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0 | 0.02 | 0 | 0 | 0 | 0.02 | 0.024 | 0.028 | 0.06 | 0.787 | 0.28 | 0 |
| 21 | 0.088 | 0.13 | 0.044 | 0.131 | 0.004 | 0 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.401 | 0.131 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 0.088 | 0.13 | 0.044 | 0.135 | 0.02 | 0.229 | 0.284 | 0.122 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0.004 | 0.02 | 0 | 0 | 0 | 0.02 | 0.024 | 0.028 | 0.06 | 1.21 | -- | -- |
| Max | 0.088 | 0.13 | 0.044 | 0.131 | 0.016 | 0.229 | 0.28 | 0.122 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0.004 | 0.02 | 0 | 0 | 0 | 0.02 | 0.024 | 0.028 | 0.06 | -- | 0.28 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, BP_mmHg"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 654 | 652 |
| 2 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 653 | 652 | 652 | 652 | 652 | 651 | 651 | 652 | 652 | 652 | 652 | 651 | 652 | 654 | 651 |
| 3 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 651 | 651 | 650 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 650 | 650 | 650 | 650 | 652 | 649 |
| 4 | 650 | 650 | 650 | 650 | 650 | 651 | 651 | 652 | 652 | 653 | 653 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 654 | 654 | 654 | 652 | 654 | 650 |
| 5 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 656 | 656 | 657 | 657 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 654 |
| 6 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 657 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 657 | 655 |
| 7 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 652 | 654 | 655 | 652 |
| 8 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 651 | 651 | 650 | 650 | 650 | 650 | 649 | 649 | 649 | 650 | 650 | 649 | 651 | 652 | 649 |
| 9 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 648 | 648 | 647 | 647 | 647 | 647 | 647 | 648 | 648 | 648 | 648 | 648 | 648 | 649 | 647 |
| 10 | 648 | 648 | 648 | 647 | 648 | 648 | 648 | 649 | 650 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 651 | 652 | 652 | 652 | 652 | 652 | 650 | 652 | 647 |
| 11 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 652 |
| 12 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 651 |
| 13 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 652 | 653 | 652 |
| 14 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 653 |
| 15 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 651 |
| 16 | 652 | 652 | 652 | 652 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 652 |
| 17 | 654 | 654 | 654 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 654 | 654 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 655 | 652 |
| 18 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 653 | 654 | 652 |
| 19 | 654 | 654 | 653 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 655 | 653 |
| 20 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 652 | 653 | 651 |
| 21 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 653 | 654 | 652 |
| 22 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 655 | 653 |
| 23 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 654 | 652 |
| 24 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 654 | 654 | 654 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 654 | 654 | 653 | 654 | 652 |
| 25 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 656 | 656 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 654 |
| 26 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 657 | 657 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 654 | 654 | 655 | 657 | 654 |
| 27 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 654 | 654 | 653 | 653 | 652 | 651 | 651 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 649 | 649 | 652 | 654 | 649 |
| 28 | 649 | 649 | 649 | 649 | 649 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 650 | 650 | 649 | 650 | 649 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 650 | 651 | 649 |
| 29 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 650 | 649 | 649 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 649 |
| 30 | 651 | 651 | 650 | 650 | 650 | 650 | 651 | 651 | 652 | 652 | 652 | 652 | 652 | 651 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 652 | 653 | 650 |
| 31 | 653 | 654 | 654 | 653 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 655 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 655 | 653 |
| Avg | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 654 | 654 | 653 | 653 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 652 | 653 | -- | -- |
| Max | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 657 | 656 | 656 | 656 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | -- | 657 | -- |
| Min | 648 | 648 | 648 | 647 | 648 | 648 | 648 | 649 | 649 | 649 | 649 | 649 | 648 | 648 | 647 | 647 | 647 | 647 | 647 | 648 | 648 | 648 | 648 | 648 | -- | -- | 647 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, BP_mmHg"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 654 | 654 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 654 |
| 2 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 654 | 654 | 653 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 653 | 655 | 651 |
| 3 | 652 | 651 | 651 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 651 | 650 | 650 | 649 | 649 | 649 | 648 | 648 | 649 | 649 | 649 | 649 | 649 | 649 | 650 | 652 | 648 |
| 4 | 648 | 648 | 648 | 648 | 648 | 648 | 649 | 649 | 650 | 650 | 649 | 649 | 648 | 648 | 647 | 647 | 647 | 647 | 647 | 647 | 648 | 648 | 649 | 649 | 648 | 650 | 647 |
| 5 | 649 | 650 | 650 | 650 | 650 | 651 | 651 | 652 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 655 | 655 | 655 | 656 | 656 | 653 | 656 | 649 |
| 6 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 658 | 658 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 658 | 658 | 657 | 658 | 656 |
| 7 | 657 | 657 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 658 | 658 | 657 | 656 | 656 | 656 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 658 | 655 |
| 8 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 655 | 655 | 654 | 654 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 656 | 653 |
| 9 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 654 |
| 10 | 655 | 656 | 655 | 655 | 655 | 656 | 656 | 656 | 657 | 657 | 657 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 657 | 655 |
| 11 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 655 |
| 12 | 657 | 657 | 657 | 657 | 657 | 657 | 658 | 658 | 659 | 659 | 659 | 658 | 658 | 658 | 657 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 658 | 658 | 659 | 657 |
| 13 | 658 | 658 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 656 | 655 | 655 | 654 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 656 | 658 | 654 |
| 14 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 653 | 652 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 650 | 650 | 653 | 654 | 650 |
| 15 | 650 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 649 | 648 | 647 | 646 | 646 | 645 | 645 | 645 | 645 | 646 | 646 | 646 | 647 | 647 | 647 | 650 | 645 |
| 16 | 647 | 647 | 647 | 647 | 647 | 647 | 648 | 648 | 648 | 649 | 649 | 649 | 649 | 648 | 648 | 648 | 648 | 648 | 649 | 649 | 649 | 650 | 650 | 650 | 648 | 650 | 647 |
| 17 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 653 | 654 | 654 | 655 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 653 | 655 | 651 |
| 18 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 656 | 656 | 655 | 655 | 654 | 654 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 656 | 653 |
| 19 | 653 | 653 | 653 | 653 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 652 | 652 | 651 | 651 | 651 | 651 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 652 | 653 | 650 |
| 20 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 651 | 650 | 650 | 650 | 649 | 649 | 649 | 649 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 651 | 649 |
| 21 | 650 | 650 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 652 | 652 | 652 | 651 | 651 | 650 | 650 | 650 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 650 |
| 22 | 650 | 650 | 649 | 649 | 648 | 648 | 649 | 649 | 649 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 651 | 650 | 651 | 648 |
| 23 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 653 | 652 | 652 | 653 | 652 | 652 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 651 |
| 24 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 654 | 655 | 653 |
| 25 | 654 | 654 | 655 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 655 | 657 | 654 |
| 26 | 657 | 657 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 658 | 658 | 657 | 657 | 657 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 658 | 656 |
| 27 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 656 | 653 |
| 28 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 655 | 654 | 654 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 654 | 655 | 653 |
| 29 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 656 | 656 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 655 |
| 30 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 657 | 655 |
| Avg | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 653 | -- | -- |
| Max | 658 | 658 | 657 | 657 | 657 | 657 | 658 | 658 | 659 | 659 | 659 | 658 | 658 | 658 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 658 | 658 | -- | 659 | -- |
| Min | 647 | 647 | 647 | 647 | 647 | 647 | 648 | 648 | 648 | 649 | 649 | 648 | 647 | 646 | 646 | 645 | 645 | 645 | 645 | 646 | 646 | 646 | 647 | 647 | -- | -- | 645 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: Table100, BP_mmHg"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 656 | 656 | 656 | 656 | 655 | 656 | 656 | 657 | 657 | 657 | 657 | 657 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 655 |
| 2 | 656 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 654 | 654 | 653 | 652 | 652 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 653 | 656 | 651 |
| 3 | 650 | 650 | 650 | 649 | 649 | 649 | 649 | 649 | 649 | 650 | 649 | 649 | 648 | 648 | 647 | 647 | 647 | 647 | 647 | 646 | 647 | 647 | 647 | 647 | 648 | 650 | 646 |
| 4 | 647 | 647 | 646 | 646 | 646 | 647 | 647 | 647 | 648 | 648 | 648 | 648 | 648 | 647 | 648 | 648 | 648 | 648 | 648 | 649 | 649 | 649 | 649 | 649 | 648 | 649 | 646 |
| 5 | 649 | 649 | 649 | 648 | 648 | 649 | 649 | 649 | 650 | 650 | 650 | 650 | 650 | 649 | 649 | 650 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 652 | 650 | 652 | 648 |
| 6 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 653 | 654 | 654 | 655 | 654 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 653 | 652 | 653 | 655 | 652 |
| 7 | 652 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 651 | 651 | 650 | 650 | 650 | 650 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 650 |
| 8 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 653 | 653 | 653 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 652 | 652 | 652 | 652 | 652 | 652 | 653 | 651 |
| 9 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 654 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 657 | 655 | 657 | 652 |
| 10 | 657 | 657 | 657 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 656 | 656 | 655 | 654 | 655 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 655 | 656 | 657 | 654 |
| 11 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 657 | 657 | 657 | 657 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 656 | 657 | 655 |
| 12 | 657 | 657 | 657 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 656 | 656 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 657 | 654 |
| 13 | 654 | 654 | 654 | 654 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 655 | 655 | 655 | 654 | 655 | 653 |
| 14 | 655 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 657 | 657 | 658 | 658 | 658 | 657 | 657 | 657 | 657 | 657 | 658 | 658 | 658 | 658 | 659 | 658 | 657 | 659 | 655 |
| 15 | 658 | 659 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 658 | 659 | 657 |
| 16 | 657 | 657 | 657 | 657 | 657 | 656 | 657 | 657 | 657 | 658 | 658 | 658 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 658 | 658 | 657 | 658 | 656 |
| 17 | 658 | 657 | 658 | 658 | 657 | 657 | 658 | 658 | 658 | 659 | 659 | 658 | 657 | 657 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 659 | 656 |
| 18 | 655 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 655 | 654 | 654 | 653 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 650 | 650 | 650 | 649 | 653 | 655 | 649 |
| 19 | 649 | 649 | 649 | 648 | 648 | 648 | 648 | 648 | 648 | 648 | 648 | 647 | 647 | 646 | 646 | 645 | 645 | 645 | 646 | 646 | 646 | 646 | 646 | 646 | 647 | 649 | 645 |
| 20 | 645 | 645 | 645 | 644 | 644 | 644 | 645 | 645 | 645 | 645 | 645 | 645 | 645 | 644 | 644 | 645 | 645 | 645 | 645 | 646 | 646 | 646 | 646 | 646 | 645 | 646 | 644 |
| 21 | 646 | 646 | 646 | 646 | 646 | 646 | 647 | 647 | 648 | 648 | 648 | 648 | 648 | 648 | 648 | 649 | 649 | 649 | 650 | 650 | 651 | 651 | 651 | 652 | 648 | 652 | 646 |
| 22 | 652 | 652 | 653 | 653 | 653 | 653 | 654 | 654 | 655 | 656 | 656 | 656 | 656 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 655 | 657 | 652 |
| 23 | 657 | 657 | 657 | 658 | 657 | 658 | 658 | 658 | 659 | 659 | 659 | 659 | 659 | 659 | 659 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 659 | 657 |
| 24 | 657 | 657 | 657 | 657 | 657 | 656 | 657 | 657 | 657 | 657 | 657 | 657 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 655 |
| 25 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 658 | 658 | 658 | 658 | 657 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 658 | 656 |
| 26 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 656 | 656 | 656 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 656 | 657 | 655 |
| 27 | 656 | 657 | 657 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 658 | 657 | 656 | 656 | 656 | 655 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 656 | 658 | 655 |
| 28 | 655 | 655 | 655 | 655 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 654 | 653 | 652 | 652 | 652 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 653 | 655 | 651 |
| 29 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 651 | 652 | 652 | 653 | 652 | 652 | 652 | 652 | 652 | 653 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 652 | 655 | 651 |
| 30 | 655 | 655 | 655 | 656 | 656 | 656 | 656 | 656 | 657 | 658 | 658 | 658 | 657 | 656 | 656 | 656 | 656 | 656 | 657 | 657 | 657 | 657 | 658 | 657 | 657 | 658 | 655 |
| 31 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 657 | 656 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 655 | 656 | 657 | 655 |
| Avg | 654 | 654 | 654 | 654 | 653 | 653 | 654 | 654 | 654 | 655 | 655 | 655 | 654 | 653 | 653 | 653 | 653 | 653 | 653 | 654 | 654 | 654 | 654 | 654 | 654 | -- | -- |
| Max | 658 | 659 | 658 | 658 | 658 | 658 | 658 | 658 | 659 | 659 | 659 | 659 | 659 | 659 | 659 | 658 | 658 | 658 | 658 | 658 | 658 | 658 | 659 | 658 | -- | 659 | -- |
| Min | 645 | 645 | 645 | 644 | 644 | 644 | 645 | 645 | 645 | 645 | 645 | 645 | 645 | 644 | 644 | 645 | 645 | 645 | 645 | 646 | 646 | 646 | 646 | 646 | -- | -- | 644 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, WS_ms_10m"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.8 | 0.8 | 0.8 | 0.9 | 1.6 | 2.0 | 1.1 | 0.7 | 0.7 | 0.9 | 1.5 | 2.6 | 3.6 | 4.0 | 3.4 | 3.7 | 3.4 | 3.1 | 1.8 | 0.7 | 1.4 | 2.1 | 1.0 | 0.9 | 1.8 | 4.0 | 0.7 |
| 2 | 0.5 | 2.2 | 1.0 | 0.6 | 0.5 | 1.5 | 1.8 | 1.8 | 0.9 | 1.2 | 2.6 | 2.6 | 3.0 | 3.5 | 3.5 | 3.9 | 3.9 | 3.3 | 2.2 | 0.7 | 0.4 | 1.2 | 1.8 | 2.1 | 1.9 | 3.9 | 0.4 |
| 3 | 1.6 | 1.0 | 1.1 | 1.0 | 1.4 | 1.3 | 1.0 | 1.4 | 1.9 | 2.3 | 3.1 | 4.1 | 4.8 | 4.8 | 4.6 | 5.4 | 5.3 | 4.2 | 2.2 | 0.7 | 0.3 | 0.4 | 0.7 | 0.7 | 2.3 | 5.4 | 0.3 |
| 4 | 1.0 | 1.0 | 0.8 | 0.9 | 0.8 | 1.0 | 2.5 | 2.4 | 1.3 | 1.7 | 2.1 | 2.7 | 4.4 | 4.4 | 4.9 | 4.5 | 5.1 | 4.6 | 3.0 | 0.8 | 0.2 | 2.2 | 7.3 | 10.6 | 2.9 | 10.6 | 0.2 |
| 5 | 9.7 | 10.3 | 11.0 | 11.2 | 11.3 | 10.8 | 9.6 | 8.2 | 7.7 | 9.7 | 8.0 | 7.7 | 4.8 | 2.9 | 3.2 | 4.4 | 3.4 | 2.4 | 2.4 | 3.5 | 6.2 | 2.2 | 3.7 | 5.2 | 6.6 | 11.3 | 2.2 |
| 6 | 4.4 | 4.0 | 6.9 | 6.4 | 2.8 | 2.7 | 3.1 | 9.5 | 11.3 | 6.7 | 6.9 | 4.6 | 4.1 | 2.2 | 2.1 | 1.7 | 1.8 | 3.0 | 3.9 | 3.6 | 3.9 | 5.0 | 3.6 | 5.3 | 4.6 | 11.3 | 1.7 |
| 7 | 4.3 | 1.5 | 3.7 | 5.5 | 3.0 | 2.9 | 3.4 | 2.6 | 3.6 | 6.4 | 6.0 | 4.4 | 3.1 | 3.1 | 2.7 | 3.2 | 3.7 | 2.1 | 1.0 | 1.2 | 3.5 | 2.3 | 1.8 | 1.1 | 3.2 | 6.4 | 1.0 |
| 8 | 0.9 | 0.5 | 0.6 | 3.9 | 3.3 | 0.5 | 1.0 | 3.1 | 2.9 | 2.5 | 4.0 | 3.9 | 5.5 | 5.5 | 5.5 | 5.4 | 5.3 | 4.0 | 1.4 | 0.5 | 0.6 | 0.9 | 1.1 | 1.2 | 2.7 | 5.5 | 0.5 |
| 9 | 1.1 | 1.2 | 1.5 | 1.7 | 3.3 | 1.5 | 0.8 | 0.8 | 3.8 | 4.9 | 6.4 | 7.6 | 7.5 | 8.6 | 8.4 | 7.9 | 7.1 | 6.6 | 4.9 | 4.5 | 3.7 | 2.9 | 2.8 | 2.7 | 4.3 | 8.6 | 0.8 |
| 10 | 3.3 | 3.3 | 4.2 | 4.6 | 6.4 | 4.7 | 6.1 | 3.7 | 1.1 | 3.3 | 2.5 | 2.3 | 3.0 | 3.8 | 2.8 | 2.6 | 1.4 | 1.7 | 0.9 | 1.4 | 2.0 | 2.2 | 3.1 | 2.9 | 3.1 | 6.4 | 0.9 |
| 11 | 0.9 | 2.4 | 0.8 | 1.9 | 4.9 | 4.9 | 2.6 | 3.6 | 1.6 | 1.3 | 1.7 | 2.2 | 2.8 | 3.2 | 2.5 | 3.1 | 2.7 | 2.7 | 1.5 | 0.9 | 1.0 | 0.7 | 0.3 | 0.6 | 2.1 | 4.9 | 0.3 |
| 12 | 0.7 | 0.9 | 0.8 | 1.1 | 2.0 | 1.9 | 0.9 | 2.0 | 4.1 | 4.3 | 4.6 | 4.5 | 4.5 | 3.1 | 3.9 | 3.7 | 3.6 | 2.8 | 1.4 | 0.6 | 1.5 | 2.3 | 0.8 | 1.8 | 2.4 | 4.6 | 0.6 |
| 13 | 1.2 | 0.8 | 0.5 | 0.5 | 0.7 | 1.5 | 1.2 | 0.7 | 2.4 | 4.4 | 5.7 | 6.0 | 5.4 | 5.0 | 4.9 | 5.3 | 4.9 | 3.8 | 1.6 | 0.9 | 1.0 | 0.6 | 0.4 | 0.3 | 2.5 | 6.0 | 0.3 |
| 14 | 0.6 | 0.8 | 0.7 | 1.1 | 1.8 | 1.1 | 1.8 | 1.1 | 1.2 | 1.2 | 1.9 | 2.8 | 2.9 | 3.9 | 3.5 | 3.9 | 4.3 | 3.3 | 1.0 | 1.6 | 0.7 | 0.7 | 0.8 | 0.8 | 1.8 | 4.3 | 0.6 |
| 15 | 4.4 | 3.3 | 3.0 | 2.0 | 3.4 | 2.6 | 2.4 | 1.6 | 1.1 | 1.1 | 1.7 | 3.3 | 4.2 | 3.9 | 4.1 | 4.3 | 4.2 | 3.9 | 1.6 | 1.1 | 0.4 | 0.6 | 0.4 | 0.6 | 2.5 | 4.4 | 0.4 |
| 16 | 1.0 | 2.1 | 1.6 | 3.2 | 1.8 | 0.8 | 2.7 | 3.3 | 2.5 | 2.2 | 3.5 | 2.0 | 2.7 | 2.9 | 2.5 | 4.0 | 3.8 | 3.8 | 0.8 | 0.6 | 0.3 | 0.6 | 0.5 | 0.7 | 2.1 | 4.0 | 0.3 |
| 17 | 1.1 | 1.3 | 3.0 | 4.1 | 4.5 | 3.9 | 2.5 | 2.3 | 2.2 | 1.1 | 1.7 | 2.1 | 2.9 | 3.7 | 3.1 | 3.6 | 3.3 | 3.2 | 1.3 | 0.4 | 0.1 | 0.5 | 0.4 | 0.2 | 2.2 | 4.5 | 0.1 |
| 18 | 0.9 | 0.6 | 0.2 | 1.4 | 1.0 | 0.8 | 1.0 | 1.4 | 2.1 | 2.0 | 1.7 | 2.0 | 3.3 | 2.9 | 3.8 | 4.1 | 4.0 | 2.6 | 1.1 | 0.6 | 1.6 | 1.1 | 0.9 | 0.9 | 1.8 | 4.1 | 0.2 |
| 19 | 1.0 | 1.4 | 1.1 | 1.7 | 2.4 | 1.2 | 1.4 | 2.5 | 2.4 | 2.5 | 2.4 | 2.5 | 1.8 | 2.2 | 3.1 | 2.9 | 3.5 | 2.9 | 1.2 | 0.6 | 0.7 | 0.7 | 0.4 | 0.6 | 1.8 | 3.5 | 0.4 |
| 20 | 1.6 | 0.5 | 1.3 | 3.0 | 1.9 | 0.7 | 0.8 | 0.8 | 1.6 | 1.0 | 1.7 | 2.1 | 2.8 | 3.4 | 3.5 | 3.4 | 3.4 | 2.8 | 1.8 | 0.9 | 0.5 | 0.6 | 0.6 | 0.6 | 1.7 | 3.5 | 0.5 |
| 21 | 0.7 | 0.6 | 0.9 | 0.7 | 0.5 | 0.7 | 0.6 | 2.3 | 3.6 | 1.5 | 1.7 | 1.6 | 2.3 | 3.7 | 3.8 | 3.6 | 3.7 | 2.3 | 1.0 | 1.2 | 2.3 | 1.0 | 0.5 | 0.9 | 1.7 | 3.8 | 0.5 |
| 22 | 1.2 | 2.3 | 2.0 | 2.2 | 6.3 | 6.3 | 3.9 | 3.2 | 3.0 | 5.4 | 4.4 | 4.9 | 5.3 | 3.5 | 2.9 | 2.7 | 2.5 | 3.4 | 4.2 | 3.5 | 4.8 | 4.3 | 5.2 | 5.1 | 3.9 | 6.3 | 1.2 |
| 23 | 4.8 | 4.9 | 4.0 | 3.0 | 4.7 | 5.9 | 6.6 | 6.7 | 6.9 | 7.0 | 5.4 | 6.5 | 3.9 | 2.8 | 2.7 | 2.8 | 2.1 | 1.8 | 3.6 | 3.8 | 3.2 | 1.3 | 2.0 | 5.0 | 4.2 | 7.0 | 1.3 |
| 24 | 3.7 | 2.5 | 3.2 | 3.4 | 2.2 | 2.2 | 2.3 | 2.4 | 3.3 | 6.9 | 5.5 | 3.8 | 2.7 | 3.0 | 4.3 | 4.3 | 3.6 | 1.8 | 0.3 | 0.9 | 0.6 | 0.5 | 0.7 | 1.0 | 2.7 | 6.9 | 0.3 |
| 25 | 1.4 | 0.7 | 0.3 | 0.3 | 0.4 | 0.3 | 1.5 | 0.5 | 0.8 | 1.1 | 1.4 | 2.7 | 3.3 | 3.5 | 3.8 | 4.2 | 3.8 | 2.4 | 1.4 | 0.2 | 0.7 | 0.9 | 1.5 | 0.9 | 1.6 | 4.2 | 0.2 |
| 26 | 2.1 | 2.0 | 2.3 | 1.3 | 1.3 | 1.7 | 5.7 | 7.4 | 8.6 | 8.9 | 7.9 | 7.3 | 4.4 | 2.7 | 2.4 | 1.6 | 2.2 | 2.1 | 0.5 | 1.2 | 1.1 | 3.3 | 4.1 | 3.9 | 3.6 | 8.9 | 0.5 |
| 27 | 3.2 | 4.6 | 4.5 | 4.3 | 4.2 | 4.8 | 3.3 | 3.2 | 4.8 | 5.5 | 5.8 | 3.8 | 3.8 | 3.7 | 4.8 | 5.1 | 4.4 | 2.8 | 0.7 | 0.8 | 0.4 | 1.3 | 1.2 | 1.1 | 3.4 | 5.8 | 0.4 |
| 28 | 1.0 | 1.3 | 1.0 | 0.9 | 1.2 | 1.8 | 2.9 | 2.4 | 3.8 | 5.1 | 6.7 | 6.7 | 6.0 | 6.3 | 6.2 | 4.9 | 4.1 | 4.8 | 5.3 | 4.7 | 3.3 | 3.4 | 4.5 | 4.8 | 3.9 | 6.7 | 0.9 |
| 29 | 3.3 | 1.5 | 1.8 | 0.7 | 0.9 | 0.9 | 1.0 | 0.8 | 0.9 | 4.2 | 5.0 | 5.2 | 5.6 | 5.8 | 5.9 | 5.8 | 5.9 | 4.4 | 1.3 | 1.4 | 1.1 | 0.5 | 0.5 | 1.3 | 2.7 | 5.9 | 0.5 |
| 30 | 1.1 | 1.8 | 0.7 | 0.5 | 1.0 | 0.5 | 1.0 | 1.1 | 0.8 | 1.8 | 3.7 | 3.6 | 3.9 | 3.9 | 4.4 | 3.9 | 3.8 | 2.6 | 1.5 | 0.9 | 0.7 | 1.1 | 0.9 | 0.9 | 1.9 | 4.4 | 0.5 |
| 31 | 1.1 | 0.5 | 0.7 | 1.6 | 4.7 | 5.9 | 5.2 | 4.7 | 1.3 | 0.9 | 1.7 | 2.2 | 3.1 | 2.8 | 3.1 | 3.6 | 4.0 | 2.3 | 1.0 | 0.3 | 0.3 | 0.4 | 0.1 | 0.6 | 2.2 | 5.9 | 0.1 |
| Avg | 2.1 | 2.0 | 2.1 | 2.4 | 2.8 | 2.6 | 2.6 | 2.8 | 3.0 | 3.5 | 3.8 | 3.9 | 3.9 | 3.8 | 3.9 | 4.0 | 3.8 | 3.1 | 1.9 | 1.4 | 1.6 | 1.5 | 1.7 | 2.1 | 2.8 | -- | -- |
| Max | 9.7 | 10.3 | 11.0 | 11.2 | 11.3 | 10.8 | 9.6 | 9.5 | 11.3 | 9.7 | 8.0 | 7.7 | 7.5 | 8.6 | 8.4 | 7.9 | 7.1 | 6.6 | 5.3 | 4.7 | 6.2 | 5.0 | 7.3 | 10.6 | -- | 11.3 | -- |
| Min | 0.5 | 0.5 | 0.2 | 0.3 | 0.4 | 0.3 | 0.6 | 0.5 | 0.7 | 0.9 | 1.4 | 1.6 | 1.8 | 2.2 | 2.1 | 1.6 | 1.4 | 1.7 | 0.3 | 0.2 | 0.1 | 0.4 | 0.1 | 0.2 | -- | -- | 0.1 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, WS_ms_10m"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.3 | 0.6 | 0.2 | 0.8 | 1.0 | 0.6 | 1.8 | 3.9 | 2.3 | 3.2 | 2.2 | 3.3 | 2.3 | 3.1 | 2.7 | 4.0 | 3.2 | 2.0 | 1.1 | 1.1 | 1.8 | 1.1 | 2.7 | 1.8 | 2.0 | 4.0 | 0.2 |
| 2 | 4.4 | 6.7 | 4.6 | 4.2 | 4.8 | 6.8 | 6.3 | 5.6 | 6.6 | 7.6 | 8.3 | 8.1 | 6.8 | 4.7 | 3.4 | 3.0 | 2.3 | 3.9 | 2.2 | 2.6 | 4.3 | 2.0 | 2.9 | 3.7 | 4.8 | 8.3 | 2.0 |
| 3 | 4.5 | 2.5 | 3.7 | 5.5 | 3.3 | 4.3 | 4.1 | 3.3 | 2.6 | 2.9 | 3.0 | 3.4 | 4.2 | 5.1 | 5.1 | 4.3 | 4.0 | 2.7 | 1.1 | 0.7 | 1.4 | 0.8 | 1.3 | 1.6 | 3.1 | 5.5 | 0.7 |
| 4 | 2.0 | 2.7 | 1.6 | 4.1 | 4.9 | 5.5 | 3.5 | 1.7 | 2.0 | 3.2 | 3.9 | 4.6 | 5.0 | 4.9 | 4.5 | 4.3 | 3.2 | 2.8 | 0.7 | 0.8 | 0.8 | 0.5 | 4.3 | 2.5 | 3.1 | 5.5 | 0.5 |
| 5 | 1.1 | 1.3 | 1.2 | 1.0 | 1.4 | 0.5 | 0.8 | 0.8 | 1.0 | 1.4 | 1.9 | 2.4 | 3.4 | 3.5 | 3.6 | 4.4 | 3.9 | 2.1 | 0.5 | 0.5 | 2.2 | 2.9 | 3.3 | 1.8 | 1.9 | 4.4 | 0.5 |
| 6 | 6.1 | 6.1 | 2.5 | 2.0 | 1.4 | 1.6 | 2.4 | 2.8 | 2.8 | 2.3 | 4.1 | 5.7 | 4.6 | 2.5 | 1.9 | 2.0 | 3.3 | 3.4 | 4.0 | 5.7 | 3.8 | 3.3 | 3.9 | 6.4 | 3.5 | 6.4 | 1.4 |
| 7 | 8.8 | 4.0 | 5.2 | 9.4 | 7.4 | 7.6 | 6.5 | 5.5 | 4.8 | 4.6 | 4.6 | 5.9 | 6.1 | 3.5 | 3.9 | 2.6 | 3.5 | 3.6 | 3.8 | 4.7 | 4.5 | 4.6 | 3.1 | 2.5 | 5.0 | 9.4 | 2.5 |
| 8 | 3.0 | 3.1 | 4.1 | 6.0 | 2.9 | 2.6 | 2.2 | 3.2 | 2.9 | 2.8 | 2.7 | 2.3 | 1.5 | 2.9 | 3.2 | 3.2 | 3.8 | 2.2 | 0.9 | 0.4 | 0.7 | 0.4 | 0.7 | 0.4 | 2.4 | 6.0 | 0.4 |
| 9 | 0.6 | 0.6 | 1.5 | 1.5 | 4.2 | 2.6 | 1.7 | 1.3 | 1.6 | 1.1 | 1.6 | 1.3 | 2.6 | 3.4 | 2.8 | 2.7 | 3.4 | 2.0 | 0.6 | 1.4 | 1.8 | 1.1 | 0.9 | 0.7 | 1.8 | 4.2 | 0.6 |
| 10 | 0.9 | 1.9 | 3.7 | 2.8 | 1.4 | 1.7 | 1.6 | 4.2 | 3.2 | 1.3 | 1.8 | 3.0 | 3.9 | 2.6 | 2.9 | 1.5 | 2.4 | 4.1 | 4.7 | 4.0 | 1.8 | 1.9 | 1.3 | 0.9 | 2.5 | 4.7 | 0.9 |
| 11 | 1.6 | 1.4 | 1.9 | 1.8 | 1.3 | 1.6 | 3.1 | 2.1 | 2.2 | 3.7 | 6.2 | 5.5 | 5.7 | 3.0 | 2.7 | 3.4 | 3.2 | 2.3 | 3.0 | 2.4 | 1.8 | 4.5 | 4.2 | 4.3 | 3.0 | 6.2 | 1.3 |
| 12 | 5.4 | 3.5 | 3.1 | 3.2 | 2.8 | 3.7 | 3.5 | 4.2 | 4.7 | 6.7 | 6.4 | 4.2 | 3.3 | 4.6 | 4.2 | 4.4 | 5.2 | 5.2 | 4.0 | 5.6 | 2.9 | 4.0 | 3.1 | 5.9 | 4.3 | 6.7 | 2.8 |
| 13 | 6.7 | 8.9 | 10.6 | 10.8 | 12.2 | 10.8 | 11.4 | 10.1 | 11.3 | 8.3 | 9.4 | 4.0 | 2.9 | 2.8 | 2.1 | 4.1 | 5.1 | 4.6 | 4.8 | 6.6 | 6.4 | 6.3 | 4.7 | 4.8 | 7.1 | 12.2 | 2.1 |
| 14 | 2.1 | 2.4 | 4.8 | 3.8 | 5.0 | 4.7 | 4.2 | 6.6 | 6.1 | 5.5 | 2.5 | 2.8 | 2.8 | 2.2 | 2.1 | 4.0 | 3.1 | 2.0 | 0.6 | 1.8 | 1.9 | 1.9 | 2.5 | 2.3 | 3.2 | 6.6 | 0.6 |
| 15 | 1.5 | 0.8 | 2.5 | 3.5 | 2.6 | 1.3 | 1.6 | 1.8 | 1.1 | 3.3 | 3.6 | 5.6 | 6.5 | 6.6 | 6.4 | 6.7 | 4.4 | 5.2 | 5.9 | 2.7 | 2.9 | 3.4 | 3.7 | 2.6 | 3.6 | 6.7 | 0.8 |
| 16 | 2.3 | 1.8 | 1.0 | 1.9 | 2.6 | 2.4 | 3.0 | 2.5 | 2.3 | 2.7 | 3.8 | 3.4 | 4.4 | 4.7 | 4.7 | 4.7 | 4.8 | 2.9 | 1.4 | 0.9 | 1.2 | 0.5 | 0.9 | 0.4 | 2.5 | 4.8 | 0.4 |
| 17 | 0.4 | 0.8 | 0.7 | 0.9 | 1.1 | 0.9 | 0.4 | 0.4 | 0.5 | 2.0 | 3.6 | 3.4 | 2.4 | 2.3 | 2.3 | 1.9 | 1.7 | 1.7 | 0.9 | 2.0 | 3.0 | 2.1 | 1.1 | 0.7 | 1.6 | 3.6 | 0.4 |
| 18 | 1.0 | 1.8 | 2.8 | 3.0 | 2.9 | 2.2 | 1.6 | 2.0 | 1.7 | 1.4 | 2.2 | 2.0 | 1.7 | 1.8 | 3.7 | 3.0 | 2.9 | 1.8 | 0.9 | 1.4 | 2.4 | 0.9 | 0.5 | 0.8 | 1.9 | 3.7 | 0.5 |
| 19 | 1.2 | 0.4 | 0.3 | 0.5 | 0.6 | 2.3 | 1.3 | 3.7 | 4.4 | 1.8 | 1.4 | 3.0 | 4.0 | 5.0 | 4.2 | 3.5 | 3.1 | 2.0 | 0.4 | 0.8 | 0.6 | 0.5 | 0.3 | 1.5 | 2.0 | 5.0 | 0.3 |
| 20 | 1.8 | 1.3 | 0.6 | 0.8 | 0.3 | 0.8 | 1.6 | 1.3 | 0.6 | 1.0 | 0.9 | 2.3 | 3.8 | 4.3 | 3.6 | 3.0 | 2.7 | 2.1 | 1.0 | 0.0 | 0.5 | 0.6 | 0.2 | 0.7 | 1.5 | 4.3 | 0.0 |
| 21 | 0.3 | 0.6 | 0.7 | 0.8 | 0.6 | 0.6 | 0.4 | 0.8 | 1.2 | 1.2 | 3.5 | 3.5 | 3.1 | 3.0 | 3.5 | 2.6 | 1.4 | 1.4 | 1.4 | 1.0 | 1.2 | 1.9 | 4.9 | 3.3 | 1.8 | 4.9 | 0.3 |
| 22 | 4.8 | 4.4 | 4.8 | 6.9 | 8.9 | 5.2 | 1.9 | 2.1 | 2.0 | 2.8 | 2.7 | 1.8 | 3.0 | 2.7 | 3.3 | 1.3 | 1.4 | 1.7 | 1.7 | 1.2 | 1.0 | 1.2 | 2.6 | 2.1 | 3.0 | 8.9 | 1.0 |
| 23 | 1.6 | 0.8 | 1.2 | 2.3 | 1.8 | 2.4 | 3.1 | 3.7 | 2.1 | 6.8 | 9.4 | 8.8 | 7.8 | 7.9 | 6.8 | 8.4 | 6.3 | 8.1 | 7.8 | 6.4 | 5.5 | 4.1 | 3.2 | 3.0 | 5.0 | 9.4 | 0.8 |
| 24 | 3.1 | 4.9 | 4.4 | 3.7 | 3.8 | 7.4 | 6.8 | 6.7 | 6.2 | 5.4 | 5.8 | 5.4 | 5.3 | 4.5 | 3.6 | 2.5 | 3.8 | 4.6 | 4.5 | 3.7 | 3.6 | 5.6 | 6.9 | 6.9 | 5.0 | 7.4 | 2.5 |
| 25 | 5.3 | 1.9 | 5.2 | 5.0 | 1.8 | 1.1 | 1.4 | 0.8 | 0.5 | 0.7 | 0.9 | 1.2 | 2.5 | 2.9 | 2.8 | 2.3 | 2.5 | 1.4 | 0.8 | 2.6 | 2.3 | 2.5 | 6.0 | 8.3 | 2.6 | 8.3 | 0.5 |
| 26 | 5.3 | 4.2 | 7.4 | 5.0 | 4.3 | 3.5 | 7.5 | 10.7 | 10.3 | 5.4 | 4.1 | 4.6 | 4.3 | 4.0 | 5.2 | 4.3 | 4.1 | 4.2 | 3.8 | 2.9 | 4.0 | 4.9 | 3.7 | 3.9 | 5.1 | 10.7 | 2.9 |
| 27 | 3.7 | 8.9 | 8.9 | 6.7 | 5.6 | 4.2 | 7.0 | 6.9 | 9.6 | 9.1 | 5.9 | 4.9 | 4.9 | 4.3 | 7.4 | 9.1 | 6.4 | 7.8 | 8.4 | 6.7 | 5.3 | 4.3 | 7.2 | 7.8 | 6.7 | 9.6 | 3.7 |
| 28 | 5.7 | 4.2 | 8.5 | 8.5 | 6.4 | 4.8 | 7.5 | 5.7 | 3.8 | 4.5 | 3.7 | 3.0 | 4.5 | 3.4 | 4.1 | 3.9 | 3.1 | 3.4 | 5.9 | 5.7 | 4.0 | 3.3 | 3.2 | 2.8 | 4.7 | 8.5 | 2.8 |
| 29 | 2.4 | 3.9 | 4.6 | 5.1 | 5.6 | 5.0 | 4.7 | 4.0 | 2.6 | 4.2 | 3.9 | 3.0 | 2.9 | 3.1 | 2.1 | 2.1 | 3.4 | 0.7 | 0.7 | 1.0 | 1.3 | 1.1 | 0.9 | 0.5 | 2.9 | 5.6 | 0.5 |
| 30 | 0.8 | 2.6 | 2.0 | 0.8 | 0.8 | 0.6 | 1.3 | 1.3 | 1.1 | 2.3 | 2.1 | 2.3 | 2.3 | 1.9 | 2.3 | 2.0 | 1.4 | 0.8 | 0.4 | 0.3 | 0.9 | 0.9 | 0.6 | 0.2 | 1.3 | 2.6 | 0.2 |
| Avg | 3.0 | 3.0 | 3.5 | 3.7 | 3.4 | 3.3 | 3.5 | 3.7 | 3.5 | 3.6 | 3.9 | 3.8 | 4.0 | 3.7 | 3.7 | 3.6 | 3.4 | 3.1 | 2.6 | 2.6 | 2.5 | 2.4 | 2.8 | 2.8 | 3.3 | -- | -- |
| Max | 8.8 | 8.9 | 10.6 | 10.8 | 12.2 | 10.8 | 11.4 | 10.7 | 11.3 | 9.1 | 9.4 | 8.8 | 7.8 | 7.9 | 7.4 | 9.1 | 6.4 | 8.1 | 8.4 | 6.7 | 6.4 | 6.3 | 7.2 | 8.3 | -- | 12.2 | -- |
| Min | 0.3 | 0.4 | 0.2 | 0.5 | 0.3 | 0.5 | 0.4 | 0.4 | 0.5 | 0.7 | 0.9 | 1.2 | 1.5 | 1.8 | 1.9 | 1.3 | 1.4 | 0.7 | 0.4 | 0.0 | 0.5 | 0.4 | 0.2 | 0.2 | -- | -- | 0.0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, WS_ms_10m"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.2 | 0.3 | 0.9 | 1.3 | 1.9 | 0.6 | 0.9 | 1.8 | 1.0 | 0.6 | 1.4 | 2.8 | 2.1 | 2.6 | 3.7 | 2.3 | 1.7 | 0.8 | 0.8 | 0.9 | 0.8 | 0.7 | 0.8 | 1.0 | 1.3 | 3.7 | 0.2 |
| 2 | 0.8 | 1.8 | 3.0 | 2.9 | 2.1 | 0.7 | 0.6 | 1.6 | 1.1 | 0.8 | 1.1 | 1.8 | 2.0 | 2.0 | 2.1 | 2.1 | 2.4 | 2.1 | 0.7 | 1.0 | 0.6 | 1.5 | 1.1 | 1.2 | 1.5 | 3.0 | 0.6 |
| 3 | 1.0 | 0.9 | 0.9 | 0.7 | 0.7 | 0.4 | 0.6 | 0.9 | 0.7 | 0.9 | 2.7 | 2.7 | 2.9 | 4.2 | 4.5 | 4.1 | 3.2 | 1.1 | 1.2 | 1.6 | 1.3 | 1.1 | 1.0 | 1.1 | 1.7 | 4.5 | 0.4 |
| 4 | 1.1 | 1.4 | 1.0 | 0.8 | 0.9 | 0.6 | 1.4 | 1.3 | 2.7 | 4.5 | 6.8 | 5.2 | 6.2 | 5.7 | 5.9 | 2.6 | 0.9 | 1.0 | 1.7 | 1.4 | 1.5 | 1.5 | 1.3 | 1.0 | 2.4 | 6.8 | 0.6 |
| 5 | 0.7 | 1.0 | 0.6 | 0.6 | 0.7 | 0.4 | 1.0 | 0.4 | 1.2 | 1.7 | 3.1 | 3.9 | 3.4 | 3.4 | 3.9 | 4.2 | 4.0 | 2.0 | 1.0 | 0.3 | 0.3 | 0.5 | 0.9 | 0.9 | 1.7 | 4.2 | 0.3 |
| 6 | 0.5 | 0.7 | 0.7 | 0.5 | 0.8 | 1.5 | 3.4 | 2.4 | 1.8 | 2.1 | 1.4 | 1.9 | 2.1 | 2.1 | 1.9 | 2.9 | 2.7 | 2.2 | 1.0 | 0.7 | 1.2 | 0.8 | 0.9 | 1.1 | 1.6 | 3.4 | 0.5 |
| 7 | 0.4 | 0.9 | 0.6 | 0.3 | 0.3 | 0.9 | 1.4 | 1.1 | 0.6 | 0.8 | 1.4 | 2.3 | 3.6 | 4.3 | 4.3 | 4.4 | 3.8 | 2.0 | 1.1 | 0.8 | 1.5 | 2.2 | 2.8 | 3.3 | 1.9 | 4.4 | 0.3 |
| 8 | 5.4 | 4.3 | 3.9 | 2.2 | 1.5 | 2.3 | 4.1 | 2.0 | 1.7 | 1.8 | 3.6 | 4.0 | 4.3 | 4.8 | 4.6 | 4.1 | 3.4 | 2.4 | 2.4 | 2.5 | 1.2 | 0.7 | 1.0 | 0.8 | 2.9 | 5.4 | 0.7 |
| 9 | 0.6 | 1.1 | 0.9 | 0.6 | 1.4 | 0.5 | 0.5 | 0.8 | 0.7 | 0.9 | 1.5 | 3.3 | 3.3 | 2.6 | 3.3 | 2.9 | 2.9 | 3.5 | 2.6 | 2.8 | 2.7 | 2.8 | 1.6 | 3.1 | 2.0 | 3.5 | 0.5 |
| 10 | 4.3 | 3.6 | 3.5 | 4.5 | 4.1 | 4.2 | 4.1 | 7.2 | 6.3 | 8.1 | 7.7 | 6.2 | 5.7 | 4.8 | 4.1 | 3.5 | 4.0 | 4.9 | 5.4 | 5.0 | 7.0 | 4.2 | 3.1 | 2.9 | 4.9 | 8.1 | 2.9 |
| 11 | 2.3 | 3.6 | 4.3 | 4.0 | 4.1 | 7.0 | 6.8 | 4.6 | 4.0 | 4.2 | 4.6 | 3.8 | 3.4 | 2.9 | 3.9 | 3.9 | 3.9 | 2.6 | 2.2 | 3.2 | 4.6 | 5.9 | 4.8 | 3.9 | 4.1 | 7.0 | 2.2 |
| 12 | 3.7 | 4.2 | 4.8 | 4.3 | 4.0 | 5.5 | 3.5 | 3.5 | 4.3 | 4.8 | 5.1 | 5.4 | 4.9 | 4.2 | 3.1 | 2.5 | 4.8 | 3.2 | 2.0 | 1.5 | 0.8 | 0.6 | 0.9 | 0.3 | 3.4 | 5.5 | 0.3 |
| 13 | 0.7 | 0.8 | 1.0 | 1.8 | 0.5 | 1.0 | 1.6 | 0.8 | 1.6 | 0.8 | 1.1 | 2.0 | 2.4 | 2.7 | 3.1 | 2.7 | 3.3 | 1.9 | 1.2 | 0.6 | 0.8 | 1.4 | 0.6 | 0.8 | 1.5 | 3.3 | 0.5 |
| 14 | 0.9 | 1.2 | 0.6 | 1.1 | 0.7 | 1.1 | 2.3 | 2.2 | 3.6 | 4.2 | 7.4 | 7.7 | 5.4 | 3.2 | 2.8 | 2.5 | 3.1 | 3.4 | 2.7 | 1.9 | 1.8 | 2.2 | 1.7 | 1.4 | 2.7 | 7.7 | 0.6 |
| 15 | 4.9 | 7.6 | 7.8 | 7.1 | 8.1 | 7.2 | 4.6 | 1.6 | 3.5 | 4.0 | 3.3 | 4.1 | 3.1 | 2.4 | 2.3 | 2.1 | 2.9 | 1.9 | 1.5 | 3.5 | 3.3 | 3.1 | 4.8 | 4.8 | 4.1 | 8.1 | 1.5 |
| 16 | 3.5 | 4.8 | 6.1 | 5.9 | 5.0 | 3.9 | 1.5 | 3.9 | 7.5 | 8.6 | 3.9 | 2.6 | 2.7 | 2.2 | 2.0 | 2.6 | 2.2 | 1.0 | 1.7 | 2.6 | 4.1 | 2.2 | 3.4 | 3.9 | 3.7 | 8.6 | 1.0 |
| 17 | 6.4 | 1.5 | 1.9 | 2.6 | 2.3 | 3.3 | 5.0 | 5.2 | 5.3 | 5.9 | 7.5 | 4.8 | 6.5 | 6.3 | 3.3 | 3.1 | 3.2 | 5.5 | 4.8 | 6.7 | 2.8 | 2.5 | 2.6 | 3.4 | 4.3 | 7.5 | 1.5 |
| 18 | 2.6 | 4.4 | 2.9 | 2.9 | 3.2 | 5.5 | 4.3 | 3.1 | 2.8 | 3.4 | 2.5 | 3.9 | 3.8 | 3.5 | 3.0 | 2.2 | 2.5 | 2.4 | 1.1 | 0.8 | 3.0 | 1.4 | 0.8 | 0.5 | 2.8 | 5.5 | 0.5 |
| 19 | 0.5 | 1.2 | 1.5 | 1.3 | 1.6 | 1.5 | 2.9 | 3.7 | 4.0 | 4.2 | 5.0 | 5.3 | 6.1 | 5.9 | 5.1 | 5.3 | 5.3 | 4.1 | 1.3 | 0.7 | 1.7 | 2.4 | 1.9 | 1.4 | 3.1 | 6.1 | 0.5 |
| 20 | 1.1 | 0.6 | 3.3 | 4.4 | 3.4 | 3.3 | 3.1 | 3.0 | 4.2 | 4.2 | 2.4 | 2.7 | 1.7 | 2.9 | 2.2 | 3.3 | 2.4 | 1.4 | 1.1 | 2.0 | 1.9 | 1.8 | 1.8 | 2.5 | 2.5 | 4.4 | 0.6 |
| 21 | 1.3 | 3.0 | 3.2 | 3.5 | 3.8 | 3.4 | 3.5 | 3.5 | 2.9 | 3.4 | 2.8 | 3.6 | 4.1 | 4.3 | 3.7 | 2.9 | 1.2 | 1.1 | 1.5 | 0.7 | 0.4 | 0.7 | 0.8 | 1.3 | 2.5 | 4.3 | 0.4 |
| 22 | 1.1 | 1.1 | 1.2 | 1.2 | 1.8 | 2.5 | 1.3 | 1.2 | 2.7 | 1.6 | 1.0 | 2.0 | 2.1 | 2.4 | 2.9 | 2.7 | 2.8 | 1.6 | 0.7 | 0.8 | 1.3 | 1.3 | 1.0 | 3.9 | 1.8 | 3.9 | 0.7 |
| 23 | 3.4 | 4.1 | 5.3 | 6.7 | 3.9 | 3.7 | 4.4 | 4.1 | 3.1 | 3.5 | 3.4 | 2.9 | 3.4 | 2.6 | 2.1 | 2.4 | 2.3 | 2.6 | 7.1 | 7.9 | 6.3 | 3.7 | 4.4 | 3.9 | 4.1 | 7.9 | 2.1 |
| 24 | 4.6 | 5.3 | 7.1 | 5.5 | 3.2 | 2.7 | 5.4 | 3.8 | 3.0 | 3.2 | 5.8 | 3.2 | 2.3 | 3.1 | 2.9 | 2.9 | 1.6 | 1.1 | 1.1 | 1.8 | 2.7 | 2.2 | 8.6 | 11.0 | 3.9 | 11.0 | 1.1 |
| 25 | 8.1 | 9.9 | 13.1 | 14.7 | 6.5 | 5.8 | 10.7 | 6.0 | 7.4 | 11.5 | 3.8 | 5.9 | 4.5 | 4.4 | 4.0 | 2.7 | 2.7 | 3.5 | 3.3 | 7.5 | 11.2 | 11.9 | 15.8 | 16.3 | 8.0 | 16.3 | 2.7 |
| 26 | 13.8 | 14.4 | 17.2 | 17.1 | 14.9 | 15.3 | 13.5 | 8.4 | 9.1 | 8.3 | 6.8 | 11.9 | 10.0 | 5.5 | 3.7 | 2.7 | 4.7 | 4.3 | 5.2 | 3.8 | 1.5 | 1.9 | 2.5 | 3.6 | 8.3 | 17.2 | 1.5 |
| 27 | 1.9 | 6.2 | 6.5 | 11.3 | 8.1 | 8.1 | 3.2 | 4.3 | 10.9 | 10.4 | 11.1 | 9.8 | 5.8 | 6.5 | 5.4 | 4.3 | 2.6 | 3.5 | 4.7 | 2.6 | 2.2 | 2.6 | 2.3 | 1.3 | 5.6 | 11.3 | 1.3 |
| 28 | 1.4 | 1.1 | 1.2 | 1.0 | 1.9 | 2.0 | 2.0 | 2.0 | 2.0 | 2.3 | 2.5 | 2.9 | 2.6 | 1.6 | 2.1 | 2.3 | 2.0 | 0.7 | 1.5 | 2.5 | 1.6 | 2.7 | 0.7 | 1.6 | 1.8 | 2.9 | 0.7 |
| 29 | 2.7 | 1.3 | 2.6 | 2.8 | 2.0 | 1.8 | 3.8 | 3.6 | 1.9 | 1.9 | 3.3 | 3.3 | 3.2 | 2.3 | 2.2 | 3.4 | 3.1 | 2.0 | 2.9 | 2.3 | 4.9 | 3.6 | 3.4 | 2.0 | 2.8 | 4.9 | 1.3 |
| 30 | 1.3 | 1.0 | 0.9 | 1.1 | 1.9 | 1.1 | 1.4 | 1.0 | 0.9 | 1.1 | 1.4 | 1.5 | 2.2 | 2.9 | 2.6 | 2.3 | 2.6 | 1.6 | 0.9 | 0.5 | 0.5 | 1.0 | 1.0 | 2.0 | 1.5 | 2.9 | 0.5 |
| 31 | 1.6 | 2.6 | 4.0 | 1.9 | 2.0 | 1.9 | 1.7 | 1.6 | 1.2 | 2.5 | 3.8 | 3.3 | 2.4 | 2.6 | 2.2 | 1.9 | 1.4 | 2.0 | 3.9 | 4.5 | 4.4 | 3.6 | 2.2 | 3.2 | 2.6 | 4.5 | 1.2 |
| Avg | 2.7 | 3.1 | 3.6 | 3.8 | 3.1 | 3.2 | 3.4 | 2.9 | 3.4 | 3.7 | 3.8 | 4.1 | 3.8 | 3.6 | 3.3 | 3.0 | 2.9 | 2.4 | 2.3 | 2.4 | 2.6 | 2.4 | 2.6 | 2.9 | 3.1 | -- | -- |
| Max | 13.8 | 14.4 | 17.2 | 17.1 | 14.9 | 15.3 | 13.5 | 8.4 | 10.9 | 11.5 | 11.1 | 11.9 | 10.0 | 6.5 | 5.9 | 5.3 | 5.3 | 5.5 | 7.1 | 7.9 | 11.2 | 11.9 | 15.8 | 16.3 | -- | 17.2 | -- |
| Min | 0.2 | 0.3 | 0.6 | 0.3 | 0.3 | 0.4 | 0.5 | 0.4 | 0.6 | 0.6 | 1.0 | 1.5 | 1.7 | 1.6 | 1.9 | 1.9 | 0.9 | 0.7 | 0.7 | 0.3 | 0.3 | 0.5 | 0.6 | 0.3 | -- | -- | 0.2 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, WD_10m"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 295 | 32 | 0 | 347 | 17 | 32 | 1 | 115 | 166 | 176 | 148 | 249 | 250 | 259 | 261 | 237 | 234 | 243 | 286 | 4 | 16 | 3 | 355 | 6 | 318 | 355 | 0 |
| 2 | 321 | 24 | 45 | 4 | 32 | 23 | 46 | 114 | 156 | 193 | 208 | 238 | 245 | 260 | 256 | 256 | 252 | 245 | 271 | 325 | 16 | 48 | 26 | 39 | 324 | 325 | 4 |
| 3 | 50 | 304 | 68 | 55 | 58 | 24 | 42 | 61 | 134 | 139 | 199 | 206 | 214 | 229 | 224 | 236 | 241 | 253 | 262 | 310 | 291 | 176 | 52 | 81 | 198 | 310 | 24 |
| 4 | 53 | 45 | 114 | 229 | 345 | 22 | 42 | 70 | 134 | 203 | 177 | 240 | 255 | 238 | 221 | 239 | 253 | 250 | 261 | 296 | 33 | 17 | 20 | 20 | 297 | 345 | 17 |
| 5 | 29 | 25 | 24 | 24 | 28 | 42 | 36 | 49 | 54 | 50 | 42 | 30 | 22 | 39 | 10 | 3 | 21 | 48 | 57 | 48 | 48 | 173 | 181 | 61 | 40 | 181 | 3 |
| 6 | 243 | 149 | 39 | 65 | 229 | 219 | 269 | 42 | 44 | 46 | 31 | 49 | 54 | 77 | 121 | 246 | 115 | 48 | 65 | 93 | 69 | 64 | 62 | 68 | 69 | 269 | 31 |
| 7 | 50 | 131 | 52 | 58 | 63 | 290 | 282 | 133 | 135 | 51 | 84 | 83 | 73 | 153 | 184 | 198 | 246 | 272 | 317 | 1 | 47 | 36 | 14 | 358 | 59 | 358 | 1 |
| 8 | 9 | 308 | 339 | 47 | 86 | 298 | 17 | 53 | 75 | 159 | 159 | 195 | 211 | 215 | 220 | 210 | 205 | 209 | 158 | 54 | 105 | 45 | 110 | 106 | 126 | 339 | 9 |
| 9 | 57 | 81 | 101 | 102 | 111 | 148 | 267 | 253 | 133 | 141 | 155 | 182 | 192 | 202 | 196 | 210 | 224 | 233 | 232 | 231 | 239 | 250 | 181 | 224 | 188 | 267 | 57 |
| 10 | 252 | 224 | 198 | 193 | 229 | 213 | 202 | 251 | 195 | 242 | 256 | 239 | 218 | 234 | 227 | 204 | 208 | 182 | 273 | 35 | 47 | 29 | 44 | 35 | 225 | 273 | 29 |
| 11 | 279 | 85 | 350 | 94 | 65 | 72 | 57 | 86 | 148 | 203 | 182 | 188 | 186 | 218 | 217 | 213 | 237 | 258 | 300 | 27 | 45 | 42 | 8 | 294 | 140 | 350 | 8 |
| 12 | 298 | 312 | 356 | 25 | 61 | 28 | 293 | 292 | 64 | 72 | 92 | 142 | 158 | 172 | 236 | 234 | 248 | 253 | 296 | 335 | 17 | 36 | 349 | 18 | 346 | 356 | 17 |
| 13 | 36 | 354 | 24 | 334 | 72 | 92 | 98 | 138 | 108 | 162 | 156 | 176 | 204 | 205 | 228 | 220 | 217 | 233 | 264 | 41 | 46 | 8 | 35 | 307 | 113 | 354 | 8 |
| 14 | 297 | 38 | 39 | 47 | 38 | 32 | 42 | 66 | 106 | 182 | 212 | 190 | 260 | 249 | 238 | 235 | 242 | 247 | 311 | 343 | 270 | 246 | 288 | 338 | 292 | 343 | 32 |
| 15 | 56 | 42 | 43 | 68 | 58 | 55 | 68 | 61 | 153 | 152 | 221 | 247 | 247 | 249 | 240 | 245 | 248 | 253 | 286 | 294 | 86 | 60 | 308 | 5 | 351 | 308 | 5 |
| 16 | 25 | 34 | 32 | 55 | 24 | 324 | 333 | 321 | 221 | 104 | 67 | 134 | 219 | 235 | 248 | 266 | 262 | 244 | 296 | 325 | 3 | 339 | 286 | 273 | 317 | 339 | 3 |
| 17 | 14 | 4 | 51 | 52 | 64 | 55 | 37 | 41 | 125 | 174 | 176 | 152 | 211 | 235 | 222 | 241 | 246 | 263 | 289 | 332 | 324 | 25 | 335 | 330 | 346 | 335 | 4 |
| 18 | 6 | 209 | 325 | 34 | 20 | 25 | 349 | 49 | 347 | 240 | 187 | 279 | 335 | 251 | 235 | 236 | 263 | 264 | 337 | 357 | 32 | 25 | 11 | 275 | 324 | 357 | 6 |
| 19 | 292 | 283 | 263 | 322 | 326 | 14 | 331 | 349 | 328 | 61 | 189 | 48 | 254 | 219 | 205 | 216 | 263 | 268 | 309 | 328 | 344 | 355 | 345 | 260 | 303 | 355 | 14 |
| 20 | 28 | 278 | 24 | 35 | 305 | 344 | 302 | 246 | 125 | 157 | 159 | 181 | 250 | 249 | 246 | 251 | 242 | 260 | 299 | 36 | 27 | 5 | 276 | 347 | 293 | 347 | 5 |
| 21 | 350 | 358 | 334 | 19 | 309 | 3 | 353 | 22 | 70 | 166 | 174 | 209 | 194 | 248 | 254 | 238 | 246 | 267 | 317 | 2 | 33 | 206 | 348 | 333 | 314 | 358 | 2 |
| 22 | 304 | 7 | 257 | 270 | 55 | 57 | 7 | 265 | 275 | 41 | 74 | 55 | 49 | 55 | 114 | 147 | 140 | 69 | 57 | 65 | 78 | 64 | 42 | 41 | 50 | 304 | 7 |
| 23 | 50 | 32 | 335 | 278 | 17 | 30 | 33 | 31 | 39 | 46 | 71 | 61 | 61 | 105 | 135 | 194 | 179 | 120 | 56 | 54 | 55 | 301 | 46 | 67 | 52 | 335 | 17 |
| 24 | 83 | 171 | 102 | 66 | 50 | 206 | 203 | 355 | 54 | 65 | 76 | 83 | 139 | 178 | 221 | 260 | 261 | 261 | 313 | 2 | 287 | 329 | 333 | 38 | 39 | 355 | 2 |
| 25 | 36 | 305 | 317 | 282 | 319 | 334 | 52 | 251 | 275 | 193 | 204 | 239 | 246 | 240 | 248 | 238 | 244 | 265 | 307 | 345 | 303 | 360 | 264 | 344 | 284 | 360 | 36 |
| 26 | 355 | 64 | 42 | 273 | 196 | 141 | 57 | 59 | 60 | 51 | 53 | 54 | 44 | 76 | 10 | 24 | 327 | 273 | 342 | 58 | 18 | 63 | 82 | 75 | 43 | 355 | 10 |
| 27 | 61 | 52 | 68 | 58 | 71 | 53 | 35 | 74 | 71 | 87 | 78 | 91 | 162 | 192 | 207 | 231 | 232 | 229 | 295 | 38 | 43 | 41 | 46 | 60 | 70 | 295 | 35 |
| 28 | 85 | 115 | 67 | 91 | 110 | 104 | 115 | 132 | 157 | 175 | 193 | 201 | 210 | 202 | 208 | 207 | 215 | 194 | 187 | 182 | 165 | 142 | 156 | 162 | 160 | 215 | 67 |
| 29 | 167 | 182 | 189 | 186 | 44 | 38 | 7 | 13 | 157 | 167 | 179 | 210 | 228 | 222 | 246 | 252 | 261 | 274 | 295 | 292 | 310 | 302 | 11 | 49 | 245 | 310 | 7 |
| 30 | 46 | 36 | 22 | 252 | 30 | 206 | 329 | 272 | 144 | 229 | 251 | 237 | 236 | 229 | 242 | 236 | 245 | 248 | 276 | 324 | 20 | 16 | 310 | 316 | 280 | 329 | 16 |
| 31 | 302 | 237 | 237 | 28 | 55 | 55 | 66 | 61 | 132 | 213 | 168 | 176 | 255 | 230 | 254 | 246 | 247 | 255 | 302 | 343 | 17 | 354 | 304 | 308 | 282 | 354 | 17 |
| Avg | 9 | 22 | 25 | 31 | 40 | 34 | 16 | 46 | 115 | 146 | 156 | 180 | 219 | 218 | 226 | 233 | 239 | 249 | 298 | 359 | 22 | 20 | 4 | 8 | 346 | -- | -- |
| Max | 355 | 358 | 356 | 347 | 345 | 344 | 353 | 355 | 347 | 242 | 256 | 279 | 335 | 260 | 261 | 266 | 327 | 274 | 342 | 357 | 344 | 360 | 355 | 358 | -- | 360 | -- |
| Min | 6 | 4 | 0 | 4 | 17 | 3 | 1 | 13 | 39 | 41 | 31 | 30 | 22 | 39 | 10 | 3 | 21 | 48 | 56 | 1 | 3 | 3 | 8 | 5 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, WD_10m"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 18 | 5 | 301 | 321 | 265 | 358 | 16 | 59 | 65 | 226 | 234 | 138 | 253 | 337 | 345 | 240 | 256 | 274 | 323 | 38 | 2 | 337 | 359 | 291 | 326 | 359 | 2 |
| 2 | 19 | 62 | 79 | 43 | 348 | 78 | 72 | 68 | 66 | 76 | 81 | 55 | 58 | 63 | 110 | 112 | 72 | 56 | 92 | 100 | 71 | 95 | 251 | 109 | 72 | 348 | 19 |
| 3 | 97 | 143 | 117 | 65 | 36 | 61 | 68 | 68 | 65 | 88 | 152 | 153 | 199 | 216 | 240 | 236 | 244 | 256 | 343 | 93 | 31 | 305 | 41 | 37 | 88 | 343 | 31 |
| 4 | 41 | 43 | 28 | 61 | 64 | 58 | 49 | 117 | 121 | 155 | 151 | 169 | 185 | 201 | 211 | 234 | 231 | 236 | 257 | 141 | 116 | 227 | 231 | 233 | 158 | 257 | 28 |
| 5 | 91 | 294 | 6 | 54 | 40 | 82 | 286 | 109 | 251 | 229 | 252 | 259 | 218 | 271 | 250 | 234 | 246 | 228 | 127 | 36 | 50 | 69 | 74 | 269 | 271 | 294 | 6 |
| 6 | 0 | 35 | 22 | 212 | 276 | 239 | 276 | 254 | 229 | 224 | 76 | 54 | 42 | 27 | 34 | 34 | 59 | 55 | 79 | 66 | 278 | 351 | 23 | 38 | 17 | 351 | 0 |
| 7 | 38 | 357 | 352 | 36 | 19 | 26 | 7 | 340 | 339 | 339 | 105 | 69 | 66 | 143 | 121 | 119 | 47 | 76 | 59 | 59 | 56 | 66 | 45 | 337 | 43 | 357 | 7 |
| 8 | 41 | 18 | 38 | 57 | 40 | 61 | 70 | 80 | 77 | 83 | 76 | 79 | 256 | 263 | 266 | 213 | 243 | 266 | 318 | 325 | 8 | 334 | 312 | 308 | 9 | 334 | 8 |
| 9 | 2 | 340 | 40 | 24 | 49 | 36 | 11 | 8 | 30 | 150 | 181 | 187 | 193 | 252 | 218 | 210 | 250 | 275 | 318 | 58 | 89 | 355 | 330 | 292 | 347 | 355 | 2 |
| 10 | 335 | 54 | 44 | 28 | 341 | 350 | 332 | 53 | 83 | 78 | 272 | 59 | 91 | 55 | 52 | 344 | 58 | 49 | 52 | 66 | 355 | 14 | 293 | 301 | 26 | 355 | 14 |
| 11 | 293 | 325 | 298 | 345 | 315 | 308 | 15 | 330 | 284 | 261 | 41 | 31 | 44 | 57 | 42 | 53 | 50 | 10 | 51 | 56 | 243 | 66 | 49 | 67 | 9 | 345 | 10 |
| 12 | 45 | 72 | 43 | 131 | 286 | 304 | 289 | 57 | 82 | 46 | 50 | 81 | 113 | 150 | 82 | 56 | 73 | 71 | 83 | 56 | 76 | 109 | 65 | 52 | 68 | 304 | 43 |
| 13 | 85 | 48 | 43 | 41 | 40 | 35 | 39 | 37 | 37 | 24 | 34 | 355 | 71 | 51 | 61 | 50 | 60 | 53 | 35 | 45 | 45 | 41 | 50 | 46 | 45 | 355 | 24 |
| 14 | 324 | 150 | 60 | 68 | 76 | 69 | 74 | 78 | 70 | 71 | 95 | 157 | 172 | 198 | 219 | 252 | 268 | 272 | 345 | 35 | 37 | 39 | 47 | 44 | 68 | 345 | 35 |
| 15 | 40 | 349 | 66 | 81 | 67 | 125 | 99 | 139 | 111 | 141 | 156 | 160 | 173 | 185 | 208 | 202 | 201 | 229 | 211 | 220 | 246 | 217 | 198 | 217 | 168 | 349 | 40 |
| 16 | 230 | 255 | 257 | 269 | 237 | 228 | 234 | 230 | 206 | 209 | 248 | 236 | 231 | 222 | 220 | 231 | 239 | 254 | 288 | 28 | 27 | 20 | 264 | 25 | 247 | 288 | 20 |
| 17 | 143 | 359 | 333 | 38 | 40 | 47 | 148 | 49 | 112 | 141 | 130 | 156 | 190 | 177 | 247 | 259 | 260 | 279 | 61 | 58 | 52 | 12 | 335 | 11 | 63 | 359 | 11 |
| 18 | 26 | 15 | 41 | 61 | 59 | 37 | 328 | 308 | 260 | 305 | 184 | 105 | 216 | 251 | 243 | 260 | 248 | 281 | 341 | 40 | 60 | 35 | 261 | 2 | 336 | 341 | 2 |
| 19 | 323 | 281 | 35 | 358 | 24 | 352 | 341 | 71 | 58 | 138 | 183 | 184 | 186 | 261 | 240 | 230 | 229 | 268 | 33 | 306 | 227 | 339 | 326 | 37 | 312 | 358 | 24 |
| 20 | 40 | 15 | 1 | 16 | 63 | 241 | 53 | 233 | 250 | 203 | 193 | 222 | 228 | 242 | 237 | 228 | 213 | 226 | 243 | 100 | 276 | 256 | 326 | 79 | 247 | 326 | 1 |
| 21 | 255 | 305 | 40 | 52 | 63 | 33 | 188 | 262 | 79 | 167 | 145 | 166 | 171 | 203 | 253 | 269 | 263 | 285 | 21 | 122 | 324 | 88 | 57 | 81 | 125 | 324 | 21 |
| 22 | 74 | 72 | 44 | 76 | 90 | 192 | 346 | 75 | 226 | 268 | 235 | 225 | 234 | 234 | 251 | 192 | 204 | 199 | 199 | 141 | 222 | 275 | 254 | 254 | 213 | 346 | 44 |
| 23 | 234 | 189 | 255 | 202 | 158 | 209 | 104 | 184 | 241 | 52 | 52 | 40 | 63 | 65 | 68 | 67 | 74 | 89 | 90 | 65 | 82 | 64 | 330 | 266 | 94 | 330 | 40 |
| 24 | 157 | 46 | 52 | 53 | 116 | 42 | 47 | 47 | 48 | 37 | 48 | 52 | 64 | 59 | 64 | 78 | 67 | 72 | 66 | 54 | 60 | 69 | 69 | 67 | 62 | 157 | 37 |
| 25 | 62 | 16 | 71 | 72 | 337 | 301 | 356 | 324 | 224 | 143 | 197 | 259 | 216 | 252 | 248 | 263 | 265 | 266 | 350 | 26 | 278 | 330 | 54 | 68 | 313 | 356 | 16 |
| 26 | 62 | 314 | 67 | 29 | 27 | 299 | 44 | 51 | 54 | 53 | 50 | 59 | 45 | 72 | 47 | 42 | 68 | 45 | 87 | 109 | 70 | 48 | 31 | 100 | 52 | 314 | 27 |
| 27 | 82 | 42 | 33 | 39 | 25 | 54 | 22 | 39 | 39 | 49 | 48 | 345 | 16 | 5 | 37 | 44 | 32 | 36 | 39 | 40 | 15 | 348 | 50 | 39 | 33 | 348 | 5 |
| 28 | 33 | 39 | 53 | 60 | 40 | 22 | 50 | 31 | 307 | 1 | 355 | 99 | 80 | 94 | 84 | 82 | 94 | 47 | 53 | 46 | 20 | 19 | 46 | 19 | 45 | 355 | 1 |
| 29 | 25 | 54 | 57 | 45 | 54 | 62 | 58 | 55 | 336 | 47 | 60 | 74 | 90 | 151 | 192 | 210 | 254 | 272 | 306 | 289 | 341 | 68 | 45 | 66 | 45 | 341 | 25 |
| 30 | 57 | 76 | 81 | 4 | 312 | 342 | 357 | 269 | 299 | 227 | 217 | 253 | 271 | 79 | 124 | 191 | 247 | 103 | 93 | 40 | 231 | 272 | 286 | 77 | 317 | 357 | 4 |
| Avg | 37 | 21 | 35 | 43 | 30 | 25 | 27 | 47 | 49 | 109 | 124 | 117 | 157 | 182 | 204 | 217 | 242 | 300 | 31 | 58 | 25 | 19 | 4 | 27 | 40 | -- | -- |
| Max | 335 | 359 | 352 | 358 | 348 | 358 | 357 | 340 | 339 | 339 | 355 | 355 | 271 | 337 | 345 | 344 | 268 | 285 | 350 | 325 | 355 | 355 | 359 | 337 | -- | 359 | -- |
| Min | 0 | 5 | 1 | 4 | 19 | 22 | 7 | 8 | 30 | 1 | 34 | 31 | 16 | 5 | 34 | 34 | 32 | 10 | 21 | 26 | 2 | 12 | 23 | 2 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, WD_10m"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 18 | 269 | 295 | 359 | 12 | 308 | 302 | 44 | 215 | 161 | 212 | 144 | 127 | 268 | 267 | 267 | 252 | 283 | 333 | 350 | 31 | 360 | 329 | 307 | 307 | 360 | 12 |
| 2 | 279 | 342 | 40 | 37 | 29 | 339 | 292 | 335 | 234 | 190 | 176 | 228 | 278 | 237 | 271 | 237 | 277 | 289 | 337 | 2 | 299 | 13 | 3 | 306 | 304 | 342 | 2 |
| 3 | 40 | 21 | 58 | 288 | 11 | 28 | 66 | 277 | 210 | 130 | 146 | 155 | 172 | 198 | 198 | 203 | 215 | 344 | 41 | 53 | 68 | 66 | 55 | 82 | 82 | 344 | 11 |
| 4 | 27 | 318 | 38 | 37 | 268 | 106 | 104 | 113 | 183 | 195 | 224 | 245 | 246 | 250 | 250 | 247 | 148 | 247 | 287 | 276 | 281 | 273 | 201 | 193 | 238 | 318 | 27 |
| 5 | 191 | 217 | 350 | 228 | 193 | 296 | 260 | 15 | 256 | 246 | 247 | 262 | 256 | 243 | 237 | 235 | 241 | 259 | 266 | 109 | 261 | 331 | 41 | 47 | 256 | 350 | 15 |
| 6 | 18 | 32 | 32 | 22 | 42 | 54 | 52 | 79 | 85 | 102 | 163 | 147 | 141 | 241 | 218 | 234 | 244 | 282 | 279 | 37 | 52 | 26 | 70 | 30 | 55 | 282 | 18 |
| 7 | 251 | 18 | 343 | 2 | 5 | 11 | 43 | 287 | 228 | 187 | 187 | 162 | 216 | 201 | 223 | 235 | 228 | 294 | 78 | 285 | 110 | 192 | 204 | 197 | 234 | 343 | 2 |
| 8 | 187 | 192 | 190 | 165 | 154 | 202 | 242 | 282 | 285 | 265 | 238 | 245 | 246 | 233 | 212 | 218 | 237 | 248 | 259 | 246 | 209 | 147 | 323 | 250 | 228 | 323 | 147 |
| 9 | 277 | 291 | 38 | 45 | 27 | 115 | 298 | 293 | 55 | 171 | 199 | 17 | 80 | 46 | 7 | 41 | 48 | 25 | 296 | 234 | 260 | 213 | 100 | 252 | 3 | 298 | 7 |
| 10 | 270 | 281 | 256 | 291 | 290 | 273 | 309 | 40 | 42 | 43 | 50 | 41 | 38 | 34 | 72 | 63 | 81 | 57 | 57 | 54 | 64 | 51 | 20 | 63 | 28 | 309 | 20 |
| 11 | 314 | 69 | 59 | 55 | 29 | 55 | 58 | 35 | 28 | 45 | 20 | 11 | 336 | 358 | 56 | 33 | 30 | 104 | 187 | 271 | 69 | 56 | 51 | 50 | 39 | 358 | 11 |
| 12 | 295 | 98 | 92 | 58 | 89 | 37 | 48 | 62 | 63 | 89 | 92 | 80 | 105 | 78 | 56 | 51 | 68 | 54 | 337 | 31 | 59 | 340 | 18 | 352 | 55 | 352 | 18 |
| 13 | 293 | 6 | 331 | 9 | 271 | 350 | 47 | 311 | 65 | 149 | 169 | 218 | 245 | 252 | 253 | 246 | 255 | 281 | 331 | 278 | 333 | 25 | 263 | 10 | 301 | 350 | 6 |
| 14 | 0 | 26 | 271 | 358 | 78 | 39 | 251 | 280 | 74 | 161 | 81 | 70 | 44 | 110 | 105 | 29 | 116 | 15 | 306 | 360 | 240 | 177 | 240 | 85 | 47 | 360 | 0 |
| 15 | 340 | 27 | 60 | 56 | 40 | 59 | 54 | 294 | 270 | 148 | 170 | 100 | 114 | 150 | 15 | 302 | 295 | 319 | 308 | 75 | 352 | 237 | 93 | 23 | 29 | 352 | 15 |
| 16 | 65 | 49 | 63 | 71 | 62 | 39 | 323 | 28 | 72 | 72 | 229 | 181 | 156 | 184 | 251 | 56 | 93 | 327 | 25 | 10 | 42 | 1 | 26 | 34 | 47 | 327 | 1 |
| 17 | 71 | 311 | 309 | 32 | 34 | 50 | 68 | 61 | 69 | 71 | 67 | 68 | 70 | 65 | 60 | 109 | 163 | 60 | 39 | 62 | 17 | 42 | 49 | 47 | 55 | 311 | 17 |
| 18 | 351 | 47 | 337 | 332 | 1 | 49 | 43 | 74 | 97 | 77 | 343 | 38 | 60 | 67 | 69 | 100 | 67 | 73 | 291 | 348 | 44 | 138 | 285 | 235 | 38 | 351 | 1 |
| 19 | 158 | 111 | 160 | 100 | 98 | 119 | 115 | 117 | 127 | 132 | 151 | 177 | 191 | 195 | 187 | 200 | 213 | 235 | 109 | 248 | 202 | 196 | 157 | 156 | 160 | 248 | 98 |
| 20 | 134 | 176 | 87 | 108 | 130 | 221 | 216 | 66 | 80 | 70 | 184 | 184 | 167 | 193 | 242 | 257 | 239 | 267 | 221 | 253 | 223 | 251 | 249 | 195 | 195 | 267 | 66 |
| 21 | 184 | 241 | 245 | 232 | 232 | 237 | 239 | 240 | 236 | 203 | 228 | 233 | 234 | 247 | 244 | 252 | 253 | 31 | 343 | 319 | 19 | 290 | 2 | 33 | 255 | 343 | 2 |
| 22 | 356 | 7 | 39 | 20 | 33 | 34 | 1 | 50 | 53 | 137 | 208 | 204 | 175 | 225 | 244 | 253 | 251 | 271 | 322 | 20 | 37 | 7 | 345 | 49 | 0 | 356 | 1 |
| 23 | 36 | 51 | 63 | 49 | 82 | 93 | 74 | 350 | 205 | 197 | 251 | 283 | 50 | 78 | 68 | 58 | 42 | 77 | 53 | 56 | 32 | 31 | 353 | 346 | 48 | 353 | 31 |
| 24 | 29 | 22 | 46 | 39 | 2 | 20 | 52 | 37 | 321 | 43 | 59 | 60 | 110 | 99 | 112 | 108 | 126 | 16 | 46 | 33 | 34 | 260 | 49 | 30 | 47 | 321 | 2 |
| 25 | 39 | 45 | 48 | 49 | 58 | 250 | 42 | 67 | 74 | 56 | 120 | 62 | 37 | 47 | 47 | 83 | 93 | 84 | 80 | 56 | 50 | 49 | 50 | 48 | 59 | 250 | 37 |
| 26 | 46 | 47 | 47 | 49 | 54 | 54 | 46 | 34 | 43 | 50 | 42 | 49 | 51 | 42 | 69 | 78 | 58 | 49 | 69 | 82 | 335 | 254 | 17 | 56 | 48 | 335 | 17 |
| 27 | 249 | 39 | 76 | 57 | 45 | 50 | 290 | 320 | 36 | 44 | 40 | 39 | 37 | 49 | 56 | 41 | 11 | 359 | 40 | 325 | 174 | 168 | 209 | 57 | 36 | 359 | 11 |
| 28 | 274 | 297 | 324 | 325 | 81 | 234 | 295 | 252 | 262 | 232 | 120 | 82 | 72 | 142 | 192 | 190 | 217 | 278 | 356 | 46 | 116 | 69 | 305 | 34 | 282 | 356 | 34 |
| 29 | 50 | 143 | 36 | 45 | 27 | 6 | 44 | 53 | 335 | 170 | 198 | 227 | 225 | 233 | 203 | 339 | 10 | 125 | 204 | 240 | 108 | 242 | 154 | 248 | 164 | 339 | 6 |
| 30 | 236 | 318 | 280 | 265 | 339 | 287 | 286 | 314 | 274 | 217 | 229 | 243 | 245 | 242 | 275 | 271 | 246 | 282 | 22 | 324 | 277 | 303 | 346 | 356 | 283 | 356 | 22 |
| 31 | 346 | 46 | 69 | 18 | 354 | 51 | 54 | 321 | 245 | 202 | 249 | 228 | 29 | 90 | 87 | 81 | 139 | 89 | 67 | 67 | 56 | 57 | 31 | 48 | 52 | 354 | 18 |
| Avg | 344 | 16 | 27 | 28 | 36 | 28 | 13 | 7 | 56 | 137 | 175 | 152 | 126 | 176 | 198 | 230 | 199 | 340 | 354 | 1 | 30 | 356 | 15 | 30 | 26 | -- | -- |
| Max | 356 | 342 | 350 | 359 | 354 | 350 | 323 | 350 | 335 | 265 | 343 | 283 | 336 | 358 | 275 | 339 | 295 | 359 | 356 | 360 | 352 | 360 | 353 | 356 | -- | 360 | -- |
| Min | 0 | 6 | 32 | 2 | 1 | 6 | 1 | 15 | 28 | 43 | 20 | 11 | 29 | 34 | 7 | 29 | 10 | 15 | 22 | 2 | 17 | 1 | 2 | 10 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, DeltaTemp_C"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.44 | 2.12 | 2.24 | 1.96 | 1.70 | 1.41 | 1.37 | 0.49 | -0.56 | -0.87 | -1.39 | -0.99 | -1.19 | -0.97 | -0.87 | -0.90 | -0.71 | -0.30 | 0.21 | 1.01 | 1.49 | 0.70 | 1.19 | 1.41 | 0.42 | 2.24 | -1.39 |
| 2 | 1.08 | 1.01 | 1.58 | 1.96 | 1.42 | 1.40 | 0.77 | -0.13 | -0.79 | -1.00 | -1.20 | -1.06 | -1.15 | -0.97 | -0.96 | -0.89 | -0.63 | -0.31 | 0.06 | 0.57 | 1.56 | 1.60 | 0.97 | 1.19 | 0.25 | 1.96 | -1.20 |
| 3 | 1.19 | 0.77 | 0.95 | 1.32 | 0.91 | 0.84 | 1.08 | -0.15 | -1.31 | -1.53 | -1.36 | -1.94 | -1.75 | -1.38 | -1.24 | -1.11 | -0.63 | -0.22 | 0.25 | 0.48 | 1.09 | 0.67 | 0.91 | 0.47 | -0.07 | 1.32 | -1.94 |
| 4 | 0.90 | 0.73 | 0.50 | 0.54 | 1.02 | 1.16 | 0.68 | -0.43 | -1.14 | -0.99 | -1.43 | -1.05 | -1.12 | -1.13 | -1.63 | -0.98 | -0.59 | -0.25 | 0.03 | 0.16 | 0.86 | 0.89 | 0.15 | 0.07 | -0.13 | 1.16 | -1.63 |
| 5 | 0.08 | 0.07 | 0.08 | 0.07 | 0.07 | 0.11 | 0.16 | -0.18 | -0.89 | -1.21 | -1.41 | -1.59 | -1.54 | -1.47 | -1.36 | -1.13 | -0.73 | -0.24 | 0.05 | 0.13 | 0.14 | 0.22 | 0.22 | 0.20 | -0.42 | 0.22 | -1.59 |
| 6 | 0.25 | 0.39 | 0.25 | 0.33 | 0.34 | 0.48 | 0.56 | -0.02 | -0.62 | -1.11 | -1.19 | -1.42 | -1.62 | -1.22 | -1.42 | -1.05 | -0.79 | -0.07 | 0.32 | 0.31 | 0.53 | 0.52 | 0.53 | 0.40 | -0.22 | 0.56 | -1.62 |
| 7 | 0.54 | 0.84 | 0.70 | 0.44 | 0.27 | 0.42 | 0.23 | -0.01 | -0.50 | -0.96 | -1.16 | -1.45 | -1.66 | -1.50 | -1.57 | -1.20 | -0.22 | -0.02 | 0.36 | 1.40 | 0.85 | 0.61 | 0.83 | 1.40 | -0.06 | 1.40 | -1.66 |
| 8 | 1.31 | 1.51 | 1.92 | 0.89 | 0.59 | 0.88 | 1.61 | 0.29 | -1.12 | -1.61 | -2.17 | -1.60 | -1.82 | -1.54 | -1.34 | -1.45 | -1.03 | -0.33 | 0.32 | 0.59 | 0.49 | 0.66 | 0.72 | 0.68 | -0.07 | 1.92 | -2.17 |
| 9 | 1.01 | 0.98 | 1.08 | 0.88 | 0.64 | 0.67 | 0.80 | 0.64 | -0.91 | -1.43 | -1.81 | -2.23 | -2.23 | -1.77 | -1.62 | -1.23 | -0.59 | -0.22 | -0.13 | -0.14 | -0.08 | -0.07 | -0.14 | -0.13 | -0.33 | 1.08 | -2.23 |
| 10 | -0.19 | -0.33 | -0.45 | -0.42 | -0.29 | -0.36 | -0.37 | -0.36 | -0.43 | -0.42 | -0.46 | -0.78 | -1.02 | -1.05 | -1.02 | -1.23 | -0.91 | -0.62 | -0.06 | 0.30 | 0.37 | 0.32 | 0.51 | 0.52 | -0.36 | 0.52 | -1.23 |
| 11 | 0.66 | 0.46 | 0.88 | 0.73 | 0.36 | 0.40 | 0.42 | -0.04 | -0.93 | -0.83 | -1.20 | -1.37 | -1.57 | -1.36 | -1.17 | -1.31 | -0.75 | -0.26 | 0.02 | 0.45 | 0.72 | 1.48 | 1.42 | 1.38 | -0.06 | 1.48 | -1.57 |
| 12 | 1.15 | 1.51 | 1.41 | 1.53 | 0.75 | 0.56 | 0.73 | 0.58 | -0.54 | -1.03 | -1.55 | -2.03 | -2.23 | -1.73 | -0.95 | -0.89 | -0.60 | -0.23 | 0.08 | 0.74 | 1.51 | 0.80 | 0.90 | 1.20 | 0.07 | 1.53 | -2.23 |
| 13 | 0.97 | 1.21 | 1.15 | 1.34 | 1.19 | 0.79 | 0.82 | 0.62 | -0.99 | -1.66 | -1.92 | -2.32 | -2.12 | -1.94 | -1.14 | -1.22 | -0.91 | -0.25 | 0.23 | 0.90 | 1.20 | 1.38 | 1.39 | 1.51 | 0.01 | 1.51 | -2.32 |
| 14 | 1.04 | 1.96 | 1.65 | 1.62 | 1.49 | 1.11 | 1.03 | 0.41 | -1.06 | -0.94 | -1.12 | -1.60 | -0.96 | -0.92 | -0.98 | -0.80 | -0.60 | -0.19 | 0.30 | 0.58 | 0.82 | 0.67 | 0.77 | 1.34 | 0.23 | 1.96 | -1.60 |
| 15 | 0.55 | 0.61 | 0.74 | 0.56 | 0.57 | 0.60 | 0.55 | 0.43 | -0.84 | -1.05 | -0.79 | -0.90 | -0.99 | -0.84 | -0.94 | -0.88 | -0.54 | -0.21 | 0.15 | 0.41 | 0.73 | 1.07 | 1.08 | 1.35 | 0.06 | 1.35 | -1.05 |
| 16 | 1.65 | 1.28 | 0.82 | 0.47 | 0.62 | 0.93 | 0.76 | 0.12 | -0.58 | -0.85 | -1.60 | -1.59 | -1.15 | -1.43 | -1.05 | -0.79 | -0.57 | -0.22 | 0.07 | 0.41 | 1.18 | 0.93 | 1.26 | 1.07 | 0.07 | 1.65 | -1.60 |
| 17 | 1.40 | 1.26 | 0.63 | 0.53 | 0.45 | 0.48 | 0.56 | 0.19 | -1.01 | -0.93 | -1.39 | -1.63 | -1.31 | -1.13 | -1.25 | -0.75 | -0.55 | -0.15 | 0.06 | 0.59 | 1.16 | 1.67 | 1.07 | 1.66 | 0.07 | 1.67 | -1.63 |
| 18 | 2.20 | 0.99 | 1.44 | 2.11 | 1.77 | 1.77 | 1.48 | 0.63 | -0.59 | -0.77 | -0.95 | -0.82 | -1.12 | -0.77 | -0.92 | -0.88 | -0.44 | -0.07 | 0.29 | 1.17 | 1.75 | 1.27 | 1.51 | 1.02 | 0.50 | 2.20 | -1.12 |
| 19 | 0.93 | 1.19 | 1.02 | 1.17 | 0.81 | 1.82 | 1.38 | 0.75 | -0.26 | -1.19 | -1.05 | -1.39 | -0.83 | -1.40 | -1.45 | -1.07 | -0.50 | -0.07 | 0.32 | 1.30 | 1.71 | 1.48 | 1.65 | 1.71 | 0.33 | 1.82 | -1.45 |
| 20 | 2.50 | 1.83 | 2.37 | 1.11 | 1.08 | 1.36 | 1.42 | 0.57 | -0.95 | -0.87 | -1.35 | -1.37 | -0.85 | -0.97 | -0.86 | -0.73 | -0.58 | -0.09 | 0.17 | 0.98 | 1.65 | 1.83 | 1.53 | 1.87 | 0.49 | 2.50 | -1.37 |
| 21 | 2.37 | 2.12 | 1.69 | 2.07 | 1.63 | 1.90 | 1.92 | 0.87 | -1.06 | -1.26 | -1.29 | -1.10 | -1.40 | -0.96 | -0.64 | -0.75 | -0.45 | 0.05 | 0.62 | 1.85 | 1.39 | 1.03 | 1.62 | 1.40 | 0.57 | 2.37 | -1.40 |
| 22 | 1.55 | 1.12 | 0.84 | 0.73 | 0.52 | 0.39 | 0.28 | 0.30 | -0.25 | -0.77 | -1.08 | -1.38 | -1.57 | -1.39 | -1.28 | -1.31 | -0.63 | 0.09 | 0.26 | 0.35 | 0.38 | 0.38 | 0.25 | 0.24 | -0.08 | 1.55 | -1.57 |
| 23 | 0.22 | 0.16 | 0.16 | 0.25 | 0.18 | 0.21 | 0.19 | 0.11 | -0.37 | -0.76 | -1.11 | -1.44 | -1.40 | -1.53 | -1.40 | -1.19 | -0.78 | 0.10 | 0.38 | 0.26 | 0.36 | 0.66 | 0.45 | 0.38 | -0.25 | 0.66 | -1.53 |
| 24 | 0.27 | 0.29 | 0.32 | 0.29 | 0.23 | 0.22 | 0.48 | 0.02 | -0.43 | -0.97 | -1.42 | -1.52 | -1.71 | -1.68 | -0.83 | -0.48 | -0.15 | 0.07 | 0.77 | 1.54 | 0.94 | 1.28 | 1.75 | 1.98 | 0.05 | 1.98 | -1.71 |
| 25 | 2.75 | 1.85 | 2.08 | 2.05 | 2.36 | 2.24 | 1.84 | 1.27 | -0.25 | -0.68 | -0.83 | -0.80 | -0.93 | -0.95 | -0.80 | -0.66 | -0.42 | 0.06 | 0.28 | 1.26 | 1.48 | 1.69 | 0.84 | 1.44 | 0.72 | 2.75 | -0.95 |
| 26 | 0.89 | 0.70 | 0.73 | 0.66 | 0.64 | 0.61 | 0.46 | 0.20 | -0.71 | -1.13 | -1.36 | -1.62 | -1.44 | -1.41 | -1.13 | -0.76 | -0.45 | 0.13 | 0.92 | 1.05 | 1.23 | 0.66 | 0.52 | 0.41 | -0.01 | 1.23 | -1.62 |
| 27 | 0.33 | 0.23 | 0.15 | 0.15 | 0.17 | 0.15 | 0.10 | 0.03 | -0.50 | -0.80 | -1.24 | -1.73 | -1.93 | -1.57 | -1.50 | -0.84 | -0.51 | 0.02 | 0.27 | 1.31 | 1.53 | 2.03 | 2.35 | 1.53 | -0.01 | 2.35 | -1.93 |
| 28 | 0.99 | 0.40 | 0.50 | 0.53 | 0.44 | 0.39 | 0.31 | 0.06 | -0.39 | -0.90 | -1.56 | -1.98 | -1.71 | -1.74 | -1.04 | -0.78 | -0.33 | -0.15 | -0.06 | -0.03 | 0.11 | 0.11 | 0.15 | 0.14 | -0.27 | 0.99 | -1.98 |
| 29 | 0.19 | 0.25 | 0.35 | 0.46 | 1.35 | 1.53 | 1.19 | 0.99 | -0.62 | -1.65 | -2.05 | -1.63 | -1.26 | -1.35 | -0.47 | -0.41 | -0.30 | -0.24 | 0.04 | 0.28 | 0.33 | 0.67 | 0.90 | 0.79 | -0.03 | 1.53 | -2.05 |
| 30 | 0.83 | 0.68 | 1.23 | 0.55 | 1.06 | 0.83 | 1.04 | 0.14 | -0.82 | -0.53 | -0.64 | -0.96 | -1.04 | -1.35 | -1.05 | -0.84 | -0.55 | -0.08 | 0.13 | 0.28 | 0.63 | 1.12 | 0.86 | 1.08 | 0.11 | 1.23 | -1.35 |
| 31 | 1.06 | 0.99 | 1.10 | 0.82 | 0.45 | 0.30 | 0.33 | 0.12 | -0.92 | -0.61 | -1.43 | -1.48 | -0.81 | -1.26 | -0.66 | -0.69 | -0.38 | -0.07 | 0.10 | 0.90 | 1.46 | 1.70 | 1.32 | 1.29 | 0.15 | 1.70 | -1.48 |
| Avg | 1.04 | 0.94 | 0.97 | 0.89 | 0.80 | 0.83 | 0.78 | 0.27 | -0.72 | -1.01 | -1.31 | -1.44 | -1.40 | -1.31 | -1.11 | -0.94 | -0.57 | -0.14 | 0.22 | 0.69 | 0.95 | 0.97 | 0.95 | 1.00 | 0.06 | -- | -- |
| Max | 2.75 | 2.12 | 2.37 | 2.11 | 2.36 | 2.24 | 1.92 | 1.27 | -0.25 | -0.42 | -0.46 | -0.78 | -0.81 | -0.77 | -0.47 | -0.41 | -0.15 | 0.13 | 0.92 | 1.85 | 1.75 | 2.03 | 2.35 | 1.98 | -- | 2.75 | -- |
| Min | -0.19 | -0.33 | -0.45 | -0.42 | -0.29 | -0.36 | -0.37 | -0.43 | -1.31 | -1.66 | -2.17 | -2.32 | -2.23 | -1.94 | -1.63 | -1.45 | -1.03 | -0.62 | -0.13 | -0.14 | -0.08 | -0.07 | -0.14 | -0.13 | -- | -- | -2.32 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, DeltaTemp_C"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.51 | 1.81 | 1.56 | 1.49 | 0.99 | 1.83 | 1.25 | 0.42 | -0.87 | -0.41 | -0.69 | -1.41 | -0.96 | -1.18 | -0.84 | -0.70 | -0.33 | 0.10 | 0.51 | 1.20 | 1.14 | 1.35 | 0.64 | 1.26 | 0.40 | 1.83 | -1.41 |
| 2 | 0.67 | 0.37 | 0.65 | 0.52 | 0.34 | 0.24 | 0.28 | 0.15 | -0.49 | -0.72 | -1.03 | -1.11 | -1.10 | -1.27 | -1.06 | -0.61 | -0.40 | 0.23 | 0.31 | 0.56 | 0.36 | 0.51 | 0.23 | 0.16 | -0.09 | 0.67 | -1.27 |
| 3 | 0.21 | 0.32 | 0.31 | 0.09 | -0.02 | -0.02 | 0.08 | -0.06 | -0.49 | -1.28 | -1.69 | -1.87 | -1.72 | -1.61 | -0.93 | -0.85 | -0.43 | 0.00 | 0.13 | 0.45 | 1.26 | 0.88 | 1.12 | 1.34 | -0.20 | 1.34 | -1.87 |
| 4 | 1.13 | 1.10 | 1.05 | 0.55 | 0.41 | 0.33 | 0.18 | 0.37 | -0.88 | -1.53 | -1.86 | -2.03 | -2.20 | -1.84 | -1.56 | -0.65 | -0.29 | -0.11 | 0.10 | -0.02 | -0.13 | -0.04 | -0.05 | -0.01 | -0.33 | 1.13 | -2.20 |
| 5 | 0.09 | 0.14 | 0.43 | 0.33 | 0.30 | 0.39 | 0.54 | -0.26 | -0.55 | -0.58 | -0.60 | -0.71 | -1.19 | -0.95 | -0.84 | -1.27 | -0.54 | -0.22 | -0.05 | 0.60 | 0.53 | 0.27 | 0.32 | 0.35 | -0.14 | 0.60 | -1.27 |
| 6 | 0.24 | 0.17 | 0.28 | 0.62 | 0.69 | 0.77 | 0.77 | 0.78 | -0.23 | -0.54 | -1.21 | -1.32 | -1.44 | -1.16 | -0.98 | -0.79 | -0.23 | 0.16 | 0.38 | 0.36 | 0.37 | 0.39 | 0.33 | 0.32 | -0.05 | 0.78 | -1.44 |
| 7 | 0.26 | 0.32 | 0.35 | 0.26 | 0.30 | 0.16 | 0.16 | 0.17 | -0.24 | -0.39 | -0.98 | -1.16 | -1.13 | -1.20 | -1.21 | -0.76 | -0.22 | 0.14 | 0.25 | 0.22 | 0.19 | 0.21 | 0.17 | 0.14 | -0.17 | 0.35 | -1.21 |
| 8 | 0.13 | 0.13 | 0.17 | 0.28 | 0.28 | 0.19 | 0.22 | 0.17 | -0.50 | -0.60 | -1.03 | -1.32 | -0.83 | -0.72 | -0.75 | -1.12 | -0.35 | 0.08 | 0.30 | 1.12 | 1.20 | 1.55 | 1.52 | 1.47 | 0.07 | 1.55 | -1.32 |
| 9 | 1.83 | 1.56 | 1.95 | 0.97 | 0.60 | 0.78 | 0.91 | 1.24 | -0.46 | -0.96 | -0.99 | -0.97 | -1.34 | -0.69 | -0.94 | -1.16 | -0.17 | 0.13 | 0.65 | 1.50 | 0.68 | 1.13 | 1.29 | 1.77 | 0.39 | 1.95 | -1.34 |
| 10 | 1.95 | 1.32 | 0.58 | 0.64 | 1.45 | 1.05 | 0.97 | 0.38 | 0.10 | -0.36 | -0.33 | -0.83 | -1.18 | -0.98 | -1.09 | -0.53 | -0.10 | 0.14 | 0.25 | 0.48 | 0.72 | 0.68 | 0.99 | 1.34 | 0.32 | 1.95 | -1.18 |
| 11 | 1.07 | 1.59 | 1.12 | 1.01 | 1.24 | 1.38 | 0.44 | 0.71 | -0.12 | -0.60 | -1.14 | -1.12 | -1.42 | -1.38 | -0.90 | -0.76 | -0.19 | 0.40 | 0.64 | 0.50 | 0.64 | 0.58 | 0.53 | 0.49 | 0.20 | 1.59 | -1.42 |
| 12 | 0.43 | 0.50 | 0.68 | 0.58 | 0.58 | 0.55 | 0.50 | 0.27 | -0.41 | -0.63 | -0.98 | -1.05 | -1.26 | -1.29 | -0.78 | -0.49 | -0.24 | 0.04 | 0.09 | 0.08 | 0.09 | 0.05 | 0.03 | 0.04 | -0.11 | 0.68 | -1.29 |
| 13 | 0.02 | -0.01 | -0.02 | -0.04 | -0.03 | 0.02 | 0.02 | 0.01 | -0.43 | -0.57 | -0.94 | -0.86 | -1.27 | -1.34 | -1.03 | -0.89 | -0.38 | -0.05 | 0.01 | 0.04 | 0.05 | 0.07 | 0.10 | 0.09 | -0.31 | 0.10 | -1.34 |
| 14 | 0.05 | 0.09 | 0.13 | 0.08 | 0.16 | 0.23 | 0.26 | 0.19 | -0.76 | -1.15 | -0.94 | -1.57 | -1.80 | -1.39 | -0.82 | -0.52 | -0.34 | 0.09 | 0.52 | 1.31 | 0.81 | 0.79 | 0.96 | 1.26 | -0.10 | 1.31 | -1.80 |
| 15 | 1.17 | 1.48 | 0.57 | 0.41 | 0.46 | 0.49 | 0.47 | 0.14 | -0.13 | -0.54 | -1.12 | -1.61 | -1.40 | -1.23 | -0.72 | -0.54 | 0.04 | 0.15 | 0.20 | 0.36 | 0.20 | 0.21 | 0.09 | 0.00 | -0.04 | 1.48 | -1.61 |
| 16 | -0.01 | -0.04 | -0.07 | -0.04 | -0.05 | -0.07 | -0.07 | -0.14 | -0.36 | -0.59 | -0.56 | -0.66 | -0.85 | -0.86 | -1.06 | -0.65 | -0.32 | 0.00 | 0.25 | 0.49 | 1.70 | 0.91 | 0.39 | 0.46 | -0.09 | 1.70 | -1.06 |
| 17 | 0.56 | 1.22 | 0.95 | 0.64 | 0.53 | 0.62 | 0.69 | 0.62 | -0.31 | -0.62 | -1.25 | -1.66 | -1.29 | -1.11 | -0.71 | -0.58 | -0.32 | -0.05 | 0.38 | 0.42 | 0.45 | 0.41 | 0.45 | 0.58 | 0.03 | 1.22 | -1.66 |
| 18 | 0.95 | 0.74 | 0.57 | 0.39 | 0.38 | 0.54 | 0.49 | 0.47 | 0.18 | -0.30 | -0.70 | -1.36 | -1.06 | -0.83 | -0.50 | -0.45 | -0.25 | 0.06 | 0.31 | 1.14 | 0.47 | 1.75 | 0.98 | 1.70 | 0.24 | 1.75 | -1.36 |
| 19 | 1.35 | 1.23 | 1.54 | 1.84 | 1.49 | 0.76 | 0.90 | 0.45 | -0.38 | -0.90 | -1.01 | -1.78 | -1.63 | -0.74 | -0.63 | -0.72 | -0.44 | 0.04 | 0.19 | 0.35 | 0.57 | 0.75 | 1.13 | 1.31 | 0.24 | 1.84 | -1.78 |
| 20 | 1.11 | 1.10 | 0.92 | 0.86 | 0.49 | 0.28 | 0.25 | 0.16 | -0.14 | -0.55 | -0.68 | -0.82 | -0.98 | -0.53 | -0.56 | -0.48 | -0.39 | -0.18 | -0.07 | -0.30 | 0.00 | 0.02 | -0.20 | -0.11 | -0.03 | 1.11 | -0.98 |
| 21 | 0.42 | 0.49 | 0.76 | 0.28 | 0.12 | 0.20 | 0.26 | 0.24 | -0.20 | -0.39 | -0.74 | -1.27 | -1.48 | -1.05 | -0.42 | -0.35 | -0.18 | 0.02 | -0.01 | -0.05 | 0.19 | 0.32 | 0.22 | 0.14 | -0.10 | 0.76 | -1.48 |
| 22 | 0.32 | 0.22 | 0.20 | 0.28 | 0.35 | 0.16 | -0.03 | 0.17 | -0.08 | -0.21 | -0.24 | -0.29 | -0.26 | -0.27 | -0.27 | -0.38 | -0.35 | -0.28 | -0.24 | -0.26 | -0.22 | -0.16 | -0.20 | -0.19 | -0.09 | 0.35 | -0.38 |
| 23 | -0.21 | -0.25 | -0.09 | -0.20 | 0.01 | 0.01 | 0.08 | 0.06 | -0.03 | 0.08 | 0.06 | 0.03 | 0.04 | 0.04 | -0.10 | -0.20 | -0.03 | 0.05 | 0.03 | 0.12 | 0.11 | 0.02 | 0.06 | 0.05 | -0.01 | 0.12 | -0.25 |
| 24 | 0.03 | 0.02 | 0.00 | 0.00 | 0.02 | 0.08 | 0.05 | 0.04 | -0.03 | -0.18 | -0.13 | 0.00 | 0.00 | -0.27 | -0.39 | -0.32 | -0.05 | 0.14 | 0.26 | 0.33 | 0.29 | 0.31 | 0.28 | 0.28 | 0.03 | 0.33 | -0.39 |
| 25 | 0.33 | 0.52 | 0.33 | 0.30 | 0.47 | 0.63 | 0.94 | 0.71 | -0.07 | -0.69 | -0.49 | -0.52 | -1.00 | -0.43 | -0.39 | -0.38 | -0.26 | 0.05 | 0.47 | 0.52 | 0.37 | 0.47 | 0.46 | 0.36 | 0.11 | 0.94 | -1.00 |
| 26 | 0.53 | 0.55 | 0.37 | 0.45 | 0.39 | 0.34 | 0.28 | 0.23 | -0.25 | -0.75 | -1.08 | -1.27 | -1.06 | -1.13 | -0.78 | -0.42 | -0.06 | 0.20 | 0.24 | 0.32 | 0.28 | 0.23 | 0.21 | 0.17 | -0.08 | 0.55 | -1.27 |
| 27 | 0.14 | 0.17 | 0.17 | 0.14 | 0.13 | 0.11 | 0.13 | 0.07 | -0.05 | -0.23 | -0.29 | -0.29 | -0.34 | -0.38 | -0.38 | -0.32 | -0.04 | 0.08 | 0.17 | 0.18 | 0.19 | 0.21 | 0.13 | 0.15 | -0.01 | 0.21 | -0.38 |
| 28 | 0.17 | 0.15 | 0.23 | 0.30 | 0.29 | 0.20 | 0.25 | 0.15 | -0.07 | -0.24 | -0.52 | -0.58 | -0.85 | -1.01 | -0.76 | -0.46 | -0.12 | 0.10 | 0.21 | 0.24 | 0.19 | 0.17 | 0.15 | 0.14 | -0.07 | 0.30 | -1.01 |
| 29 | 0.12 | 0.14 | 0.16 | 0.17 | 0.21 | 0.19 | 0.14 | 0.13 | -0.08 | -0.37 | -0.72 | -0.99 | -1.33 | -1.55 | -0.99 | -0.82 | -0.23 | 0.19 | 0.99 | 0.62 | 0.68 | 0.86 | 1.51 | 1.22 | 0.01 | 1.51 | -1.55 |
| 30 | 1.15 | 1.02 | 0.95 | 0.90 | 1.25 | 2.06 | 1.32 | 1.04 | 0.41 | -0.15 | -0.29 | -0.28 | -0.41 | -0.49 | -0.60 | -0.41 | -0.09 | 0.11 | 0.34 | 0.71 | 0.47 | 0.79 | 0.62 | 0.69 | 0.46 | 2.06 | -0.60 |
| Avg | 0.59 | 0.61 | 0.56 | 0.47 | 0.46 | 0.48 | 0.42 | 0.30 | -0.26 | -0.57 | -0.81 | -1.02 | -1.09 | -0.96 | -0.77 | -0.62 | -0.24 | 0.06 | 0.26 | 0.45 | 0.46 | 0.52 | 0.48 | 0.57 | 0.02 | -- | -- |
| Max | 1.95 | 1.81 | 1.95 | 1.84 | 1.49 | 2.06 | 1.32 | 1.24 | 0.41 | 0.08 | 0.06 | 0.03 | 0.04 | 0.04 | -0.10 | -0.20 | 0.04 | 0.40 | 0.99 | 1.50 | 1.70 | 1.75 | 1.52 | 1.77 | -- | 2.06 | -- |
| Min | -0.21 | -0.25 | -0.09 | -0.20 | -0.05 | -0.07 | -0.07 | -0.26 | -0.88 | -1.53 | -1.86 | -2.03 | -2.20 | -1.84 | -1.56 | -1.27 | -0.54 | -0.28 | -0.24 | -0.30 | -0.22 | -0.16 | -0.20 | -0.19 | -- | -- | -2.20 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, DeltaTemp_C"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.12 | 1.18 | 1.24 | 0.89 | 1.04 | 1.38 | 0.98 | 0.59 | 0.15 | -0.69 | -0.84 | -1.23 | -1.22 | -0.48 | -0.50 | -0.39 | -0.21 | 0.13 | 0.73 | 1.09 | 1.45 | 1.49 | 0.99 | 1.14 | 0.42 | 1.49 | -1.23 |
| 2 | 0.95 | 1.34 | 0.96 | 0.74 | 0.86 | 1.90 | 1.44 | 1.57 | 0.46 | -0.43 | -0.81 | -0.64 | -0.50 | -0.47 | -0.41 | -0.43 | -0.34 | 0.00 | 0.40 | 1.07 | 1.01 | 0.98 | 0.99 | 0.97 | 0.48 | 1.90 | -0.81 |
| 3 | 1.56 | 1.17 | 1.58 | 1.22 | 1.29 | 1.53 | 1.33 | 1.10 | 0.16 | -0.68 | -1.33 | -1.63 | -1.56 | -1.66 | -1.49 | -1.10 | -0.37 | 0.54 | 1.58 | 1.25 | 1.05 | 0.76 | 0.98 | 0.64 | 0.33 | 1.58 | -1.66 |
| 4 | 0.54 | 0.75 | 1.73 | 1.46 | 0.88 | 0.54 | 0.53 | 0.41 | -0.11 | -0.57 | -0.41 | -0.20 | -0.26 | -0.28 | -0.26 | -0.27 | -0.36 | -0.16 | -0.14 | -0.13 | -0.13 | -0.06 | -0.18 | -0.21 | 0.13 | 1.73 | -0.57 |
| 5 | -0.28 | -0.18 | -0.28 | -0.22 | -0.34 | -0.29 | 0.03 | -0.30 | -0.21 | -0.43 | -0.54 | -0.58 | -0.60 | -0.77 | -0.77 | -0.73 | -0.39 | -0.14 | 0.06 | 0.22 | 0.39 | 0.81 | 1.34 | 1.53 | -0.11 | 1.53 | -0.77 |
| 6 | 1.37 | 1.47 | 1.29 | 1.64 | 1.26 | 0.97 | 0.44 | 0.43 | -0.31 | -1.08 | -0.95 | -1.17 | -1.23 | -0.94 | -0.84 | -0.71 | -0.40 | -0.10 | 0.25 | 0.75 | 0.60 | 1.08 | 0.67 | 1.39 | 0.25 | 1.64 | -1.23 |
| 7 | 0.94 | 1.33 | 1.18 | 1.77 | 1.40 | 1.76 | 1.02 | 0.77 | 0.04 | -0.59 | -0.92 | -1.61 | -0.99 | -1.77 | -1.16 | -0.68 | -0.48 | -0.09 | -0.09 | -0.11 | -0.03 | -0.08 | -0.10 | -0.15 | 0.06 | 1.77 | -1.77 |
| 8 | -0.17 | -0.09 | -0.07 | -0.10 | -0.11 | -0.06 | -0.02 | -0.04 | -0.14 | -0.24 | -0.37 | -0.52 | -0.50 | -0.62 | -1.19 | -0.79 | -0.29 | -0.07 | -0.05 | -0.09 | -0.17 | -0.15 | 0.19 | -0.04 | -0.24 | 0.19 | -1.19 |
| 9 | -0.05 | 0.31 | 1.17 | 1.20 | 1.45 | 0.74 | 0.75 | 0.80 | -0.21 | -0.72 | -0.83 | -1.07 | -1.18 | -0.99 | -0.91 | -0.67 | -0.28 | 0.05 | 0.11 | 0.28 | 0.32 | 0.39 | 0.34 | 0.50 | 0.06 | 1.45 | -1.18 |
| 10 | 0.35 | 0.56 | 0.52 | 0.27 | 0.32 | 0.48 | 0.36 | 0.24 | 0.07 | -0.21 | -0.39 | -0.46 | -0.50 | -0.43 | -0.54 | -0.31 | -0.12 | 0.09 | 0.25 | 0.36 | 0.29 | 0.18 | 0.19 | 0.18 | 0.07 | 0.56 | -0.54 |
| 11 | 0.16 | 0.16 | 0.23 | 0.15 | 0.16 | 0.28 | 0.29 | 0.16 | -0.02 | -0.26 | -0.45 | -0.56 | -0.51 | -0.67 | -0.60 | -0.39 | -0.11 | 0.11 | 0.16 | 0.25 | 0.25 | 0.19 | 0.20 | 0.17 | -0.03 | 0.29 | -0.67 |
| 12 | 0.22 | 0.16 | 0.16 | 0.16 | 0.13 | 0.15 | 0.14 | 0.17 | -0.09 | -0.44 | -0.70 | -0.83 | -0.90 | -0.83 | -0.50 | -0.22 | -0.05 | 0.08 | 0.25 | 0.79 | 0.60 | 0.52 | 0.84 | 0.81 | 0.03 | 0.84 | -0.90 |
| 13 | 1.07 | 1.19 | 1.39 | 0.96 | 0.88 | 1.11 | 1.04 | 0.90 | -0.08 | -0.60 | -0.80 | -0.82 | -0.63 | -0.57 | -0.59 | -0.51 | -0.35 | -0.03 | 0.30 | 0.59 | 0.81 | 1.05 | 0.79 | 1.53 | 0.36 | 1.53 | -0.82 |
| 14 | 1.07 | 0.81 | 1.02 | 1.29 | 1.36 | 0.95 | 0.47 | 0.45 | 0.00 | -0.60 | -0.80 | -0.87 | -0.86 | -0.83 | -0.71 | -0.48 | -0.22 | 0.14 | 0.33 | 0.20 | 0.49 | 0.69 | 0.60 | 0.85 | 0.22 | 1.36 | -0.87 |
| 15 | 0.33 | 0.26 | 0.26 | 0.26 | 0.22 | 0.24 | 0.45 | 0.69 | 0.33 | -0.58 | -0.95 | -0.98 | -0.91 | -1.00 | -0.70 | -0.53 | -0.38 | 0.13 | 0.52 | 0.59 | 0.49 | 0.55 | 0.46 | 0.34 | 0.00 | 0.69 | -1.00 |
| 16 | 0.38 | 0.46 | 0.30 | 0.37 | 0.47 | 0.56 | 0.88 | 0.97 | 0.07 | -0.52 | -0.86 | -1.12 | -1.43 | -1.02 | -0.43 | -0.33 | 0.13 | 0.74 | 1.44 | 0.98 | 0.70 | 1.59 | 0.94 | 1.08 | 0.26 | 1.59 | -1.43 |
| 17 | 0.57 | 0.83 | 1.13 | 0.62 | 0.48 | 0.40 | 0.49 | 0.43 | 0.06 | -0.55 | -0.96 | -0.87 | -0.84 | -0.72 | -0.51 | -0.37 | -0.17 | 0.32 | 0.43 | 0.48 | 0.49 | 0.31 | 0.67 | 0.41 | 0.13 | 1.13 | -0.96 |
| 18 | 0.25 | 0.30 | 0.32 | 0.40 | 0.31 | 0.27 | 0.18 | 0.12 | 0.05 | -0.02 | -0.31 | -0.49 | -0.44 | -0.67 | -0.80 | -0.45 | -0.02 | 0.33 | 0.74 | 0.79 | 0.91 | 0.67 | 1.02 | 1.38 | 0.20 | 1.38 | -0.80 |
| 19 | 1.48 | 0.72 | 0.54 | 0.83 | 0.95 | 0.68 | 0.61 | 0.52 | -0.07 | -0.78 | -1.30 | -1.74 | -1.68 | -1.51 | -1.56 | -1.07 | -0.40 | -0.01 | 0.19 | 0.06 | -0.23 | -0.26 | -0.30 | -0.30 | -0.19 | 1.48 | -1.74 |
| 20 | -0.27 | -0.28 | -0.07 | -0.03 | -0.03 | -0.13 | -0.22 | 0.04 | 0.12 | -0.18 | -0.69 | -0.83 | -0.74 | -0.86 | -0.40 | -0.25 | -0.31 | -0.17 | -0.19 | -0.14 | -0.21 | -0.17 | -0.20 | -0.29 | -0.27 | 0.12 | -0.86 |
| 21 | -0.27 | -0.15 | -0.14 | -0.14 | -0.14 | -0.14 | -0.14 | -0.12 | -0.15 | -0.37 | -0.28 | -0.30 | -0.37 | -0.28 | -0.33 | -0.24 | -0.21 | 0.14 | 0.48 | 0.60 | 0.35 | 0.88 | 1.15 | 0.93 | 0.03 | 1.15 | -0.37 |
| 22 | 1.05 | 1.37 | 1.72 | 1.59 | 1.28 | 0.93 | 0.77 | 0.67 | 0.17 | -0.53 | -0.56 | -0.86 | -1.10 | -0.68 | -0.44 | -0.35 | -0.25 | -0.01 | 0.39 | 0.97 | 0.72 | 0.94 | 0.76 | 0.55 | 0.38 | 1.72 | -1.10 |
| 23 | 0.56 | 0.57 | 0.50 | 0.40 | 0.39 | 0.45 | 0.49 | 0.43 | 0.12 | -0.24 | -0.35 | -0.64 | -0.77 | -0.78 | -0.67 | -0.45 | -0.12 | 0.25 | 0.42 | 0.42 | 0.44 | 0.42 | 0.43 | 0.47 | 0.11 | 0.57 | -0.78 |
| 24 | 0.47 | 0.41 | 0.49 | 0.48 | 0.48 | 0.57 | 0.36 | 0.45 | 0.22 | -0.44 | -0.92 | -0.76 | -0.84 | -0.94 | -0.97 | -0.61 | -0.26 | 0.36 | 0.88 | 1.30 | 0.64 | 0.69 | 0.49 | 0.37 | 0.12 | 1.30 | -0.97 |
| 25 | 0.38 | 0.34 | 0.30 | 0.29 | 0.29 | 0.43 | 0.35 | 0.14 | -0.04 | -0.38 | -0.77 | -1.00 | -0.84 | -0.69 | -0.69 | -0.48 | -0.16 | 0.40 | 0.50 | 0.23 | 0.20 | 0.20 | 0.19 | 0.18 | -0.03 | 0.50 | -1.00 |
| 26 | 0.18 | 0.16 | 0.15 | 0.13 | 0.21 | 0.19 | 0.20 | 0.25 | 0.01 | -0.39 | -0.59 | -0.85 | -0.90 | -0.90 | -0.71 | -0.57 | -0.11 | 0.17 | 0.34 | 0.33 | 0.84 | 0.74 | 0.57 | 0.57 | 0.00 | 0.84 | -0.90 |
| 27 | 0.56 | 0.65 | 0.29 | 0.29 | 0.33 | 0.33 | 0.50 | 0.34 | 0.11 | -0.38 | -0.71 | -0.85 | -0.97 | -0.80 | -0.74 | -0.48 | -0.18 | 0.13 | 0.24 | 0.40 | 0.56 | 0.56 | 0.57 | 1.19 | 0.08 | 1.19 | -0.97 |
| 28 | 1.12 | 1.07 | 1.50 | 1.47 | 0.43 | 0.70 | 0.79 | 0.57 | 0.29 | -0.19 | -0.62 | -0.86 | -0.93 | -1.05 | -1.04 | -0.91 | -0.36 | 0.05 | 0.51 | 0.48 | 0.44 | 0.40 | 0.74 | 1.02 | 0.23 | 1.50 | -1.05 |
| 29 | 0.63 | 0.49 | 0.55 | 0.51 | 1.14 | 1.33 | 0.50 | 0.44 | 0.26 | -0.68 | -0.84 | -0.81 | -0.98 | -0.76 | -0.76 | -0.58 | -0.29 | 0.19 | 0.59 | 0.30 | 0.33 | 0.43 | 0.47 | 0.56 | 0.13 | 1.33 | -0.98 |
| 30 | 0.55 | 1.30 | 0.84 | 1.12 | 0.89 | 0.86 | 1.17 | 1.17 | 0.75 | -0.33 | -0.63 | -0.69 | -0.55 | -0.77 | -0.54 | -0.43 | -0.23 | 0.12 | 0.78 | 1.43 | 1.12 | 1.17 | 1.72 | 1.25 | 0.50 | 1.72 | -0.77 |
| 31 | 1.29 | 1.37 | 0.77 | 0.60 | 0.66 | 0.71 | 0.60 | 0.53 | 0.69 | -0.39 | -0.33 | -0.55 | -0.69 | -0.87 | -0.88 | -0.73 | -0.48 | 0.34 | 0.48 | 0.44 | 0.60 | 0.81 | 1.44 | 0.66 | 0.30 | 1.44 | -0.88 |
| Avg | 0.58 | 0.65 | 0.70 | 0.66 | 0.61 | 0.64 | 0.54 | 0.48 | 0.09 | -0.47 | -0.70 | -0.85 | -0.85 | -0.83 | -0.73 | -0.53 | -0.25 | 0.13 | 0.42 | 0.52 | 0.50 | 0.57 | 0.61 | 0.64 | 0.13 | -- | -- |
| Max | 1.56 | 1.47 | 1.73 | 1.77 | 1.45 | 1.90 | 1.44 | 1.57 | 0.75 | -0.02 | -0.28 | -0.20 | -0.26 | -0.28 | -0.26 | -0.22 | 0.13 | 0.74 | 1.58 | 1.43 | 1.45 | 1.59 | 1.72 | 1.53 | -- | 1.90 | -- |
| Min | -0.28 | -0.28 | -0.28 | -0.22 | -0.34 | -0.29 | -0.22 | -0.30 | -0.31 | -1.08 | -1.33 | -1.74 | -1.68 | -1.77 | -1.56 | -1.10 | -0.48 | -0.17 | -0.19 | -0.14 | -0.23 | -0.26 | -0.30 | -0.30 | -- | -- | -1.77 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, Temp_2m_C"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 21.0 | 21.1 | 21.0 | 20.5 | 20.2 | 20.4 | 19.6 | 21.5 | 24.3 | 26.4 | 28.4 | 28.9 | 29.6 | 29.9 | 29.9 | 30.0 | 29.7 | 28.7 | 27.3 | 25.9 | 24.8 | 24.5 | 23.3 | 23.0 | 25.0 | 30.0 | 19.6 |
| 2 | 22.2 | 21.5 | 21.3 | 20.8 | 20.1 | 19.7 | 19.9 | 21.4 | 24.2 | 26.0 | 27.1 | 27.4 | 28.3 | 28.7 | 29.0 | 29.1 | 28.7 | 27.8 | 26.5 | 25.4 | 24.4 | 23.5 | 23.2 | 22.8 | 24.5 | 29.1 | 19.7 |
| 3 | 23.0 | 22.1 | 21.6 | 20.4 | 19.7 | 19.4 | 19.6 | 21.2 | 24.0 | 25.4 | 26.7 | 28.1 | 28.7 | 28.7 | 29.0 | 29.3 | 28.8 | 27.8 | 26.0 | 24.8 | 23.9 | 23.3 | 22.2 | 21.8 | 24.4 | 29.3 | 19.4 |
| 4 | 21.1 | 20.5 | 20.1 | 19.7 | 18.5 | 17.8 | 18.2 | 19.9 | 22.2 | 23.6 | 25.1 | 25.4 | 26.1 | 26.3 | 27.2 | 26.5 | 25.8 | 24.7 | 23.3 | 22.3 | 21.0 | 20.5 | 20.5 | 19.7 | 22.3 | 27.2 | 17.8 |
| 5 | 19.0 | 18.5 | 18.2 | 17.4 | 16.8 | 16.7 | 17.4 | 18.4 | 19.4 | 20.6 | 21.4 | 22.8 | 24.3 | 25.2 | 25.9 | 25.8 | 25.0 | 23.9 | 22.4 | 21.7 | 21.0 | 20.5 | 20.5 | 21.2 | 21.0 | 25.9 | 16.7 |
| 6 | 20.1 | 19.6 | 20.0 | 20.1 | 18.3 | 16.7 | 17.6 | 21.3 | 22.3 | 23.5 | 24.1 | 25.5 | 27.3 | 28.3 | 29.7 | 29.4 | 29.4 | 28.1 | 26.5 | 25.3 | 23.9 | 23.6 | 23.4 | 23.6 | 23.7 | 29.7 | 16.7 |
| 7 | 23.7 | 22.1 | 22.1 | 22.8 | 22.3 | 21.2 | 22.6 | 23.0 | 24.4 | 26.3 | 27.7 | 29.2 | 31.1 | 31.4 | 31.7 | 31.6 | 29.7 | 28.7 | 27.7 | 26.1 | 25.9 | 25.5 | 24.1 | 23.5 | 26.0 | 31.7 | 21.2 |
| 8 | 22.5 | 22.5 | 21.6 | 22.5 | 22.8 | 20.8 | 19.9 | 22.1 | 25.4 | 27.2 | 28.7 | 28.6 | 29.3 | 29.3 | 29.5 | 29.6 | 28.8 | 27.3 | 25.2 | 24.6 | 24.1 | 23.4 | 22.3 | 21.3 | 25.0 | 29.6 | 19.9 |
| 9 | 20.6 | 20.7 | 20.6 | 20.3 | 20.8 | 20.2 | 18.9 | 19.9 | 23.4 | 25.1 | 26.9 | 28.3 | 29.0 | 28.9 | 29.3 | 29.0 | 27.1 | 24.9 | 23.3 | 22.0 | 20.7 | 19.4 | 18.6 | 17.6 | 23.1 | 29.3 | 17.6 |
| 10 | 16.5 | 16.1 | 16.1 | 15.9 | 14.9 | 14.1 | 13.7 | 10.0 | 9.9 | 10.3 | 10.8 | 11.9 | 13.9 | 15.0 | 15.5 | 16.1 | 16.0 | 15.6 | 14.8 | 13.9 | 13.6 | 12.9 | 12.9 | 13.0 | 13.9 | 16.5 | 9.9 |
| 11 | 12.1 | 12.4 | 11.7 | 11.5 | 11.9 | 11.6 | 11.7 | 12.4 | 15.2 | 16.8 | 18.8 | 20.0 | 21.0 | 21.1 | 21.5 | 22.1 | 21.4 | 20.3 | 19.1 | 17.8 | 16.8 | 16.0 | 15.6 | 15.1 | 16.4 | 22.1 | 11.5 |
| 12 | 15.6 | 15.6 | 15.7 | 15.2 | 15.9 | 16.4 | 15.8 | 17.4 | 20.6 | 22.5 | 24.3 | 25.9 | 26.7 | 26.9 | 26.4 | 25.9 | 25.4 | 24.3 | 22.9 | 21.7 | 20.4 | 20.4 | 19.8 | 18.7 | 20.9 | 26.9 | 15.2 |
| 13 | 19.0 | 18.5 | 18.0 | 17.9 | 17.4 | 17.6 | 17.5 | 18.1 | 21.8 | 23.8 | 24.7 | 26.1 | 26.4 | 26.7 | 26.0 | 26.5 | 26.1 | 24.5 | 22.8 | 21.0 | 20.3 | 20.0 | 19.3 | 18.6 | 21.6 | 26.7 | 17.4 |
| 14 | 18.2 | 17.2 | 16.6 | 16.1 | 15.7 | 15.4 | 15.5 | 16.0 | 19.4 | 20.8 | 21.9 | 23.4 | 23.6 | 24.1 | 24.1 | 24.1 | 23.5 | 22.3 | 20.8 | 20.4 | 18.9 | 17.8 | 17.5 | 17.1 | 19.6 | 24.1 | 15.4 |
| 15 | 18.1 | 17.7 | 17.3 | 16.7 | 17.3 | 16.8 | 16.3 | 17.0 | 19.5 | 21.9 | 22.6 | 23.3 | 23.7 | 23.8 | 24.1 | 23.8 | 23.1 | 21.9 | 20.5 | 19.7 | 18.5 | 17.6 | 17.1 | 16.4 | 19.8 | 24.1 | 16.3 |
| 16 | 15.7 | 15.8 | 15.3 | 15.7 | 14.3 | 13.7 | 14.5 | 16.0 | 17.8 | 19.7 | 21.6 | 22.4 | 22.9 | 23.9 | 23.9 | 23.7 | 23.1 | 21.9 | 20.2 | 19.3 | 18.0 | 17.1 | 16.5 | 15.7 | 18.7 | 23.9 | 13.7 |
| 17 | 15.6 | 15.3 | 16.0 | 16.1 | 15.9 | 15.4 | 14.8 | 15.5 | 18.5 | 20.1 | 22.1 | 23.3 | 23.5 | 23.8 | 24.3 | 23.9 | 23.3 | 21.9 | 20.4 | 19.5 | 18.4 | 17.6 | 17.2 | 16.4 | 19.1 | 24.3 | 14.8 |
| 18 | 16.4 | 15.8 | 15.5 | 15.2 | 15.1 | 14.6 | 14.2 | 15.7 | 18.8 | 21.0 | 22.8 | 23.7 | 24.8 | 24.8 | 25.4 | 25.3 | 24.3 | 23.0 | 21.8 | 19.9 | 18.9 | 18.4 | 17.8 | 18.2 | 19.6 | 25.4 | 14.2 |
| 19 | 17.8 | 17.5 | 17.1 | 16.8 | 17.7 | 16.1 | 16.0 | 17.4 | 20.1 | 23.2 | 24.0 | 25.4 | 25.8 | 27.2 | 27.8 | 27.4 | 26.3 | 24.7 | 23.2 | 21.3 | 20.2 | 19.3 | 18.9 | 18.0 | 21.2 | 27.8 | 16.0 |
| 20 | 17.9 | 17.4 | 17.2 | 18.3 | 17.0 | 16.0 | 15.4 | 16.1 | 20.4 | 22.0 | 23.7 | 24.9 | 25.1 | 25.5 | 25.5 | 25.5 | 25.2 | 23.8 | 22.3 | 20.7 | 19.4 | 18.9 | 18.6 | 17.9 | 20.6 | 25.5 | 15.4 |
| 21 | 18.0 | 17.7 | 17.3 | 17.0 | 16.5 | 16.0 | 15.5 | 17.3 | 21.3 | 23.0 | 24.6 | 25.3 | 26.8 | 26.9 | 26.6 | 26.7 | 26.0 | 24.7 | 23.1 | 21.3 | 21.0 | 19.9 | 19.6 | 19.8 | 21.3 | 26.9 | 15.5 |
| 22 | 20.2 | 21.0 | 20.5 | 19.9 | 21.4 | 21.1 | 20.2 | 19.6 | 22.2 | 23.5 | 24.9 | 26.6 | 27.7 | 28.6 | 29.2 | 29.4 | 28.7 | 27.1 | 26.0 | 25.3 | 24.8 | 24.4 | 24.0 | 23.9 | 24.2 | 29.4 | 19.6 |
| 23 | 23.4 | 22.9 | 22.3 | 21.8 | 22.1 | 22.5 | 22.2 | 22.4 | 23.5 | 24.8 | 26.6 | 28.1 | 29.2 | 30.5 | 30.7 | 30.7 | 30.1 | 28.6 | 27.3 | 26.6 | 26.2 | 24.7 | 24.9 | 24.9 | 25.7 | 30.7 | 21.8 |
| 24 | 25.0 | 24.3 | 23.5 | 23.0 | 22.5 | 21.9 | 21.4 | 22.6 | 24.1 | 26.0 | 27.6 | 28.6 | 29.9 | 30.2 | 29.1 | 28.1 | 26.7 | 25.9 | 24.7 | 23.7 | 23.2 | 21.6 | 20.7 | 20.2 | 24.8 | 30.2 | 20.2 |
| 25 | 19.5 | 19.1 | 18.8 | 18.5 | 17.8 | 17.7 | 17.9 | 17.9 | 21.1 | 23.3 | 25.0 | 25.6 | 26.3 | 26.7 | 26.7 | 26.6 | 25.8 | 24.3 | 23.3 | 21.7 | 20.9 | 20.1 | 20.0 | 19.6 | 21.8 | 26.7 | 17.7 |
| 26 | 20.7 | 20.6 | 20.2 | 19.3 | 18.9 | 19.2 | 20.9 | 20.9 | 22.5 | 23.9 | 25.2 | 26.3 | 27.4 | 28.1 | 28.5 | 28.2 | 27.7 | 25.9 | 24.5 | 23.1 | 22.5 | 23.6 | 23.2 | 23.3 | 23.5 | 28.5 | 18.9 |
| 27 | 23.6 | 23.4 | 22.5 | 21.9 | 21.5 | 21.4 | 21.1 | 21.4 | 22.7 | 23.9 | 25.4 | 27.4 | 28.8 | 29.3 | 29.7 | 28.6 | 27.4 | 25.8 | 23.9 | 22.2 | 21.6 | 20.5 | 20.1 | 20.3 | 23.9 | 29.7 | 20.1 |
| 28 | 20.3 | 20.4 | 20.0 | 19.2 | 18.6 | 18.6 | 18.7 | 18.9 | 20.1 | 21.9 | 23.0 | 24.1 | 24.5 | 25.1 | 24.3 | 23.7 | 22.9 | 22.3 | 21.4 | 20.4 | 19.8 | 19.7 | 19.6 | 19.3 | 21.1 | 25.1 | 18.6 |
| 29 | 18.9 | 18.2 | 17.6 | 16.9 | 15.7 | 15.2 | 14.9 | 15.2 | 18.1 | 21.1 | 22.5 | 22.7 | 22.6 | 22.7 | 19.9 | 18.6 | 17.3 | 16.4 | 15.7 | 15.1 | 14.5 | 13.9 | 13.3 | 13.1 | 17.5 | 22.7 | 13.1 |
| 30 | 12.8 | 12.5 | 12.0 | 11.2 | 11.0 | 10.7 | 10.4 | 10.7 | 13.7 | 14.1 | 14.6 | 15.7 | 16.4 | 17.4 | 17.4 | 17.3 | 17.0 | 15.8 | 15.0 | 14.7 | 13.8 | 13.3 | 12.5 | 11.9 | 13.8 | 17.4 | 10.4 |
| 31 | 11.6 | 11.6 | 10.9 | 11.4 | 12.1 | 12.4 | 12.1 | 12.2 | 13.8 | 15.6 | 18.1 | 19.4 | 19.2 | 20.1 | 19.8 | 20.0 | 19.3 | 17.9 | 16.8 | 15.5 | 14.5 | 14.0 | 13.5 | 12.9 | 15.2 | 20.1 | 10.9 |
| Avg | 19.0 | 18.7 | 18.3 | 18.1 | 17.8 | 17.3 | 17.2 | 18.0 | 20.5 | 22.2 | 23.6 | 24.7 | 25.5 | 26.0 | 26.0 | 25.9 | 25.1 | 23.9 | 22.5 | 21.4 | 20.5 | 19.9 | 19.4 | 19.0 | 21.3 | -- | -- |
| Max | 25.0 | 24.3 | 23.5 | 23.0 | 22.8 | 22.5 | 22.6 | 23.0 | 25.4 | 27.2 | 28.7 | 29.2 | 31.1 | 31.4 | 31.7 | 31.6 | 30.1 | 28.7 | 27.7 | 26.6 | 26.2 | 25.5 | 24.9 | 24.9 | -- | 31.7 | -- |
| Min | 11.6 | 11.6 | 10.9 | 11.2 | 11.0 | 10.7 | 10.4 | 10.0 | 9.9 | 10.3 | 10.8 | 11.9 | 13.9 | 15.0 | 15.5 | 16.1 | 16.0 | 15.6 | 14.8 | 13.9 | 13.6 | 12.9 | 12.5 | 11.9 | -- | -- | 9.9 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, Temp_2m_C"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 12.7 | 12.6 | 12.3 | 12.4 | 12.3 | 12.3 | 13.0 | 14.5 | 17.4 | 18.8 | 20.3 | 22.0 | 23.0 | 24.4 | 24.7 | 23.9 | 22.4 | 20.9 | 19.8 | 17.9 | 17.9 | 17.6 | 19.4 | 18.1 | 17.9 | 24.7 | 12.3 |
| 2 | 19.0 | 19.9 | 18.7 | 19.4 | 19.2 | 19.7 | 20.2 | 20.0 | 21.4 | 22.4 | 23.9 | 24.8 | 25.7 | 26.8 | 27.3 | 26.8 | 26.6 | 25.3 | 24.3 | 22.9 | 22.6 | 20.9 | 21.1 | 20.5 | 22.5 | 27.3 | 18.7 |
| 3 | 20.0 | 19.2 | 19.2 | 18.3 | 18.1 | 17.8 | 17.4 | 17.6 | 18.8 | 21.0 | 22.4 | 23.5 | 24.4 | 24.8 | 23.8 | 23.7 | 23.0 | 21.7 | 20.8 | 19.1 | 18.3 | 17.3 | 16.8 | 16.6 | 20.2 | 24.8 | 16.6 |
| 4 | 16.4 | 16.7 | 15.8 | 17.1 | 16.8 | 16.4 | 15.5 | 14.6 | 18.1 | 20.8 | 21.8 | 22.9 | 23.9 | 24.0 | 23.8 | 22.5 | 21.8 | 21.2 | 20.1 | 19.1 | 18.6 | 18.4 | 15.8 | 13.3 | 19.0 | 24.0 | 13.3 |
| 5 | 12.3 | 12.2 | 12.8 | 13.1 | 13.5 | 13.4 | 12.5 | 12.7 | 14.4 | 15.0 | 15.7 | 16.6 | 17.9 | 18.2 | 18.5 | 19.4 | 18.3 | 17.4 | 16.4 | 15.4 | 15.4 | 15.6 | 14.8 | 13.5 | 15.2 | 19.4 | 12.2 |
| 6 | 13.7 | 12.4 | 11.9 | 10.3 | 10.1 | 9.9 | 10.1 | 10.9 | 13.8 | 16.2 | 18.0 | 18.9 | 20.4 | 21.4 | 22.3 | 22.8 | 21.8 | 20.9 | 19.5 | 19.9 | 18.4 | 18.5 | 19.2 | 19.9 | 16.7 | 22.8 | 9.9 |
| 7 | 19.5 | 18.2 | 18.2 | 19.5 | 18.8 | 17.9 | 17.6 | 17.3 | 18.3 | 19.4 | 21.3 | 22.3 | 23.3 | 24.3 | 24.9 | 24.6 | 23.7 | 22.5 | 21.6 | 21.2 | 21.0 | 20.7 | 20.4 | 20.0 | 20.7 | 24.9 | 17.3 |
| 8 | 19.7 | 19.4 | 19.1 | 18.9 | 18.8 | 18.7 | 18.2 | 18.2 | 19.9 | 20.5 | 22.3 | 23.8 | 24.6 | 25.0 | 25.1 | 25.6 | 24.2 | 22.6 | 21.8 | 20.1 | 19.1 | 18.4 | 18.0 | 17.4 | 20.8 | 25.6 | 17.4 |
| 9 | 16.9 | 16.9 | 16.6 | 17.6 | 17.6 | 16.8 | 16.4 | 16.2 | 19.9 | 22.8 | 25.2 | 26.0 | 25.8 | 25.2 | 25.8 | 26.2 | 24.5 | 23.0 | 21.7 | 19.8 | 20.0 | 19.0 | 19.0 | 18.2 | 20.7 | 26.2 | 16.2 |
| 10 | 18.0 | 18.0 | 18.7 | 18.5 | 17.4 | 17.9 | 17.3 | 18.7 | 19.6 | 21.7 | 23.2 | 24.9 | 26.4 | 26.6 | 27.0 | 26.4 | 25.6 | 24.9 | 24.5 | 23.8 | 22.5 | 22.2 | 21.4 | 20.5 | 21.9 | 27.0 | 17.3 |
| 11 | 20.7 | 19.8 | 19.9 | 19.7 | 19.8 | 19.2 | 20.7 | 19.8 | 21.7 | 24.4 | 25.7 | 26.5 | 28.1 | 28.9 | 29.0 | 28.9 | 27.8 | 26.5 | 24.7 | 24.1 | 22.8 | 24.0 | 24.0 | 23.7 | 23.8 | 29.0 | 19.2 |
| 12 | 24.0 | 22.8 | 21.8 | 21.4 | 20.0 | 20.9 | 21.2 | 23.1 | 24.1 | 25.1 | 26.4 | 27.0 | 27.7 | 27.9 | 27.4 | 26.6 | 25.9 | 24.7 | 23.8 | 22.8 | 21.8 | 20.8 | 20.3 | 19.9 | 23.6 | 27.9 | 19.9 |
| 13 | 19.2 | 18.9 | 18.4 | 17.8 | 17.7 | 17.6 | 17.0 | 17.3 | 18.1 | 18.9 | 20.4 | 21.1 | 22.1 | 22.8 | 22.8 | 22.7 | 21.7 | 20.6 | 19.8 | 19.6 | 19.2 | 18.6 | 18.3 | 18.0 | 19.5 | 22.8 | 17.0 |
| 14 | 17.4 | 16.8 | 16.4 | 16.2 | 15.9 | 15.8 | 15.8 | 15.7 | 17.6 | 19.1 | 20.5 | 22.9 | 24.2 | 24.7 | 24.7 | 24.1 | 23.2 | 21.6 | 20.5 | 19.1 | 19.0 | 18.8 | 18.8 | 18.3 | 19.5 | 24.7 | 15.7 |
| 15 | 17.7 | 16.7 | 17.9 | 18.2 | 17.3 | 16.9 | 17.6 | 17.6 | 18.4 | 19.7 | 21.1 | 23.0 | 23.2 | 23.3 | 22.7 | 22.5 | 20.5 | 20.1 | 20.2 | 16.8 | 17.2 | 16.5 | 16.1 | 15.6 | 19.0 | 23.3 | 15.6 |
| 16 | 15.1 | 15.0 | 15.0 | 14.7 | 14.5 | 14.2 | 13.8 | 13.3 | 13.6 | 14.2 | 14.7 | 15.7 | 16.5 | 17.2 | 18.2 | 17.9 | 17.3 | 16.1 | 15.3 | 14.8 | 13.7 | 14.0 | 14.1 | 13.9 | 15.1 | 18.2 | 13.3 |
| 17 | 13.6 | 12.7 | 12.7 | 12.7 | 12.6 | 12.0 | 12.1 | 12.2 | 13.8 | 16.0 | 17.7 | 19.0 | 19.2 | 19.7 | 20.0 | 20.3 | 19.8 | 18.7 | 17.4 | 17.2 | 17.8 | 17.4 | 17.3 | 16.8 | 16.2 | 20.3 | 12.0 |
| 18 | 16.3 | 15.9 | 15.7 | 16.0 | 16.6 | 16.4 | 15.8 | 16.0 | 17.1 | 18.7 | 20.6 | 22.6 | 23.2 | 23.1 | 23.0 | 22.6 | 22.0 | 20.8 | 19.8 | 18.2 | 18.2 | 17.1 | 16.3 | 15.8 | 18.7 | 23.2 | 15.7 |
| 19 | 15.5 | 15.5 | 15.0 | 14.8 | 14.5 | 14.9 | 14.2 | 15.4 | 17.7 | 18.7 | 20.7 | 22.6 | 23.0 | 21.9 | 21.7 | 21.7 | 21.0 | 19.2 | 18.3 | 18.1 | 17.1 | 16.3 | 15.4 | 14.8 | 17.8 | 23.0 | 14.2 |
| 20 | 14.9 | 14.5 | 13.9 | 14.1 | 14.1 | 13.9 | 14.5 | 14.7 | 15.0 | 16.4 | 18.0 | 19.1 | 19.6 | 18.6 | 18.4 | 18.1 | 18.0 | 17.5 | 17.1 | 17.3 | 16.9 | 16.6 | 16.6 | 16.5 | 16.4 | 19.6 | 13.9 |
| 21 | 15.7 | 15.1 | 15.2 | 15.7 | 15.4 | 15.5 | 15.1 | 15.1 | 16.2 | 17.1 | 18.1 | 19.2 | 20.1 | 20.0 | 18.9 | 18.5 | 18.1 | 17.5 | 17.2 | 16.7 | 15.3 | 14.3 | 14.3 | 14.1 | 16.6 | 20.1 | 14.1 |
| 22 | 14.2 | 13.9 | 14.7 | 15.4 | 17.0 | 16.2 | 13.5 | 13.6 | 13.1 | 11.1 | 10.1 | 10.0 | 9.9 | 9.8 | 9.5 | 9.7 | 9.7 | 9.7 | 9.4 | 9.4 | 9.4 | 9.3 | 9.0 | 8.2 | 11.5 | 17.0 | 8.2 |
| 23 | 8.1 | 8.1 | 8.1 | 8.6 | 8.6 | 8.3 | 8.0 | 7.5 | 7.5 | 7.5 | 7.2 | 6.9 | 6.3 | 6.9 | 7.5 | 8.3 | 7.8 | 7.9 | 8.2 | 7.9 | 7.9 | 7.8 | 7.8 | 7.1 | 7.7 | 8.6 | 6.3 |
| 24 | 7.3 | 7.2 | 7.1 | 7.1 | 6.4 | 6.2 | 6.4 | 6.1 | 5.8 | 6.4 | 6.6 | 6.4 | 6.6 | 7.2 | 7.9 | 8.6 | 8.1 | 7.4 | 7.0 | 7.2 | 7.2 | 6.7 | 6.4 | 6.5 | 6.9 | 8.6 | 5.8 |
| 25 | 6.5 | 5.7 | 5.9 | 5.6 | 5.2 | 4.8 | 4.6 | 4.5 | 6.1 | 8.4 | 9.9 | 11.3 | 12.8 | 12.3 | 12.4 | 12.6 | 12.3 | 11.0 | 9.9 | 10.4 | 10.2 | 10.7 | 11.2 | 11.0 | 9.0 | 12.8 | 4.5 |
| 26 | 10.7 | 10.9 | 12.0 | 12.0 | 11.8 | 10.5 | 11.7 | 10.8 | 11.2 | 12.7 | 13.9 | 14.6 | 15.4 | 16.4 | 16.1 | 16.3 | 15.5 | 14.1 | 13.2 | 13.2 | 13.0 | 12.9 | 12.3 | 12.0 | 13.1 | 16.4 | 10.5 |
| 27 | 11.5 | 12.3 | 12.5 | 12.1 | 11.5 | 11.4 | 11.6 | 11.4 | 12.2 | 12.9 | 13.3 | 13.7 | 14.2 | 14.6 | 14.7 | 14.7 | 14.3 | 13.8 | 13.6 | 13.4 | 13.0 | 12.5 | 12.2 | 11.9 | 12.9 | 14.7 | 11.4 |
| 28 | 12.0 | 11.6 | 11.7 | 11.6 | 11.4 | 11.1 | 11.1 | 10.9 | 11.7 | 12.9 | 13.8 | 15.0 | 16.5 | 17.7 | 18.2 | 18.2 | 17.7 | 16.5 | 15.7 | 15.9 | 15.9 | 15.9 | 15.8 | 15.6 | 14.4 | 18.2 | 10.9 |
| 29 | 15.6 | 15.3 | 14.8 | 14.4 | 14.0 | 13.7 | 13.9 | 14.0 | 14.8 | 15.9 | 17.6 | 19.0 | 20.5 | 21.5 | 21.1 | 21.1 | 19.4 | 17.8 | 16.2 | 16.1 | 16.0 | 14.7 | 13.3 | 13.3 | 16.4 | 21.5 | 13.3 |
| 30 | 13.3 | 14.1 | 14.4 | 13.6 | 13.1 | 12.2 | 13.3 | 13.0 | 14.9 | 16.8 | 17.7 | 18.4 | 18.9 | 19.9 | 20.2 | 19.7 | 17.9 | 15.7 | 14.6 | 14.1 | 13.9 | 13.9 | 13.5 | 12.2 | 15.4 | 20.2 | 12.2 |
| Avg | 15.3 | 14.9 | 14.9 | 14.9 | 14.7 | 14.4 | 14.3 | 14.4 | 15.7 | 17.0 | 18.3 | 19.3 | 20.1 | 20.5 | 20.6 | 20.5 | 19.7 | 18.6 | 17.7 | 17.0 | 16.6 | 16.2 | 16.0 | 15.4 | 17.0 | -- | -- |
| Max | 24.0 | 22.8 | 21.8 | 21.4 | 20.0 | 20.9 | 21.2 | 23.1 | 24.1 | 25.1 | 26.4 | 27.0 | 28.1 | 28.9 | 29.0 | 28.9 | 27.8 | 26.5 | 24.7 | 24.1 | 22.8 | 24.0 | 24.0 | 23.7 | -- | 29.0 | -- |
| Min | 6.5 | 5.7 | 5.9 | 5.6 | 5.2 | 4.8 | 4.6 | 4.5 | 5.8 | 6.4 | 6.6 | 6.4 | 6.3 | 6.9 | 7.5 | 8.3 | 7.8 | 7.4 | 7.0 | 7.2 | 7.2 | 6.7 | 6.4 | 6.5 | -- | -- | 4.5 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, Temp_2m_C"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 11.9 | 12.4 | 12.6 | 12.9 | 12.7 | 11.6 | 11.3 | 12.0 | 12.8 | 15.4 | 17.9 | 19.6 | 20.6 | 20.3 | 19.3 | 18.4 | 17.7 | 16.3 | 15.1 | 14.1 | 13.1 | 12.6 | 12.8 | 12.5 | 14.8 | 20.6 | 11.3 |
| 2 | 12.5 | 12.1 | 12.0 | 11.7 | 11.1 | 10.5 | 9.9 | 10.2 | 12.0 | 14.2 | 16.7 | 17.4 | 17.5 | 17.8 | 17.8 | 18.0 | 17.3 | 15.7 | 14.5 | 13.3 | 12.4 | 12.4 | 12.6 | 13.0 | 13.9 | 18.0 | 9.9 |
| 3 | 13.0 | 12.3 | 12.3 | 12.1 | 11.4 | 11.1 | 11.2 | 10.4 | 11.9 | 14.7 | 17.2 | 18.2 | 19.4 | 20.3 | 20.4 | 19.9 | 18.7 | 16.7 | 15.5 | 15.5 | 15.3 | 15.2 | 14.7 | 14.6 | 15.1 | 20.4 | 10.4 |
| 4 | 14.2 | 14.0 | 12.9 | 12.7 | 12.7 | 12.3 | 11.6 | 11.3 | 12.4 | 13.6 | 13.8 | 13.1 | 13.3 | 12.7 | 10.2 | 9.4 | 9.2 | 9.1 | 8.8 | 8.4 | 8.3 | 8.1 | 7.8 | 7.5 | 11.1 | 14.2 | 7.5 |
| 5 | 7.2 | 7.0 | 7.0 | 6.8 | 6.6 | 6.6 | 5.8 | 5.8 | 6.0 | 6.6 | 7.3 | 7.6 | 8.0 | 8.7 | 8.7 | 8.5 | 7.8 | 6.7 | 5.8 | 5.0 | 4.5 | 3.7 | 3.0 | 2.7 | 6.4 | 8.7 | 2.7 |
| 6 | 2.5 | 2.1 | 2.0 | 2.1 | 1.7 | 2.0 | 2.5 | 2.3 | 3.5 | 5.8 | 6.7 | 7.4 | 8.2 | 8.7 | 9.1 | 9.0 | 8.2 | 6.8 | 5.7 | 4.4 | 4.1 | 3.5 | 3.8 | 3.2 | 4.8 | 9.1 | 1.7 |
| 7 | 2.4 | 2.9 | 2.6 | 2.6 | 2.5 | 2.2 | 2.6 | 2.1 | 3.3 | 5.7 | 7.9 | 9.6 | 9.8 | 10.9 | 10.4 | 9.6 | 8.9 | 7.7 | 7.6 | 6.9 | 7.8 | 8.0 | 8.0 | 7.7 | 6.2 | 10.9 | 2.1 |
| 8 | 7.5 | 6.7 | 6.6 | 6.3 | 6.1 | 6.4 | 6.6 | 6.2 | 6.2 | 6.9 | 8.0 | 8.4 | 8.8 | 9.1 | 10.4 | 9.9 | 8.8 | 8.0 | 7.7 | 7.4 | 7.0 | 6.5 | 6.0 | 5.8 | 7.4 | 10.4 | 5.8 |
| 9 | 5.3 | 4.1 | 2.8 | 2.5 | 2.2 | 1.7 | 1.0 | 0.7 | 2.2 | 4.4 | 6.3 | 7.7 | 8.3 | 9.5 | 9.7 | 9.4 | 8.7 | 7.3 | 6.2 | 5.4 | 4.7 | 3.9 | 3.6 | 4.7 | 5.1 | 9.7 | 0.7 |
| 10 | 5.7 | 5.4 | 5.6 | 6.9 | 6.4 | 5.2 | 6.1 | 7.9 | 8.0 | 8.9 | 9.8 | 10.2 | 11.2 | 12.2 | 12.4 | 12.1 | 12.3 | 11.7 | 11.6 | 11.3 | 11.2 | 11.2 | 11.2 | 10.9 | 9.4 | 12.4 | 5.2 |
| 11 | 11.1 | 11.3 | 11.2 | 11.2 | 11.3 | 11.4 | 11.4 | 11.4 | 11.9 | 12.6 | 13.7 | 15.1 | 16.5 | 17.7 | 18.4 | 18.4 | 17.8 | 16.9 | 16.2 | 16.5 | 16.4 | 16.4 | 16.3 | 16.1 | 14.5 | 18.4 | 11.1 |
| 12 | 15.4 | 14.9 | 14.8 | 15.0 | 14.9 | 14.9 | 14.9 | 14.5 | 14.4 | 15.1 | 16.1 | 17.5 | 18.4 | 18.6 | 18.1 | 17.3 | 16.2 | 15.1 | 13.9 | 12.6 | 11.7 | 11.7 | 10.6 | 9.7 | 14.8 | 18.6 | 9.7 |
| 13 | 9.1 | 8.3 | 7.8 | 7.6 | 7.0 | 6.8 | 6.4 | 5.8 | 8.3 | 10.2 | 11.8 | 12.7 | 13.1 | 13.4 | 13.7 | 13.6 | 12.9 | 11.5 | 10.8 | 9.7 | 8.7 | 8.6 | 7.8 | 7.7 | 9.7 | 13.7 | 5.8 |
| 14 | 7.6 | 8.2 | 7.0 | 7.2 | 7.1 | 6.6 | 6.9 | 7.8 | 10.6 | 11.8 | 12.9 | 13.4 | 14.6 | 16.0 | 16.7 | 16.7 | 16.0 | 14.8 | 13.2 | 12.8 | 11.7 | 10.4 | 9.7 | 9.4 | 11.2 | 16.7 | 6.6 |
| 15 | 10.7 | 10.9 | 11.8 | 11.2 | 10.4 | 9.7 | 9.2 | 8.7 | 10.0 | 14.3 | 16.5 | 16.6 | 17.7 | 19.5 | 20.0 | 19.4 | 17.4 | 15.4 | 14.6 | 15.7 | 15.5 | 14.9 | 15.6 | 16.2 | 14.2 | 20.0 | 8.7 |
| 16 | 15.4 | 15.2 | 14.5 | 13.6 | 13.7 | 13.5 | 12.4 | 13.0 | 15.2 | 17.2 | 19.1 | 20.5 | 21.9 | 22.6 | 22.3 | 22.2 | 21.3 | 19.2 | 17.3 | 18.1 | 19.0 | 17.0 | 17.8 | 17.2 | 17.5 | 22.6 | 12.4 |
| 17 | 18.4 | 16.6 | 16.6 | 18.0 | 17.7 | 18.1 | 18.2 | 18.0 | 18.6 | 19.7 | 21.2 | 21.8 | 22.2 | 23.2 | 23.8 | 23.7 | 22.7 | 21.9 | 21.5 | 21.1 | 20.2 | 20.2 | 19.4 | 19.5 | 20.1 | 23.8 | 16.6 |
| 18 | 19.4 | 19.4 | 19.1 | 18.8 | 18.8 | 18.5 | 18.3 | 17.9 | 18.1 | 18.2 | 19.9 | 20.6 | 20.7 | 21.2 | 22.7 | 22.8 | 21.4 | 20.5 | 18.8 | 18.4 | 18.0 | 17.4 | 16.2 | 15.3 | 19.2 | 22.8 | 15.3 |
| 19 | 15.6 | 16.0 | 14.7 | 13.6 | 13.1 | 13.2 | 13.1 | 13.2 | 14.1 | 15.5 | 17.0 | 18.1 | 18.5 | 19.0 | 19.3 | 18.8 | 17.2 | 15.2 | 13.4 | 13.0 | 12.4 | 12.0 | 11.7 | 11.4 | 15.0 | 19.3 | 11.4 |
| 20 | 11.2 | 11.0 | 11.4 | 12.1 | 12.0 | 8.2 | 6.8 | 6.5 | 7.1 | 7.9 | 8.5 | 9.1 | 10.0 | 9.9 | 9.4 | 8.8 | 8.6 | 8.5 | 8.1 | 7.6 | 7.1 | 6.8 | 6.8 | 6.8 | 8.8 | 12.1 | 6.5 |
| 21 | 6.6 | 6.5 | 6.3 | 6.3 | 6.2 | 6.0 | 5.8 | 5.7 | 5.7 | 6.0 | 6.2 | 6.6 | 7.0 | 7.0 | 7.3 | 7.5 | 7.7 | 7.2 | 7.2 | 6.2 | 6.0 | 6.0 | 5.4 | 5.7 | 6.4 | 7.7 | 5.4 |
| 22 | 5.0 | 4.8 | 4.8 | 4.6 | 4.7 | 5.1 | 5.1 | 5.0 | 6.4 | 8.4 | 9.7 | 11.1 | 11.9 | 11.9 | 11.8 | 11.5 | 11.0 | 9.8 | 9.1 | 7.9 | 7.6 | 7.3 | 7.0 | 8.1 | 7.9 | 11.9 | 4.6 |
| 23 | 8.2 | 8.5 | 8.8 | 9.6 | 9.2 | 8.6 | 8.5 | 8.7 | 9.5 | 11.4 | 12.8 | 14.0 | 14.7 | 15.3 | 16.0 | 16.1 | 15.5 | 14.5 | 15.1 | 14.9 | 14.7 | 13.7 | 13.6 | 13.0 | 12.3 | 16.1 | 8.2 |
| 24 | 13.9 | 13.3 | 13.4 | 13.0 | 11.4 | 10.7 | 11.8 | 11.4 | 11.1 | 12.8 | 14.3 | 15.0 | 15.9 | 16.7 | 17.3 | 17.4 | 17.1 | 15.3 | 13.2 | 12.6 | 13.0 | 12.4 | 15.5 | 15.2 | 13.9 | 17.4 | 10.7 |
| 25 | 15.0 | 14.9 | 14.5 | 13.7 | 13.3 | 11.5 | 13.2 | 11.3 | 10.8 | 12.5 | 13.8 | 14.4 | 15.3 | 16.4 | 17.1 | 17.3 | 17.0 | 15.6 | 14.1 | 13.7 | 13.4 | 13.7 | 13.3 | 13.1 | 14.1 | 17.3 | 10.8 |
| 26 | 13.0 | 12.5 | 11.5 | 11.0 | 11.7 | 11.6 | 12.1 | 12.6 | 12.5 | 12.6 | 13.3 | 14.1 | 15.0 | 16.3 | 16.8 | 17.0 | 16.4 | 14.9 | 14.1 | 14.0 | 12.4 | 11.6 | 11.7 | 12.3 | 13.4 | 17.0 | 11.0 |
| 27 | 11.6 | 11.9 | 12.8 | 12.1 | 12.9 | 13.8 | 11.3 | 11.5 | 14.2 | 14.8 | 15.5 | 16.4 | 17.5 | 17.7 | 17.9 | 17.9 | 17.6 | 16.8 | 16.3 | 14.1 | 13.4 | 13.1 | 12.3 | 11.1 | 14.4 | 17.9 | 11.1 |
| 28 | 10.9 | 10.0 | 9.4 | 9.6 | 10.7 | 10.0 | 10.4 | 10.4 | 10.9 | 12.8 | 13.7 | 14.7 | 15.8 | 16.9 | 17.1 | 16.7 | 15.5 | 14.2 | 13.0 | 12.6 | 11.6 | 12.2 | 11.0 | 11.0 | 12.5 | 17.1 | 9.4 |
| 29 | 11.4 | 10.5 | 10.5 | 10.3 | 9.3 | 8.6 | 9.5 | 9.5 | 10.0 | 12.2 | 14.7 | 15.1 | 16.0 | 16.5 | 17.3 | 17.2 | 16.7 | 15.3 | 13.4 | 12.3 | 13.2 | 12.4 | 11.9 | 10.7 | 12.7 | 17.3 | 8.6 |
| 30 | 10.5 | 9.3 | 8.6 | 8.6 | 9.0 | 8.1 | 7.7 | 7.6 | 8.2 | 11.0 | 13.3 | 15.0 | 16.2 | 16.8 | 15.7 | 15.9 | 15.0 | 13.5 | 12.1 | 11.0 | 10.3 | 11.0 | 11.1 | 11.6 | 11.5 | 16.8 | 7.6 |
| 31 | 11.1 | 11.6 | 12.5 | 12.9 | 12.4 | 11.9 | 11.8 | 11.9 | 11.4 | 14.2 | 15.1 | 16.2 | 17.2 | 18.2 | 19.2 | 19.5 | 19.2 | 17.1 | 15.4 | 14.9 | 14.4 | 14.0 | 12.8 | 13.6 | 14.5 | 19.5 | 11.1 |
| Avg | 10.8 | 10.5 | 10.3 | 10.2 | 10.0 | 9.6 | 9.5 | 9.4 | 10.2 | 11.8 | 13.2 | 14.1 | 14.9 | 15.5 | 15.7 | 15.5 | 14.8 | 13.5 | 12.6 | 12.0 | 11.6 | 11.2 | 11.0 | 10.9 | 12.0 | -- | -- |
| Max | 19.4 | 19.4 | 19.1 | 18.8 | 18.8 | 18.5 | 18.3 | 18.0 | 18.6 | 19.7 | 21.2 | 21.8 | 22.2 | 23.2 | 23.8 | 23.7 | 22.7 | 21.9 | 21.5 | 21.1 | 20.2 | 20.2 | 19.4 | 19.5 | -- | 23.8 | -- |
| Min | 2.4 | 2.1 | 2.0 | 2.1 | 1.7 | 1.7 | 1.0 | 0.7 | 2.2 | 4.4 | 6.2 | 6.6 | 7.0 | 7.0 | 7.3 | 7.5 | 7.7 | 6.7 | 5.7 | 4.4 | 4.1 | 3.5 | 3.0 | 2.7 | -- | -- | 0.7 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, SR_Wm2_2m"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 176 | 423 | 621 | 771 | 855 | 872 | 818 | 702 | 528 | 313 | 92 | 0 | 0 | 0 | 0 | 0 | 0 | 257 | 872 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 169 | 411 | 605 | 753 | 837 | 854 | 800 | 687 | 515 | 304 | 85 | 0 | 0 | 0 | 0 | 0 | 0 | 251 | 854 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 167 | 418 | 617 | 764 | 844 | 858 | 784 | 677 | 508 | 298 | 82 | 0 | 0 | 0 | 0 | 0 | 0 | 251 | 858 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 154 | 400 | 593 | 742 | 825 | 842 | 787 | 671 | 499 | 285 | 73 | 0 | 0 | 0 | 0 | 0 | 0 | 245 | 842 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 164 | 435 | 644 | 800 | 882 | 885 | 821 | 698 | 521 | 301 | 78 | 0 | 0 | 0 | 0 | 0 | 0 | 260 | 885 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 155 | 429 | 630 | 779 | 860 | 873 | 809 | 685 | 506 | 288 | 73 | 0 | 0 | 0 | 0 | 0 | 0 | 254 | 873 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 144 | 407 | 622 | 723 | 819 | 812 | 757 | 518 | 467 | 118 | 39 | 0 | 0 | 0 | 0 | 0 | 0 | 226 | 819 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 132 | 397 | 589 | 757 | 821 | 835 | 772 | 646 | 481 | 270 | 60 | 0 | 0 | 0 | 0 | 0 | 0 | 240 | 835 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 126 | 376 | 592 | 747 | 813 | 794 | 630 | 606 | 459 | 167 | 35 | 0 | 0 | 0 | 0 | 0 | 0 | 223 | 813 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 12 | 33 | 173 | 295 | 511 | 696 | 709 | 574 | 490 | 265 | 55 | 0 | 0 | 0 | 0 | 0 | 0 | 159 | 709 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 123 | 396 | 593 | 742 | 826 | 833 | 771 | 650 | 475 | 261 | 55 | 0 | 0 | 0 | 0 | 0 | 0 | 239 | 833 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 120 | 391 | 587 | 733 | 813 | 823 | 762 | 643 | 467 | 254 | 50 | 0 | 0 | 0 | 0 | 0 | 0 | 235 | 823 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 112 | 376 | 571 | 717 | 801 | 814 | 756 | 637 | 464 | 251 | 47 | 0 | 0 | 0 | 0 | 0 | 0 | 231 | 814 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 111 | 373 | 567 | 715 | 797 | 814 | 759 | 639 | 462 | 249 | 46 | 0 | 0 | 0 | 0 | 0 | 0 | 231 | 814 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 109 | 371 | 565 | 713 | 798 | 812 | 751 | 631 | 454 | 242 | 43 | 0 | 0 | 0 | 0 | 0 | 0 | 229 | 812 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 108 | 378 | 575 | 724 | 804 | 819 | 754 | 632 | 454 | 239 | 41 | 0 | 0 | 0 | 0 | 0 | 0 | 230 | 819 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 105 | 377 | 570 | 715 | 795 | 806 | 747 | 624 | 446 | 232 | 38 | 0 | 0 | 0 | 0 | 0 | 0 | 227 | 806 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 100 | 368 | 565 | 715 | 800 | 812 | 746 | 623 | 442 | 228 | 35 | 0 | 0 | 0 | 0 | 0 | 0 | 227 | 812 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 100 | 379 | 573 | 718 | 800 | 808 | 744 | 621 | 441 | 224 | 32 | 0 | 0 | 0 | 0 | 0 | 0 | 227 | 808 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 95 | 363 | 555 | 700 | 783 | 797 | 736 | 616 | 438 | 223 | 32 | 0 | 0 | 0 | 0 | 0 | 0 | 223 | 797 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 91 | 360 | 547 | 684 | 767 | 777 | 717 | 598 | 423 | 210 | 27 | 0 | 0 | 0 | 0 | 0 | 0 | 217 | 777 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 85 | 358 | 553 | 694 | 774 | 783 | 720 | 595 | 419 | 209 | 26 | 0 | 0 | 0 | 0 | 0 | 0 | 217 | 783 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 79 | 316 | 538 | 676 | 756 | 762 | 695 | 581 | 402 | 192 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 209 | 762 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 89 | 322 | 521 | 581 | 685 | 678 | 556 | 493 | 298 | 91 | 31 | 0 | 0 | 0 | 0 | 0 | 0 | 181 | 685 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 73 | 334 | 523 | 660 | 744 | 759 | 698 | 578 | 403 | 195 | 22 | 0 | 0 | 0 | 0 | 0 | 0 | 208 | 759 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 72 | 343 | 534 | 672 | 750 | 758 | 695 | 562 | 266 | 181 | 20 | 0 | 0 | 0 | 0 | 0 | 0 | 202 | 758 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 68 | 334 | 523 | 661 | 741 | 748 | 681 | 538 | 387 | 189 | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 203 | 748 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 70 | 170 | 356 | 600 | 735 | 725 | 519 | 294 | 173 | 72 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 155 | 735 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 63 | 321 | 510 | 646 | 725 | 735 | 511 | 148 | 191 | 66 | 19 | 0 | 0 | 0 | 0 | 0 | 0 | 164 | 735 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 83 | 258 | 442 | 533 | 728 | 741 | 677 | 557 | 380 | 173 | 15 | 0 | 0 | 0 | 0 | 0 | 0 | 191 | 741 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 60 | 320 | 505 | 643 | 722 | 736 | 673 | 556 | 379 | 172 | 14 | 0 | 0 | 0 | 0 | 0 | 0 | 199 | 736 | 0 |
| Avg | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 107 | 353 | 547 | 689 | 781 | 795 | 721 | 590 | 427 | 218 | 42 | 0 | 0 | 0 | 0 | 0 | 0 | 220 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 176 | 435 | 644 | 800 | 882 | 885 | 821 | 702 | 528 | 313 | 92 | 0 | 0 | 0 | 0 | 0 | 0 | -- | 885 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 12 | 33 | 173 | 295 | 511 | 678 | 511 | 148 | 173 | 66 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, SR_Wm2_2m"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 57 | 320 | 513 | 649 | 729 | 737 | 675 | 554 | 377 | 169 | 13 | 0 | 0 | 0 | 0 | 0 | 0 | 200 | 737 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 53 | 325 | 521 | 660 | 737 | 742 | 670 | 507 | 250 | 196 | 13 | 0 | 0 | 0 | 0 | 0 | 0 | 195 | 742 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 46 | 197 | 457 | 537 | 617 | 601 | 635 | 486 | 356 | 156 | 12 | 0 | 0 | 0 | 0 | 0 | 0 | 171 | 635 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 44 | 295 | 481 | 619 | 690 | 722 | 611 | 464 | 273 | 62 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 178 | 722 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 72 | 348 | 320 | 430 | 627 | 666 | 494 | 582 | 437 | 169 | 12 | 0 | 0 | 0 | 0 | 0 | 0 | 173 | 666 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 38 | 308 | 503 | 648 | 726 | 733 | 662 | 541 | 362 | 156 | 10 | 0 | 0 | 0 | 0 | 0 | 0 | 195 | 733 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 34 | 302 | 497 | 642 | 722 | 731 | 662 | 541 | 360 | 153 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 194 | 731 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 45 | 281 | 334 | 608 | 680 | 684 | 627 | 498 | 342 | 138 | 10 | 0 | 0 | 0 | 0 | 0 | 0 | 177 | 684 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 30 | 275 | 459 | 597 | 670 | 681 | 625 | 508 | 336 | 140 | 9 | 0 | 0 | 0 | 0 | 0 | 0 | 180 | 681 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 41 | 120 | 345 | 337 | 528 | 573 | 374 | 505 | 211 | 64 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 129 | 573 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 26 | 263 | 448 | 587 | 662 | 673 | 610 | 491 | 325 | 120 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 175 | 673 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 23 | 268 | 466 | 566 | 590 | 615 | 506 | 326 | 201 | 96 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 152 | 615 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 22 | 261 | 444 | 583 | 650 | 660 | 605 | 484 | 319 | 102 | 7 | 0 | 0 | 0 | 0 | 0 | 0 | 172 | 660 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 23 | 254 | 437 | 573 | 650 | 660 | 602 | 486 | 324 | 99 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 171 | 660 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 19 | 92 | 244 | 377 | 548 | 421 | 307 | 179 | 144 | 39 | 1 | 0 | 4 | 3 | 0 | 0 | 0 | 99 | 548 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 19 | 82 | 233 | 363 | 651 | 488 | 385 | 487 | 305 | 100 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 130 | 651 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 36 | 186 | 217 | 516 | 639 | 528 | 524 | 482 | 309 | 95 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 147 | 639 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 40 | 97 | 297 | 433 | 619 | 611 | 405 | 426 | 309 | 97 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 139 | 619 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 30 | 206 | 338 | 509 | 634 | 643 | 585 | 471 | 305 | 89 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 159 | 643 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 35 | 104 | 271 | 410 | 444 | 488 | 268 | 309 | 106 | 20 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 102 | 488 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 38 | 105 | 145 | 260 | 393 | 522 | 331 | 192 | 125 | 48 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 90 | 522 | 0 |
| 22 | 0 | 1 | 2 | 1 | 0 | 0 | 0 | 1 | 11 | 15 | 28 | 73 | 51 | 56 | 99 | 58 | 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 18 | 99 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 2 | 39 | 45 | 47 | 30 | 57 | 98 | 210 | 282 | 67 | 3 | 0 | 0 | 1 | 0 | 0 | 0 | 37 | 282 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 78 | 147 | 158 | 79 | 148 | 274 | 258 | 203 | 46 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 58 | 274 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 11 | 210 | 397 | 535 | 616 | 635 | 587 | 469 | 303 | 95 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 161 | 635 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 11 | 214 | 403 | 540 | 623 | 635 | 585 | 470 | 307 | 95 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 162 | 635 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 32 | 164 | 296 | 315 | 353 | 325 | 343 | 289 | 255 | 55 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 101 | 353 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 10 | 207 | 403 | 542 | 621 | 635 | 580 | 467 | 304 | 93 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 161 | 635 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 11 | 188 | 366 | 534 | 614 | 629 | 564 | 458 | 285 | 100 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 156 | 629 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 14 | 123 | 264 | 357 | 335 | 380 | 343 | 268 | 172 | 48 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 96 | 380 | 0 |
| Avg | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 29 | 197 | 344 | 465 | 552 | 556 | 487 | 417 | 275 | 98 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 143 | -- | -- |
| Max | 0 | 1 | 2 | 1 | 0 | 0 | 1 | 72 | 348 | 521 | 660 | 737 | 742 | 675 | 582 | 437 | 196 | 13 | 0 | 4 | 3 | 0 | 0 | 0 | -- | 742 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 1 | 11 | 15 | 28 | 30 | 51 | 56 | 99 | 58 | 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, SR_Wm2_2m"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 24 | 206 | 375 | 527 | 606 | 649 | 494 | 317 | 226 | 88 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 147 | 649 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 180 | 380 | 515 | 608 | 603 | 442 | 372 | 311 | 89 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 146 | 608 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 23 | 176 | 354 | 492 | 602 | 617 | 564 | 462 | 300 | 100 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 154 | 617 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 22 | 124 | 282 | 268 | 136 | 257 | 194 | 64 | 40 | 26 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 59 | 282 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 128 | 285 | 409 | 400 | 611 | 534 | 404 | 275 | 104 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 132 | 611 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8 | 171 | 378 | 519 | 608 | 626 | 575 | 462 | 303 | 106 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 157 | 626 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 164 | 370 | 514 | 600 | 619 | 573 | 460 | 300 | 104 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 155 | 619 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 69 | 193 | 332 | 374 | 285 | 368 | 479 | 234 | 56 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 100 | 479 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 159 | 371 | 513 | 605 | 632 | 582 | 471 | 309 | 106 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 156 | 632 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 13 | 72 | 263 | 324 | 406 | 446 | 407 | 340 | 237 | 103 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 109 | 446 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 147 | 356 | 496 | 577 | 595 | 549 | 444 | 291 | 104 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 149 | 595 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 141 | 358 | 486 | 570 | 596 | 385 | 164 | 86 | 32 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 118 | 596 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 7 | 135 | 331 | 478 | 567 | 593 | 550 | 442 | 287 | 105 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 146 | 593 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 141 | 360 | 511 | 599 | 619 | 572 | 463 | 305 | 113 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 154 | 619 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 138 | 352 | 496 | 583 | 605 | 558 | 453 | 296 | 109 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 150 | 605 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8 | 131 | 359 | 499 | 538 | 579 | 492 | 351 | 196 | 75 | 2 | 0 | 0 | 0 | 0 | 0 | 0 | 135 | 579 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 6 | 136 | 355 | 506 | 594 | 591 | 557 | 452 | 310 | 93 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 150 | 594 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 83 | 170 | 380 | 444 | 328 | 447 | 447 | 187 | 47 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | 106 | 447 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 125 | 339 | 485 | 573 | 598 | 565 | 440 | 292 | 84 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 146 | 598 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 59 | 172 | 201 | 272 | 364 | 157 | 96 | 60 | 84 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 62 | 364 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 21 | 90 | 99 | 173 | 209 | 143 | 210 | 127 | 87 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 49 | 210 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 5 | 121 | 335 | 483 | 574 | 599 | 564 | 468 | 304 | 116 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 149 | 599 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 121 | 345 | 497 | 587 | 614 | 572 | 467 | 311 | 122 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 152 | 614 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 119 | 343 | 495 | 584 | 609 | 570 | 465 | 311 | 121 | 4 | 0 | 0 | 0 | 0 | 0 | 0 | 151 | 609 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 122 | 357 | 503 | 597 | 623 | 580 | 477 | 319 | 127 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 155 | 623 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 117 | 346 | 497 | 599 | 629 | 584 | 478 | 320 | 131 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 155 | 629 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 115 | 343 | 497 | 591 | 616 | 579 | 475 | 321 | 130 | 5 | 0 | 0 | 0 | 0 | 0 | 0 | 153 | 616 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 9 | 126 | 304 | 456 | 525 | 507 | 475 | 371 | 196 | 83 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 127 | 525 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 108 | 326 | 478 | 572 | 603 | 567 | 467 | 317 | 131 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 149 | 603 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 4 | 110 | 334 | 489 | 585 | 619 | 579 | 477 | 324 | 136 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 153 | 619 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 109 | 334 | 490 | 585 | 615 | 580 | 478 | 323 | 134 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | 152 | 615 | 0 |
| Avg | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 8 | 125 | 318 | 449 | 524 | 550 | 495 | 400 | 259 | 98 | 3 | 0 | 0 | 0 | 0 | 0 | 0 | 135 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 24 | 206 | 380 | 527 | 608 | 649 | 584 | 479 | 324 | 136 | 6 | 0 | 0 | 0 | 0 | 0 | 0 | -- | 649 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 3 | 21 | 90 | 99 | 136 | 209 | 143 | 64 | 40 | 26 | 1 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, RH_Percent"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 20 | 19 | 18 | 19 | 19 | 19 | 21 | 18 | 15 | 13 | 11 | 12 | 13 | 13 | 13 | 13 | 13 | 12 | 14 | 16 | 17 | 17 | 19 | 20 | 16 | 21 | 11 |
| 2 | 21 | 22 | 23 | 25 | 30 | 33 | 31 | 27 | 24 | 23 | 23 | 23 | 20 | 20 | 20 | 19 | 19 | 20 | 22 | 23 | 24 | 25 | 24 | 24 | 24 | 33 | 19 |
| 3 | 23 | 25 | 28 | 33 | 35 | 35 | 39 | 40 | 32 | 22 | 16 | 18 | 18 | 21 | 21 | 20 | 18 | 16 | 17 | 19 | 20 | 21 | 24 | 30 | 25 | 40 | 16 |
| 4 | 37 | 39 | 42 | 39 | 38 | 40 | 39 | 35 | 28 | 24 | 21 | 19 | 19 | 19 | 18 | 17 | 17 | 14 | 13 | 11 | 12 | 12 | 11 | 11 | 24 | 42 | 11 |
| 5 | 11 | 11 | 11 | 12 | 13 | 12 | 9 | 6 | 6 | 5 | 6 | 7 | 6 | 6 | 6 | 6 | 7 | 8 | 9 | 10 | 12 | 12 | 12 | 11 | 9 | 13 | 5 |
| 6 | 12 | 11 | 10 | 11 | 13 | 16 | 15 | 11 | 10 | 9 | 9 | 9 | 8 | 7 | 6 | 6 | 6 | 7 | 8 | 9 | 10 | 9 | 10 | 10 | 10 | 16 | 6 |
| 7 | 10 | 11 | 11 | 10 | 11 | 12 | 11 | 11 | 10 | 8 | 8 | 8 | 8 | 8 | 8 | 8 | 8 | 8 | 8 | 10 | 9 | 10 | 11 | 12 | 9 | 12 | 8 |
| 8 | 13 | 13 | 14 | 12 | 12 | 15 | 15 | 14 | 11 | 10 | 9 | 9 | 11 | 12 | 11 | 9 | 9 | 10 | 13 | 13 | 13 | 14 | 16 | 18 | 12 | 18 | 9 |
| 9 | 17 | 16 | 16 | 18 | 20 | 22 | 24 | 24 | 19 | 17 | 15 | 13 | 12 | 11 | 12 | 11 | 16 | 21 | 26 | 28 | 31 | 37 | 43 | 48 | 22 | 48 | 11 |
| 10 | 56 | 62 | 63 | 65 | 62 | 65 | 65 | 87 | 92 | 90 | 82 | 72 | 59 | 49 | 44 | 40 | 39 | 41 | 42 | 47 | 46 | 48 | 41 | 37 | 58 | 92 | 37 |
| 11 | 42 | 41 | 43 | 46 | 46 | 47 | 47 | 43 | 36 | 30 | 23 | 19 | 22 | 25 | 24 | 22 | 22 | 23 | 25 | 29 | 32 | 34 | 35 | 36 | 33 | 47 | 19 |
| 12 | 33 | 33 | 32 | 33 | 30 | 28 | 30 | 26 | 21 | 19 | 18 | 18 | 17 | 14 | 16 | 17 | 18 | 19 | 22 | 24 | 27 | 26 | 28 | 30 | 24 | 33 | 14 |
| 13 | 29 | 31 | 33 | 33 | 34 | 33 | 33 | 32 | 26 | 24 | 26 | 24 | 21 | 19 | 18 | 15 | 14 | 15 | 18 | 22 | 24 | 26 | 28 | 29 | 25 | 34 | 14 |
| 14 | 29 | 33 | 36 | 37 | 40 | 43 | 43 | 42 | 35 | 33 | 28 | 26 | 23 | 18 | 19 | 18 | 15 | 14 | 16 | 17 | 20 | 22 | 23 | 23 | 27 | 43 | 14 |
| 15 | 17 | 18 | 19 | 21 | 21 | 22 | 23 | 23 | 20 | 16 | 15 | 16 | 16 | 16 | 15 | 15 | 14 | 16 | 17 | 19 | 21 | 22 | 24 | 23 | 19 | 24 | 14 |
| 16 | 24 | 23 | 23 | 22 | 25 | 28 | 27 | 25 | 23 | 20 | 17 | 14 | 13 | 12 | 12 | 14 | 15 | 16 | 19 | 20 | 22 | 23 | 25 | 26 | 20 | 28 | 12 |
| 17 | 26 | 26 | 23 | 22 | 21 | 22 | 23 | 21 | 18 | 16 | 14 | 14 | 14 | 13 | 13 | 14 | 14 | 16 | 17 | 18 | 20 | 21 | 22 | 23 | 19 | 26 | 13 |
| 18 | 24 | 24 | 26 | 25 | 25 | 26 | 26 | 25 | 20 | 15 | 11 | 9 | 9 | 11 | 11 | 11 | 12 | 13 | 15 | 17 | 18 | 16 | 15 | 15 | 17 | 26 | 9 |
| 19 | 13 | 13 | 14 | 14 | 13 | 14 | 14 | 13 | 10 | 8 | 7 | 7 | 6 | 5 | 5 | 6 | 7 | 8 | 8 | 10 | 11 | 11 | 12 | 12 | 10 | 14 | 5 |
| 20 | 11 | 13 | 12 | 11 | 12 | 14 | 15 | 14 | 11 | 9 | 8 | 8 | 8 | 8 | 8 | 8 | 8 | 9 | 11 | 12 | 14 | 15 | 15 | 16 | 11 | 16 | 8 |
| 21 | 15 | 16 | 15 | 16 | 17 | 17 | 18 | 16 | 12 | 10 | 9 | 9 | 8 | 7 | 8 | 7 | 8 | 9 | 10 | 12 | 12 | 14 | 14 | 13 | 12 | 18 | 7 |
| 22 | 13 | 11 | 11 | 13 | 11 | 11 | 13 | 16 | 14 | 13 | 13 | 11 | 10 | 9 | 6 | 6 | 7 | 8 | 8 | 8 | 9 | 10 | 10 | 10 | 10 | 16 | 6 |
| 23 | 11 | 12 | 13 | 14 | 14 | 13 | 13 | 13 | 13 | 12 | 11 | 10 | 9 | 8 | 8 | 8 | 8 | 9 | 10 | 11 | 10 | 12 | 13 | 14 | 11 | 14 | 8 |
| 24 | 16 | 17 | 18 | 19 | 20 | 21 | 21 | 20 | 18 | 16 | 15 | 12 | 10 | 9 | 11 | 11 | 11 | 11 | 13 | 12 | 13 | 14 | 16 | 15 | 15 | 21 | 9 |
| 25 | 16 | 17 | 18 | 19 | 19 | 19 | 17 | 18 | 14 | 12 | 11 | 13 | 13 | 12 | 12 | 12 | 13 | 14 | 14 | 15 | 17 | 17 | 17 | 18 | 15 | 19 | 11 |
| 26 | 20 | 22 | 25 | 27 | 28 | 27 | 25 | 25 | 23 | 20 | 18 | 17 | 14 | 12 | 11 | 10 | 11 | 15 | 17 | 18 | 19 | 16 | 17 | 17 | 19 | 28 | 10 |
| 27 | 16 | 15 | 17 | 18 | 19 | 20 | 21 | 21 | 19 | 19 | 16 | 14 | 12 | 10 | 9 | 10 | 10 | 12 | 14 | 16 | 18 | 19 | 19 | 18 | 16 | 21 | 9 |
| 28 | 18 | 18 | 21 | 22 | 26 | 26 | 24 | 23 | 22 | 19 | 19 | 17 | 17 | 16 | 16 | 17 | 19 | 22 | 26 | 30 | 31 | 29 | 28 | 29 | 22 | 31 | 16 |
| 29 | 30 | 32 | 34 | 36 | 40 | 45 | 46 | 44 | 33 | 26 | 22 | 22 | 24 | 25 | 38 | 43 | 42 | 40 | 39 | 41 | 43 | 44 | 45 | 45 | 37 | 46 | 22 |
| 30 | 45 | 45 | 47 | 49 | 50 | 51 | 52 | 51 | 41 | 40 | 40 | 35 | 30 | 26 | 26 | 25 | 24 | 27 | 28 | 29 | 31 | 33 | 35 | 37 | 37 | 52 | 24 |
| 31 | 37 | 36 | 38 | 35 | 33 | 32 | 34 | 34 | 30 | 26 | 22 | 19 | 19 | 17 | 19 | 20 | 20 | 22 | 23 | 26 | 27 | 28 | 30 | 31 | 27 | 38 | 17 |
| Avg | 23 | 23 | 24 | 25 | 26 | 27 | 27 | 26 | 23 | 20 | 18 | 17 | 16 | 15 | 15 | 15 | 15 | 16 | 18 | 19 | 20 | 21 | 22 | 23 | 21 | -- | -- |
| Max | 56 | 62 | 63 | 65 | 62 | 65 | 65 | 87 | 92 | 90 | 82 | 72 | 59 | 49 | 44 | 43 | 42 | 41 | 42 | 47 | 46 | 48 | 45 | 48 | -- | 92 | -- |
| Min | 10 | 11 | 10 | 10 | 11 | 11 | 9 | 6 | 6 | 5 | 6 | 7 | 6 | 5 | 5 | 6 | 6 | 7 | 8 | 8 | 9 | 9 | 10 | 10 | -- | -- | 5 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, RH_Percent"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 32 | 33 | 33 | 32 | 31 | 32 | 29 | 25 | 20 | 19 | 16 | 14 | 12 | 12 | 12 | 14 | 16 | 18 | 19 | 22 | 21 | 21 | 15 | 17 | 21 | 33 | 12 |
| 2 | 15 | 13 | 15 | 14 | 14 | 13 | 12 | 12 | 11 | 10 | 9 | 8 | 7 | 7 | 7 | 7 | 7 | 8 | 9 | 10 | 10 | 12 | 13 | 19 | 11 | 19 | 7 |
| 3 | 22 | 24 | 28 | 34 | 38 | 43 | 47 | 47 | 43 | 35 | 29 | 28 | 25 | 24 | 26 | 24 | 23 | 24 | 24 | 26 | 27 | 29 | 30 | 29 | 30 | 47 | 22 |
| 4 | 29 | 29 | 30 | 29 | 31 | 33 | 36 | 39 | 33 | 32 | 30 | 26 | 24 | 24 | 25 | 29 | 28 | 28 | 30 | 32 | 32 | 31 | 48 | 72 | 33 | 72 | 24 |
| 5 | 78 | 76 | 66 | 62 | 59 | 59 | 63 | 64 | 55 | 55 | 52 | 48 | 43 | 43 | 43 | 39 | 40 | 41 | 43 | 46 | 39 | 25 | 25 | 28 | 50 | 78 | 25 |
| 6 | 20 | 14 | 13 | 14 | 13 | 12 | 11 | 10 | 8 | 5 | 4 | 4 | 4 | 4 | 3 | 2 | 4 | 4 | 6 | 6 | 8 | 9 | 9 | 10 | 8 | 20 | 2 |
| 7 | 10 | 11 | 10 | 9 | 9 | 10 | 9 | 9 | 8 | 8 | 6 | 5 | 4 | 4 | 4 | 5 | 6 | 7 | 8 | 10 | 12 | 13 | 14 | 15 | 9 | 15 | 4 |
| 8 | 16 | 18 | 19 | 19 | 20 | 20 | 20 | 20 | 18 | 18 | 16 | 15 | 15 | 15 | 16 | 15 | 17 | 20 | 23 | 25 | 26 | 27 | 29 | 30 | 20 | 30 | 15 |
| 9 | 30 | 30 | 28 | 24 | 23 | 26 | 26 | 26 | 22 | 19 | 15 | 14 | 15 | 16 | 16 | 15 | 17 | 19 | 21 | 23 | 22 | 24 | 24 | 26 | 22 | 30 | 14 |
| 10 | 26 | 25 | 23 | 24 | 27 | 25 | 26 | 22 | 21 | 18 | 17 | 16 | 15 | 15 | 14 | 15 | 15 | 16 | 16 | 17 | 19 | 20 | 21 | 22 | 20 | 27 | 14 |
| 11 | 22 | 24 | 23 | 24 | 23 | 24 | 22 | 24 | 22 | 18 | 17 | 17 | 15 | 15 | 14 | 13 | 14 | 16 | 19 | 18 | 19 | 14 | 14 | 14 | 19 | 24 | 13 |
| 12 | 12 | 13 | 14 | 15 | 17 | 17 | 17 | 16 | 14 | 12 | 12 | 13 | 14 | 15 | 17 | 19 | 20 | 23 | 23 | 26 | 28 | 28 | 28 | 28 | 18 | 28 | 12 |
| 13 | 30 | 31 | 34 | 37 | 38 | 38 | 41 | 41 | 39 | 37 | 34 | 33 | 31 | 30 | 30 | 31 | 32 | 34 | 35 | 36 | 36 | 38 | 38 | 39 | 35 | 41 | 30 |
| 14 | 40 | 42 | 43 | 44 | 44 | 45 | 45 | 45 | 40 | 36 | 33 | 29 | 26 | 24 | 23 | 25 | 27 | 31 | 33 | 35 | 34 | 31 | 30 | 31 | 35 | 45 | 23 |
| 15 | 34 | 37 | 34 | 34 | 36 | 36 | 38 | 39 | 41 | 40 | 37 | 32 | 30 | 30 | 32 | 34 | 48 | 47 | 43 | 69 | 61 | 64 | 67 | 73 | 43 | 73 | 30 |
| 16 | 76 | 77 | 76 | 78 | 77 | 77 | 79 | 81 | 80 | 74 | 71 | 63 | 56 | 49 | 43 | 42 | 43 | 47 | 49 | 52 | 57 | 55 | 55 | 56 | 63 | 81 | 42 |
| 17 | 59 | 62 | 61 | 62 | 65 | 67 | 65 | 66 | 57 | 53 | 50 | 44 | 40 | 37 | 34 | 32 | 35 | 40 | 45 | 41 | 38 | 40 | 40 | 42 | 49 | 67 | 32 |
| 18 | 44 | 44 | 44 | 42 | 39 | 40 | 42 | 41 | 39 | 35 | 31 | 27 | 26 | 29 | 30 | 31 | 31 | 36 | 39 | 43 | 41 | 45 | 48 | 50 | 38 | 50 | 26 |
| 19 | 50 | 51 | 53 | 53 | 54 | 50 | 52 | 48 | 41 | 39 | 34 | 29 | 28 | 32 | 32 | 31 | 28 | 32 | 37 | 40 | 43 | 44 | 47 | 49 | 41 | 54 | 28 |
| 20 | 49 | 51 | 53 | 54 | 54 | 54 | 52 | 51 | 49 | 44 | 38 | 37 | 35 | 39 | 39 | 40 | 37 | 39 | 42 | 42 | 44 | 45 | 44 | 45 | 45 | 54 | 35 |
| 21 | 46 | 48 | 48 | 47 | 48 | 49 | 49 | 48 | 44 | 42 | 40 | 36 | 34 | 33 | 38 | 39 | 40 | 41 | 42 | 51 | 65 | 73 | 72 | 77 | 48 | 77 | 33 |
| 22 | 79 | 81 | 72 | 67 | 58 | 67 | 88 | 89 | 92 | 94 | 95 | 95 | 95 | 95 | 95 | 94 | 94 | 94 | 93 | 94 | 94 | 94 | 95 | 97 | 88 | 97 | 58 |
| 23 | 97 | 97 | 97 | 90 | 78 | 77 | 77 | 79 | 78 | 74 | 74 | 76 | 75 | 73 | 70 | 67 | 66 | 65 | 64 | 68 | 67 | 66 | 68 | 75 | 76 | 97 | 64 |
| 24 | 69 | 67 | 67 | 65 | 70 | 70 | 68 | 69 | 72 | 68 | 69 | 72 | 73 | 71 | 66 | 63 | 63 | 64 | 65 | 62 | 61 | 63 | 64 | 63 | 67 | 73 | 61 |
| 25 | 61 | 68 | 64 | 66 | 69 | 71 | 73 | 74 | 63 | 54 | 49 | 48 | 49 | 54 | 55 | 54 | 55 | 64 | 73 | 62 | 56 | 51 | 45 | 45 | 59 | 74 | 45 |
| 26 | 46 | 46 | 40 | 38 | 39 | 45 | 40 | 44 | 45 | 41 | 39 | 38 | 35 | 30 | 30 | 25 | 23 | 26 | 28 | 27 | 29 | 30 | 31 | 32 | 35 | 46 | 23 |
| 27 | 33 | 29 | 28 | 28 | 30 | 29 | 28 | 29 | 26 | 25 | 25 | 24 | 23 | 23 | 23 | 22 | 22 | 22 | 22 | 22 | 23 | 24 | 25 | 26 | 25 | 33 | 22 |
| 28 | 25 | 26 | 26 | 26 | 27 | 28 | 28 | 28 | 27 | 25 | 25 | 24 | 23 | 22 | 22 | 22 | 23 | 25 | 26 | 27 | 28 | 28 | 28 | 29 | 26 | 29 | 22 |
| 29 | 29 | 30 | 31 | 33 | 34 | 34 | 34 | 34 | 32 | 30 | 29 | 28 | 28 | 26 | 26 | 26 | 32 | 38 | 43 | 40 | 38 | 44 | 50 | 49 | 34 | 50 | 26 |
| 30 | 48 | 42 | 41 | 45 | 48 | 52 | 46 | 46 | 40 | 35 | 33 | 33 | 32 | 31 | 31 | 35 | 46 | 56 | 60 | 60 | 60 | 58 | 57 | 66 | 46 | 66 | 31 |
| Avg | 41 | 41 | 40 | 40 | 40 | 41 | 42 | 42 | 39 | 37 | 34 | 33 | 31 | 31 | 30 | 30 | 32 | 34 | 36 | 38 | 38 | 38 | 39 | 42 | 37 | -- | -- |
| Max | 97 | 97 | 97 | 90 | 78 | 77 | 88 | 89 | 92 | 94 | 95 | 95 | 95 | 95 | 95 | 94 | 94 | 94 | 93 | 94 | 94 | 94 | 95 | 97 | -- | 97 | -- |
| Min | 10 | 11 | 10 | 9 | 9 | 10 | 9 | 9 | 8 | 5 | 4 | 4 | 4 | 4 | 3 | 2 | 4 | 4 | 6 | 6 | 8 | 9 | 9 | 10 | -- | -- | 2 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, RH_Percent"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 65 | 59 | 53 | 49 | 48 | 53 | 54 | 49 | 47 | 40 | 33 | 27 | 24 | 24 | 34 | 40 | 43 | 49 | 54 | 54 | 55 | 56 | 43 | 40 | 46 | 65 | 24 |
| 2 | 40 | 39 | 36 | 35 | 35 | 39 | 40 | 38 | 35 | 30 | 24 | 24 | 29 | 29 | 32 | 32 | 33 | 40 | 46 | 52 | 54 | 51 | 42 | 36 | 37 | 54 | 24 |
| 3 | 37 | 42 | 45 | 44 | 47 | 49 | 50 | 50 | 47 | 39 | 30 | 24 | 21 | 16 | 18 | 18 | 23 | 31 | 35 | 33 | 37 | 42 | 45 | 45 | 36 | 50 | 16 |
| 4 | 40 | 34 | 37 | 41 | 42 | 47 | 49 | 47 | 46 | 45 | 49 | 55 | 54 | 61 | 76 | 81 | 82 | 74 | 75 | 79 | 76 | 72 | 78 | 79 | 59 | 82 | 34 |
| 5 | 79 | 73 | 71 | 73 | 77 | 71 | 73 | 76 | 63 | 56 | 46 | 39 | 36 | 33 | 32 | 33 | 36 | 40 | 44 | 46 | 45 | 48 | 51 | 52 | 54 | 79 | 32 |
| 6 | 51 | 51 | 50 | 47 | 48 | 44 | 42 | 42 | 40 | 34 | 28 | 26 | 24 | 23 | 23 | 25 | 27 | 32 | 36 | 44 | 43 | 47 | 42 | 45 | 38 | 51 | 23 |
| 7 | 49 | 45 | 44 | 43 | 41 | 41 | 38 | 41 | 38 | 31 | 29 | 25 | 26 | 23 | 26 | 30 | 33 | 38 | 39 | 43 | 40 | 45 | 51 | 62 | 38 | 62 | 23 |
| 8 | 69 | 82 | 82 | 85 | 85 | 83 | 79 | 82 | 82 | 73 | 61 | 55 | 55 | 53 | 48 | 46 | 49 | 51 | 52 | 49 | 50 | 51 | 50 | 44 | 63 | 85 | 44 |
| 9 | 43 | 50 | 57 | 57 | 56 | 58 | 60 | 61 | 51 | 37 | 34 | 31 | 22 | 19 | 17 | 13 | 12 | 12 | 15 | 16 | 16 | 18 | 19 | 17 | 33 | 61 | 12 |
| 10 | 16 | 17 | 16 | 13 | 14 | 17 | 14 | 12 | 13 | 12 | 12 | 12 | 12 | 11 | 12 | 12 | 12 | 13 | 14 | 14 | 14 | 14 | 14 | 15 | 14 | 17 | 11 |
| 11 | 14 | 14 | 14 | 15 | 15 | 15 | 15 | 16 | 15 | 15 | 15 | 15 | 16 | 15 | 16 | 16 | 17 | 19 | 20 | 23 | 23 | 22 | 24 | 23 | 17 | 24 | 14 |
| 12 | 23 | 21 | 21 | 23 | 24 | 25 | 26 | 26 | 26 | 24 | 24 | 23 | 25 | 28 | 32 | 36 | 40 | 44 | 48 | 50 | 53 | 49 | 45 | 52 | 33 | 53 | 21 |
| 13 | 50 | 52 | 48 | 47 | 49 | 50 | 51 | 53 | 44 | 36 | 31 | 29 | 29 | 29 | 30 | 31 | 31 | 35 | 36 | 39 | 43 | 43 | 46 | 47 | 41 | 53 | 29 |
| 14 | 47 | 46 | 51 | 49 | 49 | 50 | 41 | 33 | 24 | 23 | 20 | 20 | 18 | 16 | 15 | 14 | 14 | 14 | 16 | 17 | 20 | 23 | 25 | 25 | 28 | 51 | 14 |
| 15 | 23 | 22 | 22 | 23 | 24 | 26 | 27 | 28 | 24 | 15 | 13 | 13 | 13 | 13 | 12 | 15 | 20 | 24 | 25 | 19 | 19 | 19 | 17 | 16 | 20 | 28 | 12 |
| 16 | 17 | 18 | 19 | 20 | 19 | 20 | 23 | 21 | 17 | 14 | 13 | 12 | 11 | 10 | 11 | 12 | 14 | 18 | 21 | 19 | 15 | 19 | 17 | 18 | 17 | 23 | 10 |
| 17 | 15 | 19 | 18 | 14 | 14 | 13 | 12 | 13 | 13 | 13 | 12 | 11 | 11 | 10 | 9 | 9 | 9 | 10 | 12 | 11 | 13 | 13 | 15 | 14 | 13 | 19 | 9 |
| 18 | 15 | 14 | 15 | 15 | 14 | 14 | 14 | 15 | 15 | 15 | 13 | 12 | 13 | 14 | 12 | 11 | 13 | 14 | 18 | 18 | 18 | 19 | 22 | 24 | 15 | 24 | 11 |
| 19 | 24 | 23 | 27 | 30 | 30 | 30 | 29 | 28 | 27 | 24 | 21 | 18 | 17 | 16 | 16 | 16 | 21 | 28 | 37 | 45 | 50 | 56 | 58 | 60 | 30 | 60 | 16 |
| 20 | 64 | 67 | 59 | 48 | 48 | 86 | 94 | 85 | 75 | 71 | 77 | 76 | 67 | 67 | 65 | 74 | 76 | 70 | 77 | 85 | 93 | 94 | 94 | 95 | 75 | 95 | 48 |
| 21 | 95 | 95 | 96 | 97 | 97 | 97 | 97 | 95 | 91 | 89 | 83 | 76 | 74 | 73 | 70 | 66 | 62 | 64 | 55 | 66 | 72 | 70 | 71 | 68 | 80 | 97 | 55 |
| 22 | 73 | 73 | 75 | 76 | 76 | 71 | 70 | 68 | 61 | 54 | 46 | 45 | 44 | 46 | 52 | 53 | 56 | 63 | 69 | 76 | 77 | 76 | 75 | 61 | 64 | 77 | 44 |
| 23 | 56 | 51 | 45 | 33 | 31 | 32 | 31 | 31 | 32 | 31 | 27 | 22 | 19 | 18 | 19 | 19 | 19 | 21 | 21 | 21 | 22 | 25 | 25 | 25 | 28 | 56 | 18 |
| 24 | 20 | 20 | 19 | 20 | 26 | 27 | 22 | 23 | 25 | 23 | 21 | 20 | 19 | 20 | 20 | 20 | 20 | 27 | 34 | 35 | 28 | 31 | 20 | 23 | 23 | 35 | 19 |
| 25 | 23 | 20 | 15 | 12 | 12 | 17 | 8 | 15 | 18 | 16 | 16 | 18 | 17 | 15 | 13 | 13 | 13 | 15 | 18 | 20 | 18 | 18 | 18 | 20 | 16 | 23 | 8 |
| 26 | 20 | 21 | 24 | 25 | 23 | 25 | 23 | 19 | 20 | 23 | 22 | 19 | 18 | 16 | 15 | 15 | 14 | 20 | 22 | 21 | 24 | 23 | 20 | 17 | 20 | 25 | 14 |
| 27 | 17 | 16 | 13 | 16 | 16 | 18 | 23 | 21 | 16 | 17 | 17 | 15 | 14 | 14 | 14 | 14 | 13 | 14 | 14 | 18 | 19 | 19 | 22 | 25 | 17 | 25 | 13 |
| 28 | 26 | 28 | 30 | 29 | 24 | 27 | 26 | 25 | 25 | 20 | 19 | 18 | 18 | 15 | 15 | 16 | 19 | 26 | 30 | 30 | 32 | 29 | 33 | 31 | 25 | 33 | 15 |
| 29 | 27 | 29 | 28 | 28 | 31 | 33 | 31 | 32 | 31 | 27 | 21 | 20 | 19 | 18 | 17 | 17 | 16 | 18 | 23 | 26 | 20 | 22 | 23 | 25 | 24 | 33 | 16 |
| 30 | 24 | 27 | 29 | 28 | 26 | 28 | 30 | 29 | 29 | 23 | 18 | 16 | 14 | 16 | 22 | 21 | 24 | 28 | 33 | 36 | 37 | 29 | 24 | 21 | 26 | 37 | 14 |
| 31 | 21 | 19 | 18 | 18 | 19 | 21 | 23 | 24 | 27 | 20 | 20 | 19 | 17 | 16 | 16 | 15 | 15 | 19 | 22 | 22 | 22 | 22 | 25 | 21 | 20 | 27 | 15 |
| Avg | 38 | 38 | 38 | 37 | 38 | 40 | 39 | 39 | 36 | 32 | 29 | 27 | 26 | 25 | 26 | 27 | 28 | 31 | 34 | 36 | 37 | 38 | 37 | 37 | 34 | -- | -- |
| Max | 95 | 95 | 96 | 97 | 97 | 97 | 97 | 95 | 91 | 89 | 83 | 76 | 74 | 73 | 76 | 81 | 82 | 74 | 77 | 85 | 93 | 94 | 94 | 95 | -- | 97 | -- |
| Min | 14 | 14 | 13 | 12 | 12 | 13 | 8 | 12 | 13 | 12 | 12 | 11 | 11 | 10 | 9 | 9 | 9 | 10 | 12 | 11 | 13 | 13 | 14 | 14 | -- | -- | 8 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, Precip_Inches"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Total | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.095 | 0.024 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.123 | 0.095 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.016 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.016 | 0.016 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.095 | 0.04 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.139 | -- | -- |
| Max | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.095 | 0.024 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | 0.095 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, Precip_Inches"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Total | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0.008 | 0.004 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 | 0.047 | 0.114 | 0 | 0 | 0 | 0 | 0.169 | 0.114 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 21 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.008 | 0.067 | 0.004 | 0.024 | 0.103 | 0.067 | 0 |
| 22 | 0.04 | 0.036 | 0.012 | 0 | 0.004 | 0 | 0.079 | 0.166 | 0.122 | 0.208 | 0.084 | 0.016 | 0.13 | 0.075 | 0.024 | 0.02 | 0.004 | 0.06 | 0.036 | 0.02 | 0 | 0 | 0.044 | 0.103 | 1.28 | 0.208 | 0 |
| 23 | 0.036 | 0.112 | 0.072 | 0.04 | 0.036 | 0.068 | 0.06 | 0.119 | 0.06 | 0.044 | 0.079 | 0.193 | 0.04 | 0.008 | 0 | 0 | 0 | 0 | 0 | 0.02 | 0.004 | 0 | 0.004 | 0.004 | 0.999 | 0.193 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0.016 | 0 | 0 | 0 | 0.008 | 0 | 0.008 | 0.028 | 0.02 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.084 | 0.028 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 0.076 | 0.148 | 0.084 | 0.044 | 0.056 | 0.068 | 0.139 | 0.285 | 0.19 | 0.252 | 0.171 | 0.237 | 0.19 | 0.087 | 0.024 | 0.024 | 0.008 | 0.06 | 0.083 | 0.154 | 0.012 | 0.067 | 0.056 | 0.135 | 2.65 | -- | -- |
| Max | 0.04 | 0.112 | 0.072 | 0.04 | 0.036 | 0.068 | 0.079 | 0.166 | 0.122 | 0.208 | 0.084 | 0.193 | 0.13 | 0.075 | 0.024 | 0.02 | 0.004 | 0.06 | 0.047 | 0.114 | 0.008 | 0.067 | 0.044 | 0.103 | -- | 0.208 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, Precip_Inches"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Total | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 2 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 3 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 4 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 |
| 5 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 6 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.11 | 0.11 | 0 |
| 7 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 8 | 0 | 0 | 0.004 | 0.004 | 0.012 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.02 | 0.012 | 0 |
| 9 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 10 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 11 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 12 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 13 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 14 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 15 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 16 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 17 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 18 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 19 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 20 | 0 | 0 | 0 | 0 | 0 | 0.217 | 0.224 | 0.071 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0 | 0 | 0 | 0.028 | 0.024 | 0.02 | 0.024 | 0.012 | 0.624 | 0.224 | 0 |
| 21 | 0.068 | 0.083 | 0.036 | 0.076 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0.263 | 0.083 | 0 |
| 22 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 23 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 24 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 25 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 26 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 27 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 28 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 29 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 30 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| 31 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 |
| Total | 0.068 | 0.083 | 0.04 | 0.08 | 0.012 | 0.217 | 0.224 | 0.071 | 0 | 0.11 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 | 0 | 0.028 | 0.024 | 0.02 | 0.024 | 0.012 | 1.02 | -- | -- |
| Max | 0.068 | 0.083 | 0.036 | 0.076 | 0.012 | 0.217 | 0.224 | 0.071 | 0 | 0.11 | 0 | 0 | 0 | 0 | 0 | 0.004 | 0.004 | 0 | 0 | 0.028 | 0.024 | 0.02 | 0.024 | 0.012 | -- | 0.224 | -- |
| Min | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | 0 | -- | -- | 0 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, BP_mmHg"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 683 | 682 | 682 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 683 | 681 |
| 2 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 682 | 682 | 681 | 681 | 680 | 680 | 680 | 680 | 680 | 681 | 680 | 680 | 680 | 681 | 683 | 680 |
| 3 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 681 | 681 | 681 | 681 | 680 | 679 | 679 | 678 | 678 | 678 | 677 | 678 | 678 | 678 | 679 | 679 | 679 | 679 | 681 | 677 |
| 4 | 679 | 680 | 680 | 680 | 680 | 680 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 681 | 681 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 681 | 683 | 679 |
| 5 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 685 | 685 | 685 | 686 | 684 |
| 6 | 685 | 686 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 686 | 684 |
| 7 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 683 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 683 | 684 | 681 |
| 8 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 680 | 680 | 679 | 679 | 679 | 679 | 678 | 678 | 679 | 679 | 679 | 679 | 680 | 681 | 678 |
| 9 | 679 | 679 | 678 | 678 | 678 | 678 | 678 | 678 | 679 | 679 | 678 | 678 | 677 | 677 | 676 | 676 | 676 | 676 | 677 | 677 | 677 | 678 | 678 | 678 | 678 | 679 | 676 |
| 10 | 678 | 678 | 678 | 678 | 678 | 678 | 679 | 680 | 680 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 682 | 678 |
| 11 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 683 | 682 | 682 | 682 | 682 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 683 | 681 |
| 12 | 682 | 682 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 681 | 680 | 680 | 680 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 680 |
| 13 | 682 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 683 | 683 | 683 | 682 | 682 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 683 | 682 | 683 | 681 |
| 14 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 684 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 684 | 682 |
| 15 | 682 | 682 | 682 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 681 | 680 | 680 | 680 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 681 | 682 | 680 |
| 16 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 684 | 684 | 685 | 685 | 684 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 683 | 685 | 682 |
| 17 | 683 | 684 | 683 | 683 | 683 | 684 | 684 | 684 | 685 | 684 | 684 | 683 | 683 | 682 | 682 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 683 | 685 | 681 |
| 18 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 683 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 682 |
| 19 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 684 | 683 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 682 | 683 | 684 | 682 |
| 20 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 682 | 682 | 681 | 681 | 680 | 680 | 680 | 680 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 683 | 680 |
| 21 | 681 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 682 | 683 | 681 |
| 22 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 685 | 685 | 684 | 684 | 684 | 683 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 685 | 682 |
| 23 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 681 | 681 | 680 | 680 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 680 |
| 24 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 682 | 682 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 683 | 683 | 683 | 682 | 683 | 681 |
| 25 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 685 | 685 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 684 | 685 | 683 |
| 26 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 683 | 685 | 686 | 683 |
| 27 | 683 | 683 | 683 | 683 | 682 | 682 | 682 | 682 | 683 | 683 | 682 | 682 | 681 | 680 | 679 | 679 | 679 | 678 | 679 | 679 | 679 | 679 | 679 | 679 | 681 | 683 | 678 |
| 28 | 679 | 679 | 679 | 679 | 679 | 679 | 679 | 680 | 680 | 680 | 680 | 680 | 680 | 679 | 679 | 679 | 679 | 679 | 679 | 680 | 680 | 680 | 680 | 681 | 679 | 681 | 679 |
| 29 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 680 | 680 | 679 | 679 | 680 | 680 | 680 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 679 |
| 30 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 683 | 683 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 684 | 684 | 682 | 684 | 681 |
| 31 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 685 | 685 | 685 | 684 | 684 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 685 | 684 | 685 | 683 |
| Avg | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 682 | 682 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 682 | -- | -- |
| Max | 685 | 686 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 685 | 685 | -- | 686 | -- |
| Min | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 679 | 679 | 678 | 678 | 677 | 677 | 676 | 676 | 676 | 676 | 677 | 677 | 677 | 678 | 678 | 678 | -- | -- | 676 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, BP_mmHg"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 686 | 684 |
| 2 | 684 | 684 | 684 | 684 | 684 | 683 | 683 | 684 | 684 | 684 | 684 | 683 | 683 | 682 | 681 | 681 | 681 | 680 | 680 | 681 | 680 | 681 | 681 | 682 | 682 | 684 | 680 |
| 3 | 681 | 681 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 679 | 679 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 679 | 681 | 678 |
| 4 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 679 | 679 | 679 | 679 | 679 | 678 | 677 | 677 | 677 | 676 | 676 | 677 | 677 | 677 | 678 | 679 | 680 | 678 | 680 | 676 |
| 5 | 680 | 680 | 680 | 680 | 680 | 681 | 682 | 682 | 683 | 683 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 685 | 685 | 685 | 686 | 686 | 686 | 683 | 686 | 680 |
| 6 | 686 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 689 | 689 | 689 | 689 | 688 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 687 | 688 | 689 | 686 |
| 7 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 687 | 687 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 688 | 685 |
| 8 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 685 | 683 |
| 9 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 685 | 685 | 684 | 686 | 684 |
| 10 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 684 | 685 | 686 | 684 |
| 11 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 686 | 686 | 685 | 686 | 684 |
| 12 | 686 | 686 | 686 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 688 | 687 | 687 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 688 | 688 | 687 | 687 | 688 | 686 |
| 13 | 687 | 687 | 687 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 686 | 686 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 687 | 684 |
| 14 | 683 | 684 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 683 | 682 | 682 | 681 | 681 | 681 | 681 | 681 | 680 | 680 | 680 | 680 | 680 | 682 | 684 | 680 |
| 15 | 679 | 679 | 679 | 678 | 678 | 678 | 678 | 678 | 679 | 678 | 678 | 677 | 677 | 676 | 675 | 675 | 674 | 674 | 675 | 675 | 676 | 676 | 677 | 677 | 677 | 679 | 674 |
| 16 | 677 | 677 | 677 | 677 | 677 | 677 | 678 | 678 | 679 | 679 | 680 | 679 | 679 | 678 | 678 | 678 | 678 | 678 | 679 | 679 | 679 | 680 | 680 | 681 | 678 | 681 | 677 |
| 17 | 681 | 681 | 682 | 682 | 682 | 682 | 683 | 683 | 684 | 684 | 685 | 684 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 683 | 685 | 681 |
| 18 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 685 | 685 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 683 | 684 | 685 | 683 |
| 19 | 683 | 683 | 683 | 683 | 682 | 682 | 682 | 682 | 683 | 683 | 682 | 682 | 681 | 681 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 681 | 683 | 680 |
| 20 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 679 | 679 | 679 | 679 | 679 | 679 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 679 |
| 21 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 681 | 681 | 682 | 682 | 681 | 681 | 680 | 680 | 680 | 680 | 680 | 681 | 681 | 681 | 681 | 681 | 680 | 681 | 682 | 680 |
| 22 | 680 | 680 | 679 | 678 | 678 | 678 | 679 | 679 | 679 | 680 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 682 | 680 | 682 | 678 |
| 23 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 683 | 684 | 682 |
| 24 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 686 | 686 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 685 | 686 | 684 |
| 25 | 686 | 686 | 686 | 685 | 685 | 685 | 685 | 686 | 686 | 687 | 687 | 687 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 687 | 687 | 687 | 686 | 687 | 685 |
| 26 | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 688 | 689 | 689 | 689 | 689 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 689 | 687 |
| 27 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 685 | 685 | 685 | 685 | 684 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 686 | 683 |
| 28 | 684 | 684 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 685 | 684 | 684 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 685 | 685 | 685 | 684 | 685 | 683 |
| 29 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 687 | 687 | 687 | 687 | 686 | 686 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 685 |
| 30 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 686 | 686 | 685 | 685 | 684 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 687 | 684 |
| Avg | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 684 | 684 | 684 | 683 | 683 | 683 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | -- | -- |
| Max | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 688 | 689 | 689 | 689 | 689 | 688 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 687 | -- | 689 | -- |
| Min | 677 | 677 | 677 | 677 | 677 | 677 | 678 | 678 | 679 | 678 | 678 | 677 | 677 | 676 | 675 | 675 | 674 | 674 | 675 | 675 | 676 | 676 | 677 | 677 | -- | -- | 674 |

**SAROAD for Resolution, West_Plant**
**"Component, Channel: Table100, BP_mmHg"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 688 | 688 | 687 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 688 | 686 |
| 2 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 684 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 681 | 681 | 681 | 683 | 686 | 681 |
| 3 | 680 | 680 | 680 | 679 | 679 | 679 | 679 | 679 | 679 | 680 | 680 | 679 | 678 | 678 | 677 | 677 | 677 | 676 | 676 | 676 | 677 | 677 | 677 | 677 | 678 | 680 | 676 |
| 4 | 677 | 676 | 676 | 676 | 676 | 677 | 677 | 678 | 678 | 679 | 679 | 679 | 678 | 678 | 678 | 679 | 679 | 679 | 679 | 679 | 680 | 680 | 680 | 680 | 678 | 680 | 676 |
| 5 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 680 | 681 | 681 | 682 | 682 | 681 | 681 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 683 | 683 | 684 | 681 | 684 | 680 |
| 6 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 686 | 686 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 686 | 684 |
| 7 | 684 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 683 | 684 | 684 | 683 | 682 | 682 | 682 | 681 | 681 | 682 | 682 | 682 | 682 | 682 | 682 | 682 | 683 | 684 | 681 |
| 8 | 682 | 682 | 682 | 682 | 682 | 683 | 683 | 684 | 684 | 684 | 685 | 684 | 684 | 683 | 683 | 683 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 684 | 683 | 685 | 682 |
| 9 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 686 | 686 | 687 | 688 | 688 | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 688 | 688 | 689 | 689 | 688 | 687 | 689 | 684 |
| 10 | 688 | 688 | 688 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 687 | 687 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 688 | 685 |
| 11 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 686 | 687 | 687 | 687 | 687 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 687 | 686 | 687 | 685 |
| 12 | 687 | 687 | 687 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 686 | 686 | 685 | 685 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 687 | 684 |
| 13 | 685 | 685 | 685 | 685 | 684 | 685 | 685 | 685 | 685 | 686 | 686 | 686 | 685 | 685 | 685 | 684 | 684 | 684 | 685 | 685 | 685 | 686 | 686 | 686 | 685 | 686 | 684 |
| 14 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 688 | 688 | 688 | 689 | 688 | 688 | 688 | 688 | 688 | 688 | 688 | 689 | 689 | 689 | 690 | 689 | 688 | 690 | 686 |
| 15 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 688 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 689 | 687 |
| 16 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 687 | 687 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 686 |
| 17 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 688 | 687 | 686 | 686 | 686 | 685 | 685 | 685 | 685 | 686 | 686 | 685 | 685 | 687 | 688 | 685 |
| 18 | 685 | 684 | 684 | 684 | 684 | 683 | 683 | 684 | 684 | 684 | 684 | 683 | 682 | 682 | 681 | 681 | 681 | 680 | 680 | 680 | 680 | 679 | 679 | 679 | 682 | 685 | 679 |
| 19 | 679 | 679 | 679 | 679 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 678 | 677 | 676 | 676 | 675 | 675 | 676 | 676 | 676 | 677 | 677 | 677 | 676 | 677 | 679 | 675 |
| 20 | 676 | 675 | 675 | 674 | 674 | 675 | 676 | 676 | 675 | 676 | 676 | 676 | 675 | 675 | 675 | 675 | 676 | 676 | 676 | 677 | 677 | 677 | 677 | 677 | 676 | 677 | 674 |
| 21 | 677 | 677 | 677 | 677 | 677 | 678 | 678 | 679 | 679 | 679 | 680 | 680 | 679 | 679 | 679 | 680 | 680 | 680 | 681 | 681 | 682 | 682 | 683 | 683 | 680 | 683 | 677 |
| 22 | 683 | 683 | 684 | 684 | 685 | 685 | 685 | 685 | 686 | 687 | 687 | 687 | 687 | 686 | 686 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 689 | 686 | 689 | 683 |
| 23 | 689 | 688 | 688 | 689 | 689 | 689 | 689 | 690 | 690 | 690 | 691 | 690 | 690 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 688 | 688 | 688 | 689 | 691 | 688 |
| 24 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 687 | 687 | 686 | 686 | 686 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 688 | 685 |
| 25 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 688 | 688 | 688 | 689 | 688 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 689 | 686 |
| 26 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 687 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 688 | 686 |
| 27 | 687 | 687 | 687 | 687 | 687 | 686 | 687 | 687 | 687 | 688 | 688 | 687 | 687 | 686 | 686 | 686 | 686 | 685 | 685 | 686 | 686 | 686 | 686 | 686 | 686 | 688 | 685 |
| 28 | 686 | 685 | 685 | 685 | 685 | 684 | 684 | 684 | 684 | 685 | 685 | 684 | 683 | 682 | 682 | 682 | 682 | 682 | 682 | 681 | 682 | 682 | 682 | 682 | 683 | 686 | 681 |
| 29 | 682 | 681 | 681 | 681 | 681 | 681 | 682 | 682 | 683 | 683 | 683 | 683 | 683 | 682 | 682 | 683 | 683 | 683 | 684 | 684 | 685 | 685 | 685 | 686 | 683 | 686 | 681 |
| 30 | 686 | 686 | 686 | 686 | 687 | 687 | 687 | 687 | 688 | 688 | 689 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 688 | 688 | 687 | 689 | 686 |
| 31 | 688 | 688 | 687 | 687 | 687 | 687 | 687 | 687 | 687 | 688 | 688 | 687 | 686 | 686 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 685 | 686 | 688 | 685 |
| Avg | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 685 | 685 | 685 | 685 | 685 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | 684 | -- | -- |
| Max | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 690 | 690 | 690 | 691 | 690 | 690 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 689 | 690 | 689 | -- | 691 | -- |
| Min | 676 | 675 | 675 | 674 | 674 | 675 | 676 | 676 | 675 | 676 | 676 | 676 | 675 | 675 | 675 | 675 | 675 | 676 | 676 | 676 | 677 | 677 | 677 | 676 | -- | -- | 674 |

# Appendix D: $PM_{10}$ and $PM_{2.5}$ Data – Hourly

## SAROAD for Resolution, East_Plant

## "Component, Channel: Table125, conc_PM10_µg/m$^3$_STP"

## Month: Oct 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 12.6 | 18.2 | 9.1 | 9.1 | 9.1 | 10.2 | 11.3 | 13.6 | 18.4 | 9.2 | 9.3 | 10.5 | 10.5 | 10.5 | 9.4 | 10.5 | 12.8 | 17.5 | 19.7 | 19.7 | 15.0 | 13.8 | 12.6 | 13.7 | 12.8 | 19.7 | 9.1 |
| 2 | 12.6 | 10.3 | 12.5 | 13.7 | 13.6 | 11.3 | 10.2 | 13.6 | 21.8 | 9.2 | 10.4 | 11.6 | 10.5 | 11.7 | 14.0 | 14.0 | 14.0 | 16.3 | 16.2 | 13.9 | 11.5 | 10.3 | 6.9 | 6.9 | 12.4 | 21.8 | 6.9 |
| 3 | 11.4 | 10.3 | 8.0 | 8.0 | 10.2 | 9.1 | 17.0 | 13.7 | 12.6 | 11.5 | 20.8 | 7.0 | 5.8 | 9.3 | 14.1 | 21.1 | 24.6 | 12.8 | 18.6 | 15.1 | 13.9 | 11.6 | 18.4 | 18.4 | 13.5 | 24.6 | 5.8 |
| 4 | 19.5 | 20.6 | 23.9 | 22.7 | 20.3 | 23.7 | 19.1 | 23.8 | 54.7 | 19.5 | 18.4 | 16.1 | 21.9 | 20.8 | 28.9 | 26.6 | 31.2 | 36.8 | 29.8 | 28.6 | 25.1 | 27.2 | 36.1 | 94.4 | 28.7 | 94.4 | 16.1 |
| 5 | 51.5 | 123.0 | 115.0 | 98.9 | 74.2 | 32.1 | 63.1 | 27.7 | 3.3 | 5.6 | 10.1 | 36.3 | 10.3 | 18.3 | 4.6 | 6.9 | 11.4 | 11.4 | 11.3 | 23.7 | 10.1 | 12.4 | 30.4 | 38.3 | 34.6 | 123.0 | 3.3 |
| 6 | 157.0 | 14.6 | 7.8 | 4.5 | 4.5 | 3.4 | 3.4 | 2.2 | 5.6 | 11.3 | 14.8 | 11.4 | 5.8 | 4.6 | 2.3 | 1.2 | 7.0 | 38.1 | 8.0 | 8.0 | 5.7 | 6.8 | 7.9 | 9.1 | 14.4 | 157.0 | 1.2 |
| 7 | 10.2 | 7.9 | 7.9 | 10.2 | 11.3 | 9.0 | 21.4 | 27.1 | 42.1 | 27.6 | 6.9 | 11.6 | 10.5 | 8.2 | 11.7 | 20.0 | 14.0 | 9.3 | 8.1 | 12.7 | 12.7 | 10.3 | 8.0 | 6.9 | 13.6 | 42.1 | 6.9 |
| 8 | 9.2 | 10.4 | 8.0 | 5.7 | 8.0 | 10.2 | 10.2 | 13.7 | 13.8 | 12.7 | 12.8 | 17.5 | 24.5 | 28.0 | 65.4 | -- | 30.3 | 18.6 | 15.1 | 15.1 | 17.4 | 13.9 | 23.1 | 26.4 | 17.8 | 65.4 | 5.7 |
| 9 | 10.3 | 10.3 | 6.9 | 4.6 | 4.6 | 4.6 | 8.0 | 11.4 | -- | 10.4 | 11.6 | 44.2 | 139.0 | 80.9 | 176.0 | 128.0 | 319.0 | 290.0 | 163.0 | 62.0 | 49.1 | 31.9 | 27.2 | 19.2 | 70.1 | 319.0 | 4.6 |
| 10 | 14.6 | 20.2 | 22.5 | 16.8 | 28.0 | 35.7 | 19.0 | 17.6 | 6.6 | 6.6 | 6.6 | 18.7 | 23.1 | 17.8 | 11.1 | 8.9 | 6.7 | 18.9 | 22.2 | 8.9 | 11.0 | 11.0 | 11.0 | 9.9 | 15.6 | 35.7 | 6.6 |
| 11 | 5.5 | 5.5 | 6.6 | 6.6 | 6.6 | 6.6 | 10.9 | 12.1 | 12.2 | 11.2 | 6.8 | 6.8 | 5.7 | 7.9 | 12.5 | 13.7 | 13.6 | 13.6 | 12.4 | 10.1 | 10.1 | 6.7 | 5.6 | 7.8 | 9.0 | 13.7 | 5.5 |
| 12 | 6.7 | 4.5 | 4.5 | 5.6 | 4.4 | 5.6 | 5.6 | 6.7 | 13.6 | 14.8 | 10.3 | 9.2 | 10.4 | 10.4 | 12.8 | 13.9 | 11.5 | 12.6 | 13.7 | 16.0 | 14.8 | 10.2 | 7.9 | 9.1 | 9.8 | 16.0 | 4.4 |
| 13 | 11.3 | 11.3 | 9.0 | 9.0 | 11.3 | 12.4 | 10.1 | 12.5 | 14.8 | 12.6 | 10.3 | 11.5 | 10.4 | 9.2 | 12.7 | 19.6 | 16.1 | 12.6 | 10.3 | 11.4 | 13.7 | 12.5 | 11.3 | 13.6 | 12.1 | 19.6 | 9.0 |
| 14 | 12.4 | 10.1 | 11.2 | 13.4 | 12.3 | 11.1 | 12.2 | 11.2 | 11.3 | 13.6 | 12.5 | 9.1 | 11.4 | 11.5 | 9.2 | 10.3 | 12.6 | 12.5 | 13.6 | 14.7 | 12.4 | 13.6 | 13.5 | 11.2 | 12.0 | 14.7 | 9.1 |
| 15 | 10.1 | 8.9 | 10.0 | 8.9 | 6.7 | 7.8 | 7.8 | 10.1 | 11.3 | 17.1 | 13.7 | 24.0 | 16.1 | 20.7 | 18.4 | 13.8 | 19.5 | 16.0 | 15.9 | 18.1 | 19.2 | 18.1 | 15.8 | 13.5 | 14.2 | 24.0 | 6.7 |
| 16 | 10.1 | 16.7 | 8.9 | 8.9 | 8.9 | 6.7 | 6.7 | 18.9 | 19.0 | 10.1 | 10.2 | 8.0 | 9.1 | 9.2 | 6.9 | 6.9 | 8.0 | 9.1 | 12.4 | 14.7 | 14.6 | 14.6 | 19.1 | 10.0 | 11.1 | 19.1 | 6.7 |
| 17 | 10.0 | 6.7 | 4.5 | 6.7 | 6.6 | 3.3 | 3.3 | 7.8 | 4.5 | 1.1 | 6.8 | 10.2 | 10.3 | 18.3 | 18.4 | 12.6 | 19.5 | 20.5 | 22.7 | 21.5 | 15.8 | 13.6 | 12.4 | 13.6 | 11.3 | 22.7 | 1.1 |
| 18 | 18.0 | 5.6 | 6.7 | 10.1 | 11.1 | 8.9 | 8.9 | 11.2 | 19.2 | 20.4 | 8.0 | 5.7 | 4.6 | 8.1 | 10.4 | 10.4 | 18.4 | 22.8 | 20.5 | 14.7 | 15.8 | 11.3 | 5.6 | 10.1 | 11.9 | 22.8 | 4.6 |
| 19 | 24.8 | 4.5 | 6.8 | 4.5 | 1.1 | 3.4 | 4.5 | 5.6 | 9.0 | 10.2 | 9.1 | 10.3 | 8.1 | 4.6 | 5.8 | 8.1 | 8.1 | 10.3 | 13.7 | 14.8 | 13.6 | 10.2 | 6.8 | 4.5 | 8.4 | 24.8 | 1.1 |
| 20 | 2.3 | 3.4 | 6.8 | 9.0 | 8.9 | 5.6 | 5.6 | 8.9 | 5.7 | 5.7 | 11.4 | 12.6 | 12.7 | 11.5 | 8.1 | 6.9 | 8.1 | 10.3 | 11.4 | 13.7 | 13.7 | 13.6 | 13.6 | 13.6 | 9.3 | 13.7 | 2.3 |
| 21 | 10.2 | 9.0 | 7.9 | 7.9 | 9.0 | 7.8 | 10.1 | 10.1 | 12.4 | 11.4 | 11.5 | 11.5 | 12.7 | 13.9 | 10.4 | 8.1 | 10.4 | 12.6 | 14.9 | 21.7 | 18.1 | 13.6 | 11.3 | 6.8 | 11.4 | 21.7 | 6.8 |
| 22 | 1.1 | 1.1 | 6.8 | 11.3 | 9.0 | 9.0 | 12.3 | 19.1 | 22.6 | 27.3 | 25.1 | 18.4 | 18.5 | 11.6 | 10.5 | 7.0 | 18.6 | 8.1 | 6.9 | 8.0 | 10.3 | 10.2 | 10.2 | 11.3 | 12.3 | 27.3 | 1.1 |
| 23 | 11.3 | 12.4 | 18.1 | 12.4 | 13.6 | 14.7 | 19.2 | 18.1 | 27.3 | 34.4 | 24.2 | 23.2 | 25.6 | 12.9 | 11.7 | 17.6 | 12.9 | 12.8 | 10.4 | 10.4 | 12.7 | 13.8 | 11.4 | 9.1 | 16.3 | 34.4 | 9.1 |
| 24 | 12.6 | 14.9 | 18.2 | 10.2 | 12.4 | 12.4 | 16.9 | 13.6 | 19.5 | 16.1 | 16.2 | 19.7 | 16.3 | 12.9 | 10.5 | 19.8 | 17.4 | 20.8 | 20.7 | 17.3 | 20.6 | 17.1 | 13.6 | 18.2 | 16.2 | 20.8 | 10.2 |
| 25 | 11.4 | 10.2 | 12.5 | 10.2 | 5.6 | 6.8 | 5.6 | 6.8 | 11.4 | 11.4 | 8.0 | 11.5 | 13.8 | 11.5 | 10.4 | 11.5 | 16.1 | 13.7 | 10.3 | 11.4 | 13.6 | 19.2 | 13.6 | 12.4 | 11.2 | 19.2 | 5.6 |
| 26 | 11.3 | 7.9 | 7.9 | 10.2 | 6.8 | 5.6 | 6.7 | 7.9 | 7.9 | 9.1 | 13.7 | 25.3 | 8.1 | 8.1 | 9.3 | 9.3 | 6.9 | 8.1 | 12.6 | 11.4 | 10.2 | 11.4 | 10.2 | 10.2 | 9.8 | 25.3 | 5.6 |
| 27 | 11.3 | 12.5 | 10.2 | 6.8 | 7.9 | 7.9 | 5.6 | 7.9 | 13.6 | 14.9 | 12.7 | 10.4 | 19.8 | 7.0 | 9.4 | 11.7 | 10.5 | 20.9 | 13.9 | 15.0 | 16.1 | 14.9 | 14.9 | 12.6 | 12.0 | 20.9 | 5.6 |
| 28 | 10.3 | 8.0 | 8.0 | 12.5 | 13.6 | 11.3 | 12.5 | 11.3 | 6.8 | 10.3 | 14.9 | 14.9 | 29.9 | 29.9 | 43.7 | 17.2 | 18.3 | 74.4 | 82.2 | 123.0 | 117.0 | 61.3 | 18.1 | 9.1 | 31.6 | 123.0 | 6.8 |
| 29 | 9.1 | 6.8 | 3.4 | 4.5 | 6.7 | 9.0 | 7.8 | 3.4 | 4.5 | 5.7 | 6.8 | 6.9 | 9.2 | 67.6 | 38.6 | 37.3 | 40.5 | 42.6 | 26.8 | 21.2 | 24.5 | 24.5 | 22.2 | 15.5 | 18.5 | 67.6 | 3.4 |
| 30 | 18.8 | 13.3 | 13.2 | 11.0 | 12.1 | 12.1 | 11.0 | 17.7 | 13.3 | 12.2 | 12.2 | 13.4 | 7.8 | 6.7 | 9.0 | 11.2 | 16.8 | 15.6 | 15.6 | 13.3 | 12.2 | 12.2 | 13.3 | 13.3 | 12.8 | 18.8 | 6.7 |
| 31 | 14.4 | 12.2 | 9.9 | 9.9 | 7.7 | 7.6 | 8.7 | 9.9 | 11.1 | -- | 11.2 | 12.3 | 11.3 | 12.4 | 13.6 | 20.3 | 18.0 | 11.2 | 12.3 | 16.7 | 13.4 | 14.5 | 12.2 | 10.0 | 12.2 | 20.3 | 7.6 |
| Avg | 17.5 | 13.9 | 13.3 | 12.4 | 11.8 | 10.5 | 12.1 | 12.7 | 15.0 | 13.1 | 12.2 | 14.8 | 17.2 | 16.7 | 20.3 | 17.5 | 25.6 | 27.5 | 22.1 | 20.2 | 18.8 | 15.7 | 14.3 | 15.4 | 16.3 | -- | -- |
| Max | 157.0 | 123.0 | 115.0 | 98.9 | 74.2 | 35.7 | 63.1 | 27.7 | 54.7 | 34.4 | 25.1 | 44.2 | 139.0 | 80.9 | 176.0 | 128.0 | 319.0 | 290.0 | 163.0 | 123.0 | 117.0 | 61.3 | 36.1 | 94.4 | -- | 319.0 | -- |
| Min | 1.1 | 1.1 | 3.4 | 4.5 | 1.1 | 3.3 | 3.3 | 2.2 | 3.3 | 1.1 | 6.6 | 5.7 | 4.6 | 4.6 | 2.3 | 1.2 | 6.7 | 8.1 | 6.9 | 8.0 | 5.7 | 6.7 | 5.6 | 4.5 | -- | -- | 1.1 |

-- Indicates Invalid Data

## SAROAD for Resolution, East_Plant

## "Component, Channel: Table125, conc_PM10_µg/m$^3$_STP"

## Month: Nov 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 11.1 | 9.9 | 7.7 | 5.5 | 6.6 | 8.8 | 8.8 | 8.8 | 8.9 | 24.7 | 5.6 | 6.8 | 6.8 | 6.9 | 6.9 | 6.9 | 10.2 | 13.6 | 14.7 | 12.3 | 11.2 | 10.1 | 6.7 | 5.6 | 9.4 | 24.7 | 5.5 |
| 2 | 6.7 | 8.9 | 5.6 | 3.4 | 6.7 | 10.0 | 11.2 | 13.4 | 12.4 | 23.8 | 21.7 | 16.1 | 11.5 | 8.1 | 8.1 | 8.1 | 11.6 | 12.7 | 13.7 | 17.1 | 14.8 | 11.4 | 12.5 | 13.6 | 11.8 | 23.8 | 3.4 |
| 3 | 12.4 | 9.0 | 4.5 | 6.7 | 10.1 | 6.7 | 3.4 | 5.6 | 6.8 | 3.4 | 2.3 | 4.6 | 3.5 | 4.6 | 8.1 | 9.2 | 8.0 | 6.9 | 8.0 | 6.8 | 4.5 | 7.9 | 10.1 | 7.9 | 6.7 | 12.4 | 2.3 |
| 4 | 6.8 | 7.9 | 7.8 | 5.6 | 7.9 | 9.0 | 4.5 | 5.6 | 6.8 | 6.8 | 6.9 | 4.6 | 3.5 | 5.8 | 2.3 | 5.7 | 22.9 | 14.9 | 18.3 | 18.2 | 14.8 | 11.4 | 28.1 | 15.6 | 10.1 | 28.1 | 2.3 |
| 5 | 11.1 | 6.6 | 6.6 | 8.8 | 8.9 | 6.6 | 7.8 | 8.9 | 7.8 | 8.9 | 11.1 | 12.3 | 12.3 | 12.3 | 10.1 | 10.1 | 11.2 | 12.3 | 15.6 | 14.5 | 12.2 | 7.7 | 6.6 | 8.8 | 10.0 | 15.6 | 6.6 |
| 6 | 6.6 | 2.2 | 2.2 | 7.7 | 5.5 | 2.2 | 1.1 | 2.2 | 9.9 | 8.8 | 6.6 | 8.9 | 10.1 | 9.0 | 3.4 | 3.4 | 6.8 | 7.8 | 6.7 | 2.2 | 4.5 | 6.7 | 7.8 | 5.6 | 5.7 | 10.1 | 1.1 |
| 7 | 2.2 | 5.5 | 7.7 | 8.8 | 9.9 | 7.7 | 9.9 | 13.2 | 13.3 | 15.7 | 11.3 | 4.5 | 3.4 | 6.8 | 5.7 | 5.7 | 5.7 | 5.7 | 5.6 | 6.7 | 9.0 | 11.2 | 11.2 | 11.1 | 8.2 | 15.7 | 2.2 |
| 8 | 10.0 | 8.9 | 7.8 | 2.2 | 3.3 | 8.9 | 4.5 | 6.7 | 12.3 | 19.1 | 9.1 | 11.4 | 11.5 | 11.5 | 11.5 | 10.3 | 11.5 | 11.4 | 9.1 | 7.9 | 9.0 | 6.8 | 6.7 | 6.7 | 9.1 | 19.1 | 2.2 |
| 9 | 3.4 | 5.6 | 9.0 | 6.7 | 5.6 | 10.0 | 10.0 | 8.9 | 10.1 | 9.1 | 6.9 | 5.7 | 6.9 | 10.3 | 9.2 | 6.9 | 8.0 | 6.8 | 6.8 | 7.9 | 4.5 | 2.2 | 6.7 | 7.9 | 7.3 | 10.3 | 2.2 |
| 10 | 6.7 | 6.7 | 8.9 | 7.8 | 6.7 | 7.8 | 7.8 | 7.8 | 6.7 | 7.9 | 11.3 | 13.7 | 13.8 | 13.8 | 19.6 | 8.1 | 19.5 | 16.0 | 12.5 | 7.9 | 6.8 | 4.5 | 2.3 | 4.5 | 9.5 | 19.6 | 2.3 |
| 11 | 7.9 | 9.0 | 7.9 | 6.7 | 7.8 | 5.6 | 5.6 | 7.9 | 9.1 | 11.4 | 14.8 | 19.5 | 15.0 | 15.1 | 11.6 | 9.3 | 11.5 | 23.0 | 14.8 | 11.4 | 6.8 | 6.8 | 9.1 | 6.8 | 10.6 | 23.0 | 5.6 |
| 12 | 5.7 | 5.7 | 4.5 | 6.8 | 6.7 | 7.9 | 7.9 | 11.2 | 11.3 | 12.5 | 20.6 | 14.9 | 10.3 | 19.6 | 50.6 | 71.2 | 46.9 | 37.6 | 32.9 | 37.2 | 32.6 | 31.4 | 41.4 | 42.4 | 23.7 | 71.2 | 4.5 |
| 13 | 30.1 | 30.0 | 21.1 | 14.4 | 12.2 | 9.9 | 9.9 | 6.6 | 8.9 | 11.2 | 11.2 | 13.5 | 10.2 | 10.2 | 12.5 | 11.3 | 10.2 | 7.9 | 6.7 | 9.0 | 8.9 | 6.7 | 7.8 | 7.8 | 12.0 | 30.1 | 6.6 |
| 14 | 7.8 | 6.7 | 7.8 | 10.0 | 10.0 | 10.0 | 10.0 | 12.2 | 14.5 | 14.6 | 11.3 | 10.3 | 10.3 | 12.6 | 11.5 | 13.8 | 14.9 | 13.7 | 13.6 | 12.4 | 13.5 | 12.4 | 12.4 | 10.1 | 11.5 | 14.9 | 6.7 |
| 15 | 9.0 | 11.3 | 12.4 | 12.4 | 10.1 | 10.1 | 12.4 | 12.4 | 25.0 | 20.5 | 19.4 | 25.2 | 25.3 | 49.5 | 85.2 | 118.0 | 71.1 | 96.4 | 73.4 | 43.1 | 129.0 | 83.7 | 35.0 | 28.1 | 42.4 | 129.0 | 9.0 |
| 16 | 21.3 | 20.2 | 19.1 | 19.1 | 15.7 | 15.7 | 14.5 | 18.9 | 13.4 | 17.8 | 17.8 | 17.9 | 21.3 | 15.7 | 22.6 | 26.0 | 19.2 | 14.6 | 17.9 | 17.9 | 14.5 | 21.2 | 15.6 | 16.7 | 18.1 | 26.0 | 13.4 |
| 17 | 16.7 | 14.5 | 18.9 | 16.7 | 17.7 | 16.6 | 10.0 | 12.2 | 15.6 | 12.3 | 10.1 | 9.0 | 7.9 | 10.2 | 11.3 | 10.2 | 7.9 | 9.0 | 10.1 | 8.9 | 10.0 | 10.0 | 10.0 | 10.0 | 11.9 | 18.9 | 7.9 |
| 18 | 8.9 | 7.8 | 6.6 | 5.5 | 3.3 | 5.5 | 6.6 | 6.7 | 8.9 | 12.3 | 10.1 | 10.2 | 11.4 | 8.0 | 8.0 | 11.4 | 12.5 | 19.3 | 18.1 | 14.6 | 12.3 | 10.1 | 11.2 | 12.3 | 10.1 | 19.3 | 3.3 |
| 19 | 10.1 | 8.9 | 8.9 | 8.9 | 8.9 | 7.8 | 10.0 | 8.9 | 7.8 | 10.1 | 17.0 | 13.7 | 10.3 | 21.7 | 12.6 | 19.4 | 12.5 | 18.1 | 19.2 | 21.4 | 20.3 | 21.3 | 15.7 | 16.8 | 13.8 | 21.7 | 7.8 |
| 20 | 19.0 | 20.1 | 22.3 | 17.8 | 24.6 | 20.1 | 22.3 | 25.7 | 21.3 | 28.1 | 21.5 | 26.1 | 23.8 | 17.0 | 19.2 | 24.8 | 28.2 | 23.6 | 23.6 | 18.0 | 23.6 | 25.8 | 20.2 | 15.7 | 22.2 | 28.2 | 15.7 |
| 21 | 14.6 | 14.6 | 14.5 | 14.6 | 14.6 | 16.8 | 16.8 | 19.0 | 15.7 | 15.7 | 15.8 | 14.7 | 14.7 | 14.7 | 14.7 | 20.3 | 14.7 | 14.6 | 23.6 | 11.2 | 12.3 | 14.5 | 11.1 | 8.9 | 15.1 | 23.6 | 8.9 |
| 22 | 6.7 | 4.5 | 5.6 | 5.6 | 6.7 | 7.9 | 7.9 | 7.8 | 6.7 | 4.4 | 3.3 | 0.0 | -3.3 | -1.1 | -1.1 | -2.2 | -1.1 | 0.0 | 2.2 | 3.3 | 6.6 | 11.0 | 12.1 | 7.7 | 4.2 | 12.1 | -3.3 |
| 23 | 5.5 | 10.9 | 14.2 | 13.1 | 9.8 | 5.4 | 5.4 | 6.5 | 5.4 | 3.2 | 1.1 | 2.2 | 2.2 | 2.2 | 2.2 | 2.2 | -2.2 | -2.2 | 1.1 | 0.0 | -1.1 | 0.0 | 2.2 | 2.2 | 3.8 | 14.2 | -2.2 |
| 24 | 1.1 | 1.1 | 0.0 | 0.0 | 2.1 | 3.2 | 3.2 | 0.0 | 0.0 | 0.0 | -1.1 | 1.1 | 1.1 | 3.2 | 4.3 | 2.2 | 3.2 | 3.2 | 4.3 | 5.4 | 5.4 | 3.2 | 3.2 | 5.4 | 2.3 | 5.4 | -1.1 |
| 25 | 1.1 | 1.1 | 4.3 | 3.2 | 3.2 | 5.4 | 6.4 | 6.4 | 5.4 | 3.3 | 1.1 | 3.3 | 5.5 | 5.5 | 5.5 | 6.6 | 5.5 | 3.3 | 5.5 | 6.5 | 5.4 | 5.4 | 3.3 | 2.2 | 4.3 | 6.6 | 1.1 |
| 26 | 5.4 | 6.5 | 5.4 | 5.4 | 3.3 | 6.5 | 8.6 | 5.4 | 6.5 | 7.6 | 6.6 | 3.3 | 5.5 | 6.6 | -- | -- | 4.4 | 4.4 | 1.1 | 2.2 | -- | 3.3 | 3.3 | 5.4 | 5.1 | 8.6 | 1.1 |
| 27 | 5.4 | 4.4 | 4.4 | 5.4 | 4.4 | 6.5 | 5.4 | 3.3 | 4.4 | 3.3 | 1.1 | 5.5 | 6.6 | 5.5 | 10.0 | 11.1 | 7.7 | 4.4 | 2.2 | 2.2 | 2.2 | 3.3 | 3.3 | 1.1 | 4.7 | 11.1 | 1.1 |
| 28 | 3.3 | 4.4 | 4.3 | 5.4 | 6.5 | 7.6 | 6.5 | 5.4 | 5.5 | 6.6 | 7.7 | 6.6 | 5.6 | 5.6 | 5.6 | 6.7 | 6.7 | 3.3 | 3.3 | 4.4 | 5.5 | 6.6 | 5.5 | 3.3 | 5.5 | 7.7 | 3.3 |
| 29 | 4.4 | 4.4 | 1.1 | 3.3 | 6.6 | 4.4 | 3.3 | 4.4 | 4.4 | 6.6 | 11.1 | 11.2 | 9.0 | 7.9 | 9.0 | 9.0 | 5.6 | 7.8 | 7.8 | 6.7 | 7.8 | 8.9 | 7.7 | 7.7 | 6.7 | 11.2 | 1.1 |
| 30 | 8.8 | 6.6 | 6.6 | 6.6 | 6.6 | 8.8 | 9.9 | 11.0 | 7.7 | 6.7 | 8.9 | 8.9 | 9.0 | 10.1 | 11.3 | 11.2 | 12.3 | 13.4 | 10.0 | 7.8 | 7.7 | 8.8 | 7.7 | 6.6 | 8.9 | 13.4 | 6.6 |
| Avg | 9.0 | 8.8 | 8.6 | 8.1 | 8.4 | 8.6 | 8.4 | 9.1 | 9.7 | 11.2 | 10.1 | 10.2 | 9.5 | 11.0 | 13.5 | 15.7 | 13.6 | 14.1 | 13.4 | 11.5 | 14.3 | 12.5 | 11.2 | 10.1 | 10.8 | -- | -- |
| Max | 30.1 | 30.0 | 22.3 | 19.1 | 24.6 | 20.1 | 22.3 | 25.7 | 25.0 | 28.1 | 21.7 | 26.1 | 25.3 | 49.5 | 85.2 | 118.0 | 71.1 | 96.4 | 73.4 | 43.1 | 129.0 | 83.7 | 41.4 | 42.4 | -- | 129.0 | -- |
| Min | 1.1 | 1.1 | 0.0 | 0.0 | 2.1 | 2.2 | 1.1 | 0.0 | 0.0 | 0.0 | -1.1 | 0.0 | -3.3 | -1.1 | -1.1 | -2.2 | -2.2 | -2.2 | 1.1 | 0.0 | -1.1 | 0.0 | 2.2 | 1.1 | -- | -- | -3.3 |

-- Indicates Invalid Data

## SAROAD for Resolution, East_Plant

## "Component, Channel: Table125, conc_PM10_µg/m$^3$_STP"

## Month: Dec 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 8.8 | 8.8 | 7.7 | 8.8 | 7.7 | 7.6 | 7.6 | 6.5 | 5.5 | 6.7 | 10.0 | 9.0 | 7.9 | 7.9 | 6.8 | 9.0 | 10.1 | 6.7 | 5.5 | 5.5 | 2.2 | 2.2 | 3.3 | 3.3 | 6.9 | 10.1 | 2.2 |
| 2 | 2.2 | 2.2 | 4.4 | 6.5 | 4.4 | 3.3 | 1.1 | 0.0 | 2.2 | 1.1 | 1.1 | 4.5 | 5.6 | 4.5 | 6.8 | 7.9 | 5.6 | 10.1 | 14.5 | 12.2 | 8.9 | 5.5 | 3.3 | 4.4 | 5.1 | 14.5 | 0.0 |
| 3 | 6.7 | 6.7 | 4.5 | 5.5 | 6.7 | 2.2 | 3.3 | 6.7 | 5.6 | 6.7 | 11.3 | 9.0 | 6.8 | 3.4 | 4.6 | 8.0 | 9.1 | 11.3 | 10.2 | 5.7 | 2.3 | 5.6 | 6.8 | 4.5 | 6.4 | 11.3 | 2.2 |
| 4 | 2.3 | 1.1 | 3.4 | 4.5 | 4.5 | 5.6 | 5.6 | 5.6 | 7.8 | 11.1 | 10.0 | 7.8 | 10.0 | 17.8 | 13.2 | 8.8 | 7.7 | 9.9 | 9.9 | 17.5 | 15.3 | 15.3 | 20.7 | 18.5 | 9.7 | 20.7 | 1.1 |
| 5 | 17.4 | 10.9 | 10.9 | 10.9 | 9.8 | 8.7 | 10.8 | 10.8 | 11.9 | 18.4 | 12.0 | 13.1 | 13.1 | 9.8 | 7.7 | 9.8 | 18.5 | 18.4 | 18.4 | 12.9 | 12.9 | 14.0 | 13.9 | 18.2 | 13.0 | 18.5 | 7.7 |
| 6 | 15.0 | 13.9 | 9.6 | 7.5 | 9.6 | 10.6 | 9.5 | 10.6 | 13.8 | 12.9 | 10.8 | 8.6 | 8.7 | 9.8 | 9.8 | 7.6 | 9.8 | 11.9 | 9.7 | 10.7 | 10.7 | 9.6 | 10.7 | 10.7 | 10.5 | 15.0 | 7.5 |
| 7 | 7.5 | 6.4 | 8.6 | 7.5 | 5.3 | 6.4 | 6.4 | 5.3 | 5.4 | 5.4 | 5.4 | 6.5 | 6.6 | 5.5 | 8.8 | 7.7 | 7.6 | 10.9 | 14.1 | 12.0 | 10.9 | 14.2 | 13.1 | 9.8 | 8.2 | 14.2 | 5.3 |
| 8 | 9.8 | 9.8 | 6.5 | 6.5 | 7.6 | 6.5 | 6.5 | 8.6 | 6.5 | 8.7 | 13.0 | 10.8 | 10.9 | 10.9 | 9.8 | 13.1 | 19.6 | 17.4 | 17.4 | 21.7 | 18.4 | 21.6 | 22.7 | 22.6 | 12.8 | 22.7 | 6.5 |
| 9 | 18.3 | 23.6 | 25.7 | 22.4 | 18.1 | 20.2 | 20.1 | 18.0 | 18.1 | 18.2 | 21.5 | 16.1 | 11.9 | 10.8 | 8.7 | 6.5 | 6.5 | 4.3 | 6.4 | 6.4 | 1.1 | 1.1 | 3.2 | 4.3 | 13.0 | 25.7 | 1.1 |
| 10 | 3.2 | 2.1 | 2.1 | 3.2 | 1.1 | -1.1 | 3.2 | 6.4 | 26.6 | 18.2 | 10.7 | 18.4 | 25.0 | 12.0 | 10.9 | 12.0 | 14.2 | 13.1 | 9.8 | 6.5 | 4.3 | 6.5 | 8.7 | 6.5 | 9.3 | 26.6 | -1.1 |
| 11 | 8.7 | 7.6 | 5.4 | 6.5 | 8.7 | 8.7 | 7.6 | 8.7 | 9.8 | 13.1 | 15.3 | 14.3 | 11.1 | 12.2 | 17.8 | 11.1 | 12.2 | 12.1 | 12.1 | 9.9 | 9.9 | 11.0 | 11.0 | 17.6 | 10.9 | 17.8 | 5.4 |
| 12 | 8.8 | 17.5 | 23.0 | 15.3 | 17.5 | 16.4 | 21.9 | 14.2 | 14.2 | 17.6 | 16.6 | 10.0 | 11.2 | 10.1 | -- | 10.0 | 6.7 | 5.5 | 4.4 | 4.4 | 7.7 | 10.9 | 10.9 | 32.8 | 13.4 | 32.8 | 4.4 |
| 13 | 30.5 | 25.0 | 23.9 | 22.7 | 23.8 | 17.3 | 17.3 | 18.4 | 17.3 | 19.7 | 20.9 | 19.8 | 14.3 | 14.4 | 19.9 | 16.6 | 15.4 | 15.3 | 16.4 | 8.7 | 10.9 | 19.5 | 12.9 | 13.0 | 18.1 | 30.5 | 8.7 |
| 14 | 9.7 | 7.6 | 7.6 | 7.5 | 6.5 | 5.4 | 5.4 | 3.3 | 2.2 | 7.6 | 28.3 | 3.3 | 5.5 | 5.5 | 8.9 | 12.2 | 7.7 | 6.6 | 3.3 | 1.1 | 1.1 | 2.2 | 3.3 | 0.0 | 6.3 | 28.3 | 0.0 |
| 15 | 0.0 | 2.2 | 3.2 | 4.3 | 2.2 | 2.2 | 4.3 | 5.4 | 4.4 | 7.7 | 8.8 | 16.6 | 14.5 | 11.2 | 6.7 | 20.2 | 12.3 | 7.8 | 4.4 | 17.7 | 7.7 | 8.8 | 5.5 | 1.1 | 7.5 | 20.2 | 0.0 |
| 16 | 3.3 | 2.2 | 2.2 | 6.6 | 6.6 | 5.5 | 8.8 | 6.6 | 16.5 | 18.8 | 13.3 | 15.6 | 10.1 | 3.4 | 7.9 | 10.2 | 10.1 | 7.8 | 4.5 | 4.5 | 4.5 | 3.3 | 4.4 | 4.4 | 7.6 | 18.8 | 2.2 |
| 17 | 4.4 | 3.3 | 3.3 | 3.3 | 2.2 | 4.4 | 3.3 | 1.1 | 2.2 | 7.8 | 10.1 | 6.7 | 7.9 | 11.3 | 9.1 | 6.8 | 6.8 | 5.6 | 4.5 | 3.4 | 4.5 | 4.5 | 4.5 | 6.7 | 5.3 | 11.3 | 1.1 |
| 18 | 6.7 | 6.7 | 5.6 | 3.4 | 3.3 | 6.7 | 8.9 | 7.8 | 8.9 | 6.7 | 5.6 | 6.7 | 7.9 | 12.4 | 14.8 | 12.5 | 9.1 | 4.5 | 0.0 | 0.0 | 3.4 | 3.4 | 2.3 | 4.5 | 6.3 | 14.8 | 0.0 |
| 19 | 6.8 | 5.6 | 9.0 | 11.2 | 9.0 | 6.7 | 5.6 | 4.5 | 5.6 | 5.6 | 5.6 | 7.9 | 10.2 | -- | 12.5 | 12.5 | 43.0 | 22.5 | 24.6 | 44.6 | 59.0 | 58.8 | 29.9 | 28.8 | 18.7 | 59.0 | 4.5 |
| 20 | 18.8 | 20.0 | 21.1 | 18.8 | 17.8 | 4.4 | 2.2 | 1.1 | 1.1 | 1.1 | 1.1 | 3.3 | 4.4 | -- | -- | -2.2 | 1.1 | 4.4 | 6.6 | 4.4 | 1.1 | 1.1 | 1.1 | 1.1 | 6.1 | 21.1 | -2.2 |
| 21 | 1.1 | 2.2 | 1.1 | -2.2 | -2.2 | 2.2 | 3.3 | 2.2 | 3.3 | 5.4 | 6.5 | 5.4 | 7.6 | 9.8 | 9.8 | 6.5 | 7.6 | 9.8 | 7.6 | 6.5 | 6.5 | 7.6 | 9.8 | 7.6 | 5.2 | 9.8 | -2.2 |
| 22 | 5.4 | 4.3 | 4.3 | 4.3 | 6.4 | 8.6 | 10.7 | 8.6 | 7.5 | 7.6 | 4.4 | 3.3 | 4.4 | 3.3 | 4.4 | 7.7 | 8.7 | 7.6 | 8.7 | 8.6 | 9.7 | 9.7 | 6.5 | 5.4 | 6.7 | 10.7 | 3.3 |
| 23 | 6.5 | 7.5 | 6.5 | 4.3 | 1.1 | 0.0 | 2.2 | 4.3 | 4.3 | 5.4 | 5.4 | 3.3 | 3.3 | 3.3 | 2.2 | 2.2 | 3.3 | 3.3 | 2.2 | 3.3 | 4.4 | 2.2 | 4.4 | 2.2 | 3.6 | 7.5 | 0.0 |
| 24 | -1.1 | 2.2 | 4.4 | 5.4 | 5.4 | 3.3 | 1.1 | 3.3 | 5.4 | 3.3 | 4.4 | 4.4 | 3.3 | 1.1 | 1.1 | 4.5 | 4.5 | 2.2 | 5.5 | 7.7 | 4.4 | 3.3 | 3.3 | 4.4 | 3.6 | 7.7 | -1.1 |
| 25 | 22.0 | 24.2 | 49.5 | 52.6 | 32.8 | 21.8 | 22.9 | 0.0 | 1.1 | 1.1 | 1.1 | 2.2 | 1.1 | 1.1 | 0.0 | 1.1 | 3.3 | 2.2 | -1.1 | 2.2 | 4.4 | 3.3 | 2.2 | 4.4 | 10.6 | 52.6 | -1.1 |
| 26 | 6.5 | 18.5 | 20.6 | 28.2 | 30.3 | 29.2 | 30.3 | 24.9 | 25.0 | 25.0 | 18.5 | 20.8 | 22.0 | 14.4 | 47.7 | 15.5 | 15.5 | 15.4 | 15.4 | 15.4 | 17.6 | 7.7 | 23.1 | 1.1 | 20.4 | 47.7 | 1.1 |
| 27 | 5.5 | 7.6 | 4.4 | 5.4 | 6.5 | 9.8 | 9.8 | 7.6 | 25.1 | 18.6 | 16.5 | -- | 14.4 | 8.9 | 6.7 | 11.1 | 12.2 | 11.1 | 12.1 | 9.9 | 7.7 | 7.7 | 9.9 | 7.6 | 10.3 | 25.1 | 4.4 |
| 28 | 8.7 | 10.9 | 9.8 | 10.9 | 10.9 | 12.0 | 14.2 | 13.1 | 12.0 | 11.0 | 18.7 | 16.6 | 13.4 | 7.8 | 5.6 | 9.0 | 10.0 | 10.0 | 19.9 | 12.1 | 12.1 | 12.1 | 9.9 | 6.6 | 11.6 | 19.9 | 5.6 |
| 29 | 5.5 | 5.5 | 6.6 | 5.4 | 6.5 | 8.7 | 10.9 | 10.9 | 8.8 | 18.8 | 28.7 | 25.5 | 6.7 | 5.6 | 3.4 | 3.4 | 3.3 | 4.4 | 5.5 | 6.6 | 7.7 | 8.8 | 5.5 | 2.2 | 8.5 | 28.7 | 2.2 |
| 30 | 2.2 | 2.2 | 2.2 | 1.1 | 2.2 | 2.2 | 1.1 | 3.2 | 2.2 | 4.4 | 6.6 | 6.6 | 5.6 | 2.2 | 5.6 | 8.9 | 8.9 | 11.0 | 9.9 | 6.6 | 5.5 | 4.4 | 4.4 | 4.4 | 4.7 | 11.0 | 1.1 |
| 31 | 4.4 | 4.4 | 4.4 | 2.2 | 0.0 | 4.4 | 9.8 | 9.8 | 7.6 | 8.8 | 11.0 | 13.3 | 13.3 | 11.2 | 10.1 | 7.9 | 5.6 | 6.7 | 7.7 | 7.7 | 8.8 | 8.8 | 7.7 | 8.8 | 7.7 | 13.3 | 0.0 |
| Avg | 8.2 | 8.8 | 9.7 | 9.7 | 8.8 | 8.1 | 8.9 | 7.7 | 9.3 | 10.4 | 11.4 | 10.3 | 9.6 | 8.3 | 9.7 | 9.0 | 10.2 | 9.4 | 9.4 | 9.6 | 9.2 | 9.5 | 9.0 | 8.6 | 9.3 | -- | -- |
| Max | 30.5 | 25.0 | 49.5 | 52.6 | 32.8 | 29.2 | 30.3 | 24.9 | 26.6 | 25.0 | 28.7 | 25.5 | 25.0 | 17.8 | 47.7 | 20.2 | 43.0 | 22.5 | 24.6 | 44.6 | 59.0 | 58.8 | 29.9 | 32.8 | -- | 59.0 | -- |
| Min | -1.1 | 1.1 | 1.1 | -2.2 | -2.2 | -1.1 | 1.1 | 0.0 | 1.1 | 1.1 | 1.1 | 2.2 | 1.1 | 1.1 | 0.0 | -2.2 | 1.1 | 2.2 | -1.1 | 0.0 | 1.1 | 1.1 | 1.1 | 0.0 | -- | -- | -2.2 |

-- Indicates Invalid Data

## SAROAD for Resolution, East_Plant

## "Component, Channel: Table126, conc_PM25_µg/m$^3$ Actual"

## Month: Oct 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 5.0 | 5.0 | 3.0 | 2.0 | 4.0 | 4.0 | 3.0 | 5.0 | 7.0 | 4.0 | 1.0 | 3.0 | 5.0 | 3.0 | 3.0 | 5.0 | 4.0 | 2.0 | 2.0 | 0.0 | 2.0 | 4.0 | 2.0 | 4.0 | 3.4 | 7.0 | 0.0 |
| 2 | 3.0 | 1.0 | 3.0 | 2.0 | 2.0 | 6.0 | 4.0 | 2.0 | 4.0 | 4.0 | 4.0 | 6.0 | 6.0 | 3.0 | 1.0 | 5.0 | 7.0 | 6.0 | 6.0 | 4.0 | 2.0 | 3.0 | 3.0 | 1.0 | 3.7 | 7.0 | 1.0 |
| 3 | 1.0 | 3.0 | 3.0 | 3.0 | 4.0 | 3.0 | 3.0 | 3.0 | 3.0 | 2.0 | 2.0 | 3.0 | 2.0 | 4.0 | 4.0 | 3.0 | 4.0 | 4.0 | 3.0 | 2.0 | 2.0 | 3.0 | 4.0 | 3.0 | 3.0 | 4.0 | 1.0 |
| 4 | 3.0 | 5.0 | 6.0 | 6.0 | 7.0 | 7.0 | 5.0 | 6.0 | 8.0 | 8.0 | 6.0 | 6.0 | 5.0 | 4.0 | 4.0 | 5.0 | 7.0 | 9.0 | 7.0 | 6.0 | 6.0 | 6.0 | 5.0 | 5.0 | 5.9 | 9.0 | 3.0 |
| 5 | 7.0 | 7.0 | 6.0 | 5.0 | 6.0 | 4.0 | 8.0 | 11.0 | 6.0 | 5.0 | 5.0 | 5.0 | 4.0 | 4.0 | 3.0 | 3.0 | 4.0 | 2.0 | 1.0 | 2.0 | 2.0 | 2.0 | 3.0 | 5.0 | 4.6 | 11.0 | 1.0 |
| 6 | 25.0 | 16.0 | 1.0 | 3.0 | 1.0 | 4.0 | 6.0 | 3.0 | 3.0 | 3.0 | 4.0 | 6.0 | 3.0 | 1.0 | 3.0 | 2.0 | 1.0 | 5.0 | 5.0 | 3.0 | 2.0 | 2.0 | 4.0 | 6.0 | 4.7 | 25.0 | 1.0 |
| 7 | 4.0 | 4.0 | 5.0 | 3.0 | 2.0 | 2.0 | 4.0 | 4.0 | 4.0 | 5.0 | 5.0 | 3.0 | 2.0 | 1.0 | 2.0 | 2.0 | 2.0 | 3.0 | 4.0 | 4.0 | 5.0 | 5.0 | 5.0 | 4.0 | 3.5 | 5.0 | 1.0 |
| 8 | 3.0 | 3.0 | 3.0 | 4.0 | 4.0 | 3.0 | 4.0 | 4.0 | 5.0 | 4.0 | 6.0 | 6.0 | 4.0 | 5.0 | -- | 10.0 | 9.0 | 2.0 | 1.0 | 3.0 | 2.0 | 0.0 | 2.0 | 5.0 | 4.0 | 10.0 | 0.0 |
| 9 | 6.0 | 5.0 | 3.0 | 3.0 | 4.0 | 4.0 | 4.0 | 5.0 | -- | 5.0 | 3.0 | 1.0 | 4.0 | 6.0 | -- | 7.0 | 25.0 | 19.0 | 18.0 | 10.0 | 9.0 | 8.0 | 8.0 | 8.0 | 7.5 | 25.0 | 1.0 |
| 10 | 7.0 | 6.0 | 6.0 | 7.0 | 6.0 | 9.0 | 9.0 | 8.0 | 6.0 | 3.0 | 6.0 | 7.0 | 7.0 | 6.0 | 3.0 | 6.0 | 6.0 | 5.0 | 4.0 | 4.0 | 5.0 | 3.0 | 4.0 | 5.0 | 5.8 | 9.0 | 3.0 |
| 11 | 4.0 | 7.0 | 6.0 | 4.0 | 3.0 | 3.0 | 4.0 | 4.0 | 3.0 | 3.0 | 2.0 | 2.0 | 4.0 | 4.0 | 6.0 | 6.0 | 4.0 | 1.0 | 2.0 | 2.0 | 2.0 | 3.0 | 5.0 | 3.0 | 3.6 | 7.0 | 1.0 |
| 12 | 1.0 | 2.0 | 1.0 | 0.0 | 1.0 | 1.0 | 2.0 | 4.0 | 5.0 | 5.0 | 3.0 | 5.0 | 4.0 | 2.0 | 2.0 | 3.0 | 3.0 | 2.0 | 3.0 | 6.0 | 8.0 | 5.0 | 3.0 | 3.0 | 3.1 | 8.0 | 0.0 |
| 13 | 5.0 | 5.0 | 4.0 | 4.0 | 3.0 | 5.0 | 5.0 | 5.0 | 5.0 | 5.0 | 6.0 | 7.0 | 6.0 | 4.0 | 2.0 | 4.0 | 6.0 | 3.0 | 1.0 | 4.0 | 4.0 | 5.0 | 5.0 | 2.0 | 4.4 | 7.0 | 1.0 |
| 14 | 6.0 | 7.0 | 5.0 | 4.0 | 5.0 | 4.0 | 5.0 | 6.0 | 5.0 | 5.0 | 5.0 | 5.0 | 6.0 | 6.0 | 4.0 | 5.0 | 5.0 | 4.0 | 4.0 | 5.0 | 6.0 | 7.0 | 6.0 | 5.0 | 5.2 | 7.0 | 4.0 |
| 15 | 5.0 | 5.0 | 4.0 | 3.0 | 3.0 | 3.0 | 3.0 | 5.0 | 6.0 | 5.0 | 4.0 | 4.0 | 4.0 | 6.0 | 5.0 | 2.0 | 4.0 | 5.0 | 4.0 | 4.0 | 6.0 | 5.0 | 2.0 | 3.0 | 4.2 | 6.0 | 2.0 |
| 16 | 5.0 | 4.0 | 2.0 | 3.0 | 5.0 | 5.0 | 6.0 | 5.0 | 4.0 | 3.0 | 1.0 | 3.0 | 2.0 | -1.0 | 0.0 | 2.0 | 2.0 | 3.0 | 2.0 | 3.0 | 6.0 | 5.0 | 3.0 | 3.0 | 3.2 | 6.0 | -1.0 |
| 17 | 6.0 | 6.0 | 4.0 | 1.0 | 1.0 | 5.0 | 6.0 | 5.0 | 2.0 | 2.0 | 5.0 | 6.0 | 7.0 | 8.0 | 6.0 | 6.0 | 6.0 | 6.0 | 6.0 | 5.0 | 4.0 | 5.0 | 6.0 | 5.0 | 5.0 | 8.0 | 1.0 |
| 18 | 2.0 | 3.0 | 5.0 | 3.0 | 1.0 | 3.0 | 5.0 | 7.0 | 7.0 | 6.0 | 6.0 | 5.0 | 3.0 | 3.0 | 4.0 | 4.0 | 4.0 | 6.0 | 7.0 | 6.0 | 4.0 | 4.0 | 3.0 | 3.0 | 4.3 | 7.0 | 1.0 |
| 19 | 7.0 | 6.0 | 2.0 | -1.0 | 2.0 | 4.0 | 4.0 | 5.0 | 4.0 | 5.0 | 5.0 | 3.0 | 3.0 | 2.0 | 0.0 | 2.0 | 2.0 | 3.0 | 3.0 | 2.0 | 3.0 | 5.0 | 4.0 | 5.0 | 3.3 | 7.0 | -1.0 |
| 20 | 5.0 | 2.0 | 2.0 | 2.0 | 0.0 | 0.0 | 1.0 | 2.0 | 0.0 | 0.0 | 0.0 | 0.0 | 3.0 | 3.0 | 1.0 | 0.0 | 2.0 | 5.0 | 5.0 | 1.0 | 1.0 | 3.0 | 3.0 | 5.0 | 1.9 | 5.0 | 0.0 |
| 21 | 5.0 | 3.0 | 3.0 | 3.0 | 2.0 | 2.0 | 4.0 | 4.0 | 4.0 | 3.0 | 3.0 | 4.0 | 3.0 | 5.0 | 5.0 | 2.0 | 3.0 | 3.0 | 2.0 | 2.0 | 3.0 | 4.0 | 4.0 | 2.0 | 3.3 | 5.0 | 2.0 |
| 22 | -1.0 | 0.0 | 2.0 | 3.0 | 2.0 | 1.0 | 1.0 | 3.0 | 4.0 | 4.0 | 6.0 | 7.0 | 6.0 | 6.0 | 4.0 | 2.0 | 3.0 | 4.0 | 4.0 | 3.0 | 2.0 | 1.0 | 1.0 | 3.0 | 3.0 | 7.0 | -1.0 |
| 23 | 4.0 | 4.0 | 5.0 | 6.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 4.0 | 5.0 | 5.0 | 3.0 | 3.0 | 3.0 | 3.0 | 4.0 | 3.0 | 5.0 | 6.0 | 3.0 | 3.0 | 2.0 | 2.0 | 3.8 | 6.0 | 2.0 |
| 24 | 4.0 | 5.0 | 4.0 | 2.0 | 4.0 | 4.0 | 2.0 | 3.0 | 6.0 | 4.0 | 3.0 | 4.0 | 3.0 | 4.0 | 3.0 | 3.0 | 4.0 | 4.0 | 6.0 | 6.0 | 7.0 | 7.0 | 6.0 | 6.0 | 4.3 | 7.0 | 2.0 |
| 25 | 6.0 | 5.0 | 4.0 | 2.0 | 1.0 | 2.0 | 3.0 | 1.0 | 1.0 | 2.0 | 3.0 | 4.0 | 2.0 | 2.0 | 2.0 | 2.0 | 3.0 | 0.0 | 1.0 | 3.0 | 2.0 | 4.0 | 4.0 | 3.0 | 2.6 | 6.0 | 0.0 |
| 26 | 3.0 | 3.0 | 4.0 | 2.0 | 0.0 | 1.0 | 2.0 | 4.0 | 4.0 | 3.0 | 2.0 | 4.0 | 5.0 | 3.0 | 1.0 | 1.0 | 2.0 | 0.0 | 1.0 | 2.0 | 3.0 | 2.0 | 0.0 | 3.0 | 2.3 | 5.0 | 0.0 |
| 27 | 4.0 | 5.0 | 4.0 | 0.0 | 2.0 | 3.0 | 1.0 | 3.0 | 4.0 | 4.0 | 4.0 | 3.0 | 4.0 | 5.0 | 4.0 | 2.0 | 3.0 | 4.0 | 3.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 3.4 | 5.0 | 0.0 |
| 28 | 4.0 | 3.0 | 3.0 | 4.0 | 6.0 | 5.0 | 5.0 | 6.0 | 5.0 | 6.0 | 7.0 | 6.0 | 5.0 | 5.0 | 5.0 | 4.0 | 4.0 | 5.0 | 5.0 | 7.0 | 10.0 | 8.0 | 5.0 | 2.0 | 5.2 | 10.0 | 2.0 |
| 29 | -1.0 | 2.0 | 2.0 | 0.0 | 2.0 | 2.0 | 1.0 | 3.0 | 4.0 | 2.0 | -1.0 | -1.0 | 0.0 | 3.0 | 3.0 | 4.0 | 5.0 | 3.0 | 4.0 | 5.0 | 4.0 | 2.0 | 2.0 | 4.0 | 2.3 | 5.0 | -1.0 |
| 30 | 4.0 | 4.0 | 4.0 | 4.0 | 2.0 | 1.0 | 3.0 | 3.0 | 4.0 | -- | 5.0 | 4.0 | 2.0 | 2.0 | 3.0 | 2.0 | 1.0 | 2.0 | 5.0 | 6.0 | 5.0 | 4.0 | 3.0 | 3.0 | 3.3 | 6.0 | 1.0 |
| 31 | 3.0 | 2.0 | 2.0 | 2.0 | 2.0 | 4.0 | 5.0 | 5.0 | 4.0 | -- | 4.0 | 2.0 | 0.0 | 1.0 | 3.0 | 5.0 | 5.0 | 5.0 | 4.0 | 2.0 | 4.0 | 5.0 | 6.0 | 5.0 | 3.5 | 6.0 | 0.0 |
| Avg | 4.7 | 4.5 | 3.6 | 2.9 | 2.9 | 3.5 | 4.0 | 4.5 | 4.3 | 3.9 | 3.9 | 4.1 | 3.8 | 3.7 | 3.1 | 3.6 | 4.7 | 4.1 | 4.1 | 3.9 | 4.1 | 4.1 | 3.8 | 3.8 | 3.9 | -- | -- |
| Max | 25.0 | 16.0 | 6.0 | 7.0 | 7.0 | 9.0 | 9.0 | 11.0 | 8.0 | 8.0 | 7.0 | 7.0 | 7.0 | 8.0 | 6.0 | 10.0 | 25.0 | 19.0 | 18.0 | 10.0 | 10.0 | 8.0 | 8.0 | 8.0 | -- | 25.0 | -- |
| Min | -1.0 | 0.0 | 1.0 | -1.0 | 0.0 | 0.0 | 1.0 | 1.0 | 0.0 | 0.0 | -1.0 | -1.0 | 0.0 | -1.0 | 0.0 | 0.0 | 1.0 | 0.0 | 1.0 | 0.0 | 1.0 | 0.0 | 0.0 | 1.0 | -- | -- | -1.0 |

-- Indicates Invalid Data

## SAROAD for Resolution, East_Plant

## "Component, Channel: Table126, conc_PM25_µg/m$^3$ Actual"

## Month: Nov 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 3.0 | 3.0 | 5.0 | 5.0 | 5.0 | 5.0 | 3.0 | 2.0 | 3.0 | 4.0 | 3.0 | 2.0 | 2.0 | 2.0 | 0.0 | 0.0 | 2.0 | 2.0 | 3.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 3.0 | 5.0 | 0.0 |
| 2 | 4.0 | 5.0 | 4.0 | 4.0 | 4.0 | 3.0 | 1.0 | 2.0 | 4.0 | 5.0 | 3.0 | 1.0 | 2.0 | 4.0 | 3.0 | 2.0 | 3.0 | 2.0 | 1.0 | 2.0 | 4.0 | 4.0 | 4.0 | 2.0 | 3.0 | 5.0 | 1.0 |
| 3 | 1.0 | 2.0 | 2.0 | 1.0 | 1.0 | 2.0 | 2.0 | 2.0 | 5.0 | 5.0 | 3.0 | 1.0 | 0.0 | 2.0 | 3.0 | 0.0 | 0.0 | 1.0 | 0.0 | 0.0 | 1.0 | 1.0 | 1.0 | 3.0 | 1.6 | 5.0 | 0.0 |
| 4 | 2.0 | 2.0 | 2.0 | 2.0 | 3.0 | 4.0 | 4.0 | 1.0 | 1.0 | 3.0 | 5.0 | 3.0 | 0.0 | 3.0 | 3.0 | 2.0 | 3.0 | 2.0 | 3.0 | 3.0 | 1.0 | 2.0 | 5.0 | 7.0 | 2.8 | 7.0 | 0.0 |
| 5 | 6.0 | 5.0 | 5.0 | 5.0 | 2.0 | 2.0 | 5.0 | 7.0 | 6.0 | 6.0 | 6.0 | 6.0 | 6.0 | 6.0 | 7.0 | 7.0 | 6.0 | 7.0 | 8.0 | 7.0 | 5.0 | 3.0 | 5.0 | 4.0 | 5.5 | 8.0 | 2.0 |
| 6 | 0.0 | 1.0 | 0.0 | 0.0 | 1.0 | 0.0 | 0.0 | 1.0 | 1.0 | 1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 1.0 | -3.0 | -2.0 | 0.0 | 2.0 | 3.0 | 4.0 | 3.0 | -1.0 | 0.0 | 0.6 | 4.0 | -3.0 |
| 7 | 1.0 | 3.0 | 2.0 | 0.0 | 2.0 | 3.0 | 2.0 | 1.0 | 1.0 | 0.0 | 2.0 | 3.0 | 2.0 | 0.0 | -1.0 | 2.0 | 1.0 | 0.0 | 2.0 | 2.0 | 3.0 | 2.0 | 2.0 | 3.0 | 1.6 | 3.0 | -1.0 |
| 8 | 2.0 | 1.0 | 0.0 | 2.0 | 3.0 | 4.0 | 3.0 | -1.0 | 1.0 | 5.0 | 4.0 | 3.0 | 2.0 | 0.0 | 0.0 | 3.0 | 2.0 | 1.0 | 3.0 | 3.0 | 2.0 | 1.0 | 0.0 | 3.0 | 2.0 | 5.0 | -1.0 |
| 9 | 4.0 | 3.0 | 1.0 | 2.0 | 2.0 | 3.0 | 5.0 | 2.0 | 2.0 | 4.0 | 5.0 | 4.0 | 2.0 | 2.0 | 3.0 | 2.0 | 3.0 | 3.0 | 2.0 | 3.0 | 2.0 | 2.0 | 1.0 | 0.0 | 2.6 | 5.0 | 0.0 |
| 10 | 3.0 | 6.0 | 3.0 | 3.0 | 5.0 | 4.0 | 4.0 | 4.0 | 4.0 | 3.0 | 5.0 | 6.0 | 4.0 | 4.0 | 4.0 | 2.0 | 2.0 | 2.0 | 2.0 | 4.0 | 4.0 | 3.0 | 3.0 | 3.0 | 3.6 | 6.0 | 2.0 |
| 11 | 4.0 | 4.0 | 3.0 | 3.0 | 1.0 | 1.0 | 4.0 | 5.0 | 5.0 | 5.0 | 3.0 | 4.0 | 5.0 | 5.0 | 3.0 | 2.0 | 1.0 | 3.0 | 4.0 | 4.0 | 4.0 | 4.0 | 3.0 | 5.0 | 3.5 | 5.0 | 1.0 |
| 12 | 6.0 | 2.0 | 1.0 | 2.0 | 1.0 | 2.0 | 2.0 | 3.0 | 5.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | 2.0 | 5.0 | 7.0 | 6.0 | 4.0 | 4.0 | 4.0 | 3.0 | 2.0 | 3.0 | 3.0 | 7.0 | 1.0 |
| 13 | 5.0 | 5.0 | 4.0 | 4.0 | 2.0 | 2.0 | 5.0 | 3.0 | 4.0 | 5.0 | 2.0 | 3.0 | 4.0 | 3.0 | 2.0 | 2.0 | 2.0 | 3.0 | 2.0 | 1.0 | 0.0 | 1.0 | 3.0 | 3.0 | 2.9 | 5.0 | 0.0 |
| 14 | 3.0 | 5.0 | 5.0 | 5.0 | 5.0 | 5.0 | 4.0 | 4.0 | 6.0 | 5.0 | 4.0 | 4.0 | 3.0 | 4.0 | 5.0 | 6.0 | 6.0 | 3.0 | 3.0 | 5.0 | 4.0 | 3.0 | 4.0 | 4.0 | 4.4 | 6.0 | 3.0 |
| 15 | 6.0 | 5.0 | 5.0 | 5.0 | 5.0 | 6.0 | 7.0 | 6.0 | 4.0 | 6.0 | 6.0 | 5.0 | 5.0 | -- | 5.0 | 7.0 | 7.0 | 8.0 | 8.0 | 6.0 | 10.0 | 12.0 | 10.0 | 9.0 | 6.7 | 12.0 | 4.0 |
| 16 | 7.0 | 7.0 | 8.0 | 7.0 | 7.0 | 7.0 | 6.0 | 6.0 | 6.0 | 7.0 | 8.0 | 9.0 | 8.0 | 6.0 | 6.0 | 6.0 | 5.0 | 7.0 | 6.0 | 5.0 | 6.0 | 5.0 | 6.0 | 9.0 | 6.7 | 9.0 | 5.0 |
| 17 | 7.0 | 5.0 | 7.0 | 7.0 | 6.0 | 7.0 | 6.0 | 4.0 | 5.0 | 6.0 | 6.0 | 7.0 | 6.0 | 5.0 | 5.0 | 4.0 | 3.0 | 3.0 | 4.0 | 2.0 | 3.0 | 6.0 | 5.0 | 4.0 | 5.1 | 7.0 | 2.0 |
| 18 | 5.0 | 6.0 | 7.0 | 6.0 | 4.0 | 5.0 | 6.0 | 6.0 | 6.0 | 5.0 | 6.0 | 5.0 | 6.0 | 6.0 | 4.0 | 7.0 | 7.0 | 6.0 | 6.0 | 5.0 | 5.0 | 5.0 | 4.0 | 4.0 | 5.5 | 7.0 | 4.0 |
| 19 | 6.0 | 7.0 | 6.0 | 6.0 | 4.0 | 3.0 | 5.0 | 5.0 | 6.0 | 6.0 | 4.0 | 4.0 | 3.0 | 7.0 | 8.0 | 4.0 | 1.0 | 2.0 | 3.0 | 4.0 | 6.0 | 6.0 | 4.0 | 5.0 | 4.8 | 8.0 | 1.0 |
| 20 | 7.0 | 4.0 | 3.0 | 6.0 | 8.0 | 9.0 | 8.0 | 7.0 | 7.0 | 7.0 | 7.0 | 8.0 | 8.0 | 6.0 | 6.0 | 6.0 | 7.0 | 6.0 | 6.0 | 6.0 | 6.0 | 6.0 | 3.0 | 3.0 | 6.3 | 9.0 | 3.0 |
| 21 | 5.0 | 5.0 | 6.0 | 7.0 | 7.0 | 6.0 | 6.0 | 3.0 | 4.0 | 7.0 | 5.0 | -- | 3.0 | 4.0 | 4.0 | 4.0 | 4.0 | 5.0 | 4.0 | 4.0 | 5.0 | 5.0 | 8.0 | 6.0 | 5.1 | 8.0 | 3.0 |
| 22 | 4.0 | 4.0 | 2.0 | 2.0 | 2.0 | 4.0 | 6.0 | 4.0 | 4.0 | 4.0 | 2.0 | 1.0 | -1.0 | 0.0 | 1.0 | 1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 4.0 | 5.0 | 2.0 | 2.0 | 2.3 | 6.0 | -1.0 |
| 23 | 5.0 | 6.0 | 7.0 | 6.0 | 3.0 | 3.0 | 4.0 | 6.0 | 6.0 | 3.0 | 2.0 | 2.0 | 2.0 | 1.0 | 2.0 | 2.0 | -1.0 | 1.0 | 3.0 | 2.0 | 1.0 | 0.0 | 3.0 | 5.0 | 3.1 | 7.0 | -1.0 |
| 24 | 2.0 | 0.0 | 0.0 | 1.0 | 0.0 | 1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 2.0 | 0.0 | 0.0 | 2.0 | 4.0 | 4.0 | 4.0 | 3.0 | 2.0 | 3.0 | 4.0 | 4.0 | 3.0 | 4.0 | 1.9 | 4.0 | 0.0 |
| 25 | 6.0 | 6.0 | 5.0 | 4.0 | 3.0 | 2.0 | 5.0 | 6.0 | 5.0 | 3.0 | 4.0 | 4.0 | 4.0 | 5.0 | 2.0 | 1.0 | 2.0 | 5.0 | 5.0 | 4.0 | 2.0 | 2.0 | 3.0 | 4.0 | 3.8 | 6.0 | 1.0 |
| 26 | 5.0 | 3.0 | 4.0 | 4.0 | 4.0 | 5.0 | 3.0 | 4.0 | 6.0 | 5.0 | 3.0 | 3.0 | 4.0 | 5.0 | -- | -- | 4.0 | 2.0 | 1.0 | 3.0 | 4.0 | 3.0 | 2.0 | 3.0 | 3.6 | 6.0 | 1.0 |
| 27 | 5.0 | 3.0 | 2.0 | 3.0 | 3.0 | 4.0 | 4.0 | 1.0 | 2.0 | 4.0 | 3.0 | 1.0 | 2.0 | 1.0 | 0.0 | 0.0 | 3.0 | 3.0 | 2.0 | 2.0 | 1.0 | 2.0 | 2.0 | 1.0 | 2.3 | 5.0 | 0.0 |
| 28 | 2.0 | 3.0 | 3.0 | 5.0 | 4.0 | 3.0 | 2.0 | 1.0 | 2.0 | 2.0 | 2.0 | 2.0 | 4.0 | 5.0 | 3.0 | 2.0 | 1.0 | 2.0 | 4.0 | 5.0 | 3.0 | 3.0 | 3.0 | 5.0 | 3.0 | 5.0 | 1.0 |
| 29 | 5.0 | 4.0 | 3.0 | 2.0 | 3.0 | 4.0 | 4.0 | 3.0 | 3.0 | 5.0 | 4.0 | 2.0 | 3.0 | 4.0 | 3.0 | 4.0 | 6.0 | 7.0 | 6.0 | 5.0 | 4.0 | 2.0 | 1.0 | 3.0 | 3.8 | 7.0 | 1.0 |
| 30 | 5.0 | 6.0 | 5.0 | 6.0 | 6.0 | 4.0 | 5.0 | 6.0 | 5.0 | 2.0 | 2.0 | 5.0 | 7.0 | 6.0 | 2.0 | 2.0 | 5.0 | 5.0 | 7.0 | 6.0 | 3.0 | 4.0 | 3.0 | 2.0 | 4.5 | 7.0 | 2.0 |
| Avg | 4.2 | 4.0 | 3.7 | 3.8 | 3.5 | 3.8 | 4.0 | 3.5 | 4.0 | 4.2 | 3.8 | 3.5 | 3.3 | 3.5 | 3.1 | 3.0 | 3.1 | 3.3 | 3.6 | 3.6 | 3.6 | 3.6 | 3.3 | 3.7 | 3.6 | -- | -- |
| Max | 7.0 | 7.0 | 8.0 | 7.0 | 8.0 | 9.0 | 8.0 | 7.0 | 7.0 | 7.0 | 8.0 | 9.0 | 8.0 | 7.0 | 8.0 | 7.0 | 7.0 | 8.0 | 8.0 | 7.0 | 10.0 | 12.0 | 10.0 | 9.0 | -- | 12.0 | -- |
| Min | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | -1.0 | 1.0 | 0.0 | 0.0 | 0.0 | -1.0 | 0.0 | -1.0 | -3.0 | -2.0 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | -1.0 | 0.0 | -- | -- | -3.0 |

-- Indicates Invalid Data

## SAROAD for Resolution, East_Plant

## "Component, Channel: Table126, conc_PM25_µg/m$^3$ Actual"

## Month: Dec 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 3.0 | 6.0 | 6.0 | 7.0 | 5.0 | 3.0 | 5.0 | 6.0 | 5.0 | 3.0 | 3.0 | 4.0 | 3.0 | 3.0 | 4.0 | 4.0 | 5.0 | 4.0 | 4.0 | 4.0 | 3.0 | 3.0 | 3.0 | 2.0 | 4.1 | 7.0 | 2.0 |
| 2 | 1.0 | 4.0 | 4.0 | 2.0 | 2.0 | 1.0 | -1.0 | 0.0 | 3.0 | 5.0 | 3.0 | 2.0 | 2.0 | 4.0 | 4.0 | 2.0 | 4.0 | 4.0 | 4.0 | 4.0 | 5.0 | 3.0 | 3.0 | 4.0 | 2.9 | 5.0 | -1.0 |
| 3 | 4.0 | 4.0 | 2.0 | 1.0 | 2.0 | 3.0 | 3.0 | 4.0 | 5.0 | 6.0 | 5.0 | 3.0 | 3.0 | 2.0 | 3.0 | 2.0 | 2.0 | 5.0 | 3.0 | 2.0 | 2.0 | 1.0 | 3.0 | 3.0 | 3.0 | 6.0 | 1.0 |
| 4 | 1.0 | -1.0 | -2.0 | 1.0 | 3.0 | 2.0 | 1.0 | 4.0 | 6.0 | 6.0 | 4.0 | 2.0 | 4.0 | 4.0 | 5.0 | 3.0 | 1.0 | 2.0 | 4.0 | 6.0 | 7.0 | 7.0 | 8.0 | 9.0 | 3.6 | 9.0 | -2.0 |
| 5 | 6.0 | 4.0 | 4.0 | 3.0 | 3.0 | 2.0 | 3.0 | 5.0 | 4.0 | 3.0 | 3.0 | 4.0 | 4.0 | 3.0 | 3.0 | 5.0 | 3.0 | 4.0 | 5.0 | 4.0 | 4.0 | 3.0 | 5.0 | 6.0 | 3.9 | 6.0 | 2.0 |
| 6 | 6.0 | 7.0 | 6.0 | 2.0 | 1.0 | 4.0 | 4.0 | 4.0 | 6.0 | 5.0 | 2.0 | 3.0 | 5.0 | 6.0 | 6.0 | 3.0 | 2.0 | 4.0 | 6.0 | 5.0 | 4.0 | 5.0 | 5.0 | 4.0 | 4.4 | 7.0 | 1.0 |
| 7 | 4.0 | 5.0 | 4.0 | 3.0 | 5.0 | 4.0 | 3.0 | 3.0 | 4.0 | 5.0 | 5.0 | 5.0 | 2.0 | 3.0 | 2.0 | 2.0 | 5.0 | 4.0 | 3.0 | 5.0 | 5.0 | 4.0 | 4.0 | 4.0 | 3.9 | 5.0 | 2.0 |
| 8 | 5.0 | 4.0 | 4.0 | 6.0 | 3.0 | 1.0 | 2.0 | 5.0 | 4.0 | 3.0 | 3.0 | 3.0 | 5.0 | 4.0 | 3.0 | 4.0 | 2.0 | 4.0 | 6.0 | 3.0 | 3.0 | 5.0 | 6.0 | 6.0 | 3.9 | 6.0 | 1.0 |
| 9 | 6.0 | 4.0 | 6.0 | 9.0 | 8.0 | 6.0 | 7.0 | 7.0 | 7.0 | 7.0 | 5.0 | 5.0 | 4.0 | 4.0 | 4.0 | 2.0 | 1.0 | 2.0 | 1.0 | 0.0 | 2.0 | 2.0 | 2.0 | 2.0 | 4.3 | 9.0 | 0.0 |
| 10 | 2.0 | 4.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | 0.0 | 3.0 | 5.0 | 3.0 | 3.0 | 4.0 | 2.0 | 1.0 | -1.0 | -1.0 | 3.0 | 2.0 | 0.0 | 1.0 | 3.0 | 3.0 | 3.0 | 2.0 | 5.0 | -1.0 |
| 11 | 4.0 | 4.0 | 2.0 | 1.0 | 1.0 | 0.0 | 1.0 | 2.0 | 2.0 | 2.0 | 2.0 | 1.0 | 2.0 | 3.0 | 2.0 | 0.0 | 3.0 | 3.0 | 3.0 | 2.0 | 1.0 | 4.0 | 4.0 | 4.0 | 2.2 | 4.0 | 0.0 |
| 12 | 3.0 | 4.0 | 6.0 | 5.0 | 5.0 | 6.0 | 6.0 | 7.0 | 8.0 | 4.0 | 2.0 | 4.0 | 4.0 | 3.0 | -- | 3.0 | 3.0 | 5.0 | -- | -- | -- | -- | -- | -- | -- | 8.0 | 2.0 |
| 13 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 7.0 | 7.0 | 7.0 | 10.0 | 11.0 | 8.0 | 8.0 | 8.0 | 7.0 | 5.0 | 6.0 | 6.0 | -- | 11.0 | 5.0 |
| 14 | 4.0 | 6.0 | 6.0 | 6.0 | 6.0 | 3.0 | 3.0 | 4.0 | 2.0 | 3.0 | 6.0 | 5.0 | 2.0 | 1.0 | 1.0 | 2.0 | 2.0 | 3.0 | 4.0 | 3.0 | 1.0 | 3.0 | 2.0 | 0.0 | 3.3 | 6.0 | 0.0 |
| 15 | 2.0 | 5.0 | 5.0 | 4.0 | 5.0 | 5.0 | 3.0 | 4.0 | 3.0 | 2.0 | 1.0 | 1.0 | 1.0 | 1.0 | 3.0 | 2.0 | 2.0 | 3.0 | 4.0 | 2.0 | 0.0 | 2.0 | 4.0 | 4.0 | 2.8 | 5.0 | 0.0 |
| 16 | 4.0 | 2.0 | -1.0 | 0.0 | 3.0 | 3.0 | 3.0 | 3.0 | 2.0 | 3.0 | 4.0 | 4.0 | 3.0 | 4.0 | 4.0 | 3.0 | 5.0 | 6.0 | 3.0 | 3.0 | 5.0 | 6.0 | 6.0 | 6.0 | 3.5 | 6.0 | -1.0 |
| 17 | 4.0 | 1.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 1.0 | 1.0 | 1.0 | 0.0 | 0.0 | 0.0 | 1.0 | 1.0 | 2.0 | 3.0 | 2.0 | 0.0 | -1.0 | 1.0 | 2.0 | -1.0 | 1.0 | 1.6 | 5.0 | -1.0 |
| 18 | 2.0 | 1.0 | 1.0 | -1.0 | 1.0 | 2.0 | 3.0 | 4.0 | 3.0 | 3.0 | 3.0 | 3.0 | 1.0 | 0.0 | 3.0 | 3.0 | 2.0 | 4.0 | 2.0 | 3.0 | 2.0 | 0.0 | 0.0 | 1.0 | 1.9 | 4.0 | -1.0 |
| 19 | 2.0 | 3.0 | 5.0 | 6.0 | 5.0 | 5.0 | 7.0 | 5.0 | 3.0 | 7.0 | 9.0 | 5.0 | 2.0 | -- | 3.0 | 3.0 | 6.0 | 6.0 | 5.0 | 4.0 | 9.0 | 23.0 | 9.0 | 10.0 | 6.2 | 23.0 | 2.0 |
| 20 | 8.0 | 6.0 | 7.0 | 9.0 | 8.0 | 5.0 | 1.0 | 4.0 | 5.0 | 3.0 | 3.0 | 2.0 | 1.0 | -- | -- | 4.0 | 4.0 | 5.0 | 5.0 | 3.0 | 2.0 | 2.0 | 1.0 | 1.0 | 4.1 | 9.0 | 1.0 |
| 21 | 1.0 | 1.0 | 5.0 | 3.0 | 2.0 | 3.0 | 2.0 | 2.0 | 4.0 | 5.0 | 3.0 | 6.0 | 7.0 | 7.0 | 9.0 | 8.0 | 9.0 | 6.0 | 4.0 | 7.0 | 6.0 | 6.0 | 7.0 | 7.0 | 5.0 | 9.0 | 1.0 |
| 22 | 8.0 | 7.0 | 6.0 | 8.0 | 8.0 | 6.0 | 5.0 | 6.0 | 9.0 | 9.0 | 5.0 | 4.0 | 5.0 | 5.0 | 5.0 | 6.0 | 8.0 | 7.0 | 7.0 | 9.0 | 7.0 | 7.0 | 8.0 | 5.0 | 6.7 | 9.0 | 4.0 |
| 23 | 6.0 | 7.0 | 6.0 | 5.0 | 2.0 | 2.0 | 2.0 | 3.0 | 4.0 | 3.0 | 1.0 | 1.0 | 2.0 | 4.0 | 2.0 | 2.0 | 3.0 | 4.0 | 2.0 | 3.0 | 5.0 | 4.0 | 4.0 | 3.0 | 3.3 | 7.0 | 1.0 |
| 24 | 2.0 | 3.0 | 3.0 | 2.0 | 0.0 | 0.0 | 3.0 | 3.0 | 3.0 | 3.0 | 1.0 | 2.0 | 3.0 | 3.0 | 2.0 | 2.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 2.0 | 4.0 | 4.0 | 2.7 | 5.0 | 0.0 |
| 25 | 4.0 | 7.0 | 16.0 | 40.0 | 33.0 | 35.0 | 42.0 | 8.0 | 6.0 | 4.0 | 4.0 | 3.0 | 1.0 | 2.0 | 1.0 | 1.0 | 3.0 | 3.0 | 1.0 | 1.0 | 2.0 | 1.0 | 1.0 | 1.0 | 9.2 | 42.0 | 1.0 |
| 26 | 2.0 | 4.0 | 4.0 | 4.0 | 6.0 | 6.0 | 4.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 5.0 | 5.0 | 5.0 | 4.0 | 3.0 | 5.0 | 5.0 | 4.0 | 3.0 | 2.0 | 3.0 | 2.0 | 4.0 | 6.0 | 2.0 |
| 27 | 2.0 | 2.0 | 2.0 | 1.0 | 0.0 | 1.0 | -1.0 | -2.0 | 2.0 | 4.0 | 3.0 | -- | 3.0 | 2.0 | 2.0 | 4.0 | 2.0 | 1.0 | 3.0 | 4.0 | 4.0 | 4.0 | 5.0 | 3.0 | 2.2 | 5.0 | -2.0 |
| 28 | 3.0 | 5.0 | 5.0 | 3.0 | 3.0 | 6.0 | 5.0 | 3.0 | 3.0 | 4.0 | 6.0 | 6.0 | 4.0 | 4.0 | 4.0 | 4.0 | 3.0 | 5.0 | 5.0 | 6.0 | 7.0 | 4.0 | 2.0 | 4.0 | 4.3 | 7.0 | 2.0 |
| 29 | 5.0 | 3.0 | 4.0 | 4.0 | 2.0 | 4.0 | 6.0 | 5.0 | 4.0 | 4.0 | 4.0 | 3.0 | 2.0 | 1.0 | 2.0 | 0.0 | 0.0 | 3.0 | 3.0 | 3.0 | 3.0 | 2.0 | 3.0 | 3.0 | 3.0 | 6.0 | 0.0 |
| 30 | 2.0 | 3.0 | 3.0 | 0.0 | 0.0 | 2.0 | 2.0 | 3.0 | 4.0 | 5.0 | 4.0 | 3.0 | 1.0 | -2.0 | -1.0 | 2.0 | 1.0 | 1.0 | 3.0 | 4.0 | 5.0 | 4.0 | 2.0 | 3.0 | 2.3 | 5.0 | -2.0 |
| 31 | 5.0 | 3.0 | 2.0 | 3.0 | 3.0 | 5.0 | 6.0 | 5.0 | 5.0 | 4.0 | 4.0 | 3.0 | 3.0 | 6.0 | 5.0 | 5.0 | 3.0 | 2.0 | 3.0 | 5.0 | 5.0 | 4.0 | 3.0 | 2.0 | 3.9 | 6.0 | 2.0 |
| Avg | 3.7 | 3.9 | 4.2 | 4.8 | 4.4 | 4.3 | 4.5 | 3.7 | 4.1 | 4.2 | 3.5 | 3.2 | 3.1 | 3.2 | 3.3 | 3.1 | 3.3 | 3.9 | 3.8 | 3.7 | 3.8 | 4.1 | 3.8 | 3.8 | 3.7 | -- | -- |
| Max | 8.0 | 7.0 | 16.0 | 40.0 | 33.0 | 35.0 | 42.0 | 8.0 | 9.0 | 9.0 | 9.0 | 6.0 | 7.0 | 7.0 | 9.0 | 10.0 | 11.0 | 8.0 | 8.0 | 9.0 | 9.0 | 23.0 | 9.0 | 10.0 | -- | 42.0 | -- |
| Min | 1.0 | -1.0 | -2.0 | -1.0 | 0.0 | 0.0 | -1.0 | -2.0 | 1.0 | 1.0 | 0.0 | 0.0 | 0.0 | -2.0 | -1.0 | -1.0 | -1.0 | 1.0 | 0.0 | -1.0 | 0.0 | 0.0 | -1.0 | 0.0 | -- | -- | -2.0 |

-- Indicates Invalid Data

## SAROAD for Resolution, West_Plant

## "Component, Channel: Table126, conc_PM10_µg/m$^3$ STP"

## Month: Oct 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 17.6 | 11.0 | 16.5 | 13.2 | 20.8 | 26.3 | 24.1 | 58.3 | 14.4 | 14.5 | 14.6 | 25.9 | 33.9 | 24.9 | 31.7 | 13.6 | 19.3 | 13.6 | 41.6 | 21.3 | 23.4 | 12.2 | 13.3 | 14.4 | 21.7 | 58.3 | 11.0 |
| 2 | 14.4 | 17.6 | 13.2 | 12.1 | 13.2 | 18.6 | 29.6 | 16.5 | 14.4 | 14.5 | 19.1 | 20.2 | 18.0 | 30.5 | 38.5 | 19.2 | 13.6 | 18.0 | 15.7 | 30.2 | 20.1 | 8.9 | 8.9 | 8.9 | 18.1 | 38.5 | 8.9 |
| 3 | 11.1 | 13.3 | 8.8 | 7.7 | 16.5 | 9.9 | 18.6 | 14.3 | 14.5 | 10.1 | 6.7 | 9.0 | 18.1 | 26.1 | 25.0 | 27.3 | 19.3 | 6.8 | 19.1 | 17.9 | 22.3 | 14.5 | 16.6 | 18.8 | 15.5 | 27.3 | 6.7 |
| 4 | 27.6 | 24.2 | 20.9 | 24.2 | 19.7 | 28.3 | 20.7 | 26.3 | 22.1 | 28.8 | 21.2 | 27.9 | 34.7 | 34.7 | 39.3 | 28.0 | 34.7 | 41.2 | 37.7 | 23.2 | 38.4 | 29.6 | 48.2 | 125.0 | 33.6 | 125.0 | 19.7 |
| 5 | 39.2 | 57.6 | 79.2 | 63.9 | 48.6 | 36.7 | 14.1 | 11.9 | 5.4 | 6.6 | 12.0 | 11.0 | 8.8 | 11.1 | 7.8 | 4.5 | 5.6 | 6.6 | 16.5 | 24.1 | 13.1 | 4.4 | 45.9 | 16.4 | 23.0 | 79.2 | 4.4 |
| 6 | 25.1 | 6.5 | 4.4 | 1.1 | 3.3 | 6.5 | 7.6 | 17.5 | 14.3 | 11.0 | 11.0 | 13.3 | 5.6 | 4.5 | 6.8 | 4.5 | 4.5 | 6.7 | 6.7 | 7.8 | 5.5 | 6.6 | 6.6 | 4.4 | 8.0 | 25.1 | 1.1 |
| 7 | 6.6 | 5.5 | 5.5 | 7.7 | 6.6 | 6.6 | 17.6 | 8.8 | 8.9 | 19.0 | 13.5 | 10.1 | 8.0 | 9.1 | 11.4 | 8.0 | 7.9 | 13.5 | 24.7 | 16.8 | 14.5 | 11.2 | 10.0 | 11.1 | 10.9 | 24.7 | 5.5 |
| 8 | 10.0 | 7.7 | 8.8 | 10.0 | 10.0 | 14.3 | 48.3 | 35.4 | 15.6 | -- | 35.0 | 36.2 | 27.2 | 30.6 | 72.7 | 35.2 | 29.5 | 20.3 | -- | -- | -- | -- | -- | -- | -- | 72.7 | 7.7 |
| 9 | 8.8 | -- | -- | 9.9 | 7.7 | 8.8 | 23.1 | 52.9 | 16.7 | 15.7 | -- | -- | 121.0 | -- | 135.0 | -- | -- | -- | -- | -- | 56.4 | 37.4 | 28.5 | 25.2 | -- | 135.0 | 7.7 |
| 10 | 21.8 | 21.8 | 14.1 | 15.2 | 33.6 | 31.3 | 19.4 | 27.6 | 15.9 | 15.9 | 17.0 | 21.3 | 27.9 | 17.2 | 23.7 | 10.8 | 10.8 | 9.7 | 9.7 | 10.7 | 8.6 | 8.6 | 7.5 | 6.4 | 16.9 | 33.6 | 6.4 |
| 11 | 6.4 | 7.5 | 6.4 | 7.5 | 8.5 | 6.4 | 6.4 | 7.5 | 9.7 | 9.7 | 8.7 | 7.7 | 9.9 | 9.9 | -- | 9.9 | 16.5 | 7.7 | 10.9 | 10.9 | 10.8 | 11.9 | 10.8 | 10.8 | 9.2 | 16.5 | 6.4 |
| 12 | 11.9 | 7.6 | 6.5 | 6.5 | 2.2 | 3.3 | 5.4 | 5.4 | 7.7 | 6.6 | 6.7 | 9.0 | 12.3 | 10.1 | 10.1 | 16.8 | 10.1 | 12.3 | 27.7 | 28.7 | 17.6 | 14.3 | 20.8 | 14.2 | 11.4 | 28.7 | 2.2 |
| 13 | 18.6 | 7.6 | 12.0 | 24.0 | 13.0 | 12.0 | 12.0 | 12.0 | 13.2 | 14.4 | 14.5 | 12.3 | 12.3 | 12.3 | 16.8 | 17.9 | 13.4 | 13.4 | 38.8 | 31.9 | 12.1 | 18.6 | 14.2 | 17.4 | 16.0 | 38.8 | 7.6 |
| 14 | 13.1 | 13.0 | 19.5 | 7.6 | 18.3 | 15.1 | 14.0 | 30.2 | 10.9 | 12.0 | 19.8 | 15.5 | 15.5 | 18.9 | 18.9 | 12.2 | 21.1 | 22.1 | 30.7 | 14.3 | 18.5 | 15.2 | 14.1 | 9.8 | 16.7 | 30.7 | 7.6 |
| 15 | 6.5 | 8.7 | 10.9 | 9.8 | 9.8 | 7.6 | 7.6 | 18.4 | 18.6 | 11.0 | 13.3 | 15.5 | 13.3 | 24.5 | 31.2 | 20.0 | 20.0 | 15.5 | 26.4 | 32.9 | 21.8 | 18.5 | 16.3 | 22.7 | 16.7 | 32.9 | 6.5 |
| 16 | 13.0 | 14.0 | 16.2 | 8.6 | 7.5 | 9.6 | 17.2 | 41.0 | 14.1 | 15.3 | 13.2 | 9.9 | 26.5 | 23.3 | 16.6 | 12.2 | 8.9 | 8.8 | 20.8 | 13.1 | 14.1 | 27.0 | 10.8 | 30.2 | 16.3 | 41.0 | 7.5 |
| 17 | 7.5 | 9.7 | 8.6 | 6.5 | 6.5 | 6.5 | 18.2 | 23.7 | 4.3 | 6.6 | 9.9 | 12.2 | 25.5 | 18.9 | 24.5 | 23.3 | 22.2 | 17.7 | 25.3 | 21.9 | 15.3 | 31.5 | 9.8 | 19.5 | 15.6 | 31.5 | 4.3 |
| 18 | 16.2 | 15.1 | 13.0 | 18.3 | 12.9 | 18.3 | 18.2 | 30.2 | 21.8 | 11.0 | 9.9 | 7.8 | 7.8 | 6.7 | 29.0 | 16.7 | 18.9 | 24.3 | 36.3 | 18.6 | 33.8 | 23.9 | 7.6 | 8.7 | 17.7 | 36.3 | 6.7 |
| 19 | 7.6 | 17.3 | 5.4 | 5.4 | 8.7 | 18.3 | 14.0 | 14.1 | 12.0 | 6.6 | 6.6 | 12.2 | 16.7 | 11.2 | 6.7 | 6.7 | 22.4 | 11.1 | 19.9 | 57.2 | 29.6 | 10.9 | 10.9 | 10.9 | 14.3 | 57.2 | 5.4 |
| 20 | 12.0 | 11.9 | 11.9 | 9.8 | 9.8 | 9.7 | 29.1 | 7.6 | 6.6 | 8.8 | 11.1 | 11.1 | 10.0 | 11.2 | 13.4 | 10.1 | 7.8 | 10.0 | 29.9 | 29.7 | 43.8 | 10.9 | 10.9 | 10.9 | 14.1 | 43.8 | 6.6 |
| 21 | 37.0 | 6.5 | 7.6 | 41.2 | 10.8 | 17.3 | 34.5 | 65.1 | 11.0 | 13.3 | 13.3 | 34.5 | 16.8 | 14.6 | 38.1 | 9.0 | 11.2 | 23.4 | 25.5 | 28.6 | 22.0 | 28.4 | 21.8 | 20.8 | 23.0 | 65.1 | 6.5 |
| 22 | 9.9 | 7.7 | 7.7 | 8.8 | 12.1 | 9.9 | 18.6 | 41.4 | 29.7 | 54.1 | 27.8 | 24.6 | 16.8 | 42.8 | 11.3 | 9.0 | 7.9 | 10.1 | 10.1 | 6.7 | 8.9 | 10.0 | 12.2 | 21.1 | 17.5 | 54.1 | 6.7 |
| 23 | 17.7 | 25.5 | 16.6 | 15.4 | 14.3 | 16.6 | 17.7 | 34.2 | 42.1 | 36.7 | 45.9 | 27.0 | 19.2 | 12.5 | 12.5 | 11.4 | 9.1 | 10.2 | 9.0 | 12.3 | 9.0 | 6.7 | 8.9 | 10.0 | 18.4 | 45.9 | 6.7 |
| 24 | 10.0 | 17.8 | 16.7 | 14.4 | 12.2 | 13.2 | 23.1 | 12.2 | 27.8 | 11.2 | 13.5 | 16.9 | 12.5 | 12.5 | 12.4 | 20.3 | 25.8 | 31.3 | 44.6 | 27.7 | 19.9 | 13.2 | 13.2 | 13.1 | 18.1 | 44.6 | 10.0 |
| 25 | 19.7 | 12.0 | 13.1 | 12.0 | 9.8 | 27.1 | 33.6 | 49.9 | -- | -- | 15.5 | 22.2 | 15.6 | 17.9 | 29.1 | 24.6 | 10.0 | 24.4 | 15.5 | 12.1 | 12.0 | 13.1 | 33.8 | 7.6 | 19.6 | 49.9 | 7.6 |
| 26 | 6.6 | 7.7 | 6.6 | 5.4 | 9.8 | 9.8 | 5.5 | 6.6 | 8.8 | 8.8 | 10.0 | 12.2 | 10.1 | 5.6 | 4.5 | 4.5 | 5.6 | 10.0 | 83.2 | 18.8 | 14.3 | 13.3 | 8.8 | 6.6 | 11.8 | 83.2 | 4.5 |
| 27 | 6.6 | 18.8 | 18.8 | 52.9 | 18.7 | 41.8 | 14.3 | 9.9 | 9.9 | 15.5 | 12.3 | 6.7 | 7.9 | 12.5 | 12.5 | 13.6 | 11.3 | 12.4 | 24.6 | 36.6 | 15.5 | 34.2 | 52.9 | 8.8 | 19.5 | 52.9 | 6.6 |
| 28 | 11.0 | 12.1 | 13.2 | 11.0 | 6.6 | 9.9 | 12.0 | 26.3 | 9.9 | 13.3 | 16.6 | 7.8 | 35.7 | 28.0 | 44.7 | 15.6 | 13.3 | 84.3 | 84.0 | 105.0 | 90.0 | 60.4 | 24.1 | 6.6 | 30.9 | 105.0 | 6.6 |
| 29 | 3.3 | 3.3 | 1.1 | 2.2 | 6.5 | 17.3 | 19.4 | 14.0 | 14.2 | -- | 10.0 | 20.0 | 24.4 | 75.5 | 60.5 | 39.4 | 35.9 | 33.6 | 29.2 | 31.3 | 22.6 | 32.2 | 28.9 | 15.0 | 23.5 | 75.5 | 1.1 |
| 30 | 15.0 | 12.8 | 8.5 | 9.6 | 20.2 | 20.2 | 12.7 | 23.4 | 17.1 | 20.4 | 34.4 | 20.5 | -- | 11.9 | 29.3 | 11.9 | 11.9 | 10.8 | 18.3 | 16.1 | 4.3 | 7.5 | 9.6 | 8.5 | 15.4 | 34.4 | 4.3 |
| 31 | 8.5 | 10.6 | 10.6 | 9.6 | 9.6 | 7.5 | 8.5 | 10.6 | 12.8 | 12.9 | 10.8 | 8.7 | 9.8 | 18.6 | 19.7 | 16.4 | 13.1 | 16.3 | 16.2 | 12.9 | 17.2 | 11.8 | 13.9 | 17.0 | 12.6 | 19.7 | 7.5 |
| Avg | 14.2 | 13.8 | 13.4 | 14.6 | 13.1 | 15.6 | 18.2 | 24.3 | 14.8 | 15.2 | 15.8 | 16.3 | 20.7 | 19.6 | 27.8 | 15.8 | 15.4 | 18.2 | 27.5 | 24.8 | 21.9 | 18.2 | 18.0 | 17.3 | 17.5 | -- | -- |
| Max | 39.2 | 57.6 | 79.2 | 63.9 | 48.6 | 41.8 | 48.3 | 65.1 | 42.1 | 54.1 | 45.9 | 36.2 | 121.0 | 75.5 | 135.0 | 39.4 | 35.9 | 84.3 | 84.0 | 105.0 | 90.0 | 60.4 | 52.9 | 125.0 | -- | 135.0 | -- |
| Min | 3.3 | 3.3 | 1.1 | 1.1 | 2.2 | 3.3 | 5.4 | 5.4 | 4.3 | 6.6 | 6.6 | 6.7 | 5.6 | 4.5 | 4.5 | 4.5 | 4.5 | 6.6 | 6.7 | 6.7 | 4.3 | 4.4 | 6.6 | 4.4 | -- | -- | 1.1 |

-- Indicates Invalid Data

## SAROAD for Resolution, West_Plant

## "Component, Channel: Table126, conc_PM10_µg/m$^3$ STP"

## Month: Nov 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 10.6 | 10.6 | 10.6 | 11.7 | 11.7 | 10.6 | 9.6 | 17.1 | 10.8 | 18.4 | 24.0 | 7.7 | 3.3 | 3.3 | 10.0 | 12.2 | 13.2 | 27.4 | 20.7 | 29.3 | 6.5 | 9.8 | 8.7 | 1.1 | 12.5 | 29.3 | 1.1 |
| 2 | 2.2 | 12.0 | 7.6 | 27.3 | 18.5 | 79.7 | 27.4 | 18.6 | 56.0 | 54.0 | 33.2 | 28.9 | 10.0 | 12.3 | 12.4 | 9.0 | 11.2 | 11.2 | 8.9 | 12.2 | 14.4 | 13.2 | 18.7 | 17.6 | 21.5 | 79.7 | 2.2 |
| 3 | 5.5 | 8.8 | 7.7 | 3.3 | 3.3 | 3.3 | 2.2 | 4.4 | 4.4 | 2.2 | 3.3 | 6.7 | 3.4 | 1.1 | 8.9 | 13.4 | 8.9 | 7.8 | 10.0 | 14.3 | 18.6 | 9.8 | 8.7 | 9.8 | 7.1 | 18.6 | 1.1 |
| 4 | 7.6 | 4.4 | 7.6 | 9.8 | 5.5 | 6.5 | 8.7 | 10.8 | 12.0 | 5.5 | 1.1 | 4.5 | 4.5 | 4.5 | 6.7 | 10.0 | 17.8 | 16.6 | 14.4 | 25.3 | 16.5 | 17.5 | 28.2 | 14.0 | 10.8 | 28.2 | 1.1 |
| 5 | 12.9 | 10.7 | 9.7 | 7.5 | 7.5 | 6.4 | 6.4 | 5.3 | 6.4 | 8.6 | 12.9 | 15.1 | 13.0 | 8.7 | 20.7 | 14.2 | 14.1 | 17.3 | 23.7 | 22.6 | 17.2 | -1.1 | 2.1 | 4.3 | 11.1 | 23.7 | -1.1 |
| 6 | 16.0 | 2.1 | 0.0 | 0.0 | 4.2 | 8.4 | 11.6 | 47.4 | 35.0 | 6.4 | 4.3 | 2.2 | 3.3 | 6.6 | 12.1 | 7.7 | 2.2 | 1.1 | 3.3 | 6.5 | 5.4 | 4.3 | 4.3 | 7.6 | 8.4 | 47.4 | 0.0 |
| 7 | 18.5 | 5.4 | 5.4 | 9.8 | 11.9 | 27.0 | 11.9 | 46.3 | 57.2 | 22.8 | 8.7 | 9.9 | 7.7 | 7.7 | 8.9 | 4.4 | 3.3 | 4.4 | 4.4 | 6.6 | 7.7 | 9.8 | 10.9 | 9.8 | 13.3 | 57.2 | 3.3 |
| 8 | 9.8 | 6.5 | 3.3 | 4.4 | 5.4 | 6.5 | 6.5 | 7.6 | 9.8 | 9.8 | 11.0 | 12.2 | 11.1 | 13.3 | 24.5 | 6.7 | 6.7 | 17.7 | 45.1 | 182.0 | 182.0 | 240.0 | 294.0 | 358.0 | 61.4 | 358.0 | 3.3 |
| 9 | 169.0 | 45.4 | 4.3 | 4.3 | 7.6 | 13.0 | 86.3 | -- | -- | -- | -- | -- | 11.1 | 52.3 | 13.4 | 11.2 | 6.7 | 6.6 | 8.8 | 6.6 | 4.4 | 6.5 | 7.6 | 6.5 | 24.8 | 169.0 | 4.3 |
| 10 | 4.3 | 5.4 | 7.6 | 6.5 | 6.5 | 8.7 | 11.9 | 11.9 | 9.8 | 10.9 | 11.0 | 13.3 | 14.5 | 12.3 | 19.0 | 41.3 | 12.2 | 8.9 | 6.7 | 6.6 | 5.5 | 5.5 | 5.5 | 5.5 | 10.5 | 41.3 | 4.3 |
| 11 | 5.5 | 6.6 | 8.7 | 6.6 | 2.2 | 6.5 | 8.8 | 41.4 | 20.8 | 14.4 | 13.3 | 17.8 | 15.7 | 12.4 | 27.0 | 4.5 | 6.7 | 11.2 | 11.1 | 10.0 | 9.9 | 8.8 | 6.6 | 7.7 | 11.8 | 41.4 | 2.2 |
| 12 | 5.5 | 4.4 | 6.6 | 7.7 | 10.9 | 10.9 | 19.7 | 53.8 | 14.3 | 18.8 | 12.2 | 7.8 | 6.7 | 11.2 | 40.2 | 62.3 | 45.6 | 34.3 | 33.1 | 43.9 | 29.5 | 29.4 | 39.2 | 83.7 | 26.3 | 83.7 | 4.4 |
| 13 | 136.0 | 318.0 | 128.0 | 99.4 | 76.7 | 52.9 | 43.1 | 21.6 | 22.7 | 33.6 | 28.3 | 16.4 | 5.5 | 32.0 | 6.6 | 6.6 | 6.6 | 7.7 | 9.8 | 10.9 | 8.7 | 5.4 | 6.5 | 4.3 | 45.3 | 318.0 | 4.3 |
| 14 | 2.2 | 5.4 | 6.5 | 7.6 | 10.8 | 9.7 | 7.6 | 6.5 | 8.7 | 12.0 | 9.9 | 8.8 | 13.3 | 15.6 | 17.8 | 34.5 | 44.4 | 12.1 | 31.9 | 18.6 | 11.0 | 8.8 | 7.7 | 7.7 | 13.3 | 44.4 | 2.2 |
| 15 | 10.9 | 12.0 | 10.9 | 13.1 | 10.9 | 19.6 | 18.6 | 25.1 | 24.1 | 30.8 | 21.0 | 20.1 | 34.6 | 49.2 | 115.0 | 115.0 | 77.7 | 76.5 | 58.7 | 43.8 | 122.0 | 77.5 | 39.2 | 28.3 | 43.9 | 122.0 | 10.9 |
| 16 | 19.5 | 22.8 | 17.4 | 19.5 | 18.4 | 19.5 | 19.4 | 19.4 | 21.5 | 11.9 | 22.7 | 23.8 | 19.6 | 16.4 | 18.6 | 21.9 | 16.4 | 17.4 | 21.7 | 16.2 | 22.6 | 18.3 | 17.2 | 18.3 | 19.2 | 23.8 | 11.9 |
| 17 | 19.3 | 18.2 | 17.1 | 18.2 | 17.1 | 13.8 | 16.0 | 18.1 | 18.2 | 10.8 | 10.8 | 8.7 | 8.7 | 9.8 | 7.7 | 6.6 | 8.8 | 10.9 | 11.9 | 11.9 | 9.8 | 8.7 | 8.7 | 5.4 | 12.3 | 19.3 | 5.4 |
| 18 | 2.2 | 6.5 | 7.5 | 5.4 | 4.3 | 5.4 | 7.5 | 23.7 | 18.4 | 16.3 | 20.8 | 6.6 | 9.9 | 17.7 | 25.4 | 12.1 | 11.0 | 12.1 | 13.1 | 13.0 | 13.0 | 8.7 | 4.3 | 6.5 | 11.3 | 25.4 | 2.2 |
| 19 | 7.5 | 4.3 | 6.5 | 7.5 | 7.5 | 7.5 | 8.6 | 8.6 | 8.7 | 10.9 | 14.3 | 10.0 | 10.0 | 50.8 | 29.8 | 13.3 | 12.1 | 12.1 | 18.6 | 14.2 | 18.5 | 17.4 | 18.4 | 23.7 | 14.2 | 50.8 | 4.3 |
| 20 | 21.6 | 21.6 | 19.4 | 15.1 | 16.1 | 16.1 | 20.5 | 30.2 | 40.0 | 28.2 | 22.9 | 18.6 | 20.9 | 20.8 | 30.6 | 27.3 | 27.3 | 26.2 | 22.9 | 15.2 | 21.7 | 23.9 | 21.7 | 18.5 | 22.8 | 40.0 | 15.1 |
| 21 | 18.4 | 18.4 | 11.9 | 11.9 | 10.8 | 13.0 | 15.1 | 17.3 | 19.5 | 16.3 | 14.2 | 17.5 | 8.8 | 12.1 | 19.7 | 16.4 | 15.3 | 13.1 | 10.9 | 21.7 | 16.2 | 15.1 | 10.8 | 6.5 | 14.6 | 21.7 | 6.5 |
| 22 | 5.4 | 1.1 | 0.0 | 3.3 | 3.3 | 4.4 | 4.3 | 4.3 | 6.4 | 3.2 | -1.1 | -1.1 | 2.1 | 2.1 | 1.1 | 3.2 | 2.1 | 0.0 | 1.1 | 0.0 | 0.0 | 0.0 | 1.1 | 1.1 | 2.0 | 6.4 | -1.1 |
| 23 | -2.1 | -2.1 | 1.1 | 4.2 | 3.2 | 2.1 | 3.2 | 5.2 | 3.1 | 1.1 | 1.1 | -3.1 | -3.1 | 0.0 | 1.1 | 1.1 | 1.1 | -1.1 | -1.1 | 0.0 | -1.1 | -1.1 | 0.0 | -1.0 | 0.5 | 5.2 | -3.1 |
| 24 | -3.1 | -4.2 | -4.2 | -4.2 | -2.1 | 0.0 | 3.1 | 0.0 | -2.1 | 1.0 | 3.1 | 0.0 | -3.1 | -3.1 | 2.1 | 2.1 | 1.1 | 2.1 | 1.0 | 1.0 | 0.0 | -1.0 | 0.0 | 2.1 | -0.3 | 3.1 | -4.2 |
| 25 | 0.0 | -2.1 | -1.0 | 0.0 | 0.0 | 1.0 | 3.1 | 2.1 | 2.1 | 4.2 | 4.2 | 2.1 | 1.1 | 1.1 | 1.1 | 3.2 | 3.2 | 6.3 | 4.2 | 3.2 | 5.3 | 6.3 | 5.3 | 4.2 | 2.5 | 6.3 | -2.1 |
| 26 | 3.2 | 3.2 | 6.3 | 5.3 | 0.0 | 1.1 | 5.3 | 4.2 | 2.1 | -- | -- | 1.1 | 2.1 | 2.2 | 1.1 | 0.0 | 1.1 | 4.3 | 1.1 | 1.1 | 1.1 | 1.1 | 3.2 | 3.2 | 2.4 | 6.3 | 0.0 |
| 27 | 5.3 | 39.3 | 10.6 | 9.6 | 4.2 | 3.2 | 9.5 | 43.4 | 30.8 | 17.0 | 10.7 | 8.5 | 11.8 | 16.1 | 10.7 | 7.5 | 4.3 | 3.2 | 4.3 | 3.2 | 2.1 | 3.2 | 1.1 | 2.1 | 10.9 | 43.4 | 1.1 |
| 28 | 2.1 | -1.1 | -2.1 | 0.0 | 1.1 | 3.2 | 4.2 | 1.1 | 3.2 | 6.4 | 8.6 | 7.5 | 2.2 | 3.3 | 2.2 | 1.1 | 3.3 | 3.2 | 3.2 | 4.3 | 5.4 | 5.4 | 3.2 | 2.2 | 3.0 | 8.6 | -2.1 |
| 29 | 3.2 | 3.2 | 4.3 | 6.4 | 4.3 | 3.2 | 3.2 | 5.3 | 7.5 | 6.4 | 3.2 | 6.5 | 7.6 | 6.6 | 6.6 | 10.9 | 17.4 | 35.7 | 18.3 | 10.8 | 9.7 | 8.6 | 9.6 | 10.6 | 8.7 | 35.7 | 3.2 |
| 30 | 7.5 | 5.3 | 4.3 | 2.1 | 4.3 | 9.5 | 13.8 | 10.6 | 6.4 | 7.5 | 7.6 | 6.5 | 7.6 | 6.5 | 3.3 | 7.6 | 26.0 | 39.8 | 33.2 | 31.0 | 26.7 | 21.3 | 14.9 | 13.8 | 13.2 | 39.8 | 2.1 |
| Avg | 17.5 | 19.7 | 10.8 | 10.8 | 9.5 | 12.4 | 13.9 | 17.6 | 16.5 | 13.9 | 12.0 | 9.8 | 8.8 | 13.5 | 16.8 | 16.2 | 14.3 | 14.9 | 15.2 | 19.5 | 20.3 | 19.4 | 20.3 | 22.7 | 15.3 | -- | -- |
| Max | 169.0 | 318.0 | 128.0 | 99.4 | 76.7 | 79.7 | 86.3 | 53.8 | 57.2 | 54.0 | 33.2 | 28.9 | 34.6 | 52.3 | 115.0 | 115.0 | 77.7 | 76.5 | 58.7 | 182.0 | 182.0 | 240.0 | 294.0 | 358.0 | -- | 358.0 | -- |
| Min | -3.1 | -4.2 | -4.2 | -4.2 | -2.1 | 0.0 | 2.2 | 0.0 | -2.1 | 1.0 | -1.1 | -3.1 | -3.1 | -3.1 | 1.1 | 0.0 | 1.1 | -1.1 | -1.1 | 0.0 | -1.1 | -1.1 | 0.0 | -1.0 | -- | -- | -4.2 |

-- Indicates Invalid Data

## SAROAD for Resolution, West_Plant

## "Component, Channel: Table126, conc_PM10_µg/m$^3$ STP"

## Month: Dec 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 12.7 | 11.7 | 8.5 | 5.3 | 4.3 | 5.3 | 7.4 | 5.3 | 3.2 | 5.4 | 4.3 | 5.4 | 6.5 | -1.1 | 3.3 | 14.1 | 13.0 | 12.9 | 23.6 | 10.7 | 5.3 | 31.8 | 4.3 | 2.1 | 8.6 | 31.8 | -1.1 |
| 2 | 1.1 | 2.1 | 3.2 | 3.2 | 1.1 | 4.2 | 6.3 | 6.3 | -- | 6.4 | 16.2 | 4.3 | 5.4 | 8.7 | 9.8 | 7.6 | 7.6 | 10.8 | 23.7 | 11.8 | 10.7 | 7.5 | 16.0 | 0.0 | 7.6 | 23.7 | 0.0 |
| 3 | 1.1 | 3.2 | 3.2 | 0.0 | -2.1 | 2.1 | 6.4 | 5.3 | 5.4 | 9.7 | 7.6 | 6.6 | 5.5 | 4.4 | 5.5 | 7.7 | 6.6 | 9.8 | 13.1 | 9.8 | 8.7 | 8.7 | 6.5 | 2.2 | 5.7 | 13.1 | -2.1 |
| 4 | 2.2 | 3.3 | 2.2 | 1.1 | 1.1 | 3.2 | 2.1 | 6.4 | 8.6 | 6.5 | 28.0 | 5.4 | 5.4 | 16.1 | 9.6 | 7.4 | 6.4 | 10.6 | 12.7 | 16.9 | 12.7 | 16.9 | 16.8 | 10.5 | 8.8 | 28.0 | 1.1 |
| 5 | 11.6 | 8.4 | 7.4 | 10.5 | 11.5 | 10.5 | 9.4 | 15.7 | 6.3 | 4.2 | 6.3 | 11.6 | 10.5 | 8.4 | 9.5 | 13.7 | 15.8 | 14.7 | 16.7 | 17.7 | 17.6 | 10.3 | 8.2 | 10.3 | 11.1 | 17.7 | 4.2 |
| 6 | 14.4 | 12.3 | 10.3 | 11.3 | 8.2 | 7.2 | 7.2 | 6.2 | 7.2 | 10.4 | 6.2 | 6.3 | 8.4 | 8.4 | 5.3 | 7.4 | 10.5 | 7.3 | 8.3 | 10.3 | 10.3 | 10.3 | 9.3 | 9.3 | 8.8 | 14.4 | 5.3 |
| 7 | 8.2 | 8.2 | 7.2 | 4.1 | 3.1 | 3.1 | 3.1 | 5.1 | 6.2 | 9.4 | 9.4 | 8.4 | 6.3 | 4.3 | 4.2 | 5.3 | 6.3 | 8.4 | 15.7 | 13.6 | 13.6 | 9.5 | 7.4 | 7.3 | 7.4 | 15.7 | 3.1 |
| 8 | 6.3 | 8.4 | 7.3 | 1.0 | -2.1 | 3.1 | 5.2 | 4.2 | 2.1 | 7.3 | 12.6 | 12.6 | 14.7 | 14.7 | 11.6 | 11.6 | 20.0 | 18.9 | 22.0 | 15.7 | 10.5 | 23.0 | 23.9 | 19.8 | 11.4 | 23.9 | -2.1 |
| 9 | 19.7 | 13.4 | 19.5 | 24.7 | 18.5 | 14.3 | 24.5 | 20.4 | 15.3 | 12.4 | 13.5 | 12.5 | 8.4 | 4.2 | 4.2 | 7.3 | 5.2 | 2.1 | 3.1 | 2.1 | 0.0 | -1.0 | 1.0 | 1.0 | 10.3 | 24.7 | -1.0 |
| 10 | 7.2 | 7.2 | 2.1 | 5.2 | 5.2 | 4.1 | 4.1 | 8.3 | 9.4 | 18.8 | 4.2 | 4.2 | 5.3 | 7.4 | 5.3 | 4.2 | 3.2 | 3.2 | 6.4 | 7.4 | 6.4 | 6.4 | 9.5 | 7.4 | 6.3 | 18.8 | 2.1 |
| 11 | 4.2 | 3.2 | 3.2 | 4.2 | 5.3 | 5.3 | 5.3 | 6.4 | 5.3 | 7.4 | 11.7 | 13.9 | 12.9 | 11.9 | 11.9 | 7.6 | 5.4 | 6.5 | 6.5 | 7.5 | 10.7 | 10.7 | 7.5 | 9.7 | 7.7 | 13.9 | 3.2 |
| 12 | 9.6 | 10.7 | 12.8 | 10.7 | 13.9 | 12.8 | 12.8 | 11.8 | 10.7 | 12.8 | 12.9 | 11.9 | 8.7 | 7.6 | 7.6 | 6.5 | 8.6 | 7.5 | 7.5 | 10.6 | 27.6 | 35.0 | 32.7 | 25.3 | 13.7 | 35.0 | 6.5 |
| 13 | 24.2 | 19.9 | 19.9 | 18.8 | 16.7 | 18.8 | 17.7 | 15.6 | 19.9 | 12.6 | 18.0 | 19.1 | 8.5 | 9.6 | 18.2 | 15.0 | 12.8 | 12.7 | 18.0 | 1.1 | 2.1 | 16.8 | 12.5 | 10.4 | 14.9 | 24.2 | 1.1 |
| 14 | 10.4 | 9.4 | 9.4 | 11.5 | 11.4 | 9.4 | 4.2 | 3.1 | 7.4 | 5.3 | 18.0 | 8.5 | 5.3 | 0.0 | 2.2 | 4.3 | 1.1 | 0.0 | 3.2 | 4.2 | 3.2 | 3.2 | 1.1 | 2.1 | 5.7 | 18.0 | 0.0 |
| 15 | 5.3 | 5.3 | 3.2 | 2.1 | 16.8 | 1.1 | 1.0 | 3.1 | 5.2 | 4.3 | 1.1 | 2.1 | 2.2 | 0.0 | 3.3 | 5.4 | 6.5 | 9.6 | 9.6 | 6.4 | 5.4 | 7.5 | 4.3 | 5.4 | 4.8 | 16.8 | 0.0 |
| 16 | 6.4 | 3.2 | 24.5 | 0.0 | 2.1 | 2.1 | 7.4 | 12.7 | 7.5 | 7.5 | 20.6 | 5.4 | 6.6 | 8.8 | 16.5 | 3.3 | 2.2 | 3.3 | 9.7 | 8.7 | 2.2 | 2.2 | 2.2 | -1.1 | 6.8 | 24.5 | -1.1 |
| 17 | 1.1 | 3.2 | 4.3 | 2.2 | 1.1 | -1.1 | 1.1 | 3.2 | 2.2 | 1.1 | 5.5 | 5.5 | 4.4 | 7.7 | 8.8 | 5.5 | 2.2 | 4.4 | 3.3 | 0.0 | 1.1 | 4.4 | 4.4 | 1.1 | 3.2 | 8.8 | -1.1 |
| 18 | 4.4 | 5.5 | 2.2 | 1.1 | 0.0 | 1.1 | 2.2 | 6.5 | 4.3 | -1.1 | 2.2 | 7.7 | 6.6 | 5.5 | 16.6 | 6.7 | 5.5 | 3.3 | 6.6 | 6.6 | 3.3 | 4.4 | 4.3 | 2.2 | 4.5 | 16.6 | -1.1 |
| 19 | 3.3 | 4.3 | 6.5 | 9.7 | 8.6 | 9.7 | 9.7 | 9.7 | 8.6 | 6.5 | 7.6 | 5.5 | 7.7 | 19.8 | -- | 15.4 | 46.0 | 21.8 | 27.0 | 32.4 | 59.2 | 56.9 | 31.1 | 24.7 | 18.8 | 59.2 | 3.3 |
| 20 | 24.7 | 11.8 | 19.3 | 18.3 | 14.0 | 12.8 | 10.6 | 5.3 | 1.1 | 1.1 | 2.1 | 4.3 | 3.2 | 2.1 | -1.1 | -1.1 | 3.2 | 3.2 | 3.2 | 3.2 | 2.1 | 5.3 | 3.2 | 3.2 | 6.5 | 24.7 | -1.1 |
| 21 | 4.2 | 1.1 | 2.1 | 3.2 | 3.2 | 2.1 | 4.2 | 8.4 | 11.5 | 10.5 | 6.3 | 5.3 | 4.2 | 5.3 | 6.3 | 7.4 | 8.4 | 6.3 | 6.3 | 5.2 | 3.1 | 5.2 | 4.2 | 4.2 | 5.3 | 11.5 | 1.1 |
| 22 | 4.2 | 3.1 | 5.2 | 7.2 | 6.2 | 4.1 | 3.1 | 6.2 | 6.2 | 16.7 | 7.3 | 5.3 | 2.1 | 5.3 | 6.4 | 6.3 | 7.4 | 9.5 | 9.4 | 7.3 | 7.3 | 6.2 | 7.3 | 5.2 | 6.4 | 16.7 | 2.1 |
| 23 | 5.2 | 4.2 | 1.0 | 0.0 | 2.1 | 4.2 | 4.2 | 2.1 | -1.0 | 0.0 | 1.1 | 1.1 | 2.1 | 0.0 | -1.1 | 0.0 | 0.0 | 1.1 | 0.0 | 3.2 | 4.3 | 2.1 | 2.1 | 4.2 | 1.8 | 5.2 | -1.1 |
| 24 | 4.3 | 3.2 | 4.3 | 5.3 | 4.2 | 1.1 | 1.1 | 0.0 | 4.2 | 2.1 | -2.1 | 2.1 | 4.3 | 6.5 | 5.4 | 2.2 | 1.1 | 3.2 | 6.4 | 5.3 | 3.2 | 4.2 | 19.3 | 54.6 | 6.1 | 54.6 | -2.1 |
| 25 | 18.2 | 16.1 | 12.8 | 36.3 | 4.3 | 4.2 | 37.2 | 6.3 | 4.2 | 2.1 | 0.0 | -2.1 | 1.1 | 5.4 | 3.2 | 1.1 | 2.2 | 4.3 | 6.4 | 3.2 | 1.1 | 3.2 | 8.5 | 15.9 | 8.1 | 37.2 | -2.1 |
| 26 | 18.0 | 30.7 | 43.3 | 42.2 | 34.9 | 31.7 | 20.1 | 21.2 | 15.9 | 21.2 | 15.9 | 14.9 | 13.9 | 14.0 | 9.7 | 7.6 | 9.7 | 9.6 | 11.7 | 11.7 | 17.0 | 11.6 | 8.5 | 6.4 | 18.4 | 43.3 | 6.4 |
| 27 | 4.2 | 3.2 | 2.1 | 4.2 | 9.6 | 10.7 | 7.4 | 9.5 | 14.9 | 13.9 | -- | 10.7 | 9.7 | 11.9 | 9.7 | 7.6 | 4.3 | 3.2 | 5.4 | 7.5 | 7.5 | 9.6 | 9.5 | 7.4 | 8.0 | 14.9 | 2.1 |
| 28 | 6.3 | 5.3 | 4.2 | 5.3 | 9.5 | 11.6 | 12.7 | 13.7 | 9.5 | 8.5 | 8.6 | 6.4 | 7.6 | 8.7 | 6.5 | 8.7 | 7.6 | 9.7 | 22.5 | 18.2 | 10.6 | 11.7 | 10.6 | 7.4 | 9.6 | 22.5 | 4.2 |
| 29 | 7.5 | 8.5 | 6.4 | 6.4 | 6.3 | 5.3 | 8.5 | 11.6 | 7.4 | 6.4 | 6.4 | 4.3 | 6.5 | 7.6 | 6.5 | 3.3 | 1.1 | 2.2 | 4.3 | 5.3 | 6.4 | 5.3 | 1.1 | 1.1 | 5.6 | 11.6 | 1.1 |
| 30 | 2.1 | 1.1 | 1.1 | 2.1 | 4.2 | 6.3 | 7.3 | 28.1 | 34.4 | 7.4 | 7.4 | 5.3 | 4.3 | 5.4 | 8.6 | 9.7 | 9.6 | 12.8 | 19.0 | 10.5 | 11.6 | 10.5 | 5.3 | 4.2 | 9.1 | 34.4 | 1.1 |
| 31 | 3.2 | 2.1 | 4.2 | 4.2 | 4.2 | 3.2 | 5.3 | 8.5 | 11.6 | 10.7 | 10.7 | 10.7 | 9.7 | 8.7 | 8.7 | 6.5 | 7.6 | 8.6 | 7.5 | 6.4 | 6.4 | 6.4 | 5.3 | 5.3 | 6.9 | 11.6 | 2.1 |
| Avg | 8.2 | 7.5 | 8.5 | 8.4 | 7.3 | 6.9 | 8.3 | 8.9 | 8.5 | 8.0 | 9.0 | 7.3 | 6.7 | 7.3 | 7.4 | 6.9 | 8.0 | 7.8 | 10.9 | 9.1 | 9.4 | 11.1 | 9.3 | 8.7 | 8.3 | -- | -- |
| Max | 24.7 | 30.7 | 43.3 | 42.2 | 34.9 | 31.7 | 37.2 | 28.1 | 34.4 | 21.2 | 28.0 | 19.1 | 14.7 | 19.8 | 18.2 | 15.4 | 46.0 | 21.8 | 27.0 | 32.4 | 59.2 | 56.9 | 32.7 | 54.6 | -- | 59.2 | -- |
| Min | 1.1 | 1.1 | 1.0 | 0.0 | -2.1 | -1.1 | 1.0 | 0.0 | -1.0 | -1.1 | -2.1 | -2.1 | 1.1 | -1.1 | -1.1 | -1.1 | 0.0 | 0.0 | 0.0 | 0.0 | 0.0 | -1.0 | 1.0 | -1.1 | -- | -- | -2.1 |

-- Indicates Invalid Data

## SAROAD for Resolution, West_Plant

## "Component, Channel: Table126, conc_PM25_µg/m$^3$ Actual"

## Month: Oct 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 2.0 | 2.0 | 0.0 | 1.0 | 3.0 | 2.0 | 0.0 | 3.0 | 3.0 | 1.0 | 0.0 | 0.0 | 1.0 | 1.0 | 3.0 | 2.0 | 1.0 | 2.0 | 2.0 | 3.0 | 3.0 | 1.0 | 2.0 | 1.0 | 1.6 | 3.0 | 0.0 |
| 2 | -1.0 | -1.0 | -1.0 | 1.0 | 3.0 | 0.0 | 2.0 | 4.0 | 2.0 | 0.0 | 0.0 | 2.0 | -1.0 | -3.0 | -1.0 | 0.0 | -3.0 | -3.0 | 0.0 | 3.0 | 3.0 | 0.0 | 1.0 | 2.0 | 0.4 | 4.0 | -3.0 |
| 3 | 1.0 | 2.0 | 1.0 | -2.0 | 0.0 | 3.0 | 4.0 | 2.0 | -1.0 | -2.0 | -3.0 | -3.0 | -1.0 | 0.0 | -3.0 | -1.0 | -1.0 | -2.0 | -1.0 | -2.0 | 0.0 | 1.0 | 0.0 | 3.0 | -0.2 | 4.0 | -3.0 |
| 4 | 4.0 | 2.0 | 2.0 | 2.0 | 0.0 | 2.0 | 3.0 | 5.0 | 4.0 | -2.0 | -1.0 | 0.0 | 2.0 | 4.0 | 3.0 | 4.0 | 3.0 | 2.0 | 4.0 | 6.0 | 4.0 | 4.0 | 4.0 | 5.0 | 2.8 | 6.0 | -2.0 |
| 5 | 4.0 | 3.0 | 3.0 | 1.0 | 2.0 | 3.0 | 3.0 | 1.0 | 1.0 | 3.0 | 3.0 | 3.0 | 2.0 | -4.0 | -2.0 | 1.0 | -2.0 | -4.0 | -1.0 | 1.0 | 0.0 | 1.0 | 0.0 | 0.0 | 0.9 | 4.0 | -4.0 |
| 6 | 0.0 | 1.0 | 0.0 | 1.0 | 1.0 | 2.0 | 3.0 | 2.0 | 3.0 | 0.0 | -1.0 | 1.0 | 2.0 | 2.0 | 0.0 | 0.0 | -1.0 | -1.0 | 1.0 | -1.0 | 0.0 | 0.0 | 0.0 | 1.0 | 0.7 | 3.0 | -1.0 |
| 7 | 2.0 | 3.0 | 2.0 | 2.0 | 2.0 | 2.0 | -1.0 | 1.0 | 1.0 | -1.0 | 1.0 | -1.0 | -2.0 | -2.0 | -2.0 | 0.0 | 1.0 | 3.0 | 2.0 | 1.0 | 2.0 | 2.0 | 2.0 | 1.0 | 0.9 | 3.0 | -2.0 |
| 8 | -1.0 | 2.0 | 3.0 | 2.0 | -1.0 | -2.0 | 2.0 | 5.0 | 2.0 | -- | 0.0 | -3.0 | -6.0 | -3.0 | -1.0 | 2.0 | 6.0 | 6.0 | 6.0 | 4.0 | 3.0 | 3.0 | 4.0 | 2.0 | 1.5 | 6.0 | -6.0 |
| 9 | 3.0 | 6.0 | 3.0 | -1.0 | 0.0 | 1.0 | 3.0 | 4.0 | 1.0 | 0.0 | 2.0 | 2.0 | 2.0 | 5.0 | 8.0 | 9.0 | 29.0 | 26.0 | 15.0 | 11.0 | 8.0 | 9.0 | 7.0 | 6.0 | 6.6 | 29.0 | -1.0 |
| 10 | 9.0 | 6.0 | 5.0 | 6.0 | 11.0 | 11.0 | 6.0 | 8.0 | 10.0 | 9.0 | 6.0 | 5.0 | 3.0 | 2.0 | 3.0 | 2.0 | -1.0 | 1.0 | 5.0 | 4.0 | 3.0 | 3.0 | 5.0 | 5.0 | 5.3 | 11.0 | -1.0 |
| 11 | 3.0 | 4.0 | 4.0 | 4.0 | 3.0 | 4.0 | 5.0 | 4.0 | -- | 1.0 | 0.0 | 1.0 | 2.0 | 2.0 | -- | 0.0 | 3.0 | 4.0 | 4.0 | 4.0 | 3.0 | 1.0 | 2.0 | 5.0 | 2.9 | 5.0 | 0.0 |
| 12 | 6.0 | 6.0 | 6.0 | 3.0 | 2.0 | 3.0 | 1.0 | 1.0 | -1.0 | -1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 0.0 | 0.0 | 1.0 | 1.0 | 3.0 | 3.0 | 1.0 | 2.0 | 4.0 | 6.0 | 2.1 | 6.0 | -1.0 |
| 13 | 5.0 | 3.0 | 2.0 | 2.0 | 4.0 | 2.0 | 1.0 | 5.0 | 1.0 | -1.0 | 2.0 | -- | 3.0 | 2.0 | -1.0 | 1.0 | 2.0 | 2.0 | 2.0 | 4.0 | 2.0 | 0.0 | 2.0 | 3.0 | 2.1 | 5.0 | -1.0 |
| 14 | 1.0 | 2.0 | 6.0 | 4.0 | 1.0 | 2.0 | 5.0 | 4.0 | 3.0 | 2.0 | 0.0 | 1.0 | 3.0 | 2.0 | 1.0 | 3.0 | 3.0 | 2.0 | 1.0 | 4.0 | 7.0 | 7.0 | 6.0 | 5.0 | 3.1 | 7.0 | 0.0 |
| 15 | 4.0 | 4.0 | 4.0 | 3.0 | 2.0 | 3.0 | 4.0 | 5.0 | 5.0 | 5.0 | 7.0 | 6.0 | 3.0 | 3.0 | 4.0 | 3.0 | 3.0 | 4.0 | 4.0 | 6.0 | 6.0 | 7.0 | 7.0 | 5.0 | 4.5 | 7.0 | 2.0 |
| 16 | 4.0 | 3.0 | 3.0 | 2.0 | 2.0 | 3.0 | 4.0 | 6.0 | 3.0 | 2.0 | 1.0 | 0.0 | 1.0 | 2.0 | 1.0 | 0.0 | 2.0 | 2.0 | 4.0 | 4.0 | 2.0 | 4.0 | 6.0 | 7.0 | 2.8 | 7.0 | 0.0 |
| 17 | 5.0 | 3.0 | 6.0 | 5.0 | 1.0 | 3.0 | 5.0 | 1.0 | -1.0 | -1.0 | 0.0 | 2.0 | 4.0 | 4.0 | 6.0 | 4.0 | 3.0 | 7.0 | 4.0 | 2.0 | 3.0 | 2.0 | 3.0 | 6.0 | 3.2 | 7.0 | -1.0 |
| 18 | 6.0 | 4.0 | 4.0 | 4.0 | 4.0 | 6.0 | 6.0 | -- | 3.0 | 1.0 | -1.0 | -1.0 | 0.0 | 3.0 | 3.0 | 2.0 | 3.0 | 4.0 | 5.0 | 5.0 | 4.0 | 5.0 | 3.0 | 0.0 | 3.2 | 6.0 | -1.0 |
| 19 | 0.0 | 1.0 | 1.0 | -1.0 | 0.0 | 2.0 | 2.0 | 1.0 | -1.0 | 1.0 | 4.0 | 3.0 | 2.0 | 0.0 | 1.0 | 2.0 | 4.0 | 4.0 | 4.0 | 7.0 | 5.0 | 4.0 | 4.0 | 4.0 | 2.3 | 7.0 | -1.0 |
| 20 | 6.0 | 7.0 | 4.0 | 2.0 | 3.0 | 3.0 | 3.0 | 3.0 | 1.0 | 1.0 | 2.0 | 4.0 | 6.0 | 5.0 | 3.0 | 3.0 | 2.0 | 0.0 | 0.0 | 5.0 | 6.0 | 3.0 | 2.0 | 1.0 | 3.1 | 7.0 | 0.0 |
| 21 | 1.0 | 2.0 | 5.0 | 2.0 | 1.0 | 3.0 | 6.0 | 5.0 | 3.0 | 1.0 | 2.0 | 2.0 | 1.0 | 3.0 | 2.0 | 2.0 | 2.0 | 2.0 | 3.0 | 3.0 | 5.0 | 6.0 | 6.0 | 6.0 | 3.1 | 6.0 | 1.0 |
| 22 | 5.0 | 3.0 | 1.0 | 2.0 | 1.0 | 1.0 | -1.0 | 2.0 | 4.0 | 1.0 | 3.0 | 4.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | 0.0 | 2.0 | 1.0 | 2.0 | 4.0 | 2.0 | 1.0 | 1.9 | 5.0 | -1.0 |
| 23 | 1.0 | 1.0 | 1.0 | 2.0 | 3.0 | 3.0 | 5.0 | 6.0 | 5.0 | 4.0 | 4.0 | 3.0 | 1.0 | 4.0 | 3.0 | 2.0 | 1.0 | -1.0 | 1.0 | 0.0 | 1.0 | 4.0 | 5.0 | 4.0 | 2.6 | 6.0 | -1.0 |
| 24 | 1.0 | 1.0 | 4.0 | 3.0 | 2.0 | 3.0 | 4.0 | 4.0 | 4.0 | 3.0 | 1.0 | 0.0 | -1.0 | -2.0 | -1.0 | 2.0 | 4.0 | 5.0 | 6.0 | 5.0 | 5.0 | 5.0 | 4.0 | 5.0 | 2.8 | 6.0 | -2.0 |
| 25 | 6.0 | 3.0 | 4.0 | 6.0 | 5.0 | 1.0 | 2.0 | 5.0 | 5.0 | -- | 5.0 | 0.0 | 0.0 | 2.0 | 1.0 | 0.0 | -1.0 | -1.0 | 1.0 | 1.0 | 1.0 | 3.0 | 5.0 | 5.0 | 2.6 | 6.0 | -1.0 |
| 26 | 3.0 | 3.0 | 3.0 | 3.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | 1.0 | -2.0 | -2.0 | -1.0 | -1.0 | -1.0 | -3.0 | -2.0 | 1.0 | 4.0 | 5.0 | 4.0 | 2.0 | 0.0 | -3.0 | 0.9 | 5.0 | -3.0 |
| 27 | -3.0 | 1.0 | 1.0 | 0.0 | 0.0 | 0.0 | 1.0 | 2.0 | 5.0 | 3.0 | -1.0 | -2.0 | -2.0 | -1.0 | -1.0 | -2.0 | -1.0 | 1.0 | 1.0 | 1.0 | 2.0 | 3.0 | 2.0 | 3.0 | 0.5 | 5.0 | -3.0 |
| 28 | 2.0 | 0.0 | 1.0 | 1.0 | 2.0 | 3.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | 0.0 | -1.0 | 0.0 | 1.0 | 2.0 | 1.0 | 3.0 | 5.0 | 6.0 | -- | -- | -- | -- | 1.7 | 6.0 | -1.0 |
| 29 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 4.0 | -2.0 | -2.0 | -4.0 | -4.0 | 2.0 | 3.0 | 6.0 | 7.0 | 2.0 | 3.0 | 2.0 | 1.0 | 1.0 | -- | 7.0 | -4.0 |
| 30 | 1.0 | 3.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | 2.0 | 2.0 | 5.0 | 3.0 | 0.0 | 3.0 | -- | 2.0 | -1.0 | 1.0 | 3.0 | 4.0 | 3.0 | 2.0 | 4.0 | 4.0 | 1.0 | 2.2 | 5.0 | -1.0 |
| 31 | 1.0 | 2.0 | 3.0 | 2.0 | 2.0 | 3.0 | 1.0 | 1.0 | 4.0 | 2.0 | 0.0 | 1.0 | -1.0 | -2.0 | -1.0 | 0.0 | 0.0 | -1.0 | 3.0 | 5.0 | 4.0 | 5.0 | 5.0 | 3.0 | 1.8 | 5.0 | -2.0 |
| Avg | 2.7 | 2.7 | 2.8 | 2.1 | 2.1 | 2.5 | 2.8 | 3.3 | 2.6 | 1.4 | 1.4 | 0.9 | 0.8 | 0.9 | 1.0 | 1.4 | 2.2 | 2.5 | 3.3 | 3.4 | 3.1 | 3.2 | 3.3 | 3.1 | 2.3 | -- | -- |
| Max | 9.0 | 7.0 | 6.0 | 6.0 | 11.0 | 11.0 | 6.0 | 8.0 | 10.0 | 9.0 | 7.0 | 6.0 | 6.0 | 5.0 | 8.0 | 9.0 | 29.0 | 26.0 | 15.0 | 11.0 | 8.0 | 9.0 | 7.0 | 7.0 | -- | 29.0 | -- |
| Min | -3.0 | -1.0 | -1.0 | -2.0 | -1.0 | -2.0 | -1.0 | 1.0 | -1.0 | -2.0 | -3.0 | -3.0 | -6.0 | -4.0 | -4.0 | -3.0 | -3.0 | -4.0 | -1.0 | -2.0 | 0.0 | 0.0 | 0.0 | -3.0 | -- | -- | -6.0 |

-- Indicates Invalid Data

## SAROAD for Resolution, West_Plant

## "Component, Channel: Table126, conc_PM25_µg/m$^3$ Actual"

## Month: Nov 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 3.0 | 4.0 | 2.0 | 3.0 | 5.0 | 2.0 | 2.0 | 4.0 | 4.0 | 4.0 | 3.0 | 2.0 | 0.0 | -2.0 | -1.0 | 1.0 | 2.0 | 3.0 | 3.0 | 3.0 | 2.0 | 0.0 | 1.0 | 2.0 | 2.2 | 5.0 | -2.0 |
| 2 | 1.0 | -1.0 | 0.0 | 4.0 | 4.0 | 3.0 | 3.0 | 2.0 | 1.0 | -1.0 | 0.0 | -1.0 | 0.0 | 1.0 | -3.0 | -2.0 | 1.0 | 1.0 | 4.0 | 4.0 | 3.0 | 1.0 | 4.0 | 4.0 | 1.4 | 4.0 | -3.0 |
| 3 | 2.0 | 3.0 | 3.0 | 1.0 | 1.0 | 0.0 | 1.0 | 3.0 | 2.0 | -1.0 | -3.0 | -4.0 | -3.0 | -2.0 | -3.0 | -1.0 | -3.0 | -1.0 | 1.0 | -1.0 | 0.0 | 0.0 | 1.0 | -2.0 | -0.3 | 3.0 | -4.0 |
| 4 | -4.0 | -2.0 | 1.0 | 0.0 | -1.0 | 1.0 | -1.0 | 1.0 | 2.0 | 0.0 | -1.0 | -2.0 | -3.0 | -3.0 | -1.0 | -1.0 | -1.0 | 0.0 | -1.0 | 0.0 | 0.0 | 2.0 | 8.0 | 6.0 | 0.0 | 8.0 | -4.0 |
| 5 | 3.0 | 4.0 | 2.0 | 1.0 | 2.0 | 1.0 | 3.0 | 5.0 | 6.0 | 4.0 | 3.0 | 1.0 | 2.0 | 4.0 | 3.0 | 3.0 | 4.0 | 5.0 | 3.0 | 0.0 | 3.0 | 3.0 | 0.0 | 2.0 | 2.8 | 6.0 | 0.0 |
| 6 | 2.0 | 1.0 | 0.0 | -2.0 | -3.0 | 0.0 | 3.0 | 4.0 | 5.0 | 3.0 | 1.0 | 0.0 | 0.0 | 0.0 | 0.0 | -1.0 | -1.0 | 1.0 | 2.0 | 1.0 | 0.0 | 1.0 | 1.0 | 0.0 | 0.8 | 5.0 | -3.0 |
| 7 | 0.0 | 2.0 | 3.0 | 3.0 | 1.0 | 0.0 | 0.0 | 3.0 | 5.0 | 0.0 | -1.0 | 0.0 | -1.0 | -1.0 | -1.0 | 0.0 | 2.0 | 1.0 | -1.0 | -1.0 | -2.0 | -1.0 | 0.0 | -2.0 | 0.4 | 5.0 | -2.0 |
| 8 | -2.0 | -1.0 | 0.0 | -2.0 | -4.0 | 0.0 | 3.0 | 2.0 | -1.0 | 0.0 | 3.0 | 1.0 | -2.0 | -1.0 | 1.0 | 1.0 | 1.0 | 3.0 | 5.0 | 6.0 | 6.0 | 7.0 | 9.0 | 13.0 | 2.0 | 13.0 | -4.0 |
| 9 | 9.0 | 4.0 | 2.0 | 2.0 | 2.0 | 1.0 | 2.0 | -- | -- | -- | -- | -- | -6.0 | -4.0 | -4.0 | -6.0 | -4.0 | 0.0 | -1.0 | 0.0 | 3.0 | 2.0 | 2.0 | 3.0 | 0.4 | 9.0 | -6.0 |
| 10 | 2.0 | 3.0 | 2.0 | 2.0 | 6.0 | 5.0 | 1.0 | 1.0 | 2.0 | 3.0 | 1.0 | -1.0 | -1.0 | -1.0 | -1.0 | -2.0 | -1.0 | 1.0 | 1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 0.0 | 1.1 | 6.0 | -2.0 |
| 11 | -2.0 | -2.0 | 1.0 | 1.0 | -1.0 | 2.0 | 0.0 | -1.0 | 4.0 | 3.0 | -1.0 | -1.0 | 0.0 | 0.0 | -3.0 | -3.0 | -1.0 | 1.0 | 4.0 | 5.0 | 3.0 | 3.0 | 1.0 | 1.0 | 0.6 | 5.0 | -3.0 |
| 12 | 2.0 | 0.0 | -1.0 | 0.0 | 1.0 | 1.0 | 1.0 | 1.0 | -1.0 | -3.0 | -2.0 | 1.0 | -1.0 | -4.0 | 0.0 | 5.0 | 5.0 | 6.0 | 2.0 | -1.0 | 1.0 | 1.0 | 2.0 | 4.0 | 0.8 | 6.0 | -4.0 |
| 13 | 4.0 | 6.0 | 6.0 | 4.0 | 0.0 | 1.0 | 4.0 | 5.0 | 6.0 | 3.0 | 0.0 | -3.0 | -3.0 | -1.0 | 1.0 | 0.0 | -2.0 | 0.0 | 2.0 | 2.0 | 1.0 | 1.0 | 1.0 | 2.0 | 1.7 | 6.0 | -3.0 |
| 14 | 1.0 | 0.0 | 2.0 | 4.0 | 3.0 | 3.0 | 3.0 | 2.0 | 3.0 | 2.0 | 1.0 | 1.0 | 2.0 | 1.0 | 3.0 | 2.0 | 4.0 | 5.0 | 1.0 | -1.0 | 1.0 | 1.0 | 0.0 | 1.0 | 1.9 | 5.0 | -1.0 |
| 15 | 1.0 | 1.0 | 0.0 | -1.0 | 0.0 | -1.0 | -1.0 | 3.0 | 2.0 | 1.0 | 3.0 | 1.0 | 1.0 | 1.0 | 6.0 | 8.0 | 6.0 | 6.0 | 5.0 | 6.0 | 16.0 | 6.0 | 5.0 | 4.0 | 3.3 | 16.0 | -1.0 |
| 16 | 3.0 | 2.0 | 5.0 | 5.0 | 5.0 | 4.0 | 6.0 | 8.0 | 3.0 | 1.0 | 3.0 | 3.0 | 4.0 | 4.0 | 3.0 | 2.0 | 2.0 | 4.0 | 6.0 | 4.0 | 4.0 | 4.0 | 4.0 | 4.0 | 3.9 | 8.0 | 1.0 |
| 17 | -15.0 | 4.0 | 0.0 | 1.0 | 4.0 | 5.0 | 5.0 | 5.0 | 5.0 | 1.0 | 1.0 | 3.0 | 2.0 | 2.0 | 2.0 | 2.0 | 2.0 | 1.0 | 3.0 | 3.0 | 2.0 | 0.0 | 0.0 | 3.0 | 1.7 | 5.0 | -15.0 |
| 18 | 2.0 | 1.0 | 2.0 | 3.0 | 4.0 | 7.0 | 7.0 | 5.0 | 3.0 | 2.0 | 1.0 | 2.0 | 1.0 | -2.0 | -1.0 | -2.0 | -3.0 | 0.0 | 2.0 | 2.0 | 1.0 | 1.0 | 3.0 | 4.0 | 1.9 | 7.0 | -3.0 |
| 19 | 3.0 | 3.0 | 4.0 | 4.0 | 3.0 | 1.0 | 0.0 | 2.0 | 3.0 | 1.0 | 3.0 | 1.0 | 0.0 | 6.0 | 6.0 | -- | 5.0 | 2.0 | 3.0 | 3.0 | 4.0 | 4.0 | 4.0 | 2.0 | 2.9 | 6.0 | 0.0 |
| 20 | 0.0 | 3.0 | 4.0 | 4.0 | 4.0 | 4.0 | 6.0 | 5.0 | 4.0 | 5.0 | 3.0 | 4.0 | 5.0 | 3.0 | 4.0 | 5.0 | 7.0 | 8.0 | 5.0 | 4.0 | 2.0 | 2.0 | 4.0 | 6.0 | 4.2 | 8.0 | 0.0 |
| 21 | 5.0 | 4.0 | 2.0 | 2.0 | 4.0 | 5.0 | 3.0 | 3.0 | 3.0 | 1.0 | 0.0 | -- | 1.0 | 3.0 | 2.0 | -1.0 | -2.0 | 1.0 | 3.0 | 5.0 | 7.0 | 6.0 | 5.0 | 4.0 | 2.9 | 7.0 | -2.0 |
| 22 | 3.0 | 2.0 | 0.0 | 0.0 | 2.0 | 3.0 | 4.0 | 3.0 | 2.0 | 2.0 | 1.0 | -1.0 | -1.0 | 1.0 | -1.0 | -2.0 | 1.0 | -1.0 | -1.0 | 2.0 | 3.0 | 2.0 | 0.0 | -1.0 | 1.0 | 4.0 | -2.0 |
| 23 | 1.0 | 2.0 | 1.0 | 4.0 | 5.0 | 3.0 | 0.0 | 1.0 | 3.0 | 3.0 | 1.0 | 0.0 | 3.0 | 4.0 | 2.0 | -2.0 | -4.0 | 0.0 | 2.0 | -1.0 | 2.0 | 1.0 | 0.0 | 1.0 | 1.3 | 5.0 | -4.0 |
| 24 | 2.0 | 2.0 | 2.0 | 2.0 | 0.0 | 0.0 | 1.0 | 3.0 | 3.0 | -1.0 | -2.0 | 0.0 | 2.0 | 0.0 | -2.0 | 0.0 | -1.0 | -2.0 | 0.0 | 4.0 | 3.0 | 1.0 | 2.0 | 0.0 | 0.8 | 4.0 | -2.0 |
| 25 | 1.0 | 1.0 | 1.0 | 2.0 | 2.0 | 4.0 | 5.0 | 4.0 | 3.0 | 1.0 | 2.0 | 2.0 | 2.0 | 1.0 | -1.0 | 0.0 | 0.0 | 0.0 | 4.0 | 5.0 | 3.0 | 2.0 | 4.0 | 4.0 | 2.2 | 5.0 | -1.0 |
| 26 | 4.0 | 3.0 | 3.0 | 4.0 | 3.0 | 2.0 | 6.0 | 3.0 | 2.0 | -- | -- | 3.0 | 0.0 | -1.0 | 0.0 | -2.0 | 0.0 | 2.0 | 2.0 | 3.0 | 2.0 | 2.0 | 1.0 | -2.0 | 1.8 | 6.0 | -2.0 |
| 27 | -3.0 | -2.0 | 2.0 | 3.0 | 1.0 | 1.0 | 0.0 | -2.0 | -1.0 | 0.0 | 0.0 | 1.0 | 0.0 | -2.0 | -2.0 | 0.0 | -1.0 | 3.0 | 4.0 | 0.0 | -1.0 | 1.0 | 4.0 | 2.0 | 0.3 | 4.0 | -3.0 |
| 28 | -2.0 | -1.0 | 0.0 | 1.0 | 3.0 | 0.0 | 0.0 | -1.0 | -2.0 | 0.0 | 3.0 | 1.0 | 1.0 | 2.0 | -1.0 | 0.0 | 0.0 | -1.0 | 0.0 | 1.0 | -1.0 | 0.0 | -1.0 | -3.0 | 0.0 | 3.0 | -3.0 |
| 29 | -2.0 | -1.0 | -2.0 | 0.0 | 1.0 | 2.0 | 1.0 | 2.0 | 0.0 | -1.0 | 1.0 | 0.0 | 1.0 | -1.0 | 0.0 | 2.0 | -1.0 | 1.0 | 5.0 | 5.0 | 3.0 | 3.0 | 3.0 | 4.0 | 1.1 | 5.0 | -2.0 |
| 30 | 6.0 | 4.0 | 2.0 | 3.0 | 3.0 | 2.0 | 3.0 | 1.0 | 1.0 | 3.0 | 1.0 | -1.0 | 1.0 | 4.0 | 4.0 | 2.0 | 1.0 | 3.0 | 6.0 | 6.0 | 6.0 | 6.0 | 5.0 | 5.0 | 3.2 | 6.0 | -1.0 |
| Avg | 1.0 | 1.6 | 1.6 | 1.9 | 2.0 | 2.1 | 2.4 | 2.7 | 2.5 | 1.3 | 0.9 | 0.5 | 0.2 | 0.4 | 0.4 | 0.3 | 0.6 | 1.8 | 2.5 | 2.3 | 2.6 | 2.1 | 2.5 | 2.4 | 1.6 | -- | -- |
| Max | 9.0 | 6.0 | 6.0 | 5.0 | 6.0 | 7.0 | 7.0 | 8.0 | 6.0 | 5.0 | 3.0 | 4.0 | 5.0 | 6.0 | 6.0 | 8.0 | 7.0 | 8.0 | 6.0 | 6.0 | 16.0 | 7.0 | 9.0 | 13.0 | -- | 16.0 | -- |
| Min | -15.0 | -2.0 | -2.0 | -2.0 | -4.0 | -1.0 | -1.0 | -2.0 | -2.0 | -3.0 | -3.0 | -4.0 | -6.0 | -4.0 | -4.0 | -6.0 | -4.0 | -2.0 | -1.0 | -1.0 | -2.0 | -1.0 | -1.0 | -3.0 | -- | -- | -15.0 |

-- Indicates Invalid Data

## SAROAD for Resolution, West_Plant

## "Component, Channel: Table126, conc_PM25_µg/m$^3$ Actual"

## Month: Dec 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 3.0 | 3.0 | 3.0 | 5.0 | 3.0 | 2.0 | 4.0 | 3.0 | -- | -- | 0.0 | -4.0 | -5.0 | -1.0 | 2.0 | 5.0 | 5.0 | 3.0 | 4.0 | 3.0 | 3.0 | 3.0 | 3.0 | 2.0 | 2.2 | 5.0 | -5.0 |
| 2 | -1.0 | 0.0 | 0.0 | -1.0 | 2.0 | 1.0 | 0.0 | 1.0 | -- | -- | -3.0 | -1.0 | -1.0 | -1.0 | 2.0 | 2.0 | 0.0 | -- | 2.0 | 6.0 | 7.0 | 5.0 | 5.0 | 3.0 | 1.3 | 7.0 | -3.0 |
| 3 | 1.0 | 3.0 | 1.0 | -1.0 | 3.0 | 2.0 | 1.0 | 1.0 | 4.0 | 4.0 | 1.0 | 0.0 | 1.0 | 1.0 | 0.0 | 0.0 | 1.0 | -- | -- | 0.0 | -- | 2.0 | 3.0 | 0.0 | 1.3 | 4.0 | -1.0 |
| 4 | -1.0 | 0.0 | 0.0 | 0.0 | -1.0 | -1.0 | 2.0 | 3.0 | 3.0 | -- | 3.0 | 4.0 | 3.0 | 1.0 | 2.0 | -1.0 | -2.0 | 0.0 | 0.0 | 1.0 | 2.0 | 4.0 | 5.0 | 4.0 | 1.4 | 5.0 | -2.0 |
| 5 | 4.0 | 3.0 | 2.0 | 0.0 | 0.0 | 3.0 | 5.0 | 4.0 | 2.0 | 3.0 | 2.0 | 3.0 | 2.0 | 0.0 | 2.0 | 2.0 | 4.0 | 7.0 | 6.0 | 6.0 | 5.0 | 4.0 | 4.0 | 6.0 | 3.3 | 7.0 | 0.0 |
| 6 | 5.0 | 4.0 | 7.0 | 6.0 | 5.0 | 5.0 | 6.0 | 4.0 | 2.0 | 4.0 | 4.0 | 4.0 | 2.0 | 1.0 | -- | -- | 1.0 | 3.0 | 5.0 | 5.0 | 5.0 | 6.0 | 4.0 | 4.0 | 4.2 | 7.0 | 1.0 |
| 7 | 5.0 | 3.0 | 4.0 | 5.0 | 4.0 | 2.0 | 3.0 | 5.0 | 6.0 | 3.0 | 1.0 | 1.0 | 4.0 | 3.0 | 2.0 | 0.0 | -2.0 | 2.0 | 6.0 | 5.0 | 5.0 | 4.0 | 2.0 | 2.0 | 3.1 | 6.0 | -2.0 |
| 8 | 3.0 | 4.0 | 3.0 | 1.0 | 0.0 | 2.0 | 1.0 | 1.0 | 2.0 | 2.0 | 1.0 | 1.0 | 1.0 | 0.0 | 1.0 | 2.0 | 2.0 | 3.0 | 4.0 | 4.0 | 2.0 | 4.0 | 6.0 | 4.0 | 2.3 | 6.0 | 0.0 |
| 9 | 3.0 | 4.0 | 5.0 | 10.0 | 11.0 | 9.0 | 8.0 | 8.0 | 6.0 | 4.0 | 4.0 | 6.0 | 3.0 | -3.0 | -2.0 | -1.0 | 0.0 | 2.0 | 2.0 | 2.0 | 3.0 | 5.0 | 3.0 | 1.0 | 3.9 | 11.0 | -3.0 |
| 10 | 0.0 | 2.0 | 3.0 | 2.0 | 2.0 | 2.0 | 1.0 | 1.0 | -2.0 | -2.0 | -2.0 | -2.0 | 0.0 | 1.0 | 1.0 | 2.0 | 1.0 | 2.0 | 2.0 | 2.0 | 2.0 | 2.0 | 4.0 | 6.0 | 1.3 | 6.0 | -2.0 |
| 11 | 6.0 | 1.0 | -2.0 | 0.0 | 2.0 | 3.0 | 4.0 | 3.0 | 3.0 | 3.0 | 3.0 | 1.0 | 0.0 | 1.0 | -1.0 | 0.0 | 1.0 | 1.0 | 2.0 | 3.0 | 3.0 | 2.0 | 3.0 | 4.0 | 1.9 | 6.0 | -2.0 |
| 12 | 5.0 | 4.0 | 4.0 | 3.0 | 3.0 | 2.0 | 0.0 | -1.0 | 0.0 | 1.0 | 0.0 | 0.0 | -1.0 | 1.0 | 3.0 | 2.0 | 2.0 | 2.0 | 2.0 | 4.0 | 6.0 | 5.0 | 4.0 | 5.0 | 2.3 | 6.0 | -1.0 |
| 13 | 6.0 | -- | -- | -- | -- | -- | -- | -- | -- | -- | 4.0 | 5.0 | 4.0 | 2.0 | 5.0 | 5.0 | 3.0 | 3.0 | 5.0 | 2.0 | 2.0 | 3.0 | 4.0 | 4.0 | -- | 6.0 | 2.0 |
| 14 | 3.0 | 4.0 | 3.0 | 3.0 | 5.0 | 5.0 | 6.0 | 5.0 | 3.0 | 1.0 | 0.0 | 1.0 | 1.0 | -1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 1.0 | 1.0 | 1.0 | 2.0 | 1.0 | 1.0 | 2.0 | 6.0 | -1.0 |
| 15 | 3.0 | 3.0 | 1.0 | 0.0 | -1.0 | -1.0 | 1.0 | 0.0 | 1.0 | 0.0 | -2.0 | 1.0 | 3.0 | -2.0 | -3.0 | -2.0 | -3.0 | 2.0 | 3.0 | 0.0 | 1.0 | 0.0 | -3.0 | -2.0 | 0.0 | 3.0 | -3.0 |
| 16 | 0.0 | 0.0 | 0.0 | 0.0 | 1.0 | 2.0 | 1.0 | 3.0 | 5.0 | 0.0 | -2.0 | -2.0 | -3.0 | 0.0 | 1.0 | -2.0 | -2.0 | 0.0 | 2.0 | 2.0 | -1.0 | -3.0 | -1.0 | 1.0 | 0.1 | 5.0 | -3.0 |
| 17 | 0.0 | 0.0 | 2.0 | 1.0 | 0.0 | -2.0 | -2.0 | -2.0 | -1.0 | -3.0 | -3.0 | -1.0 | -1.0 | 3.0 | 0.0 | -3.0 | 0.0 | 0.0 | 1.0 | 1.0 | -4.0 | -5.0 | 0.0 | 0.0 | -0.8 | 3.0 | -5.0 |
| 18 | -1.0 | -3.0 | -2.0 | 0.0 | 0.0 | -1.0 | -1.0 | -1.0 | 0.0 | 1.0 | 0.0 | -1.0 | -1.0 | 1.0 | 0.0 | -1.0 | 0.0 | 0.0 | -1.0 | 0.0 | 2.0 | 0.0 | -2.0 | 0.0 | -0.5 | 2.0 | -3.0 |
| 19 | -1.0 | -3.0 | 2.0 | 4.0 | 5.0 | 2.0 | 3.0 | 4.0 | -1.0 | -2.0 | -1.0 | 0.0 | 2.0 | 1.0 | -- | -1.0 | 0.0 | 2.0 | 2.0 | 4.0 | 9.0 | 16.0 | 8.0 | 7.0 | 2.7 | 16.0 | -3.0 |
| 20 | 7.0 | 4.0 | 3.0 | 5.0 | 4.0 | 4.0 | 4.0 | 5.0 | 2.0 | 0.0 | -- | 3.0 | 1.0 | -1.0 | 2.0 | 1.0 | 0.0 | -2.0 | -1.0 | 0.0 | 2.0 | 2.0 | 1.0 | -2.0 | 1.9 | 7.0 | -2.0 |
| 21 | 0.0 | 4.0 | 3.0 | 3.0 | 3.0 | 4.0 | 6.0 | 5.0 | 3.0 | 4.0 | 1.0 | 1.0 | 5.0 | 6.0 | 5.0 | 4.0 | 3.0 | 2.0 | 4.0 | 4.0 | 0.0 | 1.0 | 4.0 | 5.0 | 3.3 | 6.0 | 0.0 |
| 22 | 6.0 | 5.0 | 4.0 | 4.0 | 6.0 | 6.0 | 3.0 | 2.0 | 1.0 | 1.0 | 2.0 | 2.0 | 1.0 | 2.0 | 3.0 | 4.0 | 4.0 | 5.0 | 5.0 | 5.0 | 6.0 | 4.0 | 5.0 | 4.0 | 3.8 | 6.0 | 1.0 |
| 23 | 1.0 | 2.0 | 4.0 | 2.0 | 2.0 | 1.0 | -1.0 | 3.0 | 4.0 | 0.0 | -- | -2.0 | -3.0 | -4.0 | -- | -- | -2.0 | 0.0 | 2.0 | 2.0 | 1.0 | 1.0 | 0.0 | 1.0 | 0.7 | 4.0 | -4.0 |
| 24 | 1.0 | 1.0 | 0.0 | -1.0 | 0.0 | -2.0 | -2.0 | -3.0 | -1.0 | 0.0 | -1.0 | 2.0 | 2.0 | -1.0 | -1.0 | 0.0 | 1.0 | 1.0 | 1.0 | 0.0 | 0.0 | 1.0 | 1.0 | 3.0 | 0.1 | 3.0 | -3.0 |
| 25 | 1.0 | -2.0 | -1.0 | 0.0 | 1.0 | -1.0 | 0.0 | 1.0 | 1.0 | 2.0 | 0.0 | 0.0 | 1.0 | -1.0 | -3.0 | -4.0 | -2.0 | 1.0 | 0.0 | -1.0 | 0.0 | 1.0 | 1.0 | 3.0 | -0.1 | 3.0 | -4.0 |
| 26 | 2.0 | 0.0 | 1.0 | 4.0 | 4.0 | 1.0 | -2.0 | 1.0 | 5.0 | 2.0 | -1.0 | 2.0 | 5.0 | 4.0 | 1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 0.0 | 0.0 | 3.0 | 2.0 | 2.0 | 1.6 | 5.0 | -2.0 |
| 27 | 1.0 | -1.0 | -1.0 | 1.0 | 0.0 | 0.0 | 3.0 | 2.0 | 2.0 | -5.0 | -- | -9.0 | -2.0 | -1.0 | -1.0 | -2.0 | -2.0 | -2.0 | -2.0 | -2.0 | 1.0 | 5.0 | 4.0 | -2.0 | -0.6 | 5.0 | -9.0 |
| 28 | -1.0 | 2.0 | 3.0 | 2.0 | 1.0 | 3.0 | 3.0 | 4.0 | 5.0 | 6.0 | 4.0 | 1.0 | 1.0 | 0.0 | -5.0 | -6.0 | 0.0 | 5.0 | 6.0 | 4.0 | 2.0 | 6.0 | 8.0 | 3.0 | 2.4 | 8.0 | -6.0 |
| 29 | 4.0 | 7.0 | 5.0 | 2.0 | -15.0 | -5.0 | -1.0 | 2.0 | 4.0 | 4.0 | -1.0 | -3.0 | 1.0 | 1.0 | -1.0 | -2.0 | -1.0 | 1.0 | 3.0 | 3.0 | 8.0 | 5.0 | -1.0 | 2.0 | 0.9 | 8.0 | -15.0 |
| 30 | 1.0 | 0.0 | 1.0 | 1.0 | 2.0 | 3.0 | 3.0 | 1.0 | 2.0 | 3.0 | 2.0 | 0.0 | 0.0 | 3.0 | 2.0 | -1.0 | 0.0 | 0.0 | 1.0 | 2.0 | 1.0 | 2.0 | 1.0 | 1.0 | 1.3 | 3.0 | -1.0 |
| 31 | 1.0 | 1.0 | 1.0 | 1.0 | 3.0 | 5.0 | 4.0 | 1.0 | 1.0 | 1.0 | -2.0 | 0.0 | 0.0 | -3.0 | -1.0 | -1.0 | -2.0 | 0.0 | 2.0 | 5.0 | 4.0 | 1.0 | 2.0 | 21.0 | 1.9 | 21.0 | -3.0 |
| Avg | 2.2 | 1.8 | 2.0 | 2.1 | 1.8 | 1.9 | 2.1 | 2.2 | 2.2 | 1.4 | 0.5 | 0.4 | 0.8 | 0.4 | 0.6 | 0.1 | 0.4 | 1.6 | 2.4 | 2.4 | 2.6 | 2.9 | 2.6 | 3.0 | 1.6 | -- | -- |
| Max | 7.0 | 7.0 | 7.0 | 10.0 | 11.0 | 9.0 | 8.0 | 8.0 | 6.0 | 6.0 | 4.0 | 6.0 | 5.0 | 6.0 | 5.0 | 5.0 | 5.0 | 7.0 | 6.0 | 6.0 | 9.0 | 16.0 | 8.0 | 21.0 | -- | 21.0 | -- |
| Min | -1.0 | -3.0 | -2.0 | -1.0 | -15.0 | -5.0 | -2.0 | -3.0 | -2.0 | -5.0 | -3.0 | -9.0 | -5.0 | -4.0 | -5.0 | -6.0 | -3.0 | -2.0 | -2.0 | -2.0 | -4.0 | -5.0 | -3.0 | -2.0 | -- | -- | -15.0 |

-- Indicates Invalid Data

# Appendix E: $NO_2$, $SO_2$, $O_3$ Data – East Plant – Hourly

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, NO2_ppb"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | -2.0 | -- | -2.1 | -2.3 | -2.5 | -2.5 | -2.5 | -1.0 | -1.5 | -2.7 | -2.6 | -2.5 | -2.5 | -- | -1.3 | -1.7 | -1.6 | -1.6 | -1.5 | -1.5 | -1.2 | -1.6 | -1.7 | -1.7 | -1.9 | -1.0 | -2.7 |
| 2 | -1.5 | -- | -0.7 | -1.3 | -0.8 | -0.5 | -0.4 | 0.6 | 0.2 | -1.1 | -0.6 | -1.0 | -0.6 | -1.2 | -1.5 | -1.5 | -1.1 | -1.6 | -1.5 | -1.6 | -1.2 | -0.8 | -1.3 | -1.5 | -1.0 | 0.6 | -1.6 |
| 3 | -1.0 | -- | -1.2 | -0.9 | -0.7 | 0.4 | 0.6 | 0.3 | -0.9 | -0.6 | -1.0 | -1.2 | -1.3 | -1.1 | -1.1 | -1.3 | -1.6 | -1.7 | -1.4 | -1.4 | -0.9 | -0.5 | 0.2 | -0.9 | -0.8 | 0.6 | -1.7 |
| 4 | -1.0 | -- | -1.7 | -1.1 | -0.8 | -1.4 | -1.2 | 1.2 | 0.7 | -0.3 | -0.8 | -1.1 | -1.1 | -0.8 | -1.1 | -1.0 | -0.6 | 1.6 | 1.3 | 0.2 | 0.5 | 0.7 | -1.6 | -1.8 | -0.5 | 1.6 | -1.8 |
| 5 | -1.5 | -- | -1.8 | -1.8 | -1.8 | -1.7 | -1.7 | -1.7 | -1.6 | -1.5 | -1.3 | -0.9 | -1.1 | -1.2 | -0.8 | -1.1 | -1.4 | -1.2 | -1.4 | -1.3 | -0.5 | -0.8 | -1.3 | -1.5 | -1.3 | -0.5 | -1.8 |
| 6 | -1.5 | -- | -1.7 | -1.7 | -1.5 | 15.5 | -1.3 | -1.0 | -0.9 | -0.6 | -0.2 | -0.8 | -1.3 | -1.3 | -1.4 | -1.5 | -1.5 | -1.1 | -0.8 | -0.6 | -0.2 | 0.6 | 0.2 | 1.5 | -0.1 | 15.5 | -1.7 |
| 7 | 2.4 | -- | 2.1 | 2.2 | 0.3 | -0.1 | 0.9 | 0.3 | 0.0 | 0.7 | -1.2 | -0.9 | -1.5 | -1.3 | -1.2 | -0.9 | -1.4 | -1.5 | -1.5 | -1.1 | -1.3 | -1.5 | -1.7 | -1.7 | -0.4 | 2.4 | -1.7 |
| 8 | -1.3 | -- | -1.5 | -1.2 | -1.0 | -1.1 | -1.3 | 1.1 | -0.5 | -1.1 | -0.7 | -0.9 | -1.4 | -1.4 | -1.5 | -1.7 | -1.5 | -1.9 | -1.9 | -1.9 | -2.0 | -1.9 | -1.9 | -1.9 | -1.3 | 1.1 | -2.0 |
| 9 | -1.7 | -- | -2.0 | -1.7 | -1.6 | -1.6 | -1.2 | -0.4 | -0.9 | -- | -- | -- | -- | -- | -- | -- | -- | -0.3 | -0.2 | -0.3 | -0.2 | -0.2 | -0.3 | -0.3 | -- | -- | -- |
| 10 | 0.2 | -- | -0.2 | -0.3 | -0.3 | -0.1 | -0.2 | 0.6 | 1.5 | 1.7 | 1.3 | 0.8 | 0.8 | 1.0 | 1.0 | 0.9 | 0.8 | 0.7 | 1.7 | 2.0 | 2.2 | 1.7 | 2.1 | 1.0 | 0.9 | 2.2 | -0.3 |
| 11 | 1.1 | -- | 1.0 | 1.4 | 1.7 | 2.3 | 2.5 | 4.1 | 6.5 | 1.7 | 1.0 | 0.8 | 1.6 | 1.2 | 1.0 | 0.8 | 0.6 | 0.5 | 0.6 | 1.2 | 1.0 | 0.8 | 0.8 | 0.6 | 1.5 | 6.5 | 0.5 |
| 12 | 0.7 | -- | 0.7 | 0.7 | 0.5 | 0.8 | 0.8 | 1.5 | 2.0 | 0.9 | 0.3 | 1.0 | 0.6 | 0.3 | 0.5 | 0.1 | 0.0 | 0.0 | 0.3 | 0.2 | 1.0 | 0.5 | 0.1 | 0.1 | 0.6 | 2.0 | 0.0 |
| 13 | 0.3 | -- | 0.0 | 0.3 | 0.5 | 0.4 | 0.4 | 0.4 | 0.1 | 0.3 | 0.2 | 0.0 | 0.1 | 0.2 | 0.0 | -0.2 | -0.3 | -0.3 | -0.2 | -0.1 | -0.1 | 0.1 | 0.4 | 0.6 | 0.1 | 0.6 | -0.3 |
| 14 | 0.7 | -- | 1.1 | 1.1 | 0.8 | 1.7 | 2.1 | 3.1 | 2.4 | 1.1 | 0.5 | 0.7 | 0.2 | 0.0 | -0.1 | -0.1 | -0.1 | 0.0 | 0.3 | 0.3 | 0.4 | 3.8 | 0.6 | 0.0 | 0.9 | 3.8 | -0.1 |
| 15 | 0.6 | -- | 0.3 | 0.5 | 1.1 | 1.1 | 1.4 | 2.6 | 1.5 | 0.5 | 0.6 | 0.6 | 0.5 | 0.2 | 0.2 | 0.2 | 0.6 | 0.6 | 0.9 | 1.7 | 2.5 | 1.8 | 1.1 | 1.0 | 1.0 | 2.6 | 0.2 |
| 16 | 1.0 | -- | 1.1 | 1.0 | 1.3 | 0.7 | 0.8 | 1.4 | 0.8 | 0.7 | 1.0 | 0.6 | 1.0 | 0.3 | 0.1 | 0.1 | 0.2 | 0.5 | 0.9 | 1.8 | 2.3 | 2.3 | 2.0 | 1.2 | 1.0 | 2.3 | 0.1 |
| 17 | 0.7 | -- | 0.7 | 0.6 | 0.4 | 1.2 | 0.9 | 2.1 | 1.6 | 0.6 | 1.1 | 1.5 | 1.0 | 0.8 | 0.5 | 0.4 | 0.5 | 0.9 | 1.3 | 1.6 | 1.9 | 2.3 | 2.2 | 2.2 | 1.2 | 2.3 | 0.4 |
| 18 | 2.1 | -- | 1.0 | 0.6 | 0.6 | 0.6 | 0.5 | 2.2 | -- | -- | 2.0 | 0.2 | 0.1 | 0.2 | 0.3 | 0.4 | 0.8 | 1.9 | 2.3 | 2.9 | 2.6 | 1.9 | 1.8 | 1.7 | 1.3 | 2.9 | 0.1 |
| 19 | 1.2 | -- | -0.3 | 0.0 | 0.1 | 0.1 | 0.2 | 0.6 | 0.6 | 1.4 | 1.3 | 0.7 | 0.1 | 0.3 | 0.3 | 0.1 | 0.1 | 0.6 | 0.7 | 1.0 | 1.7 | 1.4 | 0.6 | 0.2 | 0.6 | 1.7 | -0.3 |
| 20 | 0.0 | -- | -0.2 | 0.0 | 0.4 | 0.4 | 0.5 | 1.3 | 2.1 | 0.4 | 1.2 | 0.8 | 0.3 | -0.1 | 0.0 | -0.2 | -0.2 | 0.0 | 0.2 | 0.5 | 0.5 | 0.6 | 0.5 | 0.7 | 0.4 | 2.1 | -0.2 |
| 21 | 0.8 | -- | 0.6 | 0.3 | 0.2 | 0.3 | 0.3 | 1.8 | 3.2 | 1.0 | 2.0 | 2.2 | 1.9 | 0.9 | 0.0 | -0.2 | -0.1 | 0.0 | 0.2 | 0.6 | 0.8 | 0.3 | 0.0 | -0.1 | 0.7 | 3.2 | -0.2 |
| 22 | 0.3 | -- | -0.2 | 0.1 | 0.3 | 1.4 | 3.5 | 3.3 | 2.2 | 2.2 | 1.6 | 1.3 | 1.0 | 0.4 | 0.6 | -0.1 | 0.0 | 0.2 | 0.2 | 0.0 | 0.4 | 0.5 | 1.2 | 1.0 | 0.9 | 3.5 | -0.2 |
| 23 | 1.3 | -- | 1.3 | 1.5 | 1.3 | 1.4 | 2.1 | 2.0 | 3.3 | 2.4 | 1.5 | 1.3 | 0.4 | 0.2 | 0.3 | 0.3 | 0.1 | -0.1 | 0.6 | 0.2 | 0.4 | 0.9 | 1.4 | 1.6 | 1.1 | 3.3 | -0.1 |
| 24 | 8.0 | -- | 1.5 | 1.9 | 2.1 | 2.2 | 2.0 | 1.8 | 1.9 | 1.0 | 1.1 | 1.7 | 0.9 | 0.0 | 0.1 | 0.2 | 0.5 | 1.0 | 1.1 | 1.1 | 0.8 | 0.4 | 0.2 | 0.3 | 1.4 | 8.0 | 0.0 |
| 25 | 0.4 | -- | -0.1 | -0.3 | -0.2 | -0.4 | -0.3 | 0.4 | 1.8 | 0.3 | 0.3 | 0.4 | 0.3 | 0.1 | 0.0 | 0.2 | 0.2 | 0.5 | 0.6 | 2.0 | 3.2 | 3.2 | 1.1 | 0.8 | 0.6 | 3.2 | -0.4 |
| 26 | 1.1 | -- | 0.2 | 0.1 | 0.0 | 0.1 | 0.8 | 0.6 | 0.6 | 1.2 | 1.4 | 0.8 | 0.3 | 0.1 | 0.0 | -0.1 | -0.1 | 0.5 | 0.2 | 1.3 | 0.9 | 2.8 | 1.9 | 1.5 | 0.7 | 2.8 | -0.1 |
| 27 | 1.5 | -- | 2.2 | 0.7 | 1.2 | 1.5 | 1.2 | 1.2 | 1.2 | 1.3 | 0.3 | 0.2 | 0.8 | 0.0 | -0.1 | -0.2 | -0.1 | -0.3 | 0.2 | 0.4 | 0.3 | 0.8 | 0.9 | -0.4 | 0.6 | 2.2 | -0.4 |
| 28 | 0.1 | -- | -0.4 | -0.3 | -0.2 | 0.2 | -0.2 | -0.1 | -0.1 | 0.0 | 0.1 | 0.3 | -0.1 | -0.2 | -0.4 | -0.4 | -0.3 | -0.4 | -0.4 | -0.5 | -0.5 | -0.5 | -0.5 | -0.6 | -0.2 | 0.3 | -0.6 |
| 29 | -0.1 | -- | -0.5 | -0.5 | -0.4 | -0.2 | -0.3 | 0.4 | -0.1 | 0.0 | -0.1 | -0.1 | 0.0 | 0.1 | 0.2 | 1.7 | 3.0 | 1.1 | 0.8 | 1.0 | 1.1 | 1.0 | 0.8 | 1.1 | 0.4 | 3.0 | -0.5 |
| 30 | 1.3 | -- | 0.5 | 0.1 | 0.6 | 0.3 | 0.3 | 0.8 | 0.6 | 1.1 | 1.0 | 0.6 | 0.4 | 0.4 | -- | 1.4 | 2.5 | 3.7 | 3.1 | 2.6 | 2.1 | 2.1 | 2.0 | 1.6 | 1.3 | 3.7 | 0.1 |
| 31 | 1.5 | -- | 0.7 | 0.3 | 0.8 | 1.7 | 2.0 | 3.0 | 2.8 | 2.2 | 2.1 | 1.9 | 1.0 | 0.7 | 0.4 | 0.5 | 1.4 | 1.8 | 3.1 | 4.0 | 3.5 | 3.1 | 1.7 | 1.3 | 1.8 | 4.0 | 0.3 |
| Avg | 0.5 | -- | 0.0 | 0.0 | 0.1 | 0.8 | 0.4 | 1.1 | 1.0 | 0.5 | 0.5 | 0.3 | 0.1 | 0.0 | -0.2 | -0.2 | 0.0 | 0.1 | 0.3 | 0.5 | 0.7 | 0.8 | 0.4 | 0.3 | 0.4 | -- | -- |
| Max | 8.0 | -- | 2.2 | 2.2 | 2.1 | 15.5 | 3.5 | 4.1 | 6.5 | 2.4 | 2.1 | 2.2 | 1.9 | 1.2 | 1.0 | 1.7 | 3.0 | 3.7 | 3.1 | 4.0 | 3.5 | 3.8 | 2.2 | 2.2 | -- | 15.5 | -- |
| Min | -2.0 | -- | -2.1 | -2.3 | -2.5 | -2.5 | -2.5 | -1.7 | -1.6 | -2.7 | -2.6 | -2.5 | -2.5 | -1.4 | -1.5 | -1.7 | -1.6 | -1.9 | -1.9 | -1.9 | -2.0 | -1.9 | -1.9 | -1.9 | -- | -- | -2.7 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, NO2_ppb"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 1.4 | -- | 0.5 | 0.4 | 0.8 | 1.0 | 2.5 | 3.8 | 3.0 | 1.9 | 1.2 | 0.9 | 0.8 | 1.1 | 0.5 | 0.7 | 1.0 | 2.0 | 2.9 | 2.4 | 3.7 | 2.7 | 1.1 | 0.3 | 1.6 | 3.8 | 0.3 |
| 2 | 0.7 | -- | 0.2 | 0.6 | 2.1 | 1.8 | 2.3 | 1.8 | 0.9 | 0.7 | 0.1 | -0.2 | -0.2 | -0.2 | -0.2 | -0.3 | 0.0 | -0.3 | 0.6 | 1.1 | 0.3 | -0.2 | 0.4 | 0.1 | 0.5 | 2.3 | -0.3 |
| 3 | 0.7 | -- | 0.3 | 2.6 | 2.1 | 3.4 | 1.6 | 1.1 | 1.1 | 0.6 | 1.7 | 0.7 | 0.2 | 0.1 | 0.1 | 0.1 | -0.1 | -0.3 | -0.3 | 0.1 | 0.1 | -0.1 | 0.5 | -0.2 | 0.7 | 3.4 | -0.3 |
| 4 | -0.2 | 0.0 | -- | 0.1 | -0.1 | 0.1 | 0.0 | 0.6 | 0.9 | 0.5 | 0.5 | 0.2 | 0.1 | 0.2 | 0.2 | 0.1 | -0.2 | -0.2 | 0.2 | 0.8 | 0.7 | 1.0 | 3.9 | 4.1 | 0.6 | 4.1 | -0.2 |
| 5 | 3.7 | 2.8 | -- | 1.5 | 1.8 | 1.0 | 0.3 | 1.5 | 2.9 | 1.9 | 1.1 | 0.9 | 0.7 | 0.5 | 0.4 | 0.4 | 0.4 | 1.1 | 1.8 | 2.4 | 1.4 | 0.3 | 0.8 | 0.1 | 1.3 | 3.7 | 0.1 |
| 6 | 0.8 | 1.0 | -- | -0.3 | 0.4 | -0.5 | -0.4 | 0.4 | -0.3 | -0.2 | 0.1 | 1.6 | 0.7 | 0.1 | -0.2 | 0.0 | 0.3 | 0.5 | 1.3 | 1.0 | 0.8 | 1.3 | 0.4 | 0.0 | 0.4 | 1.6 | -0.5 |
| 7 | 0.4 | 1.0 | -- | 1.7 | 1.9 | 2.2 | 2.0 | 2.4 | 2.8 | 2.2 | 0.4 | -0.2 | -0.2 | -0.3 | -0.3 | -0.4 | -0.4 | -0.4 | 0.3 | 0.5 | 0.7 | 1.3 | 0.7 | 1.0 | 0.8 | 2.8 | -0.4 |
| 8 | 1.0 | 1.3 | -- | 1.1 | 1.1 | 1.4 | 1.4 | 1.5 | 1.5 | 2.4 | 1.7 | 2.1 | 1.0 | 0.4 | 0.1 | 0.0 | 0.1 | 0.2 | 0.2 | 0.3 | 0.2 | 0.0 | -0.2 | -0.2 | 0.8 | 2.4 | -0.2 |
| 9 | -0.1 | 0.2 | -- | -0.2 | 0.4 | 2.0 | 1.1 | 0.7 | 1.1 | 1.2 | 1.2 | 0.5 | 0.3 | 0.2 | 0.1 | -0.1 | -0.2 | -0.2 | -0.2 | 0.5 | 0.2 | 0.2 | 0.0 | -0.1 | 0.4 | 2.0 | -0.2 |
| 10 | -0.1 | 0.3 | -- | 0.0 | -0.1 | 0.0 | 0.0 | 0.4 | 0.2 | 1.2 | 14.8 | 3.0 | 3.4 | 2.2 | 1.8 | 0.9 | 2.3 | 2.1 | 2.4 | 2.2 | 1.3 | 0.3 | -0.1 | -0.1 | 1.7 | 14.8 | -0.1 |
| 11 | 0.1 | 0.1 | -- | 0.4 | 0.2 | 1.0 | 1.2 | 1.0 | 0.8 | 1.4 | 3.0 | 3.3 | 1.9 | 1.1 | 0.2 | 0.0 | 0.4 | 1.9 | 1.6 | 1.0 | 0.6 | 0.5 | 0.5 | 0.9 | 1.0 | 3.3 | 0.0 |
| 12 | 0.5 | 0.6 | -- | 0.7 | 0.6 | 0.6 | 0.6 | 1.1 | 1.3 | 2.3 | 2.7 | 1.1 | 0.2 | 0.1 | 0.3 | 0.4 | 0.3 | 0.3 | 0.4 | 1.0 | 1.1 | 1.1 | 1.0 | 0.8 | 0.8 | 2.7 | 0.1 |
| 13 | 0.7 | 0.9 | -- | 0.6 | 0.8 | 1.1 | 1.0 | 1.2 | 1.5 | 1.3 | 1.2 | 1.0 | 1.0 | 1.0 | 0.8 | 0.8 | 0.7 | 0.9 | 0.9 | 0.9 | 1.3 | 1.0 | 1.1 | 1.2 | 1.0 | 1.5 | 0.6 |
| 14 | 1.3 | 2.0 | -- | 2.2 | 2.2 | 2.0 | 2.2 | 2.6 | 2.8 | 3.4 | 3.2 | 2.3 | 2.1 | 2.2 | 1.7 | 1.1 | 0.9 | 0.9 | 0.9 | 1.7 | 1.5 | 1.0 | 0.8 | 0.5 | 1.8 | 3.4 | 0.5 |
| 15 | 0.4 | 0.8 | -- | 0.9 | 0.8 | 1.7 | 2.2 | 1.4 | 0.7 | 0.6 | 0.8 | 1.0 | 0.6 | 0.5 | -- | -0.1 | -0.1 | -0.1 | -0.2 | -0.1 | 0.1 | 0.0 | -0.2 | -0.2 | 0.5 | 2.2 | -0.2 |
| 16 | -0.1 | 0.3 | -- | 0.0 | 0.0 | -0.1 | -0.2 | -0.1 | 0.0 | 0.1 | 0.2 | 0.4 | 0.5 | 0.4 | 0.3 | 0.1 | 0.0 | -0.1 | -0.2 | -0.2 | -0.2 | -0.1 | 0.3 | 0.6 | 0.1 | 0.6 | -0.2 |
| 17 | 0.1 | 0.3 | -- | 0.1 | 0.8 | 0.3 | -0.2 | -0.2 | 0.3 | 0.1 | 0.5 | 0.8 | 0.3 | 0.3 | 0.2 | 0.0 | -0.1 | -0.1 | 1.0 | 0.9 | 0.0 | 0.4 | -0.1 | 0.1 | 0.3 | 1.0 | -0.2 |
| 18 | 0.2 | 0.3 | -- | 0.8 | 0.6 | 1.2 | 1.0 | 0.9 | 0.7 | 1.7 | 2.2 | 3.0 | 2.5 | 0.3 | 0.5 | 0.5 | 0.4 | 0.6 | 1.2 | 2.1 | 1.1 | 0.5 | 0.8 | 0.7 | 1.0 | 3.0 | 0.2 |
| 19 | 0.4 | -- | 0.1 | 0.1 | 0.1 | 0.7 | 1.3 | 2.6 | 3.3 | 2.3 | 1.4 | 1.1 | 0.4 | 1.8 | 0.7 | 0.4 | 0.4 | 0.8 | 1.1 | 0.9 | 0.8 | 1.2 | 0.9 | 0.9 | 1.0 | 3.3 | 0.1 |
| 20 | 0.9 | -- | 1.8 | 2.0 | 2.9 | 2.7 | 3.7 | 5.3 | 4.8 | 3.0 | 2.6 | 2.5 | 1.7 | 0.6 | 0.7 | 1.2 | 0.8 | 0.8 | 0.6 | 0.4 | 0.4 | 0.4 | 0.6 | 0.6 | 1.8 | 5.3 | 0.4 |
| 21 | 0.4 | -- | 0.3 | 0.2 | 0.5 | 2.3 | 2.6 | 3.8 | 2.4 | 1.8 | 0.7 | 0.8 | 0.6 | 0.5 | 0.4 | 0.3 | 0.3 | 0.5 | 0.4 | 0.3 | 0.9 | 2.9 | 1.4 | 0.7 | 1.1 | 3.8 | 0.2 |
| 22 | 0.2 | -- | 0.5 | 0.9 | 1.3 | 0.4 | 0.5 | 0.7 | 0.9 | 2.7 | 2.0 | 1.0 | 1.0 | 1.4 | 1.5 | 0.5 | 1.1 | 1.3 | 0.9 | 1.9 | 2.2 | 1.1 | 1.4 | 1.1 | 1.2 | 2.7 | 0.2 |
| 23 | 1.3 | -- | 0.6 | 0.4 | 1.0 | 0.8 | 0.9 | 0.7 | 0.6 | 0.6 | 0.7 | 0.5 | 0.8 | 0.7 | 0.7 | 0.7 | 0.7 | 0.6 | 1.0 | 1.0 | 1.1 | 1.1 | 1.1 | 1.2 | 0.8 | 1.3 | 0.4 |
| 24 | 0.8 | -- | 0.6 | 0.5 | 0.4 | 0.4 | 0.5 | 0.4 | 0.6 | 0.8 | 1.0 | 1.1 | 0.9 | 1.0 | 1.3 | 1.5 | 1.8 | 1.6 | 1.2 | 0.8 | 1.5 | 1.6 | 1.6 | 1.7 | 1.0 | 1.8 | 0.4 |
| 25 | 1.5 | -- | 3.0 | 1.6 | 1.0 | 1.0 | 2.5 | 3.4 | 1.9 | 1.5 | 2.1 | 1.7 | 1.6 | 1.4 | 1.2 | 0.6 | 0.9 | 1.5 | 1.9 | 1.9 | 1.7 | 1.9 | 1.7 | 2.5 | 1.7 | 3.4 | 0.6 |
| 26 | 2.6 | -- | 0.9 | 1.2 | 1.3 | 1.4 | 3.5 | 3.2 | 3.3 | 2.6 | 2.1 | 1.5 | 1.3 | 1.1 | 0.8 | 1.0 | 0.1 | 0.4 | 0.9 | 0.5 | 0.4 | 0.3 | 0.5 | 0.5 | 1.4 | 3.5 | 0.1 |
| 27 | 0.4 | -- | 0.8 | 0.9 | 0.8 | 1.0 | 0.9 | 1.0 | 1.7 | 1.3 | 0.9 | 0.7 | 0.8 | -- | 0.8 | 0.6 | 0.6 | 0.7 | 1.3 | 0.8 | 1.2 | 0.9 | 1.2 | 1.3 | 0.9 | 1.7 | 0.4 |
| 28 | 0.9 | -- | 1.4 | 1.4 | 1.2 | 1.4 | 1.4 | 1.6 | 2.2 | 1.9 | 1.9 | 1.6 | 1.6 | 1.0 | 0.8 | 0.8 | 0.9 | 2.3 | 2.4 | 0.9 | 0.8 | 1.3 | 0.8 | 0.6 | 1.3 | 2.4 | 0.6 |
| 29 | 0.9 | -- | 0.8 | 1.1 | 1.3 | 1.3 | 1.4 | 1.3 | 1.5 | 1.8 | 2.6 | 2.9 | 0.9 | 1.4 | 0.8 | 0.5 | 0.8 | 2.4 | 2.3 | 2.0 | 1.5 | 1.3 | 1.4 | 1.5 | 1.5 | 2.9 | 0.5 |
| 30 | 1.5 | -- | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.3 | 1.6 | 1.5 | 1.8 | 2.9 | 3.5 | 3.6 | 2.7 | 2.3 | 3.9 | 5.3 | 2.9 | 1.7 | 1.4 | 1.0 | 0.8 | 0.9 | 2.0 | 5.3 | 0.8 |
| Avg | 0.8 | 0.8 | 0.9 | 0.8 | 1.0 | 1.1 | 1.3 | 1.6 | 1.6 | 1.5 | 1.9 | 1.4 | 1.0 | 0.9 | 0.6 | 0.5 | 0.6 | 0.9 | 1.1 | 1.1 | 1.0 | 0.9 | 0.9 | 0.8 | 1.0 | -- | -- |
| Max | 3.7 | 2.8 | 3.0 | 2.6 | 2.9 | 3.4 | 3.7 | 5.3 | 4.8 | 3.4 | 14.8 | 3.3 | 3.5 | 3.6 | 2.7 | 2.3 | 3.9 | 5.3 | 2.9 | 2.4 | 3.7 | 2.9 | 3.9 | 4.1 | -- | 14.8 | -- |
| Min | -0.2 | 0.0 | 0.1 | -0.3 | -0.1 | -0.5 | -0.4 | -0.2 | -0.3 | -0.2 | 0.1 | -0.2 | -0.2 | -0.3 | -0.3 | -0.4 | -0.4 | -0.4 | -0.3 | -0.2 | -0.2 | -0.2 | -0.2 | -0.2 | -- | -- | -0.5 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, NO2_ppb"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.9 | -- | 1.3 | 1.1 | 0.8 | 0.7 | 0.7 | 0.8 | 0.9 | 0.8 | 1.9 | 2.3 | 3.9 | 2.6 | 1.2 | 1.2 | 1.2 | 1.3 | 0.7 | 0.6 | 0.5 | 0.4 | 0.3 | 0.2 | 1.1 | 3.9 | 0.2 |
| 2 | 0.1 | -- | 0.3 | 1.1 | 0.6 | 0.3 | 0.4 | 0.5 | 1.1 | 1.9 | 1.4 | 1.1 | 0.9 | 0.9 | 1.0 | 1.2 | 0.9 | 1.1 | 0.9 | 1.9 | 1.0 | 0.7 | 0.8 | 1.7 | 1.0 | 1.9 | 0.1 |
| 3 | 1.6 | -- | 0.2 | 0.9 | 1.2 | 0.6 | 0.8 | 0.4 | 1.6 | 2.1 | 1.1 | 0.9 | 0.8 | 0.3 | 0.3 | 0.6 | 0.5 | 0.5 | -0.1 | -0.2 | -0.1 | -0.1 | -0.1 | 0.0 | 0.6 | 2.1 | -0.2 |
| 4 | 0.0 | -- | -0.3 | -0.3 | 0.0 | 0.3 | -0.1 | -0.1 | -0.1 | 0.1 | 0.1 | 0.6 | 0.3 | 1.3 | 2.5 | 0.3 | 0.6 | 1.0 | 1.0 | 1.3 | 2.3 | 3.7 | 3.1 | 2.0 | 0.9 | 3.7 | -0.3 |
| 5 | 1.4 | -- | 0.8 | 0.6 | 0.6 | 1.1 | 1.6 | 1.7 | 2.6 | 2.7 | 1.6 | 1.1 | 1.2 | 1.0 | 1.0 | 1.8 | 2.1 | 2.9 | 4.9 | 3.6 | 2.9 | 2.7 | 2.9 | 4.3 | 2.0 | 4.9 | 0.6 |
| 6 | 4.9 | -- | 0.9 | 0.8 | 0.9 | 3.4 | 3.3 | 3.2 | 3.2 | 1.8 | 1.6 | 1.2 | 1.3 | 1.1 | 1.1 | 1.1 | 0.7 | 0.7 | 1.3 | 2.1 | 1.5 | 1.2 | 1.5 | 1.0 | 1.7 | 4.9 | 0.7 |
| 7 | 0.7 | -- | 0.4 | 0.5 | 0.3 | 0.2 | 0.1 | 0.3 | 1.0 | 1.3 | 1.3 | 1.6 | 1.1 | 0.5 | 0.6 | 0.6 | 0.8 | 0.9 | 0.9 | 1.0 | 0.6 | 0.4 | 0.4 | 0.3 | 0.7 | 1.6 | 0.1 |
| 8 | 0.2 | -- | 0.0 | 0.1 | 0.0 | 0.0 | -0.1 | 0.1 | 0.2 | 0.7 | 0.4 | 0.1 | 0.1 | 0.0 | 0.1 | 0.0 | 0.1 | 0.3 | 0.4 | 0.3 | 0.3 | 1.3 | 1.4 | 1.0 | 0.3 | 1.4 | -0.1 |
| 9 | 1.3 | -- | 5.8 | 5.1 | 4.3 | 3.4 | 2.7 | 2.8 | 4.7 | 3.1 | 2.8 | 1.4 | 1.4 | 0.9 | 0.5 | 1.0 | 0.9 | 0.7 | 0.3 | 0.3 | -0.2 | -0.3 | -0.2 | -0.4 | 1.8 | 5.8 | -0.4 |
| 10 | -0.1 | -- | -0.1 | 0.2 | -0.1 | 0.0 | -0.1 | 0.6 | 1.6 | 1.5 | 1.9 | 2.0 | 1.6 | 0.6 | 0.6 | 1.4 | 1.6 | 2.0 | 1.6 | 1.3 | 1.7 | 1.6 | 1.7 | 2.0 | 1.1 | 2.0 | -0.1 |
| 11 | 1.3 | -- | 1.0 | 1.2 | 0.7 | 0.8 | 1.0 | 1.0 | 1.4 | 1.9 | 1.9 | 1.8 | 1.1 | 1.3 | 1.4 | 1.6 | 2.1 | 1.5 | 1.3 | 0.7 | 0.9 | 0.8 | 0.9 | 0.8 | 1.2 | 2.1 | 0.7 |
| 12 | 0.8 | -- | 1.3 | 1.8 | 1.8 | 1.9 | 1.8 | 1.7 | 2.1 | 1.9 | 1.9 | 1.4 | 1.4 | 1.2 | 1.3 | -- | 1.3 | 2.0 | 1.9 | 2.5 | 3.4 | 3.3 | 4.2 | 5.7 | 2.1 | 5.7 | 0.8 |
| 13 | 5.4 | -- | 5.0 | 5.4 | 4.4 | 6.1 | 4.4 | 4.3 | 6.7 | 6.7 | 5.4 | 4.8 | 3.3 | 2.6 | 2.4 | 2.2 | 2.0 | 2.0 | 2.0 | 2.1 | 1.5 | 2.7 | 2.8 | 2.2 | 3.8 | 6.7 | 1.5 |
| 14 | 1.7 | -- | 1.9 | 2.2 | 0.8 | 1.0 | 1.2 | 1.7 | 1.6 | 1.5 | 0.9 | 1.2 | 1.2 | 0.8 | 0.5 | 0.2 | 1.0 | 1.5 | 0.6 | 0.6 | 0.5 | 0.3 | 0.2 | -0.1 | 1.0 | 2.2 | -0.1 |
| 15 | 0.2 | -- | 0.3 | 0.1 | 0.2 | 0.8 | 1.3 | 0.4 | 1.0 | 0.9 | 0.9 | 2.2 | 0.9 | 0.5 | 1.1 | 2.5 | 2.1 | 0.7 | 1.2 | 0.4 | -0.3 | -0.4 | -0.3 | -0.2 | 0.7 | 2.5 | -0.4 |
| 16 | 0.6 | -- | 1.0 | 2.4 | 1.0 | 0.9 | 1.2 | 0.8 | 2.2 | 2.9 | 1.7 | 1.5 | 0.8 | 1.3 | 0.4 | 1.0 | 4.3 | 3.5 | 1.7 | 0.7 | 0.3 | 1.1 | 1.0 | 1.9 | 1.5 | 4.3 | 0.3 |
| 17 | 1.0 | -- | 0.0 | 0.0 | 0.0 | 0.7 | 1.2 | 1.3 | 0.6 | 0.6 | 1.4 | 3.7 | 3.5 | 3.0 | 1.9 | 1.5 | 1.5 | 2.9 | 2.4 | 1.1 | 1.2 | 1.8 | 1.2 | 1.3 | 1.5 | 3.7 | 0.0 |
| 18 | 1.7 | -- | 1.2 | 1.4 | 1.5 | 2.0 | 2.3 | 2.1 | 2.6 | 2.5 | 2.6 | 2.5 | 1.8 | 2.2 | 1.7 | 1.1 | 0.8 | 0.7 | 0.7 | 0.4 | 0.7 | 0.6 | 0.3 | 0.3 | 1.5 | 2.6 | 0.3 |
| 19 | 0.6 | -- | 0.5 | 0.0 | -0.2 | -0.2 | -0.1 | 0.0 | 0.0 | 0.1 | 0.3 | 0.3 | 0.4 | 0.0 | -0.2 | -0.2 | -0.1 | 0.0 | 0.2 | 1.6 | 2.1 | 0.5 | -0.1 | -0.2 | 0.2 | 2.1 | -0.2 |
| 20 | -0.1 | -- | 0.0 | 0.3 | 1.0 | 0.4 | 0.0 | -0.2 | 1.9 | 1.5 | 0.0 | 3.7 | 1.2 | -- | -- | -0.2 | 0.8 | 0.3 | 0.1 | 0.6 | 0.4 | 0.3 | 0.4 | 0.5 | 0.6 | 3.7 | -0.2 |
| 21 | 0.6 | -- | 0.5 | 0.3 | 0.3 | 0.3 | 0.2 | 0.2 | 0.3 | 0.3 | 0.4 | 0.6 | 0.8 | 0.9 | 0.9 | 0.9 | 1.1 | 1.1 | 1.4 | 1.3 | 1.2 | 1.3 | 1.2 | 1.6 | 0.8 | 1.6 | 0.2 |
| 22 | 1.3 | -- | 0.9 | 0.7 | 0.6 | 0.7 | 0.7 | 1.1 | 1.7 | 1.8 | 1.4 | 2.9 | 3.3 | 2.6 | 1.6 | 1.1 | 0.9 | 1.1 | 1.1 | 1.6 | 1.2 | 0.8 | 0.7 | 1.3 | 1.4 | 3.3 | 0.6 |
| 23 | 2.2 | -- | 2.1 | 2.5 | 4.3 | 2.4 | 0.3 | 0.1 | 0.5 | 0.9 | 2.1 | 1.7 | 0.7 | 0.5 | 0.5 | 0.7 | 0.9 | 1.5 | 1.9 | 1.8 | 1.6 | 2.1 | 2.1 | 1.7 | 1.5 | 4.3 | 0.1 |
| 24 | 1.8 | -- | 1.6 | 1.6 | 1.3 | 1.2 | 1.0 | 1.0 | 1.9 | 1.5 | 1.3 | 1.0 | 1.0 | 1.1 | 1.0 | 0.9 | 1.1 | 1.2 | 2.1 | 1.9 | 1.6 | 1.1 | 0.6 | 0.4 | 1.3 | 2.1 | 0.4 |
| 25 | -0.1 | -- | -0.4 | -0.4 | -0.1 | 0.1 | -0.3 | -0.2 | 0.1 | 0.3 | 0.3 | 0.5 | 1.1 | 0.6 | 0.0 | 0.3 | 0.3 | 0.8 | 2.1 | 1.1 | 0.6 | 0.4 | 0.8 | 0.9 | 0.4 | 2.1 | -0.4 |
| 26 | 1.6 | -- | 1.4 | 0.6 | 1.1 | 1.1 | 1.1 | 1.1 | 2.1 | 1.7 | 0.9 | 0.6 | 0.5 | 0.5 | 1.0 | 0.4 | 0.4 | 1.1 | 1.6 | 0.8 | 1.0 | 1.4 | 0.3 | 0.7 | 1.0 | 2.1 | 0.3 |
| 27 | 0.9 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- |
| 28 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- |
| 29 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- |
| 30 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 1.5 | 0.9 | 0.6 | 0.7 | 0.4 | 1.3 | 1.5 | 2.9 | 1.8 | 1.1 | 0.3 | 1.5 | -- | -- | -- |
| 31 | 1.2 | -- | 0.0 | 0.0 | 0.6 | 1.0 | 1.5 | 2.1 | 2.2 | 2.6 | 1.9 | 1.3 | 0.9 | 0.7 | 0.6 | 0.4 | 1.1 | 2.1 | 1.6 | 0.8 | 0.3 | 0.2 | 0.4 | 0.2 | 1.0 | 2.6 | 0.0 |
| Avg | 1.2 | -- | 1.0 | 1.1 | 1.0 | 1.2 | 1.0 | 1.1 | 1.7 | 1.7 | 1.5 | 1.6 | 1.4 | 1.1 | 1.0 | 0.9 | 1.1 | 1.3 | 1.3 | 1.3 | 1.1 | 1.1 | 1.0 | 1.2 | 1.2 | -- | -- |
| Max | 5.4 | -- | 5.8 | 5.4 | 4.4 | 6.1 | 4.4 | 4.3 | 6.7 | 6.7 | 5.4 | 4.8 | 3.9 | 3.0 | 2.5 | 2.5 | 4.3 | 3.5 | 4.9 | 3.6 | 3.4 | 3.7 | 4.2 | 5.7 | -- | 6.7 | -- |
| Min | -0.1 | -- | -0.4 | -0.4 | -0.2 | -0.2 | -0.3 | -0.2 | -0.1 | 0.1 | 0.0 | 0.1 | 0.1 | 0.0 | -0.2 | -0.2 | -0.1 | 0.0 | -0.1 | -0.2 | -0.3 | -0.4 | -0.3 | -0.4 | -- | -- | -0.4 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, SO2_ppb"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | -- | -1.3 | -1.3 | -1.3 | -1.4 | -1.3 | -1.3 | -1.4 | -1.4 | -1.3 | -1.2 | -1.2 | -- | -- | 1.0 | 0.9 | 0.8 | 0.8 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | -0.3 | 1.0 | -1.4 |
| 2 | -- | 0.7 | 0.7 | 0.7 | 0.7 | 0.6 | 0.6 | 0.6 | 0.9 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 0.8 | 0.9 | 0.8 | 0.8 | 0.8 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 0.8 | 1.0 | 0.6 |
| 3 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 1.2 | 1.2 | 1.2 | 1.9 | 1.7 | 1.3 | 0.9 | 0.8 | 0.7 | 0.7 | 0.8 | 0.8 | 0.9 | 1.0 | 0.9 | 0.8 | 0.9 | 1.0 | 1.0 | 1.9 | 0.7 |
| 4 | -- | 0.8 | 0.8 | 0.9 | 0.8 | 0.7 | 0.6 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.9 | 1.0 | 0.9 | 0.9 | 0.8 | 0.9 | 0.9 | 0.8 | 0.7 | 0.6 | 0.6 | 0.7 | 0.8 | 1.0 | 0.6 |
| 5 | -- | 0.6 | 0.6 | 0.6 | 0.6 | 0.6 | 0.6 | 0.6 | 0.5 | 0.5 | 0.6 | 0.6 | 0.7 | 0.6 | 0.6 | 0.6 | 0.6 | 0.6 | 0.5 | 0.6 | 0.7 | 0.6 | 0.7 | 0.8 | 0.6 | 0.8 | 0.5 |
| 6 | -- | 0.6 | 0.6 | 0.7 | 0.6 | 1.0 | 0.8 | 1.0 | 0.7 | 1.0 | 2.2 | 0.9 | 0.7 | 0.7 | 0.7 | 0.6 | 0.6 | 0.6 | 0.6 | 0.7 | 0.7 | 1.0 | 1.0 | 2.4 | 0.9 | 2.4 | 0.6 |
| 7 | -- | 3.9 | 4.3 | 3.5 | 2.0 | 0.9 | 0.7 | 0.8 | 0.8 | 0.7 | 0.6 | 0.6 | 0.6 | 0.7 | 0.8 | 1.2 | 0.9 | 0.8 | 0.7 | 0.7 | 0.6 | 0.6 | 0.8 | 0.9 | 1.2 | 4.3 | 0.6 |
| 8 | -- | 0.9 | 0.7 | 0.9 | 2.1 | 1.3 | 0.7 | 1.2 | 1.7 | 4.3 | 1.8 | 1.8 | 1.0 | 0.9 | 0.8 | 0.9 | 0.8 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 1.0 | 1.3 | 1.2 | 4.3 | 0.7 |
| 9 | -- | 0.8 | 0.7 | 1.1 | 1.1 | 1.4 | 1.2 | 1.3 | 1.5 | -- | -- | -- | -- | -- | -- | -- | -- | 0.9 | 0.9 | 0.9 | 0.7 | 0.8 | 0.8 | 1.1 | -- | -- | -- |
| 10 | -- | 0.8 | 0.8 | 0.7 | 0.7 | 0.6 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.6 | 0.7 | 0.7 | 0.6 | 0.6 | 0.7 | 0.7 | 0.6 | 0.7 | 0.7 | 0.7 | 0.7 | 0.8 | 0.7 | 0.8 | 0.6 |
| 11 | -- | 0.7 | 0.8 | 0.7 | 0.7 | 0.7 | 0.6 | 0.6 | 0.8 | 0.8 | 0.7 | 0.7 | 1.2 | 1.5 | 1.6 | 1.7 | 1.6 | 1.5 | 1.4 | 1.2 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 1.7 | 0.6 |
| 12 | -- | 0.9 | 0.8 | 0.9 | 0.7 | 0.8 | 1.8 | 5.5 | 8.3 | 2.7 | 1.0 | 1.0 | 1.4 | 1.7 | 1.9 | 1.8 | 2.0 | 1.6 | 1.1 | 1.0 | 0.9 | 0.7 | 0.8 | 1.0 | 1.8 | 8.3 | 0.7 |
| 13 | -- | 0.8 | 0.8 | 0.9 | 0.9 | 1.5 | 2.6 | 2.5 | 1.8 | 2.5 | 2.0 | 0.8 | 0.6 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 0.9 | 1.0 | 1.2 | 2.6 | 0.6 |
| 14 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.7 | 0.7 | 0.6 | 0.8 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 0.7 | 0.7 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.9 | 0.8 | 0.9 | 0.6 |
| 15 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 1.1 | 1.6 | 2.2 | 2.6 | 3.2 | 2.6 | 2.7 | 1.1 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.9 | 1.3 | 3.2 | 0.8 |
| 16 | -- | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 0.6 | 0.7 | 0.8 | 0.9 | 0.9 | 0.8 | 0.9 | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 0.8 | 0.9 | 0.8 | 0.9 | 0.6 |
| 17 | -- | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.7 | 0.8 | 2.4 | 4.9 | 3.1 | 3.9 | 4.1 | 3.3 | 2.5 | 1.8 | 1.1 | 1.0 | 1.0 | 0.9 | 0.9 | 0.9 | 1.7 | 4.9 | 0.7 |
| 18 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | -- | 0.9 | 0.9 | 0.9 | 1.4 | 1.8 | 1.5 | 1.0 | 0.8 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 1.1 | 0.9 | 1.8 | 0.8 |
| 19 | -- | 0.8 | 0.9 | 0.9 | 1.0 | 1.1 | 1.0 | 0.9 | 1.3 | 2.9 | 2.3 | 1.2 | 1.2 | 1.1 | 1.1 | 1.3 | 1.3 | 1.1 | 1.0 | 0.9 | 0.8 | 1.0 | 0.9 | 1.0 | 1.2 | 2.9 | 0.8 |
| 20 | -- | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.4 | 3.0 | 3.3 | 3.0 | 1.3 | 1.1 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 0.9 | 0.9 | 1.1 | 1.3 | 3.3 | 0.8 |
| 21 | -- | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.9 | 1.4 | 2.0 | 1.9 | 3.0 | 2.5 | 3.0 | 2.1 | 1.7 | 1.4 | 1.2 | 1.2 | 1.2 | 1.2 | 1.1 | 1.0 | 1.4 | 3.0 | 0.8 |
| 22 | -- | 1.0 | 0.9 | 1.0 | 2.3 | 4.2 | 2.7 | 1.4 | 1.3 | 0.8 | 0.8 | 0.9 | 0.9 | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 1.1 | 1.0 | 1.2 | 4.2 | 0.8 |
| 23 | -- | 1.2 | 0.9 | 0.9 | 0.9 | 0.9 | 1.1 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 0.9 | 1.2 | 1.2 | 1.0 | 1.2 | 0.9 |
| 24 | -- | 0.9 | 1.3 | 1.3 | 1.2 | 1.0 | 0.9 | 0.9 | 0.8 | 1.0 | 1.0 | 1.2 | 1.4 | 1.1 | 1.4 | 1.2 | 1.2 | 1.2 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.4 | 0.8 |
| 25 | -- | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 1.0 | 1.1 | 1.7 | 2.4 | 1.4 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.9 | 0.8 | 0.8 | 0.9 | 1.0 | 2.4 | 0.8 |
| 26 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 0.8 | 0.7 | 0.7 | 0.7 | 0.8 | 1.3 | 1.0 | 1.1 | 0.9 | 0.9 | 1.0 | 1.0 | 0.9 | 0.9 | 1.0 | 2.4 | 1.6 | 1.6 | 1.0 | 2.4 | 0.7 |
| 27 | -- | 2.6 | 2.0 | 1.0 | 0.9 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 0.9 | 1.1 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 0.8 | 0.9 | 1.0 | 0.9 | 0.9 | 1.0 | 2.6 | 0.7 |
| 28 | -- | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 1.0 | 1.2 | 1.2 | 1.1 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 1.2 | 0.8 |
| 29 | -- | 0.8 | 1.0 | 1.2 | 1.0 | 1.0 | 1.2 | 1.2 | 1.0 | 0.9 | 0.9 | 0.6 | 0.8 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 0.8 | 0.8 | 0.8 | 0.9 | 0.8 | 0.9 | 0.9 | 1.2 | 0.6 |
| 30 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.6 | 0.8 | 0.8 | 1.0 | 0.9 | 0.8 | 0.8 | 0.9 | 0.8 | -- | 0.7 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 0.8 | 1.0 | 0.6 |
| 31 | -- | 0.9 | 0.7 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 1.0 | 1.0 | 1.4 | 1.1 | 1.2 | 1.1 | 1.0 | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.4 | 0.7 |
| Avg | -- | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.1 | 1.2 | 1.2 | 1.2 | 1.2 | 1.3 | 1.2 | 1.1 | 1.0 | 1.0 | 0.9 | 0.9 | 0.8 | 0.9 | 0.9 | 1.0 | 1.0 | -- | -- |
| Max | -- | 3.9 | 4.3 | 3.5 | 2.3 | 4.2 | 2.7 | 5.5 | 8.3 | 4.3 | 3.0 | 4.9 | 3.1 | 3.9 | 4.1 | 3.3 | 2.5 | 1.8 | 1.4 | 1.2 | 1.2 | 2.4 | 1.6 | 2.4 | -- | 8.3 | -- |
| Min | -- | -1.3 | -1.3 | -1.3 | -1.4 | -1.3 | -1.3 | -1.4 | -1.4 | -1.3 | -1.2 | -1.2 | 0.6 | 0.6 | 0.6 | 0.6 | 0.6 | 0.6 | 0.5 | 0.6 | 0.6 | 0.6 | 0.6 | 0.7 | -- | -- | -1.4 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, SO2_ppb"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | -- | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 0.8 | 0.8 | 0.8 | 0.7 | 0.8 | 0.8 | 1.1 | 1.2 | 1.1 | 1.1 | 1.0 | 1.6 | 3.3 | 1.3 | 2.5 | 3.8 | 1.2 | 3.8 | 0.7 |
| 2 | -- | 1.4 | 1.3 | 2.5 | 6.0 | 3.5 | 2.2 | 2.5 | 2.0 | 1.0 | 0.8 | 0.8 | 0.8 | 0.9 | 1.0 | 1.1 | 1.2 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.1 | 1.6 | 6.0 | 0.8 |
| 3 | -- | 0.9 | 2.2 | 2.3 | 6.5 | 5.6 | 2.9 | 1.5 | 1.1 | 1.1 | 1.9 | 2.7 | 1.5 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 0.9 | 0.9 | 1.8 | 6.5 | 0.9 |
| 4 | 0.8 | -- | 0.9 | 0.9 | 1.2 | 1.6 | 2.4 | 2.2 | 1.4 | 1.5 | 1.2 | 1.3 | 1.1 | 0.9 | 1.0 | 1.0 | 1.0 | 1.1 | 1.0 | 1.1 | 1.1 | 1.0 | 1.0 | 0.9 | 1.2 | 2.4 | 0.8 |
| 5 | 1.0 | -- | 0.8 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.9 | 0.8 | 0.9 | 0.8 | 0.8 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 1.2 | 1.0 | 0.8 | 0.9 | 1.2 | 0.8 |
| 6 | 0.9 | -- | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 1.0 | 1.1 | 0.7 | 0.8 | 1.9 | 2.5 | 1.1 | 0.8 | 0.7 | 0.7 | 0.8 | 0.7 | 0.8 | 3.6 | 6.0 | 2.2 | 1.1 | 1.4 | 6.0 | 0.7 |
| 7 | 1.4 | -- | 2.9 | 2.9 | 3.1 | 4.0 | 2.1 | 2.1 | 2.4 | 1.0 | 0.7 | 0.7 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 1.5 | 1.3 | 0.9 | 1.5 | 4.0 | 0.7 |
| 8 | 1.0 | -- | 0.8 | 0.9 | 0.8 | 0.8 | 0.9 | 1.2 | 1.5 | 1.2 | 0.9 | 0.8 | 0.9 | 1.0 | 1.0 | 1.1 | 1.0 | 0.9 | 0.8 | 0.9 | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 1.5 | 0.8 |
| 9 | 1.2 | -- | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 1.1 | 1.2 | 0.9 | 0.9 | 1.1 | 1.2 | 1.2 | 1.0 | 1.0 | 1.1 | 1.0 | 0.9 | 0.9 | 0.9 | 0.6 | 1.0 | 1.2 | 0.6 |
| 10 | 1.3 | -- | 0.9 | 0.9 | 0.8 | 0.9 | 0.8 | 0.9 | 0.8 | 1.3 | 2.2 | 3.3 | 2.7 | 2.8 | 2.0 | 1.5 | 3.0 | 6.8 | 1.7 | 2.5 | 1.3 | 1.0 | 1.0 | 1.0 | 1.8 | 6.8 | 0.8 |
| 11 | 1.1 | -- | 0.9 | 0.9 | 1.0 | 1.2 | 2.0 | 2.7 | 2.5 | 1.7 | 2.0 | 2.5 | 1.8 | 1.1 | 0.9 | 0.9 | 1.3 | 2.2 | 1.9 | 1.1 | 1.0 | 0.9 | 1.0 | 1.2 | 1.5 | 2.7 | 0.9 |
| 12 | 1.1 | -- | 1.2 | 2.8 | 1.3 | 1.2 | 2.0 | 3.6 | 1.6 | 2.9 | 3.2 | 0.9 | 0.8 | 0.8 | 0.7 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.8 | 1.4 | 3.6 | 0.7 |
| 13 | 0.9 | -- | 0.7 | 0.7 | 0.8 | 0.8 | 0.7 | 0.8 | 0.8 | 0.8 | 0.8 | 0.8 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 0.9 | 0.9 | 0.8 | 0.9 | 0.8 | 0.9 | 0.8 | 0.8 | 0.9 | 0.7 |
| 14 | 0.9 | -- | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.5 | 1.9 | 2.4 | 1.1 | 1.0 | 1.2 | 1.3 | 1.3 | 1.4 | 1.4 | 1.4 | 1.3 | 1.2 | 1.2 | 1.2 | 1.1 | 1.2 | 2.4 | 0.8 |
| 15 | 1.2 | -- | 1.5 | 4.1 | 5.3 | 4.9 | 6.6 | 7.3 | 1.9 | 1.8 | 1.6 | 2.0 | 2.3 | 1.2 | -- | 1.2 | 1.1 | 1.1 | 1.2 | 1.1 | 1.2 | 1.1 | 1.0 | 1.0 | 2.4 | 7.3 | 1.0 |
| 16 | 1.1 | -- | 0.9 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 1.0 | 0.9 | 1.0 | 1.0 | 0.9 | 0.9 | 1.0 | 1.1 | 0.9 |
| 17 | 1.0 | -- | 0.9 | 0.9 | 0.9 | 0.7 | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 1.1 | 1.4 | 1.8 | 1.7 | 1.4 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.1 | 2.5 | 1.1 | 2.5 | 0.7 |
| 18 | 2.9 | -- | 1.2 | 1.1 | 1.1 | 1.1 | 1.0 | 1.3 | 2.2 | 3.5 | 2.7 | 2.8 | 2.3 | 1.0 | 1.2 | 1.4 | 1.4 | 1.2 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.6 | 3.5 | 1.0 |
| 19 | -- | 1.1 | 1.1 | 1.1 | 1.0 | 1.0 | 1.0 | 1.1 | 1.1 | 1.6 | 2.9 | 1.6 | 1.5 | 3.7 | 1.9 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.0 | 1.0 | 1.0 | 1.4 | 3.7 | 1.0 |
| 20 | -- | 1.0 | 1.0 | 1.0 | 1.1 | 1.1 | 1.0 | 1.1 | 1.1 | 1.4 | 1.7 | 5.9 | 4.1 | 1.8 | 1.2 | 1.1 | 1.0 | 1.0 | 1.1 | 1.1 | 1.0 | 1.1 | 1.0 | 1.0 | 1.5 | 5.9 | 1.0 |
| 21 | -- | 1.3 | 1.2 | 1.2 | 1.2 | 1.2 | 1.1 | 1.1 | 1.1 | 4.4 | 3.9 | 4.6 | 1.9 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 | 1.4 | 1.2 | 1.1 | 1.0 | 1.0 | 1.0 | 1.6 | 4.6 | 1.0 |
| 22 | -- | 1.0 | 1.0 | 1.0 | 1.1 | 1.5 | 2.2 | 1.9 | 1.2 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 0.9 | 0.9 | 1.0 | 1.1 | 2.2 | 0.9 |
| 23 | -- | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 0.9 | 0.8 | 0.9 | 1.0 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.9 | 1.0 | 0.8 |
| 24 | -- | 0.9 | 0.9 | 0.8 | 0.8 | 0.8 | 0.9 | 0.9 | 0.8 | 0.9 | 0.8 | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 0.9 | 0.8 | 0.9 | 0.9 | 1.0 | 0.8 |
| 25 | -- | 0.9 | 1.1 | 1.7 | 1.2 | 1.4 | 1.3 | 1.3 | 1.2 | 1.2 | 1.4 | 1.4 | 0.8 | 0.9 | 1.1 | 0.9 | 1.0 | 1.0 | 1.0 | 1.1 | 1.0 | 1.6 | 2.7 | 1.6 | 1.3 | 2.7 | 0.8 |
| 26 | -- | 4.6 | 7.7 | 3.8 | 3.8 | 3.4 | 2.5 | 1.7 | 1.8 | 1.1 | 1.0 | 0.8 | 0.9 | 0.9 | 0.9 | 0.7 | 1.3 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 0.8 | 0.9 | 1.9 | 7.7 | 0.7 |
| 27 | -- | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | -- | 0.8 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 0.8 |
| 28 | -- | 0.9 | 1.0 | 1.0 | 0.9 | 1.0 | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 0.8 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.4 | 1.1 | 1.0 | 1.1 | 1.0 | 1.4 | 0.8 |
| 29 | -- | 1.0 | 0.9 | 0.9 | 0.8 | 1.0 | 1.0 | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 1.1 | 1.1 | 1.0 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.1 | 1.3 | 1.0 | 1.3 | 0.8 |
| 30 | -- | 2.5 | 2.1 | 2.3 | 2.3 | 2.2 | 2.8 | 2.8 | 2.1 | 2.3 | 1.8 | 2.1 | 1.8 | 1.3 | 1.1 | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 1.0 | 1.0 | 1.7 | 2.8 | 0.9 |
| Avg | 1.2 | 1.3 | 1.3 | 1.4 | 1.7 | 1.6 | 1.5 | 1.6 | 1.3 | 1.4 | 1.5 | 1.6 | 1.4 | 1.2 | 1.1 | 1.0 | 1.1 | 1.2 | 1.1 | 1.1 | 1.2 | 1.2 | 1.1 | 1.1 | 1.3 | -- | -- |
| Max | 2.9 | 4.6 | 7.7 | 4.1 | 6.5 | 5.6 | 6.6 | 7.3 | 2.5 | 4.4 | 3.9 | 5.9 | 4.1 | 3.7 | 2.0 | 1.5 | 3.0 | 6.8 | 1.9 | 2.5 | 3.6 | 6.0 | 2.7 | 3.8 | -- | 7.7 | -- |
| Min | 0.8 | 0.8 | 0.7 | 0.7 | 0.8 | 0.7 | 0.7 | 0.8 | 0.8 | 0.7 | 0.7 | 0.7 | 0.8 | 0.8 | 0.7 | 0.7 | 0.7 | 0.8 | 0.7 | 0.8 | 0.8 | 0.8 | 0.8 | 0.6 | -- | -- | 0.6 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, SO2_ppb"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | -- | 2.0 | 1.8 | 1.3 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.1 | 1.0 | 1.2 | 1.0 | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.1 | 2.0 | 0.9 |
| 2 | -- | 0.9 | 0.8 | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 1.0 | 1.1 | 1.4 | 1.8 | 1.8 | 2.2 | 2.9 | 2.6 | 2.3 | 2.0 | 1.9 | 1.9 | 1.4 | 2.9 | 0.8 |
| 3 | -- | 1.3 | 1.3 | 1.2 | 1.4 | 1.3 | 1.2 | 1.1 | 1.4 | 1.7 | 2.2 | 3.2 | 4.1 | 2.4 | 1.4 | 1.2 | 0.9 | 0.8 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.1 | 1.5 | 4.1 | 0.8 |
| 4 | -- | 1.3 | 1.3 | 1.2 | 1.2 | 1.0 | 1.2 | 1.4 | 1.4 | 1.3 | 1.1 | 1.1 | 1.1 | 1.0 | 1.1 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.1 | 1.4 | 1.0 |
| 5 | -- | 1.0 | 1.0 | 1.1 | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.1 | 0.9 | 1.0 | 1.1 | 1.1 | 1.0 | 1.1 | 0.9 |
| 6 | -- | 1.0 | 1.0 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | 0.8 | 1.6 | 1.4 | 1.4 | 1.7 | 2.0 | 1.9 | 1.2 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.2 | 1.2 | 2.0 | 0.8 |
| 7 | -- | 1.1 | 1.0 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.1 | 1.2 | 5.4 | 7.7 | 7.6 | 2.3 | 1.6 | 1.1 | 1.1 | 1.1 | 1.0 | 1.0 | 1.1 | 1.1 | 0.9 | 1.0 | 1.9 | 7.7 | 0.9 |
| 8 | -- | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 1.0 | 1.0 | 1.0 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.0 | 1.1 | 0.9 |
| 9 | -- | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 1.0 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 1.0 | 1.0 | 1.0 | 0.9 | 0.9 | 1.0 | 1.0 | 1.1 | 0.9 |
| 10 | -- | 1.3 | 1.2 | 1.7 | 1.2 | 0.9 | 0.8 | 0.9 | 1.0 | 1.0 | 1.1 | 1.1 | 1.0 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.0 | 1.1 | 1.1 | 1.2 | 1.1 | 1.7 | 0.8 |
| 11 | -- | 1.1 | 1.2 | 1.1 | 1.2 | 1.1 | 1.1 | 1.1 | 1.2 | 1.3 | 1.1 | 0.9 | 0.9 | 1.0 | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 0.9 | 1.0 | 1.0 | 1.3 | 0.9 |
| 12 | -- | 0.9 | 0.9 | 0.9 | 1.0 | 1.0 | 1.0 | 1.0 | 0.9 | 0.9 | 0.9 | 1.0 | 0.9 | 1.0 | 0.7 | -- | 3.7 | 1.3 | 1.0 | 1.0 | 1.0 | 1.1 | 0.9 | 1.9 | 1.1 | 3.7 | 0.7 |
| 13 | -- | 1.2 | 1.2 | 1.1 | 1.2 | 1.1 | 1.1 | 1.2 | 1.1 | 1.3 | 1.2 | 1.2 | 1.1 | 1.3 | 1.4 | 1.3 | 1.3 | 1.4 | 1.4 | 1.3 | 1.3 | 1.3 | 1.2 | 1.3 | 1.2 | 1.4 | 1.1 |
| 14 | -- | 1.2 | 1.2 | 1.2 | 1.2 | 1.2 | 1.1 | 1.1 | 1.2 | 1.2 | 1.2 | 1.3 | 1.5 | 1.2 | 1.4 | 2.2 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.3 | 1.4 | 1.3 | 2.2 | 1.1 |
| 15 | -- | 1.1 | 1.3 | 2.0 | 1.5 | 1.4 | 1.2 | 1.6 | 2.3 | 3.8 | 3.6 | 3.4 | 2.8 | 3.5 | 2.6 | 2.2 | 3.6 | 3.0 | 4.3 | 2.4 | 1.1 | 1.1 | 1.1 | 1.2 | 2.3 | 4.3 | 1.1 |
| 16 | -- | 1.5 | 1.3 | 5.2 | 4.8 | 3.8 | 1.6 | 2.0 | 2.9 | 3.3 | 7.3 | 4.7 | 3.3 | 1.6 | 2.0 | 3.4 | 5.3 | 5.2 | 1.6 | 1.2 | 1.5 | 2.8 | 3.1 | 2.0 | 3.1 | 7.3 | 1.2 |
| 17 | -- | 1.3 | 1.2 | 1.2 | 1.3 | 1.5 | 1.5 | 1.5 | 1.4 | 1.4 | 3.3 | 3.3 | 6.1 | 3.4 | 1.7 | 1.3 | 1.3 | 2.2 | 5.1 | 2.1 | 3.6 | 3.6 | 3.4 | 4.1 | 2.5 | 6.1 | 1.2 |
| 18 | -- | 3.4 | 2.7 | 2.5 | 3.1 | 2.6 | 2.2 | 2.9 | 3.1 | 1.9 | 3.2 | 2.6 | 1.2 | 1.2 | 1.1 | 1.2 | 1.2 | 1.2 | 1.3 | 1.3 | 1.5 | 2.2 | 2.6 | 3.1 | 2.1 | 3.4 | 1.1 |
| 19 | -- | 3.4 | 2.7 | 2.2 | 1.9 | 1.6 | 1.6 | 1.7 | 1.7 | 1.7 | 1.8 | 1.5 | 1.4 | 1.3 | 1.5 | 1.3 | 1.3 | 1.4 | 1.5 | 1.5 | 1.5 | 1.4 | 1.3 | 1.4 | 1.7 | 3.4 | 1.3 |
| 20 | -- | 1.3 | 1.3 | 1.1 | 1.4 | 1.3 | 1.4 | 1.4 | 1.3 | 1.3 | 1.3 | 1.5 | 1.6 | -- | -- | 1.4 | 1.1 | 1.1 | 1.2 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.3 | 1.6 | 1.1 |
| 21 | -- | 1.1 | 1.2 | 1.2 | 1.0 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.2 | 1.1 | 1.2 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.1 | 1.1 | 1.1 | 1.1 | 1.2 | 1.1 | 1.2 | 1.0 |
| 22 | -- | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 1.0 | 1.0 | 1.0 | 1.2 | 1.7 | 1.7 | 1.5 | 2.4 | 2.0 | 1.4 | 1.2 | 1.1 | 1.0 | 1.1 | 1.0 | 1.5 | 1.3 | 2.4 | 1.0 |
| 23 | -- | 1.1 | 1.8 | 4.6 | 2.0 | 1.4 | 1.1 | 1.5 | 3.4 | 2.5 | 2.8 | 2.3 | 1.2 | 1.0 | 1.1 | 1.1 | 1.0 | 1.0 | 1.6 | 3.5 | 3.2 | 4.4 | 4.1 | 3.4 | 2.2 | 4.6 | 1.0 |
| 24 | -- | 3.1 | 3.6 | 3.3 | 3.0 | 2.7 | 2.4 | 1.6 | 2.2 | 3.2 | 1.5 | 1.1 | 1.1 | 1.1 | 1.1 | 1.0 | 1.0 | 1.0 | 1.8 | 2.5 | 7.9 | 5.9 | 2.7 | 1.3 | 2.4 | 7.9 | 1.0 |
| 25 | -- | 1.1 | 1.1 | 1.1 | 1.0 | 1.1 | 1.1 | 1.0 | 0.9 | 0.9 | 1.1 | 1.0 | 2.2 | 3.3 | 1.4 | 2.7 | 2.4 | 1.7 | 1.2 | 2.2 | 1.5 | 1.0 | 4.4 | 3.1 | 1.7 | 4.4 | 0.9 |
| 26 | -- | 3.4 | 3.1 | 1.9 | 1.9 | 3.1 | 2.6 | 1.6 | 1.8 | 1.2 | 0.9 | 0.8 | 1.1 | 1.0 | 1.0 | 1.0 | 1.0 | 1.0 | 1.1 | 2.0 | 2.4 | 1.8 | 1.4 | 2.1 | 1.7 | 3.4 | 0.8 |
| 27 | -- | 1.9 | 2.9 | 3.5 | 5.1 | 7.1 | 3.1 | 2.5 | 2.1 | 2.6 | 2.1 | -- | 1.0 | 1.2 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.1 | 1.4 | 2.4 | 1.5 | 1.5 | 2.2 | 7.1 | 1.0 |
| 28 | -- | 1.6 | 1.9 | 1.7 | 2.6 | 1.5 | 1.2 | 1.3 | 2.5 | 3.1 | 5.3 | 3.8 | 2.1 | 1.1 | 1.3 | 1.3 | 1.5 | 2.4 | 1.8 | 1.8 | 1.8 | 1.8 | 2.1 | 2.1 | 2.1 | 5.3 | 1.1 |
| 29 | -- | 2.7 | 3.3 | 3.3 | 3.9 | 2.7 | 3.0 | 2.6 | 1.7 | 1.4 | 1.5 | 1.6 | 1.6 | 1.6 | 1.6 | 1.5 | 1.4 | 1.4 | 1.4 | 1.4 | 1.3 | 1.3 | 1.3 | 1.3 | 2.0 | 3.9 | 1.3 |
| 30 | -- | 1.1 | 1.1 | 1.2 | 1.2 | 1.2 | 1.3 | 1.2 | 1.1 | 1.1 | 1.5 | 1.7 | 1.6 | 1.4 | 1.3 | 1.4 | 1.3 | 1.4 | 1.5 | 3.4 | 6.7 | 5.6 | 2.4 | 11.8 | 2.3 | 11.8 | 1.1 |
| 31 | -- | 3.8 | 2.6 | 2.4 | 7.4 | 16.8 | 17.2 | 10.3 | 7.5 | 5.8 | 2.5 | 1.4 | 1.3 | 1.3 | 1.2 | 1.3 | 1.3 | 1.3 | 1.3 | 1.3 | 1.2 | 1.2 | 1.2 | 1.3 | 4.0 | 17.2 | 1.2 |
| Avg | -- | 1.6 | 1.6 | 1.8 | 1.9 | 2.1 | 1.9 | 1.7 | 1.7 | 1.7 | 2.0 | 1.9 | 1.8 | 1.5 | 1.3 | 1.4 | 1.5 | 1.4 | 1.5 | 1.5 | 1.8 | 1.8 | 1.7 | 2.0 | 1.7 | -- | -- |
| Max | -- | 3.8 | 3.6 | 5.2 | 7.4 | 16.8 | 17.2 | 10.3 | 7.5 | 5.8 | 7.3 | 7.7 | 7.6 | 3.5 | 2.6 | 3.4 | 5.3 | 5.2 | 5.1 | 3.5 | 7.9 | 5.9 | 4.4 | 11.8 | -- | 17.2 | -- |
| Min | -- | 0.9 | 0.8 | 0.9 | 0.9 | 0.9 | 0.8 | 0.9 | 0.9 | 0.8 | 0.9 | 0.8 | 0.9 | 0.9 | 0.7 | 0.9 | 0.9 | 0.8 | 1.0 | 0.9 | 0.9 | 0.9 | 0.9 | 0.9 | -- | -- | 0.7 |

-- Indicates Invalid Data

## SAROAD for Resolution, East_Plant, rolling 8-hour average
## "Component, Channel: TableAmbient_Hourly, O3_ppm"
## Month: Oct 2013

### Hour of day

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.047 | 0.046 | 0.046 | 0.046 | 0.046 | 0.046 | 0.045 | 0.044 | 0.045 | 0.045 | 0.045 | 0.044 | 0.044 | 0.044 | 0.043 | 0.043 | 0.043 | 0.042 | 0.041 | 0.040 | 0.039 | 0.039 | 0.038 | 0.037 | 0.043 | 0.047 | 0.037 |
| 2 | 0.035 | 0.034 | 0.033 | 0.033 | 0.032 | 0.031 | 0.031 | 0.031 | 0.032 | 0.033 | 0.034 | 0.034 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.031 | 0.031 | 0.030 | 0.029 | 0.028 | 0.027 | 0.032 | 0.035 | 0.027 |
| 3 | 0.026 | 0.026 | 0.026 | 0.028 | 0.029 | 0.030 | 0.032 | 0.033 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.032 | 0.031 | 0.030 | 0.032 | 0.036 | 0.026 |
| 4 | 0.029 | 0.029 | 0.030 | 0.031 | 0.034 | 0.036 | 0.039 | 0.042 | 0.046 | 0.049 | 0.051 | 0.052 | 0.052 | 0.052 | 0.051 | 0.049 | 0.047 | 0.044 | 0.041 | 0.040 | 0.038 | 0.037 | 0.036 | 0.035 | 0.041 | 0.052 | 0.029 |
| 5 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.037 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.038 | 0.035 |
| 6 | 0.036 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.038 | 0.039 | 0.040 | 0.042 | 0.043 | 0.044 | 0.044 | 0.043 | 0.043 | 0.042 | 0.041 | 0.040 | 0.039 | 0.038 | 0.037 | 0.037 | 0.037 | 0.037 | 0.039 | 0.044 | 0.035 |
| 7 | 0.037 | 0.037 | 0.037 | 0.038 | 0.039 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.044 | 0.045 | 0.046 | 0.046 | 0.046 | 0.046 | 0.046 | 0.045 | 0.045 | 0.044 | 0.044 | 0.044 | 0.043 | 0.043 | 0.042 | 0.046 | 0.037 |
| 8 | 0.042 | 0.040 | 0.040 | 0.041 | 0.042 | 0.042 | 0.043 | 0.043 | 0.044 | 0.045 | 0.045 | 0.045 | 0.044 | 0.044 | 0.044 | 0.043 | 0.042 | 0.041 | 0.040 | 0.040 | 0.038 | 0.036 | 0.034 | 0.033 | 0.041 | 0.045 | 0.033 |
| 9 | 0.031 | 0.031 | 0.030 | 0.030 | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | -- | 0.038 | 0.038 | 0.035 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.033 | -- | -- | -- |
| 10 | 0.034 | 0.037 | 0.039 | 0.039 | 0.040 | 0.040 | 0.040 | 0.041 | 0.042 | 0.044 | 0.045 | 0.046 | 0.047 | 0.046 | 0.045 | 0.044 | 0.043 | 0.042 | 0.041 | 0.040 | 0.040 | 0.041 | 0.041 | 0.040 | 0.042 | 0.047 | 0.034 |
| 11 | 0.039 | 0.038 | 0.039 | 0.040 | 0.041 | 0.043 | 0.044 | 0.047 | 0.049 | 0.051 | 0.052 | 0.053 | 0.052 | 0.052 | 0.051 | 0.050 | 0.049 | 0.047 | 0.046 | 0.045 | 0.044 | 0.043 | 0.042 | 0.042 | 0.046 | 0.053 | 0.038 |
| 12 | 0.041 | 0.041 | 0.041 | 0.042 | 0.042 | 0.042 | 0.042 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.046 | 0.047 | 0.047 | 0.047 | 0.047 | 0.046 | 0.045 | 0.044 | 0.043 | 0.043 | 0.043 | 0.043 | 0.044 | 0.047 | 0.041 |
| 13 | 0.042 | 0.042 | 0.042 | 0.041 | 0.041 | 0.041 | 0.041 | 0.042 | 0.044 | 0.045 | 0.046 | 0.048 | 0.049 | 0.049 | 0.049 | 0.049 | 0.048 | 0.048 | 0.046 | 0.046 | 0.045 | 0.043 | 0.042 | 0.040 | 0.045 | 0.049 | 0.040 |
| 14 | 0.038 | 0.037 | 0.037 | 0.038 | 0.039 | 0.040 | 0.042 | 0.044 | 0.046 | 0.048 | 0.050 | 0.051 | 0.053 | 0.054 | 0.054 | 0.054 | 0.054 | 0.054 | 0.053 | 0.053 | 0.052 | 0.051 | 0.051 | 0.051 | 0.048 | 0.054 | 0.037 |
| 15 | 0.050 | 0.050 | 0.050 | 0.051 | 0.052 | 0.052 | 0.053 | 0.054 | 0.055 | 0.056 | 0.057 | 0.057 | 0.057 | 0.057 | 0.057 | 0.057 | 0.056 | 0.054 | 0.052 | 0.052 | 0.049 | 0.048 | 0.046 | 0.044 | 0.053 | 0.057 | 0.044 |
| 16 | 0.042 | 0.041 | 0.041 | 0.041 | 0.042 | 0.042 | 0.044 | 0.045 | 0.047 | 0.048 | 0.050 | 0.051 | 0.052 | 0.052 | 0.052 | 0.052 | 0.051 | 0.050 | 0.049 | 0.048 | 0.046 | 0.045 | 0.043 | 0.042 | 0.047 | 0.052 | 0.041 |
| 17 | 0.040 | 0.040 | 0.040 | 0.041 | 0.042 | 0.043 | 0.045 | 0.047 | 0.050 | 0.052 | 0.054 | 0.055 | 0.055 | 0.055 | 0.055 | 0.054 | 0.053 | 0.052 | 0.051 | 0.050 | 0.049 | 0.048 | 0.048 | 0.047 | 0.049 | 0.055 | 0.040 |
| 18 | 0.046 | 0.045 | 0.045 | 0.045 | 0.044 | 0.044 | 0.044 | 0.045 | 0.046 | 0.047 | 0.048 | 0.049 | 0.050 | 0.050 | 0.049 | 0.048 | 0.046 | 0.045 | 0.043 | 0.042 | 0.040 | 0.040 | 0.039 | 0.039 | 0.045 | 0.050 | 0.039 |
| 19 | 0.039 | 0.039 | 0.039 | 0.039 | 0.040 | 0.040 | 0.041 | 0.042 | 0.044 | 0.045 | 0.046 | 0.048 | 0.048 | 0.049 | 0.048 | 0.048 | 0.047 | 0.046 | 0.045 | 0.044 | 0.043 | 0.042 | 0.042 | 0.041 | 0.044 | 0.049 | 0.039 |
| 20 | 0.040 | 0.039 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.044 | 0.045 | 0.046 | 0.047 | 0.047 | 0.047 | 0.047 | 0.046 | 0.046 | 0.046 | 0.046 | 0.045 | 0.045 | 0.044 | 0.044 | 0.043 | 0.043 | 0.044 | 0.047 | 0.039 |
| 21 | 0.042 | 0.041 | 0.041 | 0.041 | 0.041 | 0.041 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.045 | 0.046 | 0.045 | 0.045 | 0.044 | 0.044 | 0.043 | 0.042 | 0.041 | 0.040 | 0.040 | 0.040 | 0.039 | 0.042 | 0.046 | 0.039 |
| 22 | 0.038 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.044 | 0.044 | 0.044 | 0.043 | 0.043 | 0.042 | 0.042 | 0.041 | 0.041 | 0.041 | 0.041 | 0.041 | 0.042 | 0.041 | 0.044 | 0.037 |
| 23 | 0.042 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.045 | 0.046 | 0.046 | 0.046 | 0.046 | 0.046 | 0.046 | 0.045 | 0.045 | 0.044 | 0.043 | 0.041 | 0.040 | 0.040 | 0.038 | 0.037 | 0.036 | 0.035 | 0.043 | 0.046 | 0.035 |
| 24 | 0.035 | 0.035 | 0.035 | 0.036 | 0.037 | 0.038 | 0.039 | 0.040 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.045 | 0.044 | 0.043 | 0.042 | 0.041 | 0.040 | 0.040 | 0.039 | 0.039 | 0.039 | 0.038 | 0.040 | 0.045 | 0.035 |
| 25 | 0.038 | 0.036 | 0.036 | 0.037 | 0.036 | 0.037 | 0.037 | 0.038 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.037 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.039 | 0.036 |
| 26 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.039 | 0.040 | 0.040 | 0.041 | 0.042 | 0.042 | 0.041 | 0.040 | 0.040 | 0.039 | 0.038 | 0.037 | 0.036 | 0.035 | 0.035 | 0.035 | 0.034 | 0.038 | 0.042 | 0.034 |
| 27 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.037 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.044 | 0.045 | 0.046 | 0.046 | 0.046 | 0.046 | 0.045 | 0.045 | 0.045 | 0.044 | 0.043 | 0.043 | 0.041 | 0.046 | 0.034 |
| 28 | 0.043 | 0.042 | 0.041 | 0.040 | 0.039 | 0.038 | 0.036 | 0.035 | 0.033 | 0.032 | 0.030 | 0.029 | 0.027 | 0.026 | 0.025 | 0.024 | 0.022 | 0.021 | 0.020 | 0.020 | 0.019 | 0.019 | 0.019 | 0.019 | 0.029 | 0.043 | 0.019 |
| 29 | 0.019 | 0.019 | 0.020 | 0.020 | 0.020 | 0.021 | 0.022 | 0.023 | 0.024 | 0.026 | 0.027 | 0.029 | 0.031 | 0.032 | 0.033 | 0.033 | 0.033 | 0.033 | 0.032 | 0.032 | 0.031 | 0.031 | 0.030 | 0.030 | 0.027 | 0.033 | 0.019 |
| 30 | 0.030 | 0.031 | 0.032 | 0.032 | 0.033 | 0.035 | 0.036 | 0.037 | 0.038 | 0.040 | 0.040 | 0.041 | 0.042 | 0.042 | 0.041 | 0.041 | 0.041 | 0.040 | 0.039 | 0.039 | 0.038 | 0.038 | 0.037 | 0.036 | 0.038 | 0.042 | 0.030 |
| 31 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.037 | 0.038 | 0.040 | 0.041 | 0.042 | 0.043 | 0.044 | 0.044 | 0.043 | 0.042 | 0.042 | 0.041 | 0.040 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.037 | 0.039 | 0.044 | 0.035 |
| Avg | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.045 | 0.044 | 0.044 | 0.043 | 0.042 | 0.041 | 0.040 | 0.040 | 0.039 | 0.038 | 0.038 | 0.041 | -- | -- |
| Max | 0.050 | 0.050 | 0.050 | 0.051 | 0.052 | 0.052 | 0.053 | 0.054 | 0.055 | 0.056 | 0.057 | 0.057 | 0.057 | 0.057 | 0.057 | 0.057 | 0.056 | 0.054 | 0.053 | 0.053 | 0.052 | 0.051 | 0.051 | 0.051 | -- | 0.057 | -- |
| Min | 0.019 | 0.019 | 0.020 | 0.020 | 0.020 | 0.021 | 0.022 | 0.023 | 0.024 | 0.026 | 0.027 | 0.029 | 0.027 | 0.026 | 0.025 | 0.024 | 0.022 | 0.021 | 0.020 | 0.020 | 0.019 | 0.019 | 0.019 | 0.019 | – | -- | 0.019 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant, rolling 8-hour average**
**"Component, Channel: TableAmbient_Hourly, O3_ppm"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.039 | 0.041 | 0.041 | 0.041 | 0.041 | 0.040 | 0.039 | 0.039 | 0.038 | 0.036 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.041 | 0.035 |
| 2 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.039 | 0.040 | 0.041 | 0.041 | 0.042 | 0.042 | 0.042 | 0.041 | 0.041 | 0.041 | 0.040 | 0.040 | 0.039 | 0.039 | 0.038 | 0.036 | 0.034 | 0.032 | 0.039 | 0.042 | 0.032 |
| 3 | 0.030 | 0.029 | 0.028 | 0.028 | 0.027 | 0.027 | 0.028 | 0.028 | 0.028 | 0.029 | 0.030 | 0.030 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.030 | 0.030 | 0.030 | 0.031 | 0.027 |
| 4 | 0.029 | 0.028 | 0.027 | 0.027 | 0.027 | 0.027 | 0.027 | 0.028 | 0.029 | 0.030 | 0.030 | 0.031 | 0.031 | 0.032 | 0.032 | 0.032 | 0.032 | 0.031 | 0.031 | 0.029 | 0.029 | 0.028 | 0.027 | 0.027 | 0.029 | 0.032 | 0.027 |
| 5 | 0.027 | 0.027 | 0.028 | 0.030 | 0.031 | 0.033 | 0.035 | 0.035 | 0.037 | 0.038 | 0.039 | 0.040 | 0.040 | 0.040 | 0.040 | 0.039 | 0.039 | 0.038 | 0.037 | 0.036 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.040 | 0.027 |
| 6 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.038 | 0.039 | 0.039 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.038 | 0.040 | 0.035 |
| 7 | 0.035 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.037 | 0.038 | 0.039 | 0.040 | 0.041 | 0.041 | 0.040 | 0.040 | 0.039 | 0.038 | 0.037 | 0.036 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.036 | 0.041 | 0.033 |
| 8 | 0.033 | 0.033 | 0.033 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.037 | 0.038 | 0.039 | 0.039 | 0.040 | 0.040 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.040 | 0.033 |
| 9 | 0.035 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.037 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.039 | 0.034 |
| 10 | 0.034 | 0.033 | 0.033 | 0.033 | 0.033 | 0.033 | 0.033 | 0.034 | 0.035 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.036 | 0.035 | 0.034 | 0.034 | 0.033 | 0.032 | 0.032 | 0.032 | 0.032 | 0.031 | 0.034 | 0.037 | 0.031 |
| 11 | 0.031 | 0.031 | 0.031 | 0.032 | 0.032 | 0.033 | 0.034 | 0.035 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.037 | 0.031 |
| 12 | 0.035 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.035 | 0.034 | 0.033 | 0.033 | 0.032 | 0.032 | 0.031 | 0.030 | 0.035 | 0.037 | 0.030 |
| 13 | 0.030 | 0.030 | 0.030 | 0.030 | 0.030 | 0.030 | 0.030 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.030 | 0.030 | 0.029 | 0.029 | 0.029 | 0.029 | 0.030 | 0.031 | 0.029 |
| 14 | 0.029 | 0.029 | 0.030 | 0.031 | 0.031 | 0.032 | 0.034 | 0.035 | 0.037 | 0.039 | 0.040 | 0.041 | 0.042 | 0.042 | 0.041 | 0.041 | 0.040 | 0.040 | 0.039 | 0.038 | 0.038 | 0.037 | 0.036 | 0.035 | 0.037 | 0.042 | 0.029 |
| 15 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.038 | 0.037 | 0.036 | 0.035 | 0.034 | 0.033 | 0.031 | 0.031 | 0.030 | 0.030 | 0.029 | 0.029 | 0.029 | 0.029 | 0.030 | 0.030 | 0.033 | 0.038 | 0.029 |
| 16 | 0.031 | 0.031 | 0.032 | 0.033 | 0.033 | 0.033 | 0.034 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.034 | 0.034 | 0.035 | 0.038 | 0.031 |
| 17 | 0.033 | 0.033 | 0.032 | 0.032 | 0.032 | 0.032 | 0.033 | 0.033 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.031 | 0.031 | 0.033 | 0.034 | 0.031 |
| 18 | 0.030 | 0.030 | 0.030 | 0.031 | 0.031 | 0.031 | 0.032 | 0.033 | 0.034 | 0.034 | 0.035 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.033 | 0.033 | 0.032 | 0.033 | 0.036 | 0.030 |
| 19 | 0.031 | 0.030 | 0.030 | 0.030 | 0.031 | 0.032 | 0.032 | 0.034 | 0.036 | 0.038 | 0.039 | 0.040 | 0.041 | 0.041 | 0.042 | 0.041 | 0.040 | 0.039 | 0.038 | 0.038 | 0.037 | 0.035 | 0.034 | 0.033 | 0.036 | 0.042 | 0.030 |
| 20 | 0.032 | 0.031 | 0.031 | 0.031 | 0.032 | 0.032 | 0.033 | 0.035 | 0.036 | 0.038 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.040 | 0.039 | 0.038 | 0.037 | 0.040 | 0.031 |
| 21 | 0.037 | 0.036 | 0.035 | 0.035 | 0.035 | 0.034 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.034 | 0.033 | 0.032 | 0.031 | 0.030 | 0.029 | 0.028 | 0.027 | 0.027 | 0.027 | 0.033 | 0.037 | 0.027 |
| 22 | 0.026 | 0.026 | 0.025 | 0.025 | 0.027 | 0.028 | 0.029 | 0.031 | 0.033 | 0.034 | 0.035 | 0.036 | 0.036 | 0.035 | 0.034 | 0.033 | 0.033 | 0.032 | 0.030 | 0.029 | 0.028 | 0.026 | 0.025 | 0.024 | 0.030 | 0.036 | 0.024 |
| 23 | 0.022 | 0.022 | 0.022 | 0.022 | 0.022 | 0.022 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.024 | 0.024 | 0.024 | 0.024 | 0.024 | 0.024 | 0.025 | 0.025 | 0.025 | 0.025 | 0.025 | 0.025 | 0.023 | 0.025 | 0.022 |
| 24 | 0.026 | 0.026 | 0.026 | 0.026 | 0.026 | 0.027 | 0.027 | 0.027 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.028 | 0.027 | 0.027 | 0.026 | 0.026 | 0.025 | 0.027 | 0.028 | 0.025 |
| 25 | 0.025 | 0.024 | 0.024 | 0.024 | 0.024 | 0.025 | 0.026 | 0.027 | 0.028 | 0.029 | 0.030 | 0.030 | 0.030 | 0.030 | 0.029 | 0.029 | 0.029 | 0.028 | 0.028 | 0.028 | 0.028 | 0.029 | 0.029 | 0.028 | 0.028 | 0.030 | 0.024 |
| 26 | 0.028 | 0.028 | 0.027 | 0.027 | 0.027 | 0.028 | 0.029 | 0.030 | 0.032 | 0.033 | 0.035 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.033 | 0.037 | 0.027 |
| 27 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.038 | 0.035 |
| 28 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.035 | 0.036 | 0.033 |
| 29 | 0.032 | 0.032 | 0.032 | 0.031 | 0.032 | 0.032 | 0.032 | 0.033 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.032 | 0.032 | 0.032 | 0.033 | 0.036 | 0.031 |
| 30 | 0.032 | 0.031 | 0.031 | 0.031 | 0.030 | 0.030 | 0.030 | 0.030 | 0.030 | 0.030 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.030 | 0.029 | 0.028 | 0.027 | 0.026 | 0.029 | 0.032 | 0.026 |
| Avg | 0.032 | 0.031 | 0.031 | 0.031 | 0.032 | 0.032 | 0.033 | 0.033 | 0.034 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.032 | 0.032 | 0.033 | -- | -- |
| Max | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.038 | 0.039 | 0.040 | 0.041 | 0.041 | 0.042 | 0.042 | 0.042 | 0.042 | 0.042 | 0.041 | 0.040 | 0.040 | 0.039 | 0.039 | 0.039 | 0.040 | 0.039 | 0.038 | -- | 0.042 | -- |
| Min | 0.022 | 0.022 | 0.022 | 0.022 | 0.022 | 0.022 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.024 | 0.024 | 0.024 | 0.024 | 0.024 | 0.024 | 0.025 | 0.025 | 0.025 | 0.025 | 0.025 | 0.024 | -- | -- | 0.022 |

**SAROAD for Resolution, East_Plant, rolling 8-hour average**
**"Component, Channel: TableAmbient_Hourly, O3_ppm"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.025 | 0.024 | 0.023 | 0.024 | 0.024 | 0.024 | 0.025 | 0.027 | 0.028 | 0.030 | 0.030 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.030 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.029 | 0.028 | 0.031 | 0.023 |
| 2 | 0.029 | 0.029 | 0.029 | 0.029 | 0.030 | 0.031 | 0.031 | 0.032 | 0.033 | 0.034 | 0.035 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.033 | 0.036 | 0.029 |
| 3 | 0.035 | 0.035 | 0.034 | 0.035 | 0.036 | 0.037 | 0.037 | 0.038 | 0.039 | 0.039 | 0.040 | 0.039 | 0.039 | 0.038 | 0.037 | 0.036 | 0.035 | 0.034 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.034 | 0.036 | 0.040 | 0.033 |
| 4 | 0.034 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.035 | 0.034 | 0.033 | 0.032 | 0.032 | 0.031 | 0.031 | 0.032 | 0.031 | 0.033 | 0.034 | 0.035 | 0.035 | 0.034 | 0.037 | 0.031 |
| 5 | 0.036 | 0.036 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.039 | 0.040 | 0.041 | 0.041 | 0.040 | 0.040 | 0.039 | 0.038 | 0.037 | 0.036 | 0.035 | 0.035 | 0.036 | 0.036 | 0.035 | 0.035 | 0.037 | 0.041 | 0.035 |
| 6 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.035 | 0.036 | 0.038 | 0.039 | 0.041 | 0.042 | 0.042 | 0.042 | 0.041 | 0.041 | 0.040 | 0.039 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.042 | 0.034 |
| 7 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.039 | 0.039 | 0.040 | 0.040 | 0.041 | 0.042 | 0.042 | 0.042 | 0.042 | 0.042 | 0.041 | 0.041 | 0.040 | 0.040 | 0.040 | 0.040 | 0.039 | 0.039 | 0.038 | 0.040 | 0.042 | 0.038 |
| 8 | 0.038 | 0.037 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.038 | 0.039 | 0.040 | 0.040 | 0.041 | 0.041 | 0.041 | 0.040 | 0.040 | 0.039 | 0.038 | 0.037 | 0.037 | 0.034 | 0.032 | 0.031 | 0.030 | 0.037 | 0.041 | 0.030 |
| 9 | 0.028 | 0.027 | 0.027 | 0.028 | 0.029 | 0.031 | 0.032 | 0.034 | 0.036 | 0.038 | 0.038 | 0.039 | 0.039 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.036 | 0.040 | 0.027 |
| 10 | 0.040 | 0.040 | 0.040 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.038 | 0.040 | 0.035 |
| 11 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.033 | 0.033 | 0.033 | 0.032 | 0.035 | 0.036 | 0.032 |
| 12 | 0.032 | 0.031 | 0.030 | 0.030 | 0.030 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.029 | 0.028 | 0.027 | 0.027 | 0.025 | 0.025 | 0.024 | 0.023 | 0.023 | 0.023 | 0.023 | 0.028 | 0.032 | 0.023 |
| 13 | 0.023 | 0.023 | 0.024 | 0.024 | 0.026 | 0.027 | 0.029 | 0.030 | 0.032 | 0.034 | 0.036 | 0.037 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.035 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.032 | 0.038 | 0.023 |
| 14 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.036 | 0.037 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.038 | 0.035 |
| 15 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.038 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.038 | 0.039 | 0.036 |
| 16 | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.038 | 0.036 |
| 17 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.037 | 0.039 | 0.035 |
| 18 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.035 | 0.036 | 0.037 | 0.037 | 0.035 | 0.037 | 0.034 |
| 19 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.039 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.039 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.038 | 0.040 | 0.035 |
| 20 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.037 | 0.038 | 0.037 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.032 | 0.032 | 0.036 | 0.038 | 0.032 |
| 21 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.033 | 0.033 | 0.033 | 0.034 | 0.034 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.032 | 0.032 | 0.033 | 0.035 | 0.032 |
| 22 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.032 | 0.032 | 0.032 | 0.033 | 0.035 | 0.035 | 0.036 | 0.036 | 0.035 | 0.035 | 0.034 | 0.033 | 0.032 | 0.031 | 0.030 | 0.029 | 0.029 | 0.029 | 0.030 | 0.032 | 0.036 | 0.029 |
| 23 | 0.031 | 0.032 | 0.032 | 0.033 | 0.033 | 0.035 | 0.036 | 0.037 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.037 | 0.037 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.039 | 0.031 |
| 24 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.038 | 0.039 | 0.039 | 0.038 | 0.039 | 0.036 |
| 25 | 0.040 | 0.041 | 0.041 | 0.041 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.039 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.036 | 0.039 | 0.041 | 0.036 |
| 26 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.038 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.038 | 0.039 | 0.035 |
| 27 | 0.037 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.038 | 0.039 | 0.039 | 0.040 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.037 | 0.038 | 0.040 | 0.036 |
| 28 | 0.037 | 0.037 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.035 | 0.035 | 0.034 | 0.033 | 0.033 | 0.032 | 0.033 | 0.032 | 0.032 | 0.032 | 0.035 | 0.037 | 0.032 |
| 29 | 0.032 | 0.031 | 0.031 | 0.032 | 0.032 | 0.032 | 0.032 | 0.033 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.035 | 0.038 | 0.031 |
| 30 | 0.036 | 0.036 | 0.035 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.036 | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.038 | 0.034 |
| 31 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.035 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.034 |
| Avg | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | -- | -- |
| Max | 0.040 | 0.041 | 0.041 | 0.041 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.041 | 0.042 | 0.042 | 0.042 | 0.042 | 0.042 | 0.041 | 0.041 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | 0.040 | -- | 0.042 | -- |
| Min | 0.023 | 0.023 | 0.023 | 0.024 | 0.024 | 0.024 | 0.025 | 0.027 | 0.028 | 0.030 | 0.030 | 0.031 | 0.031 | 0.029 | 0.028 | 0.027 | 0.027 | 0.025 | 0.025 | 0.024 | 0.023 | 0.023 | 0.023 | 0.023 | -- | -- | 0.023 |

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, O3_ppm"**
**Month: Oct 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.050 | 0.046 | -- | 0.048 | 0.048 | 0.049 | 0.049 | 0.039 | 0.044 | 0.048 | 0.048 | 0.046 | 0.044 | 0.042 | -- | 0.043 | 0.045 | 0.046 | 0.045 | 0.044 | 0.040 | 0.041 | 0.040 | 0.040 | 0.045 | 0.050 | 0.039 |
| 2 | 0.038 | 0.038 | -- | 0.038 | 0.036 | 0.033 | 0.033 | 0.031 | 0.030 | 0.030 | 0.032 | 0.031 | 0.031 | 0.032 | 0.032 | 0.035 | 0.038 | 0.039 | 0.037 | 0.034 | 0.033 | 0.030 | 0.031 | 0.030 | 0.034 | 0.039 | 0.030 |
| 3 | 0.029 | 0.029 | -- | 0.027 | 0.026 | 0.024 | 0.024 | 0.023 | 0.029 | 0.033 | 0.037 | 0.035 | 0.036 | 0.038 | 0.036 | 0.034 | 0.034 | 0.036 | 0.037 | 0.037 | 0.037 | 0.036 | 0.033 | 0.032 | 0.032 | 0.038 | 0.023 |
| 4 | 0.032 | 0.032 | -- | 0.029 | 0.027 | 0.029 | 0.028 | 0.026 | 0.032 | 0.037 | 0.044 | 0.047 | 0.049 | 0.051 | 0.053 | 0.055 | 0.055 | 0.056 | 0.053 | 0.047 | 0.043 | 0.042 | 0.040 | 0.037 | 0.041 | 0.056 | 0.026 |
| 5 | 0.035 | 0.034 | -- | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.039 | 0.039 | 0.038 | 0.037 | 0.036 | 0.037 | 0.038 | 0.038 | 0.036 | 0.039 | 0.034 |
| 6 | 0.039 | 0.037 | -- | 0.038 | 0.036 | 0.028 | 0.036 | 0.036 | 0.035 | 0.036 | 0.038 | 0.041 | 0.042 | 0.044 | 0.044 | 0.045 | 0.046 | 0.045 | 0.043 | 0.041 | 0.039 | 0.039 | 0.039 | 0.037 | 0.039 | 0.046 | 0.028 |
| 7 | 0.036 | 0.035 | -- | 0.036 | 0.037 | 0.038 | 0.037 | 0.037 | 0.038 | 0.039 | 0.042 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.048 | 0.048 | 0.049 | 0.045 | 0.043 | 0.043 | 0.045 | 0.045 | 0.042 | 0.049 | 0.035 |
| 8 | 0.046 | 0.045 | -- | 0.042 | 0.041 | 0.040 | 0.041 | 0.036 | 0.038 | 0.044 | 0.047 | 0.047 | 0.044 | 0.044 | 0.044 | 0.044 | 0.045 | 0.045 | 0.044 | 0.043 | 0.043 | 0.042 | 0.041 | 0.038 | 0.043 | 0.047 | 0.036 |
| 9 | 0.036 | 0.035 | -- | 0.031 | 0.030 | 0.030 | 0.030 | 0.029 | 0.031 | -- | -- | -- | -- | -- | -- | -- | -- | 0.037 | 0.039 | 0.038 | 0.037 | 0.038 | 0.038 | 0.036 | -- | -- | -- |
| 10 | 0.017 | 0.017 | -- | 0.038 | 0.039 | 0.042 | 0.044 | 0.039 | 0.038 | 0.038 | 0.038 | 0.039 | 0.041 | 0.045 | 0.049 | 0.051 | 0.050 | 0.050 | 0.046 | 0.040 | 0.037 | 0.039 | 0.039 | 0.042 | 0.040 | 0.051 | 0.017 |
| 11 | 0.044 | 0.040 | -- | 0.042 | 0.041 | 0.038 | 0.036 | 0.033 | 0.040 | 0.045 | 0.049 | 0.051 | 0.050 | 0.052 | 0.053 | 0.054 | 0.055 | 0.054 | 0.053 | 0.047 | 0.045 | 0.045 | 0.044 | 0.045 | 0.046 | 0.055 | 0.033 |
| 12 | 0.045 | 0.043 | -- | 0.041 | 0.039 | 0.039 | 0.041 | 0.042 | 0.042 | 0.044 | 0.045 | 0.043 | 0.040 | 0.040 | 0.044 | 0.048 | 0.049 | 0.050 | 0.050 | 0.050 | 0.044 | 0.044 | 0.043 | 0.044 | 0.044 | 0.050 | 0.039 |
| 13 | 0.043 | 0.041 | -- | 0.043 | 0.043 | 0.043 | 0.043 | 0.041 | 0.041 | 0.040 | 0.038 | 0.038 | 0.043 | 0.048 | 0.050 | 0.052 | 0.052 | 0.050 | 0.049 | 0.046 | 0.047 | 0.048 | 0.048 | 0.046 | 0.045 | 0.052 | 0.038 |
| 14 | 0.045 | 0.041 | -- | 0.038 | 0.038 | 0.036 | 0.035 | 0.032 | 0.037 | 0.043 | 0.046 | 0.047 | 0.047 | 0.049 | 0.049 | 0.051 | 0.054 | 0.057 | 0.057 | 0.058 | 0.055 | 0.052 | 0.051 | 0.051 | 0.046 | 0.058 | 0.032 |
| 15 | 0.053 | 0.050 | -- | 0.051 | 0.051 | 0.050 | 0.050 | 0.047 | 0.049 | 0.053 | 0.055 | 0.057 | 0.057 | 0.056 | 0.057 | 0.058 | 0.058 | 0.058 | 0.058 | 0.058 | 0.055 | 0.054 | 0.052 | 0.050 | 0.054 | 0.058 | 0.047 |
| 16 | 0.048 | 0.043 | -- | 0.043 | 0.044 | 0.041 | 0.039 | 0.038 | 0.040 | 0.041 | 0.043 | 0.048 | 0.050 | 0.051 | 0.051 | 0.051 | 0.052 | 0.054 | 0.054 | 0.053 | 0.051 | 0.049 | 0.048 | 0.047 | 0.047 | 0.054 | 0.038 |
| 17 | 0.046 | 0.043 | -- | 0.041 | 0.039 | 0.038 | 0.039 | 0.037 | 0.040 | 0.045 | 0.046 | 0.048 | 0.053 | 0.055 | 0.056 | 0.057 | 0.057 | 0.058 | 0.056 | 0.052 | 0.051 | 0.050 | 0.051 | 0.051 | 0.048 | 0.058 | 0.037 |
| 18 | 0.049 | 0.046 | -- | 0.047 | 0.045 | 0.045 | 0.046 | 0.044 | 0.044 | -- | 0.042 | 0.044 | 0.044 | 0.047 | 0.049 | 0.051 | 0.053 | 0.053 | 0.052 | 0.049 | 0.044 | 0.040 | 0.039 | 0.040 | 0.046 | 0.053 | 0.039 |
| 19 | 0.041 | 0.039 | -- | 0.040 | 0.039 | 0.039 | 0.039 | 0.038 | 0.040 | 0.040 | 0.040 | 0.042 | 0.044 | 0.046 | 0.048 | 0.049 | 0.050 | 0.052 | 0.051 | 0.048 | 0.045 | 0.044 | 0.045 | 0.043 | 0.044 | 0.052 | 0.038 |
| 20 | 0.043 | 0.041 | -- | 0.041 | 0.039 | 0.039 | 0.038 | 0.036 | 0.038 | 0.044 | 0.044 | 0.048 | 0.048 | 0.047 | 0.046 | 0.047 | 0.047 | 0.047 | 0.046 | 0.047 | 0.047 | 0.044 | 0.044 | 0.045 | 0.044 | 0.048 | 0.036 |
| 21 | 0.046 | 0.041 | -- | 0.043 | 0.043 | 0.041 | 0.041 | 0.037 | 0.038 | 0.043 | 0.042 | 0.043 | 0.045 | 0.047 | 0.046 | 0.045 | 0.046 | 0.046 | 0.046 | 0.045 | 0.042 | 0.042 | 0.041 | 0.041 | 0.043 | 0.047 | 0.037 |
| 22 | 0.040 | 0.037 | -- | 0.041 | 0.039 | 0.038 | 0.035 | 0.036 | 0.036 | 0.036 | 0.039 | 0.041 | 0.043 | 0.044 | 0.044 | 0.045 | 0.045 | 0.044 | 0.043 | 0.042 | 0.041 | 0.041 | 0.041 | 0.042 | 0.041 | 0.045 | 0.035 |
| 23 | 0.041 | 0.038 | -- | 0.041 | 0.043 | 0.044 | 0.044 | 0.044 | 0.044 | 0.045 | 0.047 | 0.047 | 0.047 | 0.046 | 0.046 | 0.047 | 0.046 | 0.045 | 0.043 | 0.044 | 0.043 | 0.041 | 0.039 | 0.037 | 0.044 | 0.047 | 0.037 |
| 24 | 0.036 | 0.037 | -- | 0.035 | 0.034 | 0.034 | 0.035 | 0.035 | 0.037 | 0.038 | 0.040 | 0.041 | 0.044 | 0.044 | 0.044 | 0.047 | 0.047 | 0.045 | 0.045 | 0.044 | 0.041 | 0.038 | 0.038 | 0.039 | 0.040 | 0.047 | 0.034 |
| 25 | 0.040 | 0.039 | -- | 0.042 | 0.038 | 0.038 | 0.035 | 0.032 | 0.032 | 0.037 | 0.040 | 0.041 | 0.041 | 0.042 | 0.039 | 0.038 | 0.036 | 0.035 | 0.035 | 0.037 | 0.038 | 0.034 | 0.037 | 0.038 | 0.038 | 0.042 | 0.032 |
| 26 | 0.036 | 0.034 | -- | 0.037 | 0.038 | 0.038 | 0.035 | 0.035 | 0.037 | 0.037 | 0.039 | 0.040 | 0.041 | 0.041 | 0.041 | 0.042 | 0.042 | 0.043 | 0.044 | 0.040 | 0.036 | 0.034 | 0.035 | 0.036 | 0.038 | 0.044 | 0.034 |
| 27 | 0.036 | 0.033 | -- | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.036 | 0.039 | 0.041 | 0.042 | 0.042 | 0.043 | 0.044 | 0.044 | 0.045 | 0.047 | 0.048 | 0.048 | 0.045 | 0.044 | 0.045 | 0.040 | 0.048 | 0.033 |
| 28 | 0.044 | 0.042 | -- | 0.044 | 0.042 | 0.042 | 0.042 | 0.042 | 0.039 | 0.038 | 0.035 | 0.032 | 0.032 | 0.030 | 0.029 | 0.030 | 0.031 | 0.026 | 0.022 | 0.021 | 0.021 | 0.020 | 0.020 | 0.019 | 0.032 | 0.044 | 0.019 |
| 29 | 0.019 | 0.018 | -- | 0.019 | 0.020 | 0.019 | 0.019 | 0.018 | 0.021 | 0.022 | 0.022 | 0.022 | 0.023 | 0.025 | 0.028 | 0.031 | 0.033 | 0.034 | 0.035 | 0.034 | 0.034 | 0.033 | 0.032 | 0.030 | 0.026 | 0.035 | 0.018 |
| 30 | 0.030 | 0.028 | -- | 0.032 | 0.030 | 0.030 | 0.031 | 0.032 | 0.034 | 0.035 | 0.036 | 0.038 | 0.040 | 0.042 | -- | 0.043 | 0.043 | 0.042 | 0.041 | 0.041 | 0.040 | 0.040 | 0.039 | 0.039 | 0.037 | 0.043 | 0.028 |
| 31 | 0.039 | 0.036 | -- | 0.036 | 0.035 | 0.034 | 0.033 | 0.033 | 0.036 | 0.038 | 0.038 | 0.040 | 0.043 | 0.044 | 0.045 | 0.046 | 0.046 | 0.045 | 0.042 | 0.039 | 0.039 | 0.039 | 0.041 | 0.039 | 0.039 | 0.046 | 0.033 |
| Avg | 0.039 | 0.037 | -- | 0.038 | 0.038 | 0.037 | 0.037 | 0.035 | 0.037 | 0.039 | 0.041 | 0.042 | 0.043 | 0.044 | 0.045 | 0.045 | 0.046 | 0.046 | 0.045 | 0.044 | 0.042 | 0.041 | 0.041 | 0.040 | 0.041 | -- | -- |
| Max | 0.053 | 0.050 | -- | 0.051 | 0.051 | 0.050 | 0.050 | 0.047 | 0.049 | 0.053 | 0.055 | 0.057 | 0.057 | 0.056 | 0.057 | 0.058 | 0.058 | 0.058 | 0.058 | 0.058 | 0.055 | 0.054 | 0.052 | 0.051 | -- | 0.058 | -- |
| Min | 0.017 | 0.017 | -- | 0.019 | 0.020 | 0.019 | 0.019 | 0.018 | 0.021 | 0.022 | 0.022 | 0.022 | 0.023 | 0.025 | 0.028 | 0.030 | 0.031 | 0.026 | 0.022 | 0.021 | 0.021 | 0.020 | 0.020 | 0.019 | -- | -- | 0.017 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, O3_ppm"**
**Month: Nov 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.039 | 0.036 | -- | 0.038 | 0.037 | 0.037 | 0.035 | 0.033 | 0.034 | 0.035 | 0.036 | 0.037 | 0.038 | 0.039 | 0.041 | 0.043 | 0.045 | 0.044 | 0.041 | 0.035 | 0.034 | 0.035 | 0.036 | 0.038 | 0.038 | 0.045 | 0.033 |
| 2 | 0.037 | 0.034 | -- | 0.037 | 0.036 | 0.035 | 0.035 | 0.035 | 0.036 | 0.037 | 0.040 | 0.041 | 0.042 | 0.043 | 0.043 | 0.044 | 0.043 | 0.042 | 0.039 | 0.039 | 0.040 | 0.041 | 0.039 | 0.041 | 0.039 | 0.044 | 0.034 |
| 3 | 0.038 | 0.035 | -- | 0.029 | 0.030 | 0.026 | 0.027 | 0.026 | 0.026 | 0.028 | 0.027 | 0.029 | 0.029 | 0.030 | 0.030 | 0.030 | 0.031 | 0.032 | 0.033 | 0.032 | 0.031 | 0.031 | 0.029 | 0.031 | 0.030 | 0.038 | 0.026 |
| 4 | 0.032 | 0.032 | 0.030 | -- | 0.031 | 0.028 | 0.027 | 0.025 | 0.025 | 0.027 | 0.028 | 0.029 | 0.029 | 0.030 | 0.031 | 0.032 | 0.031 | 0.031 | 0.032 | 0.032 | 0.033 | 0.034 | 0.032 | 0.032 | 0.030 | 0.034 | 0.025 |
| 5 | 0.027 | 0.024 | 0.022 | -- | 0.024 | 0.026 | 0.034 | 0.032 | 0.029 | 0.033 | 0.036 | 0.037 | 0.038 | 0.039 | 0.040 | 0.041 | 0.042 | 0.042 | 0.042 | 0.040 | 0.036 | 0.036 | 0.036 | 0.036 | 0.034 | 0.042 | 0.022 |
| 6 | 0.035 | 0.035 | 0.035 | -- | 0.038 | 0.039 | 0.038 | 0.038 | 0.039 | 0.039 | 0.038 | 0.038 | 0.040 | 0.042 | 0.042 | 0.041 | 0.040 | 0.039 | 0.038 | 0.038 | 0.039 | 0.038 | 0.038 | 0.038 | 0.038 | 0.042 | 0.035 |
| 7 | 0.037 | 0.036 | 0.033 | -- | 0.035 | 0.034 | 0.034 | 0.034 | 0.033 | 0.035 | 0.038 | 0.040 | 0.041 | 0.042 | 0.042 | 0.042 | 0.041 | 0.040 | 0.037 | 0.037 | 0.036 | 0.035 | 0.034 | 0.033 | 0.037 | 0.042 | 0.033 |
| 8 | 0.033 | 0.033 | 0.031 | -- | 0.034 | 0.034 | 0.034 | 0.034 | 0.033 | 0.033 | 0.034 | 0.036 | 0.039 | 0.040 | 0.040 | 0.041 | 0.041 | 0.039 | 0.039 | 0.039 | 0.037 | 0.038 | 0.038 | 0.037 | 0.036 | 0.041 | 0.031 |
| 9 | 0.038 | 0.038 | 0.036 | -- | 0.035 | 0.033 | 0.033 | 0.033 | 0.034 | 0.036 | 0.039 | 0.040 | 0.039 | 0.041 | 0.040 | 0.039 | 0.039 | 0.039 | 0.038 | 0.035 | 0.034 | 0.035 | 0.036 | 0.037 | 0.037 | 0.041 | 0.033 |
| 10 | 0.036 | 0.036 | 0.033 | -- | 0.034 | 0.033 | 0.034 | 0.033 | 0.032 | 0.035 | 0.028 | 0.034 | 0.035 | 0.038 | 0.039 | 0.040 | 0.038 | 0.037 | 0.035 | 0.033 | 0.032 | 0.033 | 0.033 | 0.033 | 0.034 | 0.040 | 0.028 |
| 11 | 0.032 | 0.032 | 0.029 | -- | 0.031 | 0.030 | 0.030 | 0.031 | 0.033 | 0.033 | 0.033 | 0.035 | 0.039 | 0.040 | 0.039 | 0.038 | 0.038 | 0.037 | 0.034 | 0.034 | 0.035 | 0.035 | 0.036 | 0.036 | 0.034 | 0.040 | 0.029 |
| 12 | 0.037 | 0.036 | 0.033 | -- | 0.034 | 0.035 | 0.035 | 0.034 | 0.034 | 0.034 | 0.035 | 0.038 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.037 | 0.036 | 0.035 | 0.035 | 0.034 | 0.033 | 0.033 | 0.035 | 0.038 | 0.033 |
| 13 | 0.032 | 0.031 | 0.029 | -- | 0.030 | 0.030 | 0.029 | 0.029 | 0.030 | 0.030 | 0.030 | 0.031 | 0.031 | 0.031 | 0.032 | 0.032 | 0.032 | 0.032 | 0.031 | 0.031 | 0.031 | 0.031 | 0.031 | 0.030 | 0.031 | 0.032 | 0.029 |
| 14 | 0.029 | 0.029 | 0.026 | -- | 0.029 | 0.030 | 0.030 | 0.030 | 0.030 | 0.031 | 0.033 | 0.036 | 0.039 | 0.041 | 0.043 | 0.044 | 0.043 | 0.043 | 0.043 | 0.039 | 0.038 | 0.039 | 0.038 | 0.039 | 0.036 | 0.044 | 0.026 |
| 15 | 0.038 | 0.038 | 0.033 | -- | 0.035 | 0.033 | 0.032 | 0.034 | 0.038 | 0.038 | 0.038 | 0.039 | 0.039 | 0.038 | -- | 0.035 | 0.034 | 0.033 | 0.031 | 0.029 | 0.029 | 0.029 | 0.030 | 0.030 | 0.034 | 0.039 | 0.029 |
| 16 | 0.029 | 0.030 | 0.028 | -- | 0.031 | 0.032 | 0.033 | 0.033 | 0.032 | 0.033 | 0.034 | 0.035 | 0.036 | 0.037 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.038 | 0.036 | 0.035 | 0.035 | 0.039 | 0.028 |
| 17 | 0.037 | 0.037 | 0.034 | -- | 0.031 | 0.031 | 0.032 | 0.033 | 0.032 | 0.032 | 0.032 | 0.033 | 0.034 | 0.035 | 0.035 | 0.036 | 0.035 | 0.035 | 0.030 | 0.030 | 0.033 | 0.032 | 0.034 | 0.033 | 0.033 | 0.037 | 0.030 |
| 18 | 0.032 | 0.031 | 0.029 | -- | 0.030 | 0.029 | 0.030 | 0.031 | 0.032 | 0.031 | 0.031 | 0.031 | 0.034 | 0.035 | 0.037 | 0.038 | 0.038 | 0.037 | 0.035 | 0.032 | 0.032 | 0.034 | 0.035 | 0.033 | 0.033 | 0.038 | 0.029 |
| 19 | 0.034 | 0.032 | -- | 0.033 | 0.032 | 0.030 | 0.029 | 0.027 | 0.027 | 0.031 | 0.034 | 0.037 | 0.039 | 0.037 | 0.040 | 0.042 | 0.043 | 0.044 | 0.042 | 0.042 | 0.042 | 0.038 | 0.037 | 0.036 | 0.036 | 0.044 | 0.027 |
| 20 | 0.036 | 0.036 | -- | 0.034 | 0.031 | 0.031 | 0.028 | 0.029 | 0.029 | 0.033 | 0.035 | 0.036 | 0.038 | 0.039 | 0.040 | 0.040 | 0.041 | 0.040 | 0.039 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.036 | 0.041 | 0.028 |
| 21 | 0.038 | 0.042 | -- | 0.041 | 0.040 | 0.033 | 0.033 | 0.032 | 0.034 | 0.036 | 0.036 | 0.035 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.036 | 0.036 | 0.033 | 0.031 | 0.026 | 0.028 | 0.028 | 0.035 | 0.042 | 0.026 |
| 22 | 0.029 | 0.030 | -- | 0.026 | 0.024 | 0.026 | 0.025 | 0.024 | 0.024 | 0.024 | 0.030 | 0.035 | 0.036 | 0.037 | 0.038 | 0.038 | 0.036 | 0.034 | 0.034 | 0.033 | 0.031 | 0.032 | 0.030 | 0.033 | 0.031 | 0.038 | 0.024 |
| 23 | 0.026 | 0.021 | -- | 0.022 | 0.021 | 0.022 | 0.022 | 0.022 | 0.022 | 0.023 | 0.022 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.024 | 0.024 | 0.025 | 0.025 | 0.025 | 0.024 | 0.025 | 0.023 | 0.026 | 0.021 |
| 24 | 0.025 | 0.025 | -- | 0.026 | 0.026 | 0.026 | 0.026 | 0.026 | 0.026 | 0.027 | 0.027 | 0.027 | 0.028 | 0.028 | 0.028 | 0.029 | 0.028 | 0.028 | 0.029 | 0.029 | 0.028 | 0.028 | 0.027 | 0.027 | 0.027 | 0.029 | 0.025 |
| 25 | 0.027 | 0.026 | -- | 0.025 | 0.025 | 0.025 | 0.023 | 0.020 | 0.023 | 0.025 | 0.026 | 0.028 | 0.030 | 0.031 | 0.031 | 0.030 | 0.030 | 0.031 | 0.030 | 0.029 | 0.029 | 0.027 | 0.028 | 0.027 | 0.027 | 0.031 | 0.020 |
| 26 | 0.027 | 0.029 | -- | 0.031 | 0.031 | 0.029 | 0.025 | 0.025 | 0.025 | 0.026 | 0.028 | 0.031 | 0.034 | 0.036 | 0.037 | 0.038 | 0.039 | 0.037 | 0.037 | 0.038 | 0.037 | 0.037 | 0.036 | 0.037 | 0.033 | 0.039 | 0.025 |
| 27 | 0.037 | 0.037 | -- | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.036 | 0.036 | 0.037 | -- | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.034 | 0.036 | 0.038 | 0.034 |
| 28 | 0.035 | 0.035 | -- | 0.035 | 0.035 | 0.034 | 0.034 | 0.033 | 0.033 | 0.034 | 0.034 | 0.034 | 0.035 | 0.037 | 0.037 | 0.037 | 0.037 | 0.035 | 0.034 | 0.036 | 0.036 | 0.035 | 0.036 | 0.035 | 0.035 | 0.037 | 0.033 |
| 29 | 0.034 | 0.033 | -- | 0.032 | 0.031 | 0.031 | 0.032 | 0.032 | 0.032 | 0.031 | 0.031 | 0.032 | 0.035 | 0.035 | 0.036 | 0.037 | 0.037 | 0.037 | 0.035 | 0.035 | 0.034 | 0.034 | 0.032 | 0.032 | 0.033 | 0.037 | 0.031 |
| 30 | 0.033 | 0.033 | -- | 0.032 | 0.032 | 0.032 | 0.031 | 0.030 | 0.030 | 0.030 | 0.029 | 0.029 | 0.029 | 0.030 | 0.032 | 0.031 | 0.029 | 0.026 | 0.028 | 0.029 | 0.029 | 0.030 | 0.031 | 0.031 | 0.030 | 0.033 | 0.026 |
| Avg | 0.033 | 0.033 | 0.031 | 0.032 | 0.032 | 0.031 | 0.031 | 0.031 | 0.031 | 0.032 | 0.033 | 0.034 | 0.035 | 0.036 | 0.037 | 0.037 | 0.037 | 0.036 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | -- | -- |
| Max | 0.039 | 0.042 | 0.036 | 0.041 | 0.040 | 0.039 | 0.038 | 0.038 | 0.039 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.043 | 0.044 | 0.045 | 0.044 | 0.043 | 0.042 | 0.042 | 0.041 | 0.039 | 0.041 | -- | 0.045 | -- |
| Min | 0.025 | 0.021 | 0.022 | 0.022 | 0.021 | 0.022 | 0.022 | 0.020 | 0.022 | 0.023 | 0.022 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.023 | 0.024 | 0.024 | 0.025 | 0.025 | 0.025 | 0.024 | 0.025 | -- | -- | 0.020 |

-- Indicates Invalid Data

**SAROAD for Resolution, East_Plant**
**"Component, Channel: TableAmbient_Hourly, O3_ppm"**
**Month: Dec 2013**

**Hour of day**

| Day | 1 | 2 | 3 | 4 | 5 | 6 | 7 | 8 | 9 | 10 | 11 | 12 | 13 | 14 | 15 | 16 | 17 | 18 | 19 | 20 | 21 | 22 | 23 | 24 | Avg | Max | Min |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| 1 | 0.031 | 0.027 | -- | 0.024 | 0.023 | 0.023 | 0.023 | 0.022 | 0.023 | 0.025 | 0.026 | 0.026 | 0.028 | 0.030 | 0.033 | 0.035 | 0.033 | 0.032 | 0.031 | 0.028 | 0.028 | 0.029 | 0.029 | 0.029 | 0.028 | 0.035 | 0.022 |
| 2 | 0.029 | 0.029 | -- | 0.028 | 0.029 | 0.030 | 0.029 | 0.028 | 0.028 | 0.029 | 0.033 | 0.034 | 0.035 | 0.035 | 0.037 | 0.037 | 0.037 | 0.036 | 0.035 | 0.033 | 0.034 | 0.035 | 0.034 | 0.034 | 0.033 | 0.037 | 0.028 |
| 3 | 0.034 | 0.037 | -- | 0.034 | 0.033 | 0.035 | 0.035 | 0.036 | 0.034 | 0.034 | 0.039 | 0.040 | 0.040 | 0.040 | 0.041 | 0.041 | 0.039 | 0.037 | 0.037 | 0.036 | 0.034 | 0.032 | 0.031 | 0.031 | 0.036 | 0.041 | 0.031 |
| 4 | 0.035 | 0.037 | -- | 0.034 | 0.032 | 0.031 | 0.036 | 0.038 | 0.038 | 0.038 | 0.038 | 0.036 | 0.037 | 0.035 | 0.033 | 0.035 | 0.034 | 0.033 | 0.034 | 0.031 | 0.030 | 0.029 | 0.029 | 0.030 | 0.034 | 0.038 | 0.029 |
| 5 | 0.033 | 0.037 | -- | 0.040 | 0.038 | 0.036 | 0.034 | 0.034 | 0.033 | 0.032 | 0.037 | 0.041 | 0.042 | 0.043 | 0.043 | 0.042 | 0.041 | 0.040 | 0.036 | 0.037 | 0.037 | 0.037 | 0.037 | 0.034 | 0.037 | 0.043 | 0.032 |
| 6 | 0.032 | 0.034 | -- | 0.041 | 0.040 | 0.030 | 0.032 | 0.030 | 0.030 | 0.036 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.043 | 0.044 | 0.044 | 0.042 | 0.038 | 0.036 | 0.036 | 0.036 | 0.038 | 0.038 | 0.044 | 0.030 |
| 7 | 0.038 | 0.038 | -- | 0.037 | 0.038 | 0.039 | 0.040 | 0.040 | 0.036 | 0.036 | 0.038 | 0.041 | 0.042 | 0.043 | 0.043 | 0.043 | 0.043 | 0.042 | 0.041 | 0.041 | 0.041 | 0.041 | 0.040 | 0.039 | 0.040 | 0.043 | 0.036 |
| 8 | 0.040 | 0.039 | -- | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.034 | 0.035 | 0.038 | 0.039 | 0.040 | 0.041 | 0.041 | 0.042 | 0.041 | 0.040 | 0.040 | 0.040 | 0.040 | 0.037 | 0.036 | 0.037 | 0.039 | 0.042 | 0.034 |
| 9 | 0.036 | 0.031 | -- | 0.025 | 0.025 | 0.027 | 0.027 | 0.027 | 0.025 | 0.034 | 0.035 | 0.036 | 0.038 | 0.039 | 0.040 | 0.040 | 0.040 | 0.041 | 0.039 | 0.039 | 0.040 | 0.041 | 0.041 | 0.041 | 0.035 | 0.041 | 0.025 |
| 10 | 0.040 | 0.040 | -- | 0.040 | 0.041 | 0.040 | 0.040 | 0.040 | 0.039 | 0.038 | 0.038 | 0.038 | 0.040 | 0.041 | 0.040 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.035 | 0.039 | 0.041 | 0.035 |
| 11 | 0.036 | 0.036 | -- | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.035 | 0.034 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.035 | 0.036 | 0.035 | 0.034 | 0.034 | 0.034 | 0.033 | 0.034 | 0.035 | 0.037 | 0.033 |
| 12 | 0.034 | 0.034 | -- | 0.032 | 0.031 | 0.031 | 0.030 | 0.031 | 0.030 | 0.030 | 0.030 | 0.031 | 0.032 | 0.033 | 0.032 | -- | 0.031 | 0.030 | 0.029 | 0.026 | 0.024 | 0.024 | 0.023 | 0.024 | 0.030 | 0.034 | 0.023 |
| 13 | 0.022 | 0.024 | -- | 0.022 | 0.024 | 0.022 | 0.024 | 0.026 | 0.022 | 0.027 | 0.028 | 0.031 | 0.034 | 0.036 | 0.038 | 0.040 | 0.040 | 0.039 | 0.039 | 0.037 | 0.038 | 0.035 | 0.031 | 0.034 | 0.031 | 0.040 | 0.022 |
| 14 | 0.035 | 0.034 | -- | 0.032 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.035 | 0.037 | 0.037 | 0.038 | 0.038 | 0.040 | 0.040 | 0.039 | 0.038 | 0.038 | 0.037 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.040 | 0.032 |
| 15 | 0.037 | 0.036 | -- | 0.036 | 0.035 | 0.035 | 0.035 | 0.037 | 0.038 | 0.038 | 0.038 | 0.037 | 0.039 | 0.040 | 0.040 | 0.039 | 0.039 | 0.038 | 0.037 | 0.038 | 0.039 | 0.039 | 0.039 | 0.038 | 0.038 | 0.040 | 0.035 |
| 16 | 0.038 | 0.038 | -- | 0.036 | 0.037 | 0.037 | 0.036 | 0.037 | 0.036 | 0.036 | 0.037 | 0.038 | 0.040 | 0.040 | 0.041 | 0.040 | 0.036 | 0.035 | 0.035 | 0.037 | 0.038 | 0.037 | 0.036 | 0.035 | 0.037 | 0.041 | 0.035 |
| 17 | 0.037 | 0.037 | -- | 0.038 | 0.038 | 0.037 | 0.036 | 0.036 | 0.037 | 0.037 | 0.037 | 0.035 | 0.036 | 0.037 | 0.040 | 0.041 | 0.041 | 0.038 | 0.038 | 0.039 | 0.038 | 0.036 | 0.036 | 0.036 | 0.037 | 0.041 | 0.035 |
| 18 | 0.035 | 0.035 | -- | 0.035 | 0.035 | 0.035 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.035 | 0.034 | 0.036 | 0.037 | 0.036 | 0.036 | 0.034 | 0.035 | 0.033 | 0.034 | 0.035 | 0.035 | 0.035 | 0.037 | 0.033 |
| 19 | 0.035 | 0.035 | -- | 0.039 | 0.040 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.039 | 0.041 | 0.041 | 0.041 | 0.041 | 0.041 | 0.039 | 0.037 | 0.037 | 0.036 | 0.035 | 0.037 | 0.037 | 0.037 | 0.038 | 0.041 | 0.035 |
| 20 | 0.037 | 0.035 | -- | 0.033 | 0.034 | 0.035 | 0.036 | 0.041 | 0.039 | 0.038 | 0.040 | 0.035 | 0.037 | -- | -- | 0.038 | 0.037 | 0.039 | 0.038 | 0.036 | 0.035 | 0.035 | 0.034 | 0.033 | 0.036 | 0.041 | 0.033 |
| 21 | 0.033 | 0.031 | -- | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.032 | 0.033 | 0.033 | 0.033 | 0.033 | 0.034 | 0.034 | 0.035 | 0.036 | 0.036 | 0.036 | 0.035 | 0.036 | 0.033 | 0.033 | 0.036 | 0.031 |
| 22 | 0.032 | 0.031 | -- | 0.032 | 0.030 | 0.032 | 0.031 | 0.029 | 0.029 | 0.034 | 0.034 | 0.032 | 0.032 | 0.034 | 0.036 | 0.038 | 0.038 | 0.038 | 0.037 | 0.033 | 0.030 | 0.029 | 0.029 | 0.029 | 0.033 | 0.038 | 0.029 |
| 23 | 0.030 | 0.028 | -- | 0.029 | 0.029 | 0.032 | 0.034 | 0.035 | 0.035 | 0.034 | 0.034 | 0.036 | 0.039 | 0.041 | 0.041 | 0.041 | 0.041 | 0.039 | 0.037 | 0.037 | 0.036 | 0.034 | 0.034 | 0.036 | 0.035 | 0.041 | 0.028 |
| 24 | 0.036 | 0.035 | -- | 0.036 | 0.036 | 0.036 | 0.036 | 0.037 | 0.036 | 0.037 | 0.038 | 0.039 | 0.039 | 0.040 | 0.040 | 0.041 | 0.040 | 0.038 | 0.036 | 0.038 | 0.037 | 0.037 | 0.037 | 0.035 | 0.037 | 0.041 | 0.035 |
| 25 | 0.036 | 0.038 | -- | 0.043 | 0.042 | 0.040 | 0.043 | 0.041 | 0.039 | 0.038 | 0.039 | 0.039 | 0.039 | 0.040 | 0.042 | 0.042 | 0.042 | 0.040 | 0.038 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.039 | 0.043 | 0.036 |
| 26 | 0.036 | 0.036 | -- | 0.036 | 0.036 | 0.035 | 0.035 | 0.036 | 0.035 | 0.035 | 0.035 | 0.036 | 0.039 | 0.040 | 0.040 | 0.041 | 0.041 | 0.038 | 0.038 | 0.038 | 0.038 | 0.038 | 0.040 | 0.039 | 0.037 | 0.041 | 0.035 |
| 27 | 0.038 | 0.037 | -- | 0.037 | 0.037 | 0.036 | 0.036 | 0.037 | 0.036 | 0.036 | 0.037 | -- | -- | 0.039 | 0.040 | 0.040 | 0.041 | 0.040 | 0.039 | 0.039 | 0.038 | 0.038 | 0.038 | 0.037 | 0.038 | 0.041 | 0.036 |
| 28 | 0.037 | 0.036 | -- | 0.037 | 0.037 | 0.037 | 0.036 | 0.037 | 0.036 | 0.036 | 0.036 | 0.037 | 0.037 | 0.039 | 0.039 | 0.038 | 0.036 | 0.037 | 0.036 | 0.031 | 0.033 | 0.033 | 0.032 | 0.032 | 0.036 | 0.039 | 0.031 |
| 29 | 0.034 | 0.033 | -- | 0.032 | 0.032 | 0.030 | 0.030 | 0.031 | 0.032 | 0.033 | 0.033 | 0.033 | 0.034 | 0.034 | 0.036 | 0.036 | 0.037 | 0.036 | 0.036 | 0.037 | 0.037 | 0.038 | 0.038 | 0.038 | 0.034 | 0.038 | 0.030 |
| 30 | 0.038 | 0.037 | -- | 0.037 | 0.036 | 0.035 | 0.034 | 0.035 | 0.035 | 0.036 | 0.037 | 0.037 | 0.040 | 0.040 | 0.038 | 0.039 | 0.038 | 0.036 | 0.034 | 0.031 | 0.033 | 0.035 | 0.036 | 0.034 | 0.036 | 0.040 | 0.031 |
| 31 | 0.035 | 0.035 | -- | 0.036 | 0.035 | 0.035 | 0.034 | 0.033 | 0.033 | 0.033 | 0.034 | 0.035 | 0.036 | 0.038 | 0.038 | 0.039 | 0.037 | 0.033 | 0.034 | 0.035 | 0.037 | 0.037 | 0.036 | 0.039 | 0.035 | 0.039 | 0.033 |
| Avg | 0.035 | 0.034 | -- | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.034 | 0.035 | 0.036 | 0.036 | 0.037 | 0.038 | 0.039 | 0.039 | 0.038 | 0.037 | 0.037 | 0.036 | 0.036 | 0.035 | 0.035 | 0.035 | 0.036 | -- | -- |
| Max | 0.040 | 0.040 | -- | 0.043 | 0.042 | 0.040 | 0.043 | 0.041 | 0.039 | 0.039 | 0.040 | 0.041 | 0.042 | 0.043 | 0.043 | 0.043 | 0.044 | 0.044 | 0.042 | 0.041 | 0.041 | 0.041 | 0.041 | 0.041 | -- | 0.044 | -- |
| Min | 0.022 | 0.024 | -- | 0.022 | 0.023 | 0.022 | 0.023 | 0.022 | 0.022 | 0.025 | 0.026 | 0.026 | 0.028 | 0.030 | 0.032 | 0.034 | 0.031 | 0.030 | 0.029 | 0.026 | 0.024 | 0.024 | 0.023 | 0.024 | -- | -- | 0.022 |

-- Indicates Invalid Data

# Appendix F: West Plant Meteorological Site Check Forms

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/04/2013 Time: 7:30 Operator: Kami Ballard

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
RPA 10-25-13
REVIEWED BY (KJD) DATE 10/4/13
AUDITED BY DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 2 m/s | 2.1 | 2.798 |
| Direction* 10m (deg) | E | 65.3 | 66.81 |
| Ambient Temperature (°C) | 21° | 20.63 | 19.33 |
| Relative Humidity (%) | 28% | 34.01 | 36.99 |
| Aspirated Temp 2m | 21° | 20.39 | 19.14 |
| Aspirated Temp 10m | 20° | 19.61 | 19.14 |
| Delta Temperature (°C) | N/A | -0.794 | 0.003 |
| Solar Radiation (w/m²) | Sunny / Partly cloudy / Cloudy | 194.175 | 113.7 |
| Barometric Pressure (mmHg) | N/A | 680.99 | 681.0 |
| Battery Voltage (V) | N/A | 12.93 | 12.65 |
| Time (MST) | N/A | 7:33 | 0730 L.T. |
| Date | N/A | 10/04/2013 | 10/4/13 |

7:00 0.525
7:15 ~~0.005~~
7:45 0.344
8:00 -1.017
-1.044

7:45 12.92

*Direction wind is from

Comments/Unusual Occurrences or Weather: Failed evap. par & tipped precip. gauge. Invalidated precip. at 07:45 hrs L.T. -KJD

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kami Ballard

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/18/2013 Time: 7:31 Operator: Kara BeCloud

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
RPA 11/15/13
REVIEWED BY DATE
KJD 11/14/13
AUDITED BY DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 1 m/s | .77 | 1.907 |
| Direction* 10m (deg) | E | 45.86 | 48.68 |
| Ambient Temperature (°C) | 14° | 16.23 | 16.38 |
| Relative Humidity (%) | 25% | 25.89 | 23.29 |
| Aspirated Temp 2m | 14° | 14.91 | 15.99 |
| Aspirated Temp 10m | 13° | 15.58 | 16.31 |
| Delta Temperature (°C) | N/A | .65 | 0.318 |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 29.53 | 124.5 |
| Barometric Pressure (mmHg) | N/A | 682.78 | 682.9 |
| Battery Voltage (V) | N/A | 12.08 | 12.68 |
| Time (MST) | N/A | 7:33 | 7:45 L.T. |
| Date | N/A | 10.18.2013 | 10/18/13 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Dipped precip. gauge.

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Invalidated precip. at 7:45 L.T. due to site operator maintenance. -KJD

Site Operator Signature: Kara BeCloud

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Confirmed as 10/30/13 not 10/29/13. -KJD

Date: 10/~~29~~/30/2013 Time: 12:43 Operator: Kara Ballard

| YES | NO ** | |
|---|---|---|
| ✓ | | 1. The tower is intact and upright. |
| ✓ | | 2. The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. The aspirator fans are operating. |
| ✓ | | 5. The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. The solar panel is facing south and is clean. |
| ✓ | | 7. The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. The data logger is reading the correct time and day. |
| ✓ | | 9. The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER · PORTLAND

RPA 11.15.13
REVIEWED BY DATE

KJD 11/14/13
AUDITED BY DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 2 m/s | 1.54 | 3.077 |
| Direction* 10m (deg) | | 213.58 | 236.8 |
| Ambient Temperature (°C) | 16° | 16.67 | 16.43 |
| Relative Humidity (%) | 30 % | 30.34 | 31.03 |
| Aspirated Temp 2m | 16° | 16.05 | 15.86 |
| Aspirated Temp 10m | 15° | 15.19 | 15.16 |
| Delta Temperature (°C) | N/A | -1.14 | -0.699 |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 733.56 | 742.0 |
| Barometric Pressure (mmHg) | N/A | 682.10 | 682.1 |
| Battery Voltage (V) | N/A | 12.91 | 12.91 |
| Time (MST) | N/A | 12:48 | 12:45 L.T. |
| Date | N/A | 10/~~29~~/30/2013 | 10/30/13 |

12:15 - 242.9
12:30 - 233.0
13:00 - 233.3
13:15 - 207.7

*Direction wind is from

-KJD

Comments/Unusual Occurrences or Weather: Filled evap pan & tipped precip. gauge

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Invalidated precip. at 12:45 L.T. due to site operator maintenance. -KJD

Site Operator Signature: Kara Ballard

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 11/08/2013 Time: 11:49 Operator: Karen Ballard

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
RPA 11-15-13
REVIEWED BY DATE
KJD 11/14/13
AUDITED BY DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | .4 m/s | .9 | 1.679 |
| Direction* 10m (deg) | SE | 320.34 | 4.442 |
| Ambient Temperature (°C) | 25° | 24.6 | 24.54 |
| Relative Humidity (%) | 15% | 15.5% | 15.4 |
| Aspirated Temp 2m | 25° | 23.6 | 24.08 |
| Aspirated Temp 10m | 24° | 22.9 | 22.81 |
| Delta Temperature (°C) | N/A | -0.75 | -1.274 |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 691.501 | 691.5 |
| Barometric Pressure (mmHg) | N/A | 684.63 | 684.5 |
| Battery Voltage (V) | N/A | 12.78 | 12.79 |
| Time (MST) | N/A | 11:34 | 12:00 L.T. |
| Date | N/A | 11/08/2013 | 11/8/13 |

11:30 - 100.6
11:45 - 89.5
12:15 - 315.7
12:30 - 257.7

*Direction wind is from

Comments/Unusual Occurrences or Weather: Tipped precip. gauge.

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Invalidated precip. at 12:00 L.T. due to site operator maintenance. -KJD

Site Operator Signature: Karen Ballard

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 11/15/2013 Time: 1:23 Operator: Kam Bacon

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER · PORTLAND

REVIEWED BY: KJD DATE: 11/26/13

AUDITED BY: GG. DATE: 11/21/13

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 4m/s | 3.4 | 6.21 |
| Direction* 10m (deg) | SW | 171.76 | 185 |
| Ambient Temperature (°C) | 24 | 23.66 | 23.5 |
| Relative Humidity (%) | 30% | 30.22 | 30.1 |
| Aspirated Temp 2m | 24 | 23.76 | 23.4 |
| Aspirated Temp 10m | 23 | 22.34 | 22.2 |
| Delta Temperature (°C) | N/A | -1.24 | -1.19 |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 284.37 | 284 |
| Barometric Pressure (mmHg) | N/A | 675.95 | 676 |
| Battery Voltage (V) | N/A | 12.82 | 12.8 |
| Time (MST) | N/A | 1:25 | 1530 L.T. |
| Date | N/A | 11/15/2013 | 11/15/2013 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: filled evap. pan

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kam Bacon

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 11/21/2013 Time: 11:38 Operator: Kara Ballard

| YES | NO** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
REVIEWED BY: RPA DATE: 11-27-13
AUDITED BY: KJD DATE: 11/26/13

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 3 m/s | 3.89 | 3.35 |
| Direction* 10m (deg) | SW | 147.16 | 160.1 |
| Ambient Temperature (°C) | 17° | 19.19 | 19.17 |
| Relative Humidity (%) | 35% | 34.18 | 36.19 |
| Aspirated Temp 2m | 17° | 19.30 | 19.18 |
| Aspirated Temp 10m | 16° | 18.03 | 18.01 |
| Delta Temperature (°C) | N/A | -1.27 | -1.173 |
| Solar Radiation (w/m²) | Sunny Partly cloudy (Cloudy) | 326.95 | 331.6 |
| Barometric Pressure (mmHg) | N/A | 681.43 | 681.4 |
| Battery Voltage (V) | N/A | 12.89 | 12.89 |
| Time (MST) | N/A | 11:40 | 11:45 L.T. |
| Date | N/A | 11/21/2013 | 11/21/13 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Precipitation gauge was not triggered by site operator. -KJD

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kara Ballard

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/06/2013 Time: 09:47 Operator: Tom White

| YES | NO** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
REVIEWED BY RPA 12/10/13 DATE
AUDITED BY GG. 12/09/13 DATE

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 1 m/s | 1.84 m/s | 1.7 | |
| Direction* 10m (deg) | 200° | 160° | 126° | * G.G. |
| Ambient Temperature (°C) | 5°C | 7.02°C | 6.36 | |
| Relative Humidity (%) | 30% | 31.4% | 55.6% | |
| Aspirated Temp 2m | 5°C | 6.45 | 6.05 | |
| Aspirated Temp 10m | 5.2°C | 5.31 | 4.95 | |
| Delta Temperature (°C) | N/A | -1.34 | -1.1 | |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | ~~0~~ ? | 401 | * G.G. |
| Barometric Pressure (mmHg) | N/A | 686.27 | 686 | |
| Battery Voltage (V) | N/A | 13.13 | 15.1 | |
| Time (MST) | N/A | 0956 | 09:45 | |
| Date | N/A | 12/6/13 | 12/06/13 | |

*Direction wind is from

Comments/Unusual Occurrences or Weather: *GG. - WD more than ±20° due to low WS. Operator didn't put 5# from the logger!

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: TWhite

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/13/13 Time: 09:00 Operator: Tom White

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. ★2 |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC
REVIEWED BY RPA DATE 12/19/13
AUDITED BY GG. DATE 12/13/13

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 2 | 1.23 | 1.02 | + |
| Direction* 10m (deg) | 200 | 182.81 | 118 | ★ |
| Ambient Temperature (°C) | 18 | 10.2 | 10.3 | + |
| Relative Humidity (%) | 33 | 39.87 | 39 | + |
| Aspirated Temp 2m | 18 | 9.83 | 9.58 | + |
| Aspirated Temp 10m | 17.5 | 9.32 | 8.82 | + |
| Delta Temperature (°C) | N/A | ? | -0.761 | ★ ★1 GG |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | ? | 228 | ↕ |
| Barometric Pressure (mmHg) | N/A | ? | 686 | ↕ |
| Battery Voltage (V) | N/A | ? | 13.1 | ↕ |
| Time (MST) | N/A | ? | 09:00 | ↕ |
| Date | N/A | ? | 12/13/2013 | ★ |

★3 Met site check incomplete - missing info! WD's more than 20° due to low WS.

*Direction wind is from

Comments/Unusual Occurrences or Weather: cleaned off bird droppings from solar panel

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: T White

★2 - Site operator might have tipped the precip. gauge @ 0930/12/13/13) and didn't record it. East & West site's were checked. No precip. recorded before & after 0930 hours @ RH of 39° and 45° (East).

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/19/13 Time: 14:01 Operator: TEW

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| | ✓ | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC.
REVIEWED BY APA DATE 12-26-13
AUDITED BY GG. DATE 12/23/13

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 10 | 2.76 | 5.72 | f |
| Direction* 10m (deg) | 225 | 207.78 | 215 | f |
| Ambient Temperature (°C) | 22 | 19.02 | 19.01 | f |
| Relative Humidity (%) | 30 | 16.06 | 15.8 | f |
| Aspirated Temp 2m | 22 | 18.73 | 18.9 | f |
| Aspirated Temp 10m | 21.5 | 17.55 | 17.6 | f GG. |
| Delta Temperature (°C) | N/A | -1.18 | -1.28 | f |
| Solar Radiation (w/m$^2$) | (Sunny) Partly cloudy Cloudy | 467.56 | 512 | f |
| Barometric Pressure (mmHg) | N/A | 675.96 | 676 | f |
| Battery Voltage (V) | N/A | 12.87 | 12.9 | f |
| Time (MST) | N/A | 1402 | 1400 | f |
| Date | N/A | 12/19/13 | 12/19/13 | f |

*Direction wind is from

Comments/Unusual Occurrences or Weather: _____

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: T. White

AIR SCIENCES INC.

# WEST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/27/13 Time: 10:25 Operator: TEW

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC
DENVER • PORTLAND
REVIEWED BY RPA DATE 12-30-13
AUDITED BY CG DATE 12/30/13

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 15 | 10.24 | 10.8 | f |
| Direction* 10m (deg) | 080 | 40.41 | 39.9 | f |
| Ambient Temperature (°C) | 17° | 15.63 | 15.4 | f |
| Relative Humidity (%) | 23 | 16.52 | 16.7 | f |
| Aspirated Temp 2m | 17 | 15.69 | 15.3 | f |
| Aspirated Temp 10m | | 14.73 | 14.7 | f |
| Delta Temperature (°C) | N/A | -0.96 | -0.678 | f |
| Solar Radiation (w/m$^2$) | (Sunny) Partly cloudy Cloudy | 495.75 | 485 | f |
| Barometric Pressure (mmHg) | N/A | 687.77 | 688 | f |
| Battery Voltage (V) | N/A | 12.94 | 12.9 | f |
| Time (MST) | N/A | 10:28 | 10:30 | f |
| Date | N/A | 12/27/13 | 12/27/13 | f |

*Direction wind is from

Comments/Unusual Occurrences or Weather: _____

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: TEW

# Appendix G: West Plant $PM_{10}$ and $PM_{2.5}$ Site Check Forms and Flow Audits

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/04/2013 Time: 7:35 Operator: Kara Ballard

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 9/27 - BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
RPA 10-25-13
CHECKED BY: DATE
KJD 10/4/13
DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

*Comments/Unusual Occurrences: _____

Signature: Kara Ballard

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/19/2013 Time: 7:34 Operator: Kara Bdld

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/11 → count fa Cod |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 11-15-13
REVIEWED BY DATE

KJD 11/14/13
AUDITED BY DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kara Bdld

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/30/2013 Time: 12:48 Operator: Kara BaCod

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/29 → Maint. |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| ✓ | | 5. | Inlet nozzle and nozzle are cleaned (10/28) |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 11·15·13
REVIEWED BY DATE
KJD 11/14/13
AUDITED BY DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function (10/28) |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kara BaCod

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.
DENVER • PORTLAND

# Monthly Flow Verification $PM_{10}$

**West Plant**
PARTICULATE MONITORING PROJECT
PROJECT NO. 262-1

Met One BAM 1020 $PM_{10}$: S/N: M8712
Firmware:
Calibrator: Delta Cal S/N:

Date of Flow Audit: 10/30/2013
Time of Flow Audit: 12:51

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 10.5 | 17.6 |
| Berometric Pressure mmHg | 679 | 682.5 |

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0.667 | 15.17 | -0.461 |
| *Acceptable* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| *Differential* | | | | | |
| (2) Actual Flow | 18.4 | 18.4 | 0.000 | 18.61 | -1.128 |
| *Acceptable* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| *Differential* | | | | | |
| (3) Actual Flow | 16.7 | 16.7 | 0.000 | 16.84 | -0.831 |
| *Acceptable* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |
| *Differential* | | | | | |

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

AIR SCIENCES INC.
DENVER • PORTLAND
AAA 11.15.13
REVIEWED BY DATE
KJD 11/14/13
AUDITED BY DATE

| | BAM | |
|---|---|---|
| (2) Leak Test | .2 | **Should be < 1.0 LPM** |

Comments/Abnormalities: Ran Self Test → "PASSED"

Signature: Kami Bell

Upon completion of this form, fax to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 11/08/2013 Time: 11:57 Operator: Kam Ballard

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/30/2013 → Maint. |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC. DENVER • PORTLAND

RPA 11/13/13
REVIEWED BY DATE

KJD 11/14/13
AUDITED BY DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kam Ballard

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/18/2013 Time: 1:28 Operator: K. Ballard

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/09/13 → Power fail |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | ✓ | KJD | 1. | Inlet Flow check Performed |
| | ✓ | | 2. | Visual inspection and dust removal |
| | ✓ | | 3. | Leak check performed |
| | ✓ | | 4. | PM10 particle trap cleaned |
| | ✓ | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY: KJD 11/26/13 DATE
DATED BY: 66- 11/21/13 DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | ✓ | KJD | 1. | Filter tape replaced |
| | ✓ | | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | ✓ | KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | ✓ | KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Karen Ballard

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/21/2013 Time: 11:38 Operator: Kami Bullard

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/09 → Power Fail |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | | KJD | 1. | Inlet Flow check Performed |
| | | | 2. | Visual inspection and dust removal |
| | | | 3. | Leak check performed |
| | | | 4. | PM10 particle trap cleaned |
| | | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 11/27/13
REVIEWED BY DATE

KJD 11/26/13
AUDITED BY DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | | KJD | 1. | Filter tape replaced |
| | | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | | KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | | |
|---|---|---|---|---|
| | | KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kami Bullard

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 12/06/2013 Time: 0958 Operator: Tom White

**I. BAM SAMPLER – Weekly Checks.**

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 12/6 09:58: BAM Cal Membrane 5%. |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit.** *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

G.G.

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/10/13
ENTERED BY GG DATE 12/09/13

**II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit.** *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

G.G.

**III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit.** *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

G.G.

**IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit.** *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

G.G.

**Comments/Unusual Occurrences: "Status: 10 Count"

Signature: T White

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 12/13/13 Time: 09:10 Operator: Tom White

**I. BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

GG.

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/19/13
AUDITED BY GG. DATE 12/13/13

**II. BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

GG.

**III. BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

GG.

**IV. BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

GG.

**Comments/Unusual Occurrences: Good

Signature: Tom White

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/19/13 Time: 14:05 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC
DENVER • PORTLAND
REVIEWED BY RPA DATE 12-26-13
AUDITED BY G.G. DATE 12/23/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

G.G.

**Comments/Unusual Occurrences: updated Clock ★

★ BAM went into maintenance (Error) for the 15:00 hour - invalidated by DASS due to the above procedure.

Signature: TEW

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/27/13 Time: 10:32 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Mem |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY RPA DATE 12-30-13
AUDITED BY G.G. DATE 12/30/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: 12/27/13 11:00 hrs. concentrations invalidated by DASS due to maintenance

Signature: Tom White, Resolution

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.

# Monthly Flow Verification $PM_{10}$

**West Plant**
**PARTICULATE MONITORING PROJECT**
**PROJECT NO. 262-1**

AIR SCIENCES INC.
REVIEWED BY RDA DATE 12/30/13
AUDITED BY GG DATE 12/30/13

Met One BAM 1020 $PM_{10}$: S/N: M8712
Firmware:
Calibrator: S/N: 1054 Exp. 8/2014

Date of Flow Audit: 12/27/13
Time of Flow Audit: 10:36

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 15.5 | 16.3 |
| Berometric Pressure mmHg | 691 | 688 |

6.6 6.6

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0 | 15.15 | -0.99 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.4 | 0 | 18.64 | -1.29 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.7 | 0 | 16.93 | -1.36 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | 0.0 | **Should be < 1.0 LPM** |

Comments/Abnormalities:

Signature:

Upon completion of this form, fax to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
**RESOLUTION MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/04/2013 Time: 7:37 Operator: Kami Ballard

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | ✓ | 6. | Error log was checked (F3), and errors followed up on (see manual). 9/27 – Tape Tension |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY: RPA DATE: 10.25.13
SUBMITTED BY: KJD DATE: 10/4/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kami Ballard

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/08/2013 Time: 11:54 Operator: Kane B. Collard

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Membrane 5% 10/30 → 11/08 |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 11/15/13
REVIEWED BY DATE

KJD 11/14/13
AUDITED BY DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: * WEEKLY CHECK CONDUCTED BY K. BALLARD - RPA

*

Signature: _____

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/18/2013 Time: 7:35 Operator: Karen BeCard

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/04 → 10/18 BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 11-15-13
REVIEWED BY DATE

KJD 11/14/13
AUDITED BY DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Karen BeCard

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/30/2013 Time: 12:55 Operator: Karen BaCarel

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/28 → Tape Break |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| ✓ | | 5. | Inlet nozzle and nozzle are cleaned (10/29) |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 11-15-13
REVIEWED BY DATE

KJD 11/14/13
AUDITED BY DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Filter tape replaced (10/29) |
| ✓ | | 2. | Ran the Self-Test function (10/29) |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) KJD |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) KJD |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Karen BaCarel

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY JR DATE 11/19/13

AUDITED BY RAA DATE 11.13.13

AIR SCIENCES INC.

# Monthly Flow Verification $PM_{2.5}$

**West Plant**
PARTICULATE MONITORING PROJECT
PROJECT NO. 262-1

Met One BAM 1020 $PM_{2.5}$: S/N: M6466
Firmware:
Calibrator: Delta Cal S/N: 1034

Date of Flow Audit: 9:45
Time of Flow Audit: 10/31/2013

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 14.9 | 14.8 |
| Berometric Pressure mmHg | 657 | 655.0 |

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.1 | 0.7 | 15.68 | -3.7 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.3 | -0.5 | 19.05 | -3.9 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.9 | 1.2 | 17.36 | -3.2 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

* (1) and (2)

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | .3 | **Should be < 1.0 LPM** |

Comments/Abnormalities: Self Test - "Passed"

* % DIFF CLOSE TO UPPER THRESHOLD - RPA

Signature: Ryan Bellina

Upon completion of this form, fax to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/15/2013 Time: 1:59 Operator: Kara Bold

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/1 to 11/14 → BAM Cal Membrane 50% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

KJD — REVIEWED BY — 11/26/13 DATE

GG — AUDITED BY — 11/21/13 DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: _____

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
**RESOLUTION MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/21/2013 Time: 11:34 Operator: Kahn BdC d

**I. BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/17 → 11/21 BAM Cal Membrane 5% ... again |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

RPA — REVIEWED BY — 11/27/13 — DATE
KJD — AUDITED BY — 11/26/13 — DATE

**II. BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

**III. BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

**IV. BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | KJD | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kahn BdC

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/06/2013 Time: 09:55 Operator: Tom White

**I. BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 12/06 08:53: BAM Cal membrane |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

G.G.

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY RPA DATE 12/10/13
AUDITED BY GG DATE 12/09/13

**II. BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

GG

**III. BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

G.G.

**IV. BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

G.G.

"Comments/Unusual Occurrences: "Status: 13 count"

Signature: T White

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 12/13/13 Time: 09:05 Operator: Tom White

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| | ✓ | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Ferrule 5V |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) ★ 12/13 01:00: Tape break every hour past: Tape Tension |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

GG

AIR SCIENCES INC.
RPA 12/19/13
REVIEWED BY DATE
AUDITED BY GG DATE 12/13/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

GG.

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

GG.

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

GG.

Comments/Unusual Occurrences: Tape Tension message found on PM 2.5. Opened door, unlatched pinch roller and then unlatched pinch roller, ★ tightened plastic reel cover on the right, Voila! Ran Self-test and everything is all good.

★ Invalidated automatically by DASS. (GG)

Signature: [signature]

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/19/13 Time: 14:02 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Mem. 5% |
| ✓ | | 7. | Climate control appears operational (if it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY RPA DATE 12-26-13
AUDITED BY 6.6. DATE 12/23/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) * 6.6. |

**Comments/Unusual Occurrences: updated clock

* Maintenance Error for the 15:00 hour due to the above procedure (invalidated by DAS)

Signature: TEW

**Fax completed form to Air Sciences at 303-279-3796

# WEST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/27/13 Time: 10:29 Operator: TEW

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Nem. 12/23-12/27 |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY RPA DATE 12-30-13
AUDITED BY G.G. DATE 12/30/13

YES NO

| | | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

★

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

YES NO

| | | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

★

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO G.G.

| | | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO G.G.

| | | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: Self-test passed ★

G.G. ★ 12/27/13 @ 11:00 hrs concentration invalidated by DASS due to maintenance

Signature: TEW
Tom White

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC

# Monthly Flow Verification $PM_{2.5}$

**West Plant**

PARTICULATE MONITORING PROJECT

PROJECT NO. 262-1

Met One BAM 1020 $PM_{2.5}$: S/N: M8133

Firmware:

Calibrator: S/N: 1034 Exp. 8/2014

Date of Flow Audit: Delta Cal 12/27/13 10:31

Time of Flow Audit:

AIR SCIENCES INC. DENVER • PORTLAND

REVIEWED BY: RPA DATE: 12/30/13

AUDITED BY: GG. DATE: 12/30/13

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 16.0 | 16.3 |
| Berometric Pressure mmHg | 689 | 688 |

GG. GG.

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0 | 15.26 | -1.70 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.40 | 0 | 18.93 | -2.80 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.7 | 0 | 17.07 | -2.17 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

Calculations:

(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)

(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | 0.2 | **Should be < 1.0 LPM** |

Comments/Abnormalities:

Signature:

Upon completion of this form, fax to Air Sciences at 303-279-3796

# Appendix H: East Plant Meteorological Site Check Forms

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY WR DATE 10/18/13

AUDITED BY RDA DATE 10-7-13

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/4/2013 Time: 9:17am Operator: Tom White

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 1 | 2.3 | 1.49 | ✓ |
| Direction* 10m (deg) | ~~SE~~ SW | 196° | 182.0 | ✓ |
| Ambient Temperature (°C) | 21 | 21.7 | 21.5 | ✓ |
| Relative Humidity (%) | 20 | 28.4 | 28.9 | ✓ |
| Aspirated Temp 2m | 21 | 20.25 | 20.3 | ✓ |
| Aspirated Temp 10m | 20 | 19.30 | 19.3 | ✓ |
| Delta Temperature (°C) | N/A | -1.01 | -0.979 | ✓ |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 636.5 | 633 | ✓ |
| Barometric Pressure (mmHg) | N/A | 652.5 | 653 | ✓ |
| Battery Voltage (V) | N/A | 12.79 | 12.8 | ✓ |
| Time (MST) | N/A | 9:24 | 0930 | ✓ |
| Date | N/A | 10/4/2013 | 10-4-13 | ✓ |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Refilled evap pan

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: T White

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY WR DATE 10/25/13

AUDITED BY RPA DATE 10-21-13

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/11/13 Time: 0815 Operator: TEW

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 5 | 2.71 | 2.35 |
| Direction* 10m (deg) | 90° | 72 | 61.7 |
| Ambient Temperature (°C) | 55°F | 12°C | 12.6 |
| Relative Humidity (%) | 30% | 44 | 44.3 |
| Aspirated Temp 2m | 95°F | 11.82°C | 11.9 |
| Aspirated Temp 10m | 54°F | 11.2°C | 11.2 |
| Delta Temperature (°C) | N/A | -0.61 | -0.682 |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 443.72 | 435 |
| Barometric Pressure (mmHg) | N/A | 652.79 | 653 |
| Battery Voltage (V) | N/A | 12.98 | 13.0 |
| Time (MST) | N/A | 0824 | 0830 |
| Date | N/A | 10/11/2013 | 10-11-13 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Monitor for evap pan inside pan and turned over. Took it out, drained it and then put it back in the way it was.

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

* DID NOT CHECK THE FLOAT SYSTEM INSIDE EVAP GAUGE-RPA

Site Operator Signature: TEW

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/18/2013 Time: 8:25 Operator: Tom Ballard

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
WR 10/25/13
REVIEWED BY RPA DATE 10-21-13
AUDITED BY DATE 10-21-13

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 5 m/s | 4.4 | 3.79 |
| Direction* 10m (deg) | E | 59.68 | 43.4 |
| Ambient Temperature (°C) | 16° | 16.58 | 16.4 |
| Relative Humidity (%) | 25% | 22.76 | 23.6 |
| Aspirated Temp 2m | 16° | 16.13 | 15.9 |
| Aspirated Temp 10m | 15° | 15.48 | 15.2 |
| Delta Temperature (°C) | N/A | -.69 | -0.671 |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 448.44 | 405 @0845 = 459 |
| Barometric Pressure (mmHg) | N/A | 653.47 | 654 |
| Battery Voltage (V) | N/A | 12.91 | 12.9 |
| Time (MST) | N/A | 8:34 | 0830 HRS |
| Date | N/A | 10/18/2013 | 10-18-13 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Heat chain disconnected on evap. gauge. Chain replaced & evap. gauge calibrated.

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary). EVAP DATA – GAUGE MALFUNCTION 10-9-13 @2200Hr THRU 10-18-13 @0900 HRS INVALID – RPA

Site Operator Signature: Tom Ballard

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/23/2013 Time: 1:29 Operator: Kara BaCard

| YES | NO ** | |
|---|---|---|
| ✓ | | 1. The tower is intact and upright. |
| ✓ | | 2. The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. The aspirator fans are operating. |
| ✓ | | 5. The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. The solar panel is facing south and is clean. |
| ✓ | | 7. The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. The data logger is reading the correct time and day. |
| ✓ | | 9. The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • FORTLAND

REVIEWED BY JR 11/19/13 DATE

AUDITED BY RPA 11-13-13 DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 5 m/s | 4.14 | 3.36 |
| Direction* 10m (deg) | E | 98.07 | 130.0 |
| Ambient Temperature (°C) | 26° | 27.69 | 26.7 |
| Relative Humidity (%) | 15% | 10.41 | 11.1 |
| Aspirated Temp 2m | 26° | 27.29 | 26.5 |
| Aspirated Temp 10m | 25° | 26.13 | 25.1 |
| Delta Temperature (°C) | N/A | -1.03 | -1.42 |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 709.45 | 725 |
| Barometric Pressure (mmHg) | N/A | 652.36 | 652 |
| Battery Voltage (V) | N/A | 12.72 | 12.7 |
| Time (MST) | N/A | 1:32 | 13:30 MST |
| Date | N/A | 10/23/2013 | 10/23/2013 |

1300 – 103.0
1315 – 104.0
1345 – 132.0
1400 – 113.0

*Direction wind is from

Comments/Unusual Occurrences or Weather: 2 SEC SCAN LOGGER VALUE VS 15 MIN AVE NOT +/- 20°; VALUES POINTS $x^2$ ABOVE/BELOW ARE. – RPA

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kara BaCard

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 10/30/2013 Time: 1:57 Operator: Kami Bolland

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
REVIEWED BY JR DATE 11/19/13
AUDITED BY RPA DATE 11.13.13

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 4m/s | 4.3 | 3.55 |
| Direction* 10m (deg) | | 181.60 | 199.0 |
| Ambient Temperature (°C) | 13° | 13.83 | 13.9 |
| Relative Humidity (%) | 30% | 30.89 | 30.1 |
| Aspirated Temp 2m | 13° | 13.88 | 13.7 |
| Aspirated Temp 10m | 12° | 12.01 | 12.5 |
| Delta Temperature (°C) | N/A | -1.20 | -1.25 |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 631.84 | 648 |
| Barometric Pressure (mmHg) | N/A | 651.48 | 652 |
| Battery Voltage (V) | N/A | 12.92 | 12.9 |
| Time (MST) | N/A | 1:59 | 1400 HRS |
| Date | N/A | 10/30/2013 | 10-30-2013 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Evap. Sensor knocked over in tank. Set it upright again. Filled evap pan. * TOTAL EVAP DATA INVALIDATED - RPA

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kami Bolland

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 11/18/2013 Time: 1:27 Operator: Karen Ballard

| YES | NO** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND
REVIEWED BY RPA 11/18/13 DATE
AUDITED BY 11.13.13 DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 5 m/s | 4.24 | 2.86 |
| Direction* 10m (deg) | W | 311.65 | * 240.0 |
| Ambient Temperature (°C) | 24° | 22.12 | 22.3 |
| Relative Humidity (%) | 20% | 19.1 | 18.0 |
| Aspirated Temp 2m | 24° | 21.58 | 21.3 |
| Aspirated Temp 10m | 23° | 20.63 | 20.5 |
| Delta Temperature (°C) | N/A | -0.98 | -0.808 |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 643.97 | 655 |
| Barometric Pressure (mmHg) | N/A | 654.09 | 654.0 |
| Battery Voltage (V) | N/A | 12.77 | 12.8 |
| Time (MST) | N/A | 1:28 | 1330 HRS LT |
| Date | N/A | 11/08/2013 | 11.8.2013 |

1300 – 197.0
1315 – 202.0
1345 – 249.0
1400 – 120.0

*Direction wind is from

Comments/Unusual Occurrences or Weather: * WD IS NOT +/- 20° of 15min AVE Audit vs 2ND LOGGER SCAN – ACTION PLAN CONTINUE TO MONITOR – RPA

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Karen Ballard

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 11/15/2013 Time: 1:50 Operator: Kara Bell

| YES | NO** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC. DENVER • PORTLAND

REVIEWED BY JR 11-18-13 DATE 11/18/13

AUDITED BY RPA DATE

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 4 m/s | 3.58 | 3.93 |
| Direction* 10m (deg) | SW | 226.59 | 189.4 * |
| Ambient Temperature (°C) | 21° | 19.67 | 19.42 |
| Relative Humidity (%) | 30% | 35% | 35.9 |
| Aspirated Temp 2m | 21° | 19.24 | 19.2 |
| Aspirated Temp 10m | 20° | 18.53 | 18.44 |
| Delta Temperature (°C) | N/A | -0.86 | -0.73 |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 322.44 | 409.4 |
| Barometric Pressure (mmHg) | N/A | 646.32 | 646.3 |
| Battery Voltage (V) | N/A | 12.81 | 12.81 |
| Time (MST) | N/A | 1:52 | 1400 Hrs AVE |
| Date | N/A | 11/15/2013 | 11-15-2013 |

* 202.6
199.1
181.4
203.2

*Direction wind is from

Comments/Unusual Occurrences or Weather: Refilled evap pan. * EVAP SYSTEM WIND NOT SHOWN IN VOLUME
* 2 SEC SCAN VALVE VS 15 MIN AVERAGE FOR WD OUTSIDE +/- 20° - RPA

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kara Bell

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 11/21/2013 Time: 10:54 Operator: Kami BaCCaG

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC
REVIEWED BY: WR DENVER · PORTLAND DATE: 12-10-13
AUDITED BY: RPA DATE: 11-26-13

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 2 m/s | 2.41 | 3.626 |
| Direction* 10m (deg) | SE | 194.95 | 190.8 |
| Ambient Temperature (°C) | 16° | 14.83 | 14.92 |
| Relative Humidity (%) | 40% | 48.20 | 47.95 |
| Aspirated Temp 2m | 16° | 14.14 | 14.74 |
| Aspirated Temp 10m | 15° | 14.19 | 13.98 |
| Delta Temperature (°C) | N/A | -0.04 | -0.76 |
| Solar Radiation (w/m²) | Sunny Partly cloudy (Cloudy) | 444.48 | 374.5 |
| Barometric Pressure (mmHg) | N/A | 651.61 | 651.6 |
| Battery Voltage (V) | N/A | 12.87 | 12.88 |
| Time (MST) | N/A | 10:57 | 1100 hrs 15mn Rec. |
| Date | N/A | 11/21/2013 | 11-21-13 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Reset chain & calibrated evap. gugge.

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: Kami BaCCaG

AIR SCIENCES INC.

**EAST PLANT**
**MET SITE CHECK FORM**
**Resolution**
**PROJECT NO. 262-1**

Date: 11/26/2013 Time: 1437 Operator: TEL
Tom White

| YES | NO | |
|---|---|---|
| ✓ | | 1. The tower is intact and upright. |
| ✓ | | 2. The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. The aspirator fans are operating. |
| ✓ | | 5. The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. The solar panel is facing south and is clean. |
| ✓ | | 7. The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. The data logger is reading the correct time and day. |
| ✓ | | 9. The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. Estimate and document the parameters below. |

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 30 | 7.62 | 8.55 ✓ |
| Direction* 10m (deg) | 20° | 36.02° | 35.41 ✓ |
| Ambient Temperature (°C) | 55°F | 12.09°C | 11.94 ✓ |
| Relative Humidity (%) | 10% | 38.2 | 38.33 ✓ |
| Aspirated Temp 2m | 55°F | 12.04°C | 11.88 ✓ |
| Aspirated Temp 10m | 54°F | 11.46°C | 11.33 ✓ |
| Delta Temperature (°C) | N/A | -0.59°C | -0.545 ✓ |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 437.16 | 449.1 ✓ |
| Barometric Pressure (mmHg) | N/A | 656.47 | 656.5 ✓ |
| Battery Voltage (V) | N/A | 12.94 | 12.95 ✓ |
| Time (MST) | N/A | 1442 | 1445 HRS ✓ |
| Date | N/A | 11/26/2013 | 11-26-13 ✓ |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Sunny and clear

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: T L

- Tom White of Resolution is being trained on Site operator tasks.
- Invalidated 0.008" OF PRECIP RECORDED BY THE SITE OPERATOR.
RPA

AIR SCIENCES INC.
DENVER • PORTLAND
WR 12-10-13
REVIEWED BY RPA DATE 11-26-13
AUDITED BY DATE

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/06/2013 Time: 09:10 Operator: Tom White

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC
RPA 12/10/13
REVIEWED BY DATE
AUDITED BY GG. DATE 12/09/13

| Parameter | Estimated | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | 10 m/s | 0.51 m/s | 1.14 |
| Direction* 10m (deg) | 90° | 86.41° | 83.3 |
| Ambient Temperature (°C) | 1°C | 2.42°C | 2.44 |
| Relative Humidity (%) | 20% | 42.63% | 43.5 |
| Aspirated Temp 2m | 1°C | 0°C | 1.15 |
| Aspirated Temp 10m | 0°C | 0.82°C | 0.521 |
| Delta Temperature (°C) | N/A | -0.645 | -0.628 |
| Solar Radiation (w/m$^2$) | (Sunny) Partly cloudy Cloudy | 403.88 | 375 |
| Barometric Pressure (mmHg) | N/A | 654.32 | 654 |
| Battery Voltage (V) | N/A | 13.21 | 13.2 |
| Time (MST) | N/A | 09:16 | 09:15 |
| Date | N/A | 12/06/2013 | 12/06/2013 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: Noted bird perched on temp shield

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: T White

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/12/2013 Time: 13:45 Operator: Tom White

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/19/13
AUDITED BY GG DATE 12/13/13

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 5 | 3.27 | 4.98 | + |
| Direction* 10m (deg) | 040 | 041 | 40.3 | + |
| Ambient Temperature (°C) | 20 | 14.32 | 14.8 | + |
| Relative Humidity (%) | 30% | 36.91 | 34.7 | + |
| Aspirated Temp 2m | 20 | 14.26 | 14.7 | + |
| Aspirated Temp 10m | 19.5 | 13.39 | 13.6 | + |
| Delta Temperature (°C) | N/A | -0.91 | -1.16 | + |
| Solar Radiation (w/m$^2$) | Sunny (Partly cloudy) Cloudy | 553.81 | 516 | + |
| Barometric Pressure (mmHg) | N/A | 654.67 | 655 | + |
| Battery Voltage (V) | N/A | 12.87 | 12.9 | + |
| Time (MST) | N/A | 13:51 | 13:45 | + |
| Date | N/A | 12/12/13 | 12/12/13 | + |

*Direction wind is from

Comments/Unusual Occurrences or Weather: _____

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: T White

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/19/2013 Time: 13:14 Operator: TEW

| YES | NO ** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC.
RPA DENVER • PORTLAND 12-26-13
REVIEWED BY DATE
AUDITED BY GG DATE 12/23/13

| Parameter | Estimated ~~1.5~~ | Logger | Audit |
|---|---|---|---|
| Speed 10m (m/s) | ~~10~~ 1.5 | 6.86 | 4.01 |
| Direction* 10m (deg) | 100 | 157 | 157 |
| Ambient Temperature (°C) | 18 | 15.01 | 15 |
| Relative Humidity (%) | 30% | 20.51 | 21.1 |
| Aspirated Temp 2m | 18 | 14.62 | 14.6 |
| Aspirated Temp 10m | 17.6 | 13.61 | 13.6 |
| Delta Temperature (°C) | N/A | -1.00 | -0.987 |
| Solar Radiation (w/m²) | (Sunny) Partly cloudy Cloudy | 620.14 | 606 |
| Barometric Pressure (mmHg) | N/A | 646.30 | 646 |
| Battery Voltage (V) | N/A | 12.91 | 12.9 |
| Time (MST) | N/A | 13:16 | 13 15 |
| Date | N/A | 12/19/13 | 12/19/13 |

*Direction wind is from

Comments/Unusual Occurrences or Weather: _____

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

Site Operator Signature: TEW

AIR SCIENCES INC.

# EAST PLANT
## MET SITE CHECK FORM
## Resolution
## PROJECT NO. 262-1

Date: 12/27/13 Time: 11:10 Operator: TEW

| YES | NO** | | |
|---|---|---|---|
| ✓ | | 1. | The tower is intact and upright. |
| ✓ | | 2. | The anemometer propeller and the wind direction vane are turning freely. |
| ✓ | | 3. | All temperature shields are intact, and the probes are inside their shields. |
| ✓ | | 4. | The aspirator fans are operating. |
| ✓ | | 5. | The solar radiation sensor is level and has been cleaned. |
| ✓ | | 6. | The solar panel is facing south and is clean. |
| ✓ | | 7. | The precipitation gauge is clean and free of bugs and dust. * GG |
| ✓ | | 8. | The data logger is reading the correct time and day. |
| ✓ | | 9. | The site has been visually inspected for unusual wildlife occurrences (dead birds, etc.). |
| ✓ | | 10. | Estimate and document the parameters below. |

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/30/13
AUDITED BY GG. DATE 12/30/13

| Parameter | Estimated | Logger | Audit | |
|---|---|---|---|---|
| Speed 10m (m/s) | 8 | 10.24 | 8.74 | + |
| Direction* 10m (deg) | 35 | 52.96 | 35.3 | + |
| Ambient Temperature (°C) | 16 | 11.4 | 11.5 | + |
| Relative Humidity (%) | 20 | 25.36 | 25.5 | + |
| Aspirated Temp 2m | 16 | 11.35 | 11.4 | + |
| Aspirated Temp 10m | 15.5 | 10.70 | 10.7 | + |
| Delta Temperature (°C) | N/A | -0.65 | -0.737 | + |
| Solar Radiation (w/m²) | Sunny Partly cloudy Cloudy | 607.62 | 604 | + |
| Barometric Pressure (mmHg) | N/A | 657.49 | 657 | + |
| Battery Voltage (V) | N/A | 12.96 | 13 | + |
| Time (MST) | N/A | 11:11 | 11:15 | + |
| Date | N/A | 12/27/13 | 12/27/13 | + |

*Direction wind is from

Comments/Unusual Occurrences or Weather: G.G. * 12/27/13 @ 11:15hr. precip gauge might've been tipped by Site Operator - reading 0.043. Both sites checked - no precip

When form is completed, please fax to Air Sciences Inc. @ 303-279-3796 (no cover sheet is necessary).

recorded @ RH 25.5° EAST, 15.6° WEST.

Invalidated! ✓ RPA

Site Operator Signature: Tom White

# Appendix I: East Plant $PM_{10}$ and $PM_{2.5}$ Site Check Forms and Flow Audits

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 10/4/2013 Time: 9:24 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). Power fail at 05:45 9/30/2013 |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Inlet Flow check Performed |
| | | | 2. | Visual inspection and dust removal |
| | | | 3. | Leak check performed |
| | | | 4. | PM10 particle trap cleaned |
| | | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
WR DENVER • PORTLAND 10/8/13
REVIEWED BY DATE
RPA 10.7.13
AUDITED BY DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Filter tape replaced |
| | | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences:** _____

Signature: TWis

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/11/2013 Time: 0829 Operator: TEW

**I. BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/9 Tape Latch |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

RPA

AIR SCIENCES INC.
DENVER • PORTLAND

WR 10/25/13
REVIEWED BY DATE
RPA 10-21-13
AUDITED BY DATE

**II. BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

RPA

**III. BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

**IV. BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

**Comments/Unusual Occurrences: _____

Signature: _____

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/18/2013 Time: 8:37 Operator: Kami BeCard

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/09 → Tape Latch |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Inlet Flow check Performed |
| | | | 2. Visual inspection and dust removal |
| | | | 3. Leak check performed |
| | | | 4. PM10 particle trap cleaned |
| | | | 5. Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY WR DATE 10/25/13
AUDITED BY RPA DATE 10-21-13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Filter tape replaced |
| | | | 2. Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | | 2. Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | | 2. Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: K. Ballard

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 10/30/2013 Time: 14:02 Operator: Karen BeCle a

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/09 → Tape Later |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| ✓ | | 5. | Inlet nozzle and nozzle are cleaned |

10/31

AIR SCIENCES INC
DENVER • PORTLAND
REVIEWED BY RPA DATE 11/19/13
AUDITED BY DATE 11-13-13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function – 10/31 |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

RPA

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

RPA

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Karen BeCle a

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY JR DATE 11/19/13
AUDITED BY RPA DATE 11-13-13

AIR SCIENCES INC.

# Monthly Flow Verification $PM_{10}$

**East Plant**
**PARTICULATE MONITORING PROJECT**
PROJECT NO. 262-1

Met One $PM_{10}$: S/N: M8714
Firmware:
Calibrator: Delta Cal S/N: 1034

Date of Flow Audit: 10/31/2013
Time of Flow Audit: 9:41

| | BAM | STD | Cal |
|---|---|---|---|
| Ambient Temperature (AT) °c | 13.5 | 15.1 | ~~14~~.8 * |
| Berometric Pressure mmHg | 663 | 655 | 655.5 |

RPA

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0.0 | 15.34 | -2.2 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.3 | -0.5 | 18.78 | -2.6 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.8 | 0.6 | 17.01 | -1.2 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

RPA

RPA

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | .3 | **Should be < 1.0 LPM** |

Comments/Abnormalities: Self Test - "Passed" ✓

* BP IS DRIFTING - POTENTIAL SAMPLER BP SENSOR ISSUE - CONSULT WITH MET ONE WILL BE CONDUCTED FOR CORRECTIVE ACTIONS - RPA

Signature: [signature]

Upon completion of this form, fax to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
**RESOLUTION MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/08/2013 Time: 1:32 Operator: Kam BaClard

**I. BAM SAMPLER – Weekly Checks.**

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/31 → Maintenance |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER – Routine Maintenance (monthly).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Inlet Flow check Performed |
| | | | 2. Visual inspection and dust removal |
| | | | 3. Leak check performed |
| | | | 4. PM10 particle trap cleaned |
| | | | 5. Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

JR — 11/19/13
REVIEWED BY — DATE

RAA — 11-13-13
AUDITED BY — DATE

**II. BAM SAMPLER – Routine Maintenance (every 2 months).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Filter tape replaced |
| | | | 2. Ran the Self-Test function |

**III. BAM SAMPLER – Routine Maintenance (semiannual).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | | 2. Complete calibration of flow system (*Work performed by Air Sciences) |

**IV. BAM SAMPLER – Routine Maintenance (annual).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | | 2. Inlet system cleaned (*Work performed by Air Sciences) |

**"Comments/Unusual Occurrences:** 10-31-13 = MONTHLY FLOW VERIFICATION, 1000 HRS CONCENTRATION IS INVALID. —RPA

Signature: Kam BaClard

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/15/2013 Time: 1:48 Operator: Karen Ballard

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). N/A |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

RPA

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY RPA DATE 11/18/13

AUDITED BY DATE 11-18-13

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

RPA

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

**Comments/Unusual Occurrences: _____

Signature: Karen Ballard

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/21/2013 Time: 11:01 Operator: Kara Baldwin

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/31 → Delta Pressure |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

RPA

| YES | NO | | |
|---|---|---|---|
| | | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

WR 12-10-13
REVIEWED BY DATE
RPA 1-26-13
AUDITED BY DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

RPA

| YES | NO | | |
|---|---|---|---|
| | | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

RPA

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

RPA

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kara Baldwin

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 11/26/2013 Time: 1446 Operator: TEW
Tom White

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/31 delta pressure |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

*Comments/Unusual Occurrences: _____

Signature: _____

**Fax completed form to Air Sciences at 303-279-3796

- HOURLY CONCENTRATIONS FOR 1500 THRU 1600 HRS INVALIDATED DUE TO MAINT., AND MONTHLY FLOW VERIFICATIONS. -RPA

AIR SCIENCES INC
DENVER • PORTLAND

REVIEWED BY WR DATE 12-10-13
AUDITED BY RPA DATE 11-26-13

AIR SCIENCES INC.

## Monthly Flow Verification $PM_{10}$

**East Plant**
**PARTICULATE MONITORING PROJECT**
PROJECT NO. 262-1

Met One $PM_{10}$ S/N: M~~8714~~ 8714
Firmware:
Calibrator: Bdtx Cal S/N: 1034

Date of Flow Audit: 11/26/2013
Time of Flow Audit: 1450

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 13.6 | 13.6 |
| Berometric Pressure mmHg | 664 | 656.5 * |

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) | |
|---|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.1 | 0.7 | 15.53 | -2.8 | RPA |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* | |
| (2) Actual Flow | 18.4 | 18.4 | 0.0 | 19.05 | -3.4 | RPA |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* | |
| (3) Actual Flow | 16.7 | 16.7 | 0.0 | 17.17 | -2.2 | RPA |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* | |

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | ~~0.3~~ 0.3 | **Should be < 1.0 LPM** |

Comments/Abnormalities: Self test Passed

Signature: [signature] Tom White

Upon completion of this form, fax to Air Sciences at 303-279-3796

Tom White = BACK-UP SITE OPERATOR IN TRAINING

- INVALIDATED 1500 THRU 1600 HRS DUE TO MAINT.
- BP AND 18.4 SET POINT NOTED, MONITOR DUE FOR CALIBRATION IN DECEMBER 2013.

RPA

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY WR DATE 12-10-13
AUDITED BY RPA DATE 12-26-13

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/06/2013 Time: 09:18 Operator: TEL

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/26 20:24: Reference withdraw 11/26 14:56: Maintenance |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
RPA 12/10/13
REVIEWED BY DATE
AUDITED BY G.G. DATE 12/09/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

G.G.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: Lookin' good

Signature: [signature]

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 12/12/13 Time: 13:58 Operator: Tom White

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/26 1454: Maintenance |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO GG -

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
RPA 12/19/13
REVIEWED BY DATE
AUDITED BY GG - 12/13/13
DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO GG -

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO GG -

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: Changed Filter Tape ★

★ 12/12/2013 15:00 shows conc/tape/flow error - invalidated by DAES (GG)

Signature: Tom White

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 12/19/13 Time: 13:29 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | |
|---|---|---|
| ✓ | | 1. The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. The vacuum pump is running and sounds normal. |
| ✓ | | 3. The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. The BAM is reading the correct time and day. |
| ✓ | | 5. The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. Error log was checked (F3), and errors followed up on (see manual). Nothing recent |
| ✓ | | 7. Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | G.G. | |
|---|---|---|---|
| | ✓ | | 1. Inlet Flow check Performed |
| | ✓ | | 2. Visual inspection and dust removal |
| | ✓ | | 3. Leak check performed |
| | ✓ | | 4. PM10 particle trap cleaned |
| | ✓ | | 5. Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC
DENVER • PORTLAND
REVIEWED BY APA DATE 12-26-13
AUDITED BY GG. DATE 12/23/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | G.G. | |
|---|---|---|---|
| | ✓ | | 1. Filter tape replaced |
| | ✓ | | 2. Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | G.G. | |
|---|---|---|---|
| | ✓ | | 1. Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | | 2. Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | G.G. | |
|---|---|---|---|
| | ✓ | | 1. Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | | 2. Inlet system cleaned (*Work performed by Air Sciences) |

"Comments/Unusual Occurrences: updated clock * G.G.

* Maintenance error for the 14:00 hour due to the above procedure (invalidated by DASS)

Signature: TEW

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM10 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/27/13 Time: 11:22 Operator: TEW

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/30/13
AUDITED BY GG- DATE 12/30/13

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 12/20 14:17 Power Fail #2 |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed GG. |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced #1 |
| ✓ | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) GG- |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) GG- |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: #1 self test passed

GG #1 12/27/13 12:00 hrs. concentration invalidated due to maintenance.

#2 12/20/13 14:00 to 15:00 concentration invalidated due to power outage. ✓ RPA

Signature: Tom White

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.

# Monthly Flow Verification $PM_{10}$

**East Plant**
**PARTICULATE MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/30/13
AUDITED BY DATE 12/30/13

Met One $PM_{10}$: S/N: M 8714
Firmware:
Calibrator: Delta Cal S/N: 1034 Exp. 8/2014

Date of Flow Audit: 12/27/2013
Time of Flow Audit: 11:40

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 12.3 | 12.5 |
| Berometric Pressure mmHg | 651 | 657 |

6.6. 6.6.

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0 | 15.15 | -0.99 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.4 | 0 | 18.67 | -1.45 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.7 | 0 | 16.83 | -0.77 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | .3 | **Should be < 1.0 LPM** |

Comments/Abnormalities: Self Test "Passed"

Signature: Kam Bach

Upon completion of this form, fax to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/4/2013 Time: 9:26 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). little low |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 9/30-10/4 BAM cal membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Inlet Flow check Performed |
| | | 2. | Visual Inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

RPA

AIR SCIENCES INC.
DENVER • PORTLAND

WR — REVIEWED BY — 10/8/13 — DATE

RPA — AUDITED BY — 10.9.13 — DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

RPA

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

**Comments/Unusual Occurrences: _____

Signature: _____

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 10/11/2013 Time: 0832 Operator: TEN

**I. BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/10 BAM Cal membrane 5% (1858) (2058) |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) 10/9 1435 - maintenance ,檀 - 2 messages at 1430 |

**II. BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

RPA

AIR SCIENCES INC.
WR DENVER • PORTLAND 10/25/13
REVIEWED BY RPA DATE ~~10-21-13~~
AUDITED BY DATE 10-21-13

**II. BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

RPA

**III. BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

**IV. BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

**Comments/Unusual Occurrences: _____

Signature: _____

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/18/2013 Time: 8:52 Operator: Kara Ballard

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10-14 → 10/18 → BAM CAL Membrane 6% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Inlet Flow check Performed |
| | | 2. | Visual inspection and dust removal |
| | | 3. | Leak check performed |
| | | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | | 5. | Inlet nozzle and nozzle are cleaned |

RPA

AIR SCIENCES INC.
DENVER • PORTLAND

WR 10/25/13
REVIEWED BY DATE

RPA 10-21-13
AUDITED BY DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Filter tape replaced |
| | | 2. | Ran the Self-Test function |

RPA

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

**Comments/Unusual Occurrences: _____

Signature: Kara Ballard

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 10/23/2013 Time: 1:36 Operator: Kara BeCOed

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/19 – 10/23 → BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Inlet Flow check Performed |
| | | | 2. | Visual inspection and dust removal |
| | | | 3. | Leak check performed |
| | | | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | | | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY JR DATE 11/19/13

AUDITED BY RPA DATE 11-13-13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Filter tape replaced |
| | | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | | |
|---|---|---|---|---|
| | | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kara BeCOed

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 10/30/2013 Time: 14:05 Operator: Kam Ballard

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 10/26–10/30 → BAM Cal 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| ✓ | | 5. | Inlet nozzle and nozzle are cleaned |

10/31

AIR SCIENCES INC
DENVER • PORTLAND

REVIEWED BY JR 11/19/13 DATE
AUDITED BY RPA 11.13.13 DATE

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function – 10/31 |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

RPA

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

RPA

**Comments/Unusual Occurrences: _____

Signature: Kam Ballard

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.

# Monthly Flow Verification $PM_{2.5}$

East Plant
PARTICULATE MONITORING PROJECT
PROJECT NO. 262-1

Met One $PM_{2.5}$: S/N: M8133
Firmware:
Calibrator: Delta Cal S/N:

Date of Flow Audit: 10/30/2013
Time of Flow Audit: 13:05

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 20.0 | 18.6 |
| Berometric Pressure mmHg | 685 | 682.5 |

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0.000 | 15.25 | -1.639 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.4 | 0.000 | 18.85 | -2.387 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.7 | 0.000 | 17.01 | -1.822 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | 0.2 | **Should be < 1.0 LPM** |

AIR SCIENCES INC. DENVER - PORTLAND
RPA 11/14/13
REVIEWED BY DATE
KSD 11/14/13
AUDITED BY DATE

Comments/Abnormalities: Ran Self Test — "PASSED"

Signature: Kam Bal

Upon completion of this form, fax to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
**RESOLUTION MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 11/08/2013 Time: 1:35 Operator: Ken Bace

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND

JR — REVIEWED BY — 11/19/13 DATE

RPA — AUDITED BY — 11.13.13 DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Ken Bace

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/15/2013 Time: 1:53 Operator: Kami Bold

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/11 – 11/15 → BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | ✓ | | 1. Inlet Flow check Performed |
| | ✓ | | 2. Visual inspection and dust removal |
| | ✓ | | 3. Leak check performed |
| | ✓ | | 4. PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | | 5. Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC. DENVER • PORTLAND
REVIEWED BY JR 11/18/13 DATE
AUDITED BY RPA 11-18-13 DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | ✓ | | 1. Filter tape replaced |
| | ✓ | | 2. Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | ✓ | | 1. Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | | 2. Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | ✓ | | 1. Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | | 2. Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: INVALIDATED THE 1400 HRS CONC & FLOW DUE TO A COUNT ERROR ON 11-15-13 – RPA – ERROR POPULATED DURING SITE VISIT. RPA

Signature: Kami Bold

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 11/21/2013 Time: 11:03 Operator: Kara BaCCol

**I. BAM SAMPLER – Weekly Checks.**

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/17-11/21 → BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER – Routine Maintenance (monthly).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Inlet Flow check Performed |
| | | | 2. Visual inspection and dust removal |
| | | | 3. Leak check performed |
| | | | 4. PM10 and 2.5 cyclone particle trap cleaned |
| | | | 5. Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY WR DATE 12-10-13
AUDITED BY RPA DATE 11-26-13

**II. BAM SAMPLER – Routine Maintenance (every 2 months).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Filter tape replaced |
| | | | 2. Ran the Self-Test function |

**III. BAM SAMPLER – Routine Maintenance (semiannual).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Replaced muffler on the pump (*Work performed by Air Sciences) |
| | | | 2. Complete calibration of flow system (*Work performed by Air Sciences) |

**IV. BAM SAMPLER – Routine Maintenance (annual).** Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | RPA | |
|---|---|---|---|
| | | | 1. Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | | | 2. Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: Kara BaCCol

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.

Date: 11/26/2013 Time: 14:50 Operator: [signature]

I. BAM SAMPLER – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 11/22 - 11/26 → BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. BAM SAMPLER – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Inlet Flow check Performed |
| ✓ | | 2. | Visual Inspection and dust removal |
| ✓ | | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| ✓ | | 5. | Inlet nozzle and nozzle are cleaned |

II. BAM SAMPLER – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

III. BAM SAMPLER – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) RPA |
| | | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. BAM SAMPLER – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) RPA |
| | | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: _____

Signature: [signature]

**Fax completed form to Air Sciences at 303-279-3796

– HOURLY CONCENTRATION FOR 1600 HRS ON 11-26-13 INVALIDATED DUE TO MONTHLY FLOW VERIFICATIONS.
RPA

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY WR DATE 12-10-13
AUDITED BY RPA DATE 11-26-13

AIR SCIENCES INC.

## Monthly Flow Verification PM~~10~~ 2.5

**East Plant**
PARTICULATE MONITORING PROJECT
PROJECT NO. 262-1

Met One PM~~10~~ 2.5 S/N: M~~8744~~6466
Firmware:
Calibrator: Delta Calibrator S/N: 1034

Date of Flow Audit: 11/26/2013
Time of Flow Audit: 1505

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 13.2 | 13.1 |
| Berometric Pressure mmHg | 658 | ~~656~~,5 |

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) | |
|---|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0.0 | 15.6 | -3.4 | RPA |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* | |
| (2) Actual Flow | 18.4 | 18.4 | 0.0 | 19.10 | -3.4 | RPA |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* | |
| (3) Actual Flow | 16.7 | 16.9 | 0.6 | 17.48 | -3.9 | RPA |
| *Acceptable Differential* | | *16.366 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* | |

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | ~~0.0~~ 0.4 | **Should be < 1.0 LPM** |

Comments/Abnormalities: Self-test Passed

Signature: [signature]

Upon completion of this form, fax to Air Sciences at 303-279-3796 Tom White

- Tom White = Back-up site operator.

- All set points are close to exceeding acceptable differentials, monitor due for calibration in December 2013.
RPA

AIR SCIENCES INC.
DENVER • PORTLAND

WR
REVIEWED BY 12-10-13 DATE

RPA
AUDITED BY 11-26-13 DATE

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
**RESOLUTION MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/6/2013 Time: 09:22 Operator: TEL

**I. BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 12/6 0858: BAM Cal Membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

**II. BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO G.G.

| | | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY RPA DATE 12/10/13
AUDITED BY G.G. DATE 12/09/13

**II. BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO G.G.

| | | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

**III. BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO G.G.

| | | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

**IV. BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO G.G.

| | | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

**Comments/Unusual Occurrences: Looks good

Signature: T Tucker

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/12/2013 Time: 1348 Operator: Tom White

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). 12/12 every hour; BAM cal membrane 5% |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

GG -

AIR SCIENCES INC.
RPA 12/19/13
REVIEWED BY DATE
GG- 12/13/13
AUDITED BY DATE

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

GG-

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

GG-

Comments/Unusual Occurrences: Changed Filter Tape

★ 12/12/2015 15:00 shows cont/tape/flow errors - invalidated by DASS.
Filter tape change caused BAM malfunction 3hr. later from 12/12/13 19:00 through 12/13/13 12:00 - invalidated by DASS.
Site Operator contacted - issue resolved! ~~BAM~~
BAM back online 12/13/13 13:00!

Signature: T White

**Fax completed form to Air Sciences at 303-279-3796

(G.G.)

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/19/13 Time: 13:17 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM CAL membrane 5%. |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

AIR SCIENCES INC.
REVIEWED BY RAA DATE 12-26-13
ENTERED BY GG DATE 12/23/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| | ✓ | 2. | Ran the Self-Test function |

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

YES NO 6.6.

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) * 6.6. |

**Comments/Unusual Occurrences: updated clock

* Maintenance error for the 14:00 hour due to the above procedure (unvalidated by DASS)

Signature: TEW

**Fax completed form to Air Sciences at 303-279-3796

# EAST PLANT

BAM PM 2.5 WEEKLY SITE CHECK FORM
RESOLUTION MONITORING PROJECT
PROJECT NO. 262-1

AIR SCIENCES INC.
DENVER • PORTLAND

Date: 12/27/13 Time: 11:13 Operator: TEW

I. **BAM SAMPLER** – Weekly Checks.

| YES | NO | | |
|---|---|---|---|
| ✓ | | 1. | The sampler is intact and the inlet head is unobstructed. |
| ✓ | | 2. | The vacuum pump is running and sounds normal. |
| ✓ | | 3. | The temperature shield is intact, and the sensor is inside of it. |
| ✓ | | 4. | The BAM is reading the correct time and day. |
| ✓ | | 5. | The tape is in the proper position and does not need to be changed (tape should be changed every 2 months). |
| ✓ | | 6. | Error log was checked (F3), and errors followed up on (see manual). BAM Cal Chk. 5% 12/23-12/27 |
| ✓ | | 7. | Climate control appears operational (If it's cold out the shelter should feel warm, if it's hot out the shelter should feel cool) |

II. **BAM SAMPLER** – Routine Maintenance (monthly). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Inlet Flow check Performed |
| | ✓ | 2. | Visual inspection and dust removal |
| | ✓ | 3. | Leak check performed |
| | ✓ | 4. | PM10 and 2.5 cyclone particle trap cleaned |
| | ✓ | 5. | Inlet nozzle and nozzle are cleaned |

G.G.

AIR SCIENCES INC.
DENVER • PORTLAND

RPA 12/30/13
REVIEWED BY DATE

AUDITED BY G.G. DATE 12/30/13

II. **BAM SAMPLER** – Routine Maintenance (every 2 months). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Filter tape replaced |
| ✓ | | 2. | Ran the Self-Test function |

*

III. **BAM SAMPLER** – Routine Maintenance (semiannual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Replaced muffler on the pump (*Work performed by Air Sciences) |
| | ✓ | 2. | Complete calibration of flow system (*Work performed by Air Sciences) |

G.G.

IV. **BAM SAMPLER** – Routine Maintenance (annual). Check yes if maintenance was performed during this visit. *See page 56 of BAM manual.*

| YES | NO | | |
|---|---|---|---|
| | ✓ | 1. | Carbon vanes in pump checked/replaced (*Work performed by Air Sciences) |
| | ✓ | 2. | Inlet system cleaned (*Work performed by Air Sciences) |

G.G.

**Comments/Unusual Occurrences: * self test passed

G.G.* 12/27/13 12:00 hrs. concentration invalidated due to maintenance.

Signature: T White
Tom White

**Fax completed form to Air Sciences at 303-279-3796

AIR SCIENCES INC.

# Monthly Flow Verification $PM_{2.5}$

**East Plant**
**PARTICULATE MONITORING PROJECT**
PROJECT NO. 262-1

AIR SCIENCES INC.
REVIEWED BY RPA DATE 12/30/13
AUDITED BY G.G. DATE 12/30/13

Met One $PM_{2.5}$: S/N: M6466
Firmware:
Calibrator: Delta Cal S/N: 1034 EXP. 8/2014

Date of Flow Audit: 12/27/2013
Time of Flow Audit: 11:40

| | BAM | STD |
|---|---|---|
| Ambient Temperature (AT) °c | 11.8 | 12.3 |
| Berometric Pressure mmHg | 660 | 657 |

G.G. G.G.

| | Set Point (lpm) | BAM | % Diff (1) | STD Flow Meter | % Diff (2) |
|---|---|---|---|---|---|
| (1) Actual Flow | 15 | 15.0 | 0 | 15.72 | -4.58 |
| *Acceptable Differential* | | *14.700 - 15.300* | *+/- 2%* | *14.250 - 15.750* | *+/- 5%* |
| (2) Actual Flow | 18.4 | 18.3 | -054 | 19.13 | -4.34 |
| *Acceptable Differential* | | *18.032 - 18.768* | *+/- 2%* | *17.480 - 19.320* | *+/- 5%* |
| (3) Actual Flow | 16.7 | 16.7 | 0 | 17.43 | -4.19 |
| *Acceptable Differential* | | *16.336 - 17.034* | *+/- 2%* | *15.865 - 17.535* | *+/- 5%* |

+

Calculations:
(1) % Diff = [(BAM - Set Point)/Set Point]*100 (+/- 2%)
(2) % Diff = [(BAM - Calibrator)/Calibrator]*100 (+/- 5%)

| | BAM | |
|---|---|---|
| (2) Leak Test | .4 | **Should be < 1.0 LPM** |

Comments/Abnormalities: + Monitor due for Calibration in JAN 14 - RPA

Signature:

Upon completion of this form, fax to Air Sciences at 303-279-3796

# Appendix J: East Plant $SO_2$, $NO_x$, and $O_3$ Site Check and Audit Forms

AIR SCIENCES INC.
DENVER • PORTLAND
WR 10/13/13
REVIEWED BY DATE
RPA 10-21-13
AUDITED BY DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $SO_2$ Monitoring Form

Site Operator: Kami BaClard Date: 10/18/2013

| | | |
|---|---|---|
| Sampler Make/Model | | T100 |
| Sampler SN | | SN 193 |
| Dilution Calibrator Model/SN | Primary | T700/SN191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 901 LT |
| Instrument Check Stop Time | 9:[illegible] LT |
| Filter Replacement Y/N | No |
| Shelter Temp (5 to 40 °C) | 26.5 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40% 80 |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span with the T700 Dynamic Dilution Calibrator:

| Target Dilution (PPB) | SO2 Response (PPB) | Final SO2 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .097 | — | ± 3% of Full Scale (-15 to 15 PPB) | No |
| 100 | 98.71 | — | ≤ ± 10% (90 to 110 PPB) | No |

Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T100 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .097 | .093 | ± 2 PPB | No |
| 100 PPB | 98.71 | 99.5 | ± 2 PPB | No |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (450 ± 45 cc/min)* | 456 | *Sample Press. (Ambient ± 2 in-Hg)* | 26.1 |
| *UV Lamp (1000 - 4800 mV)* | 2698.9 | *Lamp Ratio (30 - 120%)* | 75.2 |
| *Slope (1 ± 0.3)* | 1.239 | *BOX Temp. (Ambient ± 5°C)* | 32.8 |
| *Offset (< 250 mV)* | 16.7 | *HVPS (400 - 900 V)* | 571 |

**Operator comments/observations:**
INVALIDATED THE 1000 HRS HOURLY FILE ON 10/18/13 - RPA

Operator Signature: Kami BaClard

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $SO_2$ Monitoring Form

Site Operator: Kami Ballard Date: 10/30/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T100 |
| Sampler SN | | SN193 |
| Dilution Calibrator Model/SN | Primary | T700 / SN191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 14:28 |
| Instrument Check Stop Time | 14:39 |
| Filter Replacement Y/N | No |
| Shelter Temp (5 to 40 °C) | 26.6 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40% SO 40 ppm RPA |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator:

| Target Dilution (PPB) | SO2 Response (PPB) | Final SO2 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .327 | — | ± 3% of Full Scale (-15 to 15 PPB) | No |
| 100 | 99.33 | — | ≤ ± 10% (90 to 110 PPB) | No |

Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T100 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .327 | .43 | ± 2 PPB | No |
| 100 PPB | 99.33 | 99.94 | ± 2 PPB | No |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (450 ± 45 cc/min)* | 458 450 | *Sample Press. (Ambient ± 2 in-Hg)* | 25.8 25.3 |
| *UV Lamp (1000 - 4800 mV)* | 2676.5 | *Lamp Ratio (30 - 120%)* | 74.6 |
| *Slope (1 ± 0.3)* | 1.239 | *BOX Temp. (Ambient ± 5°C)* | 33.8 |
| *Offset (< 250 mV)* | 16.7 | *HVPS (400 - 900 V)* | 571 |

Operator comments/observations:

INVALIDATED THE HOURLY CONCENTRATION OF $SO_2$ @ 1500 HRS DUE TO LEVEL 1 PROCEDURES - RPA

Operator Signature: Kami Ballard

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY JR 11/19/13 DATE

AUDITED BY RPA 11-13-13 DATE

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY JR 11/19/13
AUDITED BY RPA 11-18-13 DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $SO_2$ Monitoring Form

Site Operator: Kami Ballard Date: 11/15/2013

| | | |
|---|---|---|
| Sampler Make/Model | | T100 |
| Sampler SN | | SN/193 |
| Dilution Calibrator Model/SN | Primary | T700/SN 191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 14:10 |
| Instrument Check Stop Time | 14:21 |
| Filter Replacement Y/N | Yes |
| Shelter Temp (5 to 40 °C) | 25.37 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | ~~40% SO~~ 40 PPM SO |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span with the T700 Dynamic Dilution Calibrator:

| Target Dilution (PPB) | SO2 Response (PPB) | Final SO2 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .581 | — | ± 3% of Full Scale (-15 to 15 PPB) | No |
| 100 | 98.070 | — | ≤ ± 10% (90 to 110 PPB) | No |

Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T100 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .581 | .56 | ± 2 PPB | No |
| 100 PPB | 98.070 | 98.94 | ± 2 PPB | No |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (450 ± 45 cc/min)* | 451 | *Sample Press. (Ambient ± 2 in-Hg)* | 25.8 |
| *UV Lamp (1000 - 4800 mV)* | 2652.5 | *Lamp Ratio (30 - 120%)* | 73.9 |
| *Slope (1 ± 0.3)* | 1.239 | *BOX Temp. (Ambient ± 5°C)* | 33.2 |
| *Offset (< 250 mV)* | 16.7 | *HVPS (400 - 900 V)* | 571 |

**Operator comments/observations:**
* Clock is 1 hour behind.
Clock ASS ON 11-18-13 - RPA

Operator Signature: Kami Ballard

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $SO_2$ Monitoring Form

**Site Operator:** R. ATTRIDGE **Date:** 11-27-2013

| | | |
|---|---|---|
| Sampler Make /Model | | T 100 |
| Sampler SN | | 193 |
| Dilution Calibrator Model/SN | Primary | T700 / 191 |
| | Transfer | N/A |

| | |
|---|---|
| Instrument Check Start Time | 1226 |
| Instrument Check Stop Time | 1242 |
| Filter Replacement Y/N | NO |
| Shelter Temp (5 to 40 °C) | 27.0 |
| Instrument Range | 0-500 PPB |
| Source Gas Conc. | 40 ppm $SO_2$ |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span with the T700 Dynamic Dilution Calibrator:

| Target Dilution (PPB) | SO2 Response (PPB) | Final SO2 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.65 | 0.03 | ± 3% of Full Scale (-15 to 15 PPB) | NO |
| 100 | 96.90 | 97.70 | ≤ ± 10% (90 to 110 PPB) | NO |

Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T100 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.03 | 0.23 | ± 2 PPB | NO |
| 100 PPB | 97.70 | 98.45 | ± 2 PPB | NO |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (450 ± 45 cc/min)* | 448 | *Sample Press. (Ambient ± 2 in-Hg)* | 25.7 |
| *UV Lamp (1000 - 4800 mV)* | 2629.8 | *Lamp Ratio (30 - 120%)* | 73.4 |
| *Slope (1 ± 0.3)* | 1.239 | *BOX Temp. (Ambient ± 5°C)* | 34 |
| *Offset (< 250 mV)* | 16.7 | *HVPS (400 - 900 V)* | 571 |

**Operator comments/observations:**
NONE

**Operator Signature:**

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY WR DATE 12-3-13
PRINTED BY RPA DATE 11-27-13

AIR SCIENCES INC.
DENVER • PORTLAND

WR 12-30-13
REVIEWED BY DATE
RPA 12-19-13
AUDITED BY DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST

## $SO_2$ Monitoring Form

**Site Operator:** Tom White **Date:** 12/12/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T100 |
| Sampler SN | | 193 |
| Dilution Calibrator Model/SN | Primary | T700 191 |
| | ~~Transfer~~ | |

| | |
|---|---|
| Instrument Check Start Time | 1539 |
| Instrument Check Stop Time | 1603 |
| Filter Replacement Y/(N) | NO |
| Shelter Temp, (5 to 40 °C) | 21.42 |
| Instrument Range | 500 ppb |
| Source Gas Conc. | 40% SO |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span with the T700 Dynamic Dilution Calibrator:

| Target Dilution (PPB) | SO2 Response (PPB) | Final SO2 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 3.242 | * | ± 3% of Full Scale (-15 to 15 PPB) | N |
| 100 | 98.34 | * | ≤ ± 10% (90 to 110 PPB) | N |

Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T100 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 3.242 | 3.66 | ± 2 PPB | N |
| 100 PPB | 98.34 | 99.04 | ± 2 PPB | N |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (450 ± 45 cc/min)* | 458 | *Sample Press. (Ambient ± 2 in-Hg)* | 25.8 |
| *UV Lamp (1000 - 4800 mV)* | 2616.8 ~~2616.8~~ | *Lamp Ratio (30 - 120%)* | 72.9 |
| *Slope (1 ± 0.3)* | 1.239 | *BOX Temp. (Ambient ± 5°C)* | 26.8 |
| *Offset (< 250 mV)* | 16.7 | *HVPS (400 - 900 V)* | 571 |

**Operator comments/observations:**
INVALIDATED THE HOURLY CONCENTRATION OF $SO^2$ @ 1600 HRS ON 12-12-13 – RPA

**Operator Signature:** T White

* NEED TO RECORD $SO^2$ AFTER THE T100 REACHES STABILITY – RPA

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY WR DATE 12-30-13
AUDITED BY RPA DATE 12-30-13

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $SO_2$ Monitoring Form

Site Operator: Kami BeCard Date: 12/27

| | | |
|---|---|---|
| Sampler Make /Model | | T100 |
| Sampler SN | | SN #193 |
| Dilution Calibrator Model/SN | Primary | T700/SN#191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 11:26 |
| Instrument Check Stop Time | 11:42 |
| Filter Replacement Y/N | Yes |
| Shelter Temp (5 to 40 °C) | 27.31 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40% 80 40 ppm SO |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span with the T700 Dynamic Dilution Calibrator:

| Target Dilution (PPB) | SO2 Response (PPB) | Final SO2 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .592 | ~~.592~~ | ± 3% of Full Scale (-15 to 15 PPB) | No |
| 100 | 98.62 | = | ≤ ± 10% (90 to 110 PPB) | NO |

Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T100 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .592 | .92 | ± 2 PPB | No |
| 100 PPB | ~~98.62~~ | 99.69 | ± 2 PPB | NO |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (450 ± 45 cc/min)* | 458 | *Sample Press. (Ambient ± 2 in-Hg)* | 26.2 |
| *UV Lamp (1000 - 4800 mV)* | 2589.9 | *Lamp Ratio (30 - 120%)* | 71.4 |
| *Slope (1 ± 0.3)* | 1.239 | *BOX Temp. (7 ± 2°C)* | 33.4 |
| *Offset (< 250 mV)* | 16.7 | *HVPS (400 - 900 V)* | 571 |

**Operator comments/observations:**
INVALIDATED THE HOURLY $SO^2$ CONCENTRATION ON 12-27-13 @ 1200 HRS DUE TO LEVEL 1 OPS - RPA

Operator Signature: Kami BeCard

AIR SCIENCES INC.
DENVER • PORTLAND

WL 10/25/13
REVIEWED BY RPA DATE 10-21-13
AUDITED BY DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $O_3$ Monitoring Form

Site Operator: Kami BaCard Date: 10/18/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T400 |
| Sampler SN | | SN# 224 |
| Dilution Calibrator Model/SN | Primary | T700/SN#191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 09:14 LT |
| Instrument Check Stop Time | 09:37 LT |
| Filter Replacement Y/N | No |
| Shelter Temp (5 to 40 °C) | 28.02 |
| Instrument Range | 500 PPB |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | O3 Response (PPB) | Final O3 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .4 | — | ≤ ± 2% of Full Scale (±10 PPB) | No |
| 100 | 100.2 | — | ≤ ± 7% (93 to 107 PPB) | No |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .4 | .79 | ± 2 PPB | — |
| 100 PPB | 100.2 | 101.3 | ± 2 PPB | — |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (550 ± 55 cc/min)* | 564 | *Sample Temp. (10 - 50 °C)* | 40. |
| *Photo Lamp (58 ± 1 °C)* | 58 | *BOX Temp. (30 ± 20 °C)* | 27.7 |
| *Slope (1 ± 0.15)* | .959 | *O3 Measure (2500 - 4800 mV)* | 3250.1 |
| *Offset ( 0.0 ± 5 PPB)* | .8 | *O3 Reference (2500 - 4800 mV)* | 3251.4 |

**Operator comments/observations:**
INVALIDATED THE 1000HRS HOURLY FILE ON 10-18-13 – RPA

Operator Signature: Kami BaCard

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY JRL 11/19/13 DATE
AUDITED BY RAA 11.13.13 DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST

## $O_3$ Monitoring Form

Site Operator: Kara Ballard Date: 10/30/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T400 |
| Sampler SN | | SN 224 |
| Dilution Calibrator Model/SN | Primary | T700/SN 191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 14:41 |
| Instrument Check Stop Time | 14:52 |
| Filter Replacement Y/N | No |
| Shelter Temp (5 to 40 °C) | 28.3 |
| Instrument Range | 500 PPB |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | O3 Response (PPB) | Final O3 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .6 | — | ≤ ± 2% of Full Scale (±10 PPB) | No |
| 100 | 99.7 | — | ≤ ± 7% (93 to 107 PPB) | No |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | .6 | .91 | ± 2 PPB | No |
| 100 PPB | 99.7 | 100.19 | ± 2 PPB | No |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (550 ± 55 cc/min)* | 557 | *Sample Temp. (10 - 50 °C)* | 41.1 |
| *Photo Lamp (58 ± 1 °C)* | 58.0 | *BOX Temp. (30 ± 20 °C)* | 29.2 |
| *Slope (1 ± 0.15)* | 0.887 | *O3 Measure (2500 - 4800 mV)* | 3232.6 |
| *Offset ( 0.0 ± 5 PPB)* | .8 | *O3 Reference (2500 - 4800 mV)* | 3234.6 |

Operator comments/observations:
INVALIDATED THE 1500HRS $O_3$ CONCENTRATION DUE TO LEVEL 1 PROCEDURES - RAA

Operator Signature: Kara Ballard

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY SR DATE 11/19/13
AUDITED BY RPA DATE 11-18-13

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST

## $O_3$ Monitoring Form

Site Operator: Kami Bollard Date: 11/15/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T400 |
| Sampler SN | | SN#224 |
| Dilution Calibrator Model/SN | Primary | T700/SN#191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 14:23 |
| Instrument Check Stop Time | 14:45 |
| Filter Replacement Y/N | Yes |
| Shelter Temp (5 to 40 °C) | 23.76 |
| Instrument Range | 500 PPB |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | O3 Response (PPB) | Final O3 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | -0.0 | ~~0.5~~ | ≤ ± 2% of Full Scale (±10 PPB) | No |
| 100 | 97.3 | — | ≤ ± 7% (93 to 107 PPB) | NO |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | -0.0 | 0.5 | ± 2 PPB | No |
| 100 PPB | 97.3 | 98.1 | ± 2 PPB | No |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (550 ± 55 cc/min)* | 554 | *Sample Temp. (10 - 50 °C)* | 40.1 |
| *Photo Lamp (58 ± 1 °C)* | 58.0 | *BOX Temp. (30 ± 20 °C)* | 28.1 |
| *Slope (1 ± 0.15)* | 0.887 | *O3 Measure (2500 - 4800 mV)* | 3216.7 |
| *Offset ( 0.0 ± 5 PPB)* | 0.8 | *O3 Reference (2500 - 4800 mV)* | 3218.6 |

**Operator comments/observations:**
* Clock was 1 hour behind.
* CLOCK ADJ ON 11-18-13 - RPA

Operator Signature: Kami Bollard

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST

## $O_3$ Monitoring Form

Site Operator: R. ATTRIDGE Date: 11-27-2013

| | | |
|---|---|---|
| Sampler Make /Model | | T400 |
| Sampler SN | | 224 |
| Dilution Calibrator Model/SN | Primary | T700 / 191 |
| | Transfer | N/A |

| | |
|---|---|
| Instrument Check Start Time | 1205 |
| Instrument Check Stop Time | 1225 |
| Filter Replacement Y/N | NO |
| Shelter Temp (5 to 40 °C) | 27.2 |
| Instrument Range | 0-500 ppb |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | O3 Response (PPB) | Final O3 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | -0.6 | -0.4 | ≤ ± 2% of Full Scale (±10 PPB) | NO |
| 100 | 98.2 | 99.1 | ≤ ± 7% (93 to 107 PPB) | NO |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | -0.4 | 0.14 | ± 2 PPB | NO |
| 100 PPB | 99.1 | 99.5 | ± 2 PPB | NO |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (550 ± 55 cc/min)* | 546 | *Sample Temp. (10 - 50 °C)* | 42.8 |
| *Photo Lamp (58 ± 1 °C)* | 58 | *BOX Temp. (30 ± 20 °C)* | 30.3 |
| *Slope (1 ± 0.15)* | 0.887 | *O3 Measure (2500 - 4800 mV)* | 3191.5 |
| *Offset ( 0.0 ± 5 PPB)* | 0.8 | *O3 Reference (2500 - 4800 mV)* | 3192.7 |

**Operator comments/observations:**
NONE

Operator Signature: [signature]

AIR SCIENCES INC
DENVER • PORTLAND
REVIEWED BY WR DATE 12-3-13
AUDITED BY RPA DATE 11-27-13

AIR SCIENCES INC
DENVER • PORTLAND
REVIEWED BY WK DATE 12-30-13
AUDITED BY RPA DATE 12-19-13

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST

## $O_3$ Monitoring Form

Site Operator: Tom White Date: 12/12/2013

| | | |
|---|---|---|
| Sampler Make/Model | | T400 |
| Sampler SN | | 224 |
| Dilution Calibrator Model/SN | Primary | T700 191 |
| | ~~Transfer~~ | |

| | |
|---|---|
| Instrument Check Start Time | 1516 |
| Instrument Check Stop Time | 1536 |
| Filter Replacement Y/(N) | No |
| Shelter Temp (5 to 40 °C) | 20.87 |
| Instrument Range | 500 ppb |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | O3 Response (PPB) | Final O3 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.0 | * | ≤ ± 2% of Full Scale (±10 PPB) | N |
| 100 | 99.1 | * | ≤ ± 7% (93 to 107 PPB) | N |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.0 | 0.61 | ± 2 PPB | N |
| 100 PPB | 99.1 | 100.19 | ± 2 PPB | N |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (550 ± 55 cc/min)* | 571 | *Sample Temp. (10 - 50 °C)* | 35.3 |
| *Photo Lamp (58 ± 1 °C)* | 58 | *BOX Temp. (30 ± 20 °C)* | 21.1 |
| *Slope (1 ± 0.15)* | 0.887 | *O3 Measure (2500 - 4800 mV)* | 3189.0 |
| *Offset ( 0.0 ± 5 PPB)* | 0.8 | *O3 Reference (2500 - 4800 mV)* | 3190.2 |

Operator comments/observations:
INVALIDATED THE HOURLY CONCENTRATION OF O3 @ 1600 HRS ON 12-12-13 - RPA
Operator Signature: T White

* NEED TO RECORD O3 AFTER THE T400 (1) REACHES STABILITY - RPA

AIR SCIENCES INC.
DENVER • PORTLAND

REVIEWED BY WR DATE 12-30-13
AUDITED BY RPA DATE 12-30-13

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST

## $O_3$ Monitoring Form

Site Operator: K. Bolla Date: 12/27/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T400 |
| Sampler SN | | SN 224 |
| Dilution Calibrator Model/SN | Primary | T700/SN 191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 11:42 |
| Instrument Check Stop Time | 12:06 |
| Filter Replacement Y/N | Yes |
| Shelter Temp (5 to 40 °C) | 26-27 |
| Instrument Range | 500 PPB |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | O3 Response (PPB) | Final O3 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | ~~35.2~~ -0.6 | ~~-0.15~~ | ≤ ± 2% of Full Scale (±10 PPB) | No |
| 100 | 93.9 | — | ≤ ± 7% (93 to 107 PPB) | No |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | -0.6 | -0.15 | ± 2 PPB | |
| 100 PPB | 93.9 | 94.52 | ± 2 PPB | |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (550 ± 55 cc/min)* | 580 | *Sample Temp. (10 - 50 °C)* | 37.8 |
| *Photo Lamp (58 ± 1 °C)* | 58.0 | *BOX Temp. (30 ± 20 °C)* | 22.8 |
| *Slope (1 ± 0.15)* | 0.887 | *O3 Measure (2500 - 4800 mV)* | 3145.4 |
| *Offset ( 0.0 ± 5 PPB)* | 0.8 | *O3 Reference (2500 - 4800 mV)* | 3168.3 |

**Operator comments/observations:**
INVALIDATED THE HOURLY CONCENTRATIONS OF $O_3$ @ 1200HRS AND 1300HRS ON 12-27-13 DUE TO LEVEL 1 OPS - RPA Operator Signature: Kami Bolla

AIR SCIENCES INC.
DENVER • PORTLAND

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY WR DATE 10/25/13
AUDITED BY RPA DATE 10-31-13

# Resolution EAST

## $NO_x$ Monitoring Form

Site Operator: Kami Ballard Date: 10/18/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T200 |
| Sampler SN | | SN 197 |
| Dilution Calibrator Model/SN | Primary | T700/SN 191 |
| | Transfer | |

| | |
|---|---|
| Instrument Check Start Time | 8:35 |
| Instrument Check Stop Time | 9:00 |
| Filter Replacement Y/N | No |
| Shelter Temp (5 to 40 °C) | |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40% NO |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | -0.1 | 1.3 | 1.2 | — | ±3% of full Scale (±15 PPB) | No |
| 100 PPB | 99.2 | 2.3 | 101.5 | — | ≤±10% (90 to 110 PPB) | No |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | -0.1 | NO | -0.81 | ±2 PPB | No |
| | $NO_2$ | 1.3 | $NO_2$ | 1.01 | | |
| | $NO_x$ | 1.2 | $NO_x$ | 1.06 | | |
| 100 PPB | NO | 99.2 | NO | 99.2 | ±2 PPB | NO |
| | $NO_2$ | 2.3 | $NO_2$ | 2.1 | | |
| | $NO_x$ | 101.5 | $NO_x$ | 101.4 | | |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (500 ± 50 cc/min)* | 503 | *Moly Temp. (315 ± 5°C)* | 317.5 |
| *Ozone Flow (80 ± 15 cc/min)* | 76 | *HVPS (400 - 900 V)* | 601 |
| *NOx Slope (1 ± 0.3)* | 1.305 | *NO Slope (1 ± 0.3)* | 1.289 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

Operator comments/observations:
INVALIDATED HOURLY FILES FOR 0900-1000 HRS ON 10/18/13 -RPA

Operator Signature: Kami Ballard

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $NO_x$ Monitoring Form

Site Operator: Kami Ballard Date: 10/30/2013

| Sampler Make /Model | | T200 |
|---|---|---|
| Sampler SN | | SN# 197 |
| Dilution Calibrator Model/SN | Primary | T700/ SN# 191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 14:11 |
| Instrument Check Stop Time | 14:27 |
| Filter Replacement Y/N | No |
| Shelter Temp (5 to 40 °C) | 27.47 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40% NO 40 ppm RPA |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | -0.2 | 3.4 | 3.2 | — | ±3% of full Scale (±15 PPB) | No |
| 100 PPB | 95.6 | 3.7 | 99.5 | — | ≤±10% (90 to 110 PPB) | No |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | -0.2 | NO | -0.33 | ±2 PPB | No |
| | $NO_2$ | 3.4 | $NO_2$ | 3.34 | | |
| | $NO_x$ | 3.2 | $NO_x$ | 3.21 | | |
| 100 PPB | NO | 95.6 | NO | 95.6 | ±2 PPB | No |
| | $NO_2$ | 3.7 | $NO_2$ | 3.6 | | |
| | $NO_x$ | 99.5 | $NO_x$ | 99.7 | | |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (500 ± 50 cc/min)* | 492 | *Moly Temp. (315 ± 5°C)* | 316.6 |
| *Ozone Flow (80 ± 15 cc/min)* | 75 | *HVPS (400 - 900 V)* | 601 |
| *NOx Slope (1 ± 0.3)* | 1.305 | *NO Slope (1 ± 0.3)* | 1.289 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

Operator comments/observations:

INVALIDATED NO, $NO^2$ AND NOX CONCENTRATIONS FOR THE 1500HRS AS A RESULT OF LEVEL 1 PROCEDURES - RPA

Operator Signature: Kami Ballard



AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY RPA 11/19/13 DATE
AUDITED BY DATE 11-13-13

AIR SCIENCES INC.
DENVER • PORTLAND
REVIEWED BY RPA DATE 11/19/13
AUDITED BY DATE 11-18-13

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $NO_x$ Monitoring Form

Site Operator: Kara Bidlack Date: 11/15/2013

| Sampler Make /Model | | T200 |
|---|---|---|
| Sampler SN | | SN 197 |
| Dilution Calibrator Model/SN | Primary | T700/SN 191 |
| | Transfer | — |

| Instrument Check Start Time | 13:58 |
|---|---|
| Instrument Check Stop Time | 14:10 |
| Filter Replacement Y/N | Yes |
| Shelter Temp (5 to 40 °C) | 24.4 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | ~~40% NO~~ 40 PPM NO |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | 0.0 | 0.4 | 0.4 | — | ±3% of full Scale (±15 PPB) | No |
| 100 PPB | 94.7 | 4.6 | 99.4 | — | ≤±10% (90 to 110 PPB) | No |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | 0.0 | NO | -0.5 | ±2 PPB | No |
| | $NO_2$ | 0.4 | $NO_2$ | -0.03 | | |
| | $NO_x$ | 0.4 | $NO_x$ | 0.3 | | |
| 100 PPB | NO | 94.7 | NO | 94.7 | ±2 PPB | No |
| | $NO_2$ | 4.6 | $NO_2$ | 4.5 | | |
| | $NO_x$ | 99.4 | $NO_x$ | 99.2 | | |

Verify instrument parameters:

| *Sample Flow (500 ± 50 cc/min)* | 496 | *Moly Temp. (315 ± 5°C)* | 316.3 |
|---|---|---|---|
| *Ozone Flow (80 ± 15 cc/min)* | 75 | *HVPS (400 - 900 V)* | 601 |
| *NOx Slope (1 ± 0.3)* | 1.305 | *NO Slope (1 ± 0.3)* | 1.289 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

Operator comments/observations:

* Time is 1 hour behind

CLOCK ADJUSTED ON 11-18-13 — RPA

Operator Signature: Kara Bidlack

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $NO_x$ Monitoring Form

Site Operator: R. ATTRIDGE Date: 11·27·2013

| Sampler Make /Model | | T 200 |
|---|---|---|
| Sampler SN | | 197 |
| Dilution Calibrator Model/SN | Primary | T 700 / 191 |
| | Transfer | N/A |

| Instrument Check Start Time | 1243 |
|---|---|
| Instrument Check Stop Time | 1307 |
| Filter Replacement Y/N | NO |
| Shelter Temp (5 to 40 °C) | 26.9 |
| Instrument Range | 0-500ppb |
| Source Gas Conc. | 40 ppm NO |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | -0.1 | 1.4 | 1.2 | 1.3 | ± 3% of full Scale (±15 PPB) | NO |
| 100 PPB | 96.8 | 1.7 | 98.5 | 98.7 | ≤ ± 10% (90 to 110 PPB) | NO |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | -0.2 | NO | -0.33 | ± 2 PPB | NO |
| | $NO_2$ | 1.5 | $NO_2$ | 1.29 | | |
| | $NO_x$ | 1.3 | $NO_x$ | 1.35 | | |
| 100 PPB | NO | 96.7 | NO | 96.66 | ± 2 PPB | NO |
| | $NO_2$ | 1.9 | $NO_2$ | 1.75 | | |
| | $NO_x$ | 98.7 | $NO_x$ | 98.50 | | |

Verify instrument parameters:

| *Sample Flow (500 ± 50 cc/min)* | 485 | *Moly Temp. (315 ± 5°C)* | 314.5 |
|---|---|---|---|
| *Ozone Flow (80 ± 15 cc/min)* | 75 | *HVPS (400 - 900 V)* | 601 |
| *NOx Slope (1 ± 0.3)* | 1.305 WR | *NO Slope (1 ± 0.3)* | 1.289 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

**Operator comments/observations:**

NONE

**Operator Signature:**

AIR SCIENCES INC. DENVER • PORTLAND

REVIEWED BY WR DATE 12-3-13

AUDITED BY RPA DATE 11-27-13

AIR SCIENCES INC.
DENVER • PORTLAND
WR 12-30-13
REVIEWED BY RPA DATE 12-19-13
AUDITED BY DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $NO_x$ Monitoring Form

Site Operator: Tom White Date: 12/12/2013

| | | |
|---|---|---|
| Sampler Make/Model | | T200 |
| Sampler SN | | # 197 |
| Dilution Calibrator Model/SN | Primary | T700/191 |
| | ~~Transfer~~ | |

| | |
|---|---|
| Instrument Check Start Time | 1445 |
| Instrument Check Stop Time | 1510 |
| Filter Replacement Y/(N) | No |
| Shelter Temp (5 to 40 °C) | 20.12 |
| Instrument Range | 500 ppb |
| Source Gas Conc. | 40% NO |

**Level 1 Zero/Span (once every 2 weeks)**
Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | 1.0 | 2.1 | 3.1 | * | ±3% of full Scale (±15 PPB) | N |
| 100 PPB | 102.1 | 6.5 | 108.6 | * | ≤±10% (90 to 110 PPB) | N |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | 1.0 | NO | 0.146 | ±2 PPB | N |
| | $NO_2$ | 2.1 | $NO_2$ | 1.58 | | |
| | $NO_x$ | 3.1 | $NO_x$ | 2.170 | | |
| 100 PPB | NO | 102.0 | NO | 101.88 | ±2 PPB | N |
| | $NO_2$ | 6.0 | $NO_2$ | 6.019 | | |
| | $NO_x$ | 108.0 | $NO_x$ | 107.89 | | |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (500 ± 50 cc/min)* | 495 | *Moly Temp. (315 ± 5°C)* | 315 |
| *Ozone Flow (80 ± 15 cc/min)* | 76 | *HVPS (400 - 900 V)* | 660 |
| *NOx Slope (1 ± 0.3)* | 1.546 | *NO Slope (1 ± 0.3)* | 1.461 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

**Operator comments/observations:**
INVALIDATED THE HOURLY CONCENTRATION OF $NO^*$, NO, $NO^2$ @ 1600 HRS ON 12-12-13 – RAA

Operator Signature:

* NEED TO RECORD THE NOX AFTER[1] THE T200 REACHES STABILITY – RAA

AIR SCIENCES INC.
DENVER • PORTLAND

WR 12-30-13
REVIEWED BY RPA DATE 12-30-13
AUDITED BY DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $NO_x$ Monitoring Form

Site Operator: Kami Ballard Date: 12/27/2013

| | | |
|---|---|---|
| Sampler Make /Model | | T200 |
| Sampler SN | | SN# 197 |
| Dilution Calibrator Model/SN | Primary | T700/SN 191 |
| | Transfer | — |

| | |
|---|---|
| Instrument Check Start Time | 11:10 |
| Instrument Check Stop Time | 11:26 |
| Filter Replacement Y/N | Yes |
| Shelter Temp (5 to 40 °C) | 26.85 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40% NO 40 ppm NO |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | -0.4 | 0.9 | 0.5 | — | ±3% of full Scale (±15 PPB) | N |
| 100 PPB | 102.6 | 6.5 | 109.1 | — | ≤±10% (90 to 110 PPB) | N |

? * Kind of high?

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | -0.4 | NO | -0.66 | ±2 PPB | No |
| | $NO_2$ | 0.9 | $NO_2$ | 0.74 | | |
| | $NO_x$ | 0.5 | $NO_x$ | .46 | | |
| 100 PPB | NO | 102.6 | NO | 102.18 | ±2 PPB | No |
| | $NO_2$ | 6.5 | $NO_2$ | 6.39 | | |
| | $NO_x$ | 109.1 | $NO_x$ | 108.71 | | |

Verify instrument parameters:

| | | | |
|---|---|---|---|
| *Sample Flow (500 ± 50 cc/min)* | 497 | *Moly Temp. (315 ± 5°C)* | 316.4 |
| *Ozone Flow (80 ± 15 cc/min)* | 76 | *HVPS (400 - 900 V)* | 601 |
| *NOx Slope (1 ± 0.3)* | 1.546 | *NO Slope (1 ± 0.3)* | 1.461 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

**Operator comments/observations:**

INVALIDATED THE 1200 HRS NO, NO2, AND NOX CONCENTRATIONS ON 12-27-13 @ 1200 HRS DUE TO LEVEL 1 OPS – Operator Signature: Kami Ballard

RPA



* 12-30-13 → REMOTE ZERO/SPAN CONSULTED TO CORRECT CALIBRATION FACTORS – RPA

AIR SCIENCES INC.
DENVER • PORTLAND

WR 12-30-13
REVIEWED BY DATE
RPA 12-30-13
AUDITED BY DATE

AIR SCIENCES INC.
DENVER • PORTLAND

# Resolution EAST
## $NO_x$ Monitoring Form

**Site Operator:** R. ATTRIDGE **Date:** 12-30-13

| | | |
|---|---|---|
| Sampler Make /Model | | T200 |
| Sampler SN | | 197 |
| Dilution Calibrator Model/SN | Primary | T700 / 191 |
| | Transfer | N/A |

| | |
|---|---|
| Instrument Check Start Time | 1020 HRS |
| Instrument Check Stop Time | 1100 HRS |
| Filter Replacement Y/N | NO |
| Shelter Temp (5 to 40 °C) | 24.1 |
| Instrument Range | 500 PPB |
| Source Gas Conc. | 40 ppm |

**Level 1 Zero/Span (once every 2 weeks)**

Check the Zero/Span with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | Nox Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | -0.49 | -0.04 | -0.23 | -0.0 | ± 3% of full Scale (±15 PPB) | YES |
| 100 PPB | 104.8 | 6.8 | 111.6 | 100.7 | ≤ ± 10% (90 to 110 PPB) | YES |

Check the real time Analog vs. Digital converter.

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | 0.0 | NO | -0.19 | ± 2 PPB | NO |
| | $NO_2$ | -0.0 | $NO_2$ | -0.38 | | |
| | $NO_x$ | -0.0 | $NO_x$ | -0.06 | | |
| 100 PPB | NO | 98.4 | NO | 98.1 | ± 2 PPB | NO |
| | $NO_2$ | 2.3 | $NO_2$ | 2.12 | | |
| | $NO_x$ | 100.7 | $NO_x$ | 100.3 | | |

Verify instrument parameters:


| | | | |
|---|---|---|---|
| *Sample Flow (500 ± 50 cc/min)* | 497 | *Moly Temp. (315 ± 5°C)* | 315.5 |
| *Ozone Flow (80 ± 15 cc/min)* | 76 | *HVPS (400 - 900 V)* | 600 |
| *NOx Slope (1 ± 0.6)* | 1.546 | *NO Slope (1 ± 0.6)* | 1.461 |
| *NOx Offset (0 ± 100)* | 1.3 | *NO Offset (0 ± 100)* | 0.1 |

**Operator comments/observations:**

CORRECTED CALIBRATION FACTOR DRIFT NOTED IN THE DAILY ZERO/SPAN VALVES - RPA

**Operator Signature:**

# Appendix K: Audits and Calibrations



# Air Quality Calibration Report East Plant Monitoring Station

PREPARED FOR:

RESOLUTION COPPER MINING

PREPARED BY:
RORY ATTRIDGE
AIR SCIENCES INC.

PROJECT 262-5
OCTOBER 2013

# CONTENTS PAGE

1.0 Introduction ..... 1
2.0 System Description ..... 3
3.0 Calibration Methodology ..... 4
3.1 Particulate Matter Calibration Procedures ..... 4
3.2 Ambient Gas Calibration Procedures ..... 4
4.0 Results and Recommendations ..... 5

**Tables**

Table 1. Sensor Installation Heights ..... 3

**Figures**

Figure 1: Project Location Map – East Plant and West Plant Monitoring Station Locations ..... 2

**Appendices**


Appendix A: Calibration Forms

# 1.0 INTRODUCTION

On October 8 and 9, 2013, the air quality instrumentation was calibrated at the Resolution Copper East Plant, near Superior, AZ. The East Plant monitoring station is operated by the Resolution Copper Mining company and is located approximately two miles east of the West operation plant (see Figure 1). The purpose of this document is to provide a brief synopsis of the air quality monitoring system and of the calibration procedures for the particulate and ambient gas instrumentation at the East plant site. The calibration was conducted in accordance with the following guideline documents:

- EPA-454/B-13-003, Quality Assurance Handbook for Air Pollution Measurement Systems, Volume II: Ambient Air Quality Monitoring Program, May 2013
- Transfer Standards for the calibration of Ambient Air Monitoring Analyzers for Ozone (EPA-454/B-10-001)
- Code of Federal Regulations (40 CFR Parts 50 and 58)

**Figure 1: Project Location Map – East Plant and West Plant Monitoring Station Locations**



# 2.0 SYSTEM DESCRIPTION

The parameters calibrated at the East monitoring site include particulate matter less than 10 and 2.5 microns in diameter ($PM_{10}$ & $PM_{2.5}$), nitrogen dioxide ($NO_2$), sulfur dioxide ($SO_2$), and ozone ($O_3$). The analyzers are housed in a 60-square-foot climate controlled trailer. Inlet heights are listed in Table 1.

**Table 1. Instruments and inlet heights**

| Parameter | Approximate Height (meters) |
|---|---|
| $PM_{10}$ | 3 |
| $PM_{2.5}$ | 3 |
| $NO_2$ | 3 |
| $SO_2$ | 3 |
| $O_3$ | 3 |

Monitored data parameters are recorded via analog inputs on two Campbell Scientific CR3000 dataloggers, each powered independently by either DC solar or by locally supplied AC line power.

# 3.0 CALIBRATION METHODOLOGY

This section provides the Calibration procedures for the particulate and ambient gas instrumentation at the East monitoring site. Copies of the completed Calibration forms for each parameter are included in Appendix A.

## 3.1 Particulate Matter Calibration Procedures

The BAM 1020 $PM_{10}$ and BAM 1020 $PM_{2.5}$ monitors were assessed and calibrated by comparing and then adjusting the temperature, barometric pressure, and internal flow to a certified deltaCal Volumetric Air Flow Calibrator. All required maintenance was performed on the instrument to assure optimal operations. The temperature, barometric pressure, and flow output readings from the deltaCal and the instrument were recorded on a standardized form.

## 3.2 Ambient Gas Calibration Procedures

Calibration of the Teledyne T100 $SO_2$ analyzer involved a Multi-Point Calibration (MPA) and an Analog to Digital (A2D) verification. The MPA was performed by using the T700 calibrator to dilute NIST-traceable EPA-protocol Calibration gas with a clean zero-air source to calibrate the T100 analyzer at zero, and at five points within the instrument range—typically a points from 100 to 500 PPB of $SO_2$. An A2D verification check of the T100 instrument response against the CR3000 datalogger response was performed to guarantee accurate representation of the digital scale from the analog output signals.

Calibration of the Teledyne T200 $NO_2$ analyzer involved an MPA and an A2D verification. The SPC was performed by using the T700 calibrator to dilute NIST-traceable EPA-protocol Calibration gas with a clean zero-air source to calibrate the T200 analyzer at zero, and five points within the instrument range—typically point from 100 to 500 PPB of $NO_X$. A verification check of the T200 instrument response against the CR3000 datalogger response was performed to guarantee accurate representation of the digital scale from the analog output signals.

Calibration of the Teledyne T400 $O_3$ analyzer involved an MPA, and an A2D verification. The SPC was performed by using the T700 calibrator to generate $O_3$ gas to calibrate the T400 analyzer at zero, and at a single point within the instrument range—typically a point from 100 to 500 PPB of $O_3$. An MPA was performed using a 700E transfer standard calibrator to evaluate the Calibration by verifying the analyzer's response to zero and five upscale spans. After the MPA, a verification check of the T400 instrument against the CR3000 datalogger response was performed to guarantee accurate representation of the digital scale from the analog output signals.

# 4.0 RESULTS AND RECOMMENDATIONS

All instruments and sensors were within their recommended tolerance parameters at the Resolution Copper East Plant monitoring site.

# Appendix A: Calibration Forms

# East Plant BAM-1020 $PM_{10}$ Audit Sheet

| | | | |
|---|---|---|---|
| **Model:** | **BAM-1020** | **Serial Number:** | M8712 |
| **Audit Date:** | 10/08/2013 | **Audited By:** | R. Attridge |
| **Audit Time:** | 1505hrs | | |

Firmware: 3236-06 V3.6.3

| **Flow Audits** | | | | | | |
|---|---|---|---|---|---|---|
| **Flow Reference Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Temperature Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Barometric Pressure Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |

**Leak Check Value:** as found: 0.3 LPM — Should Be: <1.0 — as left: 0.3 LPM — Should Be: <1.0

| | | BAM | Ref. Std. | | BAM | Ref. Std. | | |
|---|---|---|---|---|---|---|---|---|
| **Ambient Temperature (°C):** | as found: | 25.7 | 24.5 | as left: | 24.9 | 25.22 | Adjusted | x |
| **Barometric Pressure (mmHg):** | as found: | 652 | 652 | as left: | 652 | 652 | Adjusted | |
| **Flow Rate (15.0 LPM):** | as found: | 15.0 | 14.90 | as left: | 15.0 | 14.95 | Adjusted | |
| **Flow Rate (18.4 LPM):** | as found: | 18.4 | 18.18 | as left: | 18.4 | 18.33 | Adjusted | x |
| **Flow Rate (16.7 LPM):** | as found: | 16.7 | 16.56 | as left: | 16.7 | 16.69 | Adjusted | |

**Audit Notes:** **Monitor found in a very clean, serviceable condition.**

**Mechanical Audits**

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Pump muffler unclogged: | As found | X | As left | X | PM10 particle trap clean: | As found | | As left | X | N/A | |
| Sample nozzle clean: | As found | | As left | X | PM10 drip jar empty: | As found | | As left | X | N/A | |
| Tape support vane clean: | As found | | As left | X | PM10 bug screen clear: | As found | X | As left | X | N/A | |
| Capstan shaft clean: | As found | | As left | X | PM2.5 particle trap clean: | As found | | As left | | N/A | x |
| Rubber pinch rollers clean: | As found | | As left | X | Inlet tube water-tight seal OK: | As found | X | As left | X | | |
| Chassis ground wire installed: | As found | X | As left | X | Inlet tube perpendicular to BAM: | As found | X | As left | x | | |

**Signature:** Rory Attridge

# East Plant BAM-1020 $PM_{2.5}$ Audit Sheet

| | | | |
|---|---|---|---|
| **Model:** | **BAM-1020** | **Serial Number:** | M6646 |
| **Audit Date:** | 10/08/2013 | **Audited By:** | R. Attridge |
| **Audit Time:** | 1430hrs | | |

Firmware: 3236-06 V3.6.3

| **Flow Audits** | | | | | | |
|---|---|---|---|---|---|---|
| **Flow Reference Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Temperature Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Barometric Pressure Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| **Leak Check Value:** | as found: | 0.4 LPM | Should Be: <1.0 | as left: | 0.4 LPM | Should Be: <1.0 | | | |
| | | **BAM** | **Ref. Std.** | | **BAM** | **Ref. Std.** | | | |
| **Ambient Temperature (°C):** | as found: | 24.8 | 25.6 | as left: | 25.4 | 25.8 | Adjusted | x | |
| **Barometric Pressure (mmHg):** | as found: | 652 | 652 | as left: | 652 | 652 | Adjusted | | |
| **Flow Rate (15.0 LPM):** | as found: | 15.0 | 15.27 | as left: | 15.0 | 15.18 | Adjusted | | |
| **Flow Rate (18.4 LPM):** | as found: | 18.4 | 18.57 | as left: | 18.4 | 18.50 | Adjusted | | |
| **Flow Rate (16.7 LPM):** | as found: | 16.7 | 16.77 | as left: | 16.7 | 16.69 | Adjusted | | |

**Audit Notes:** **Instrument found in a clean, serviceable condition.- RPA**

| **Mechanical Audits** | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Pump muffler unclogged: | As found | X | As left | X | PM10 particle trap clean: | As found | | As left | X | N/A | | |
| Sample nozzle clean: | As found | | As left | X | PM10 drip jar empty: | As found | X | As left | X | N/A | | |
| Tape support vane clean: | As found | X | As left | X | PM10 bug screen clear: | As found | X | As left | X | N/A | | |
| Capstan shaft clean: | As found | X | As left | X | PM2.5 particle trap clean: | As found | | As left | X | N/A | | |
| Rubber pinch rollers clean: | As found | X | As left | X | Inlet tube water-tight seal OK: | As found | X | As left | X | | | |
| on | As found | X | As left | X | Inlet tube perpendicular to BAM: | As found | X | As left | x | | | |

**Signature:** Rory Attridge

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $NO_x$ Monitoring Form

**Site Operator: R. Attridge** **Date: 10-09-2013**

| | | |
|---|---|---|
| **Sampler Make /Model** | | T200 |
| **Sampler SN** | | 197 |
| **Dilution Calibrator Model/SN** | **Primary** | **T700/191** |
| | **Transfer** | **N/A** |

| | |
|---|---|
| **Instrument Check Start Time** | 0930 |
| **Instrument Check Stop Time** | 1700 |
| **Filter Replacement Y/N** | No |
| **Shelter Temp (5 to 40 °C)** | 26.8 |
| **Instrument Range** | 500 ppb |
| **Source Gas Conc.** | 40 ppm NO |

**Level 1 Zero/ Span (once every 2 weeks)**
**Check the Zero/ Span with the T700 Dynamic Dilution Calibrator:**

| Target Dilution (PPB) | NO Response (PPB) | $NO_2$ Response (PPB) | $NO_x$ Response (PPB) | Final $NO_x$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | 0.o | 0.0 | o.1 | 0.2 | ± 3% of full scale (± 15 PPB) | No |
| 100 PPB | 96.7 | 1.4 | 97.8 | 100.0 | ≤ ± 10% (90 to 110 PPB) | No |

**Check the real time Analog vs. Digital Converter:**

| Target Dilution (PPB) | T200 Response (PPB) | | CR3000 Response (PPM) | | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|---|---|
| Zero Air | NO | 0.000 | NO | -0.24 | ± 2 | No |
| | $NO_2$ | 0.000 | $NO_2$ | -0.23 | | |
| | $NO_x$ | 0.000 | $NO_x$ | -0.08 | | |
| 400 | NO | 96.700 | NO | 96.4 | ± 2 | No |
| | $NO_2$ | 1.400 | $NO_2$ | 0.78 | | |
| | $NO_x$ | 97.800 | $NO_x$ | 97.6 | | |

**Verify Instrument Parameters:**

| | | | |
|---|---|---|---|
| Sample Flow (500 ± 50 cc/min) | 481 | Moly Temp. (315 ± 5°C) | 315.6 |
| Ozone Flow (80 ± 15 cc/ min) | 75 | HVPS (400 – 900 V) | 601 |
| $NO_x$ Slope (1 ± 0.3) | 1.1411 | NO Slope (1 ± 0.3) | 1.288 |
| $NO_x$ Offset (0 ± 100) | 7.9 | NO Offset (0 ± 100) | 0.1 |

**Multipoint Calibration (Quarterly, or as needed):**
Check the analyzer response over 0 – 500 ppb range with the Dilution Calibrator.

*Primary Standard:*

| Target (PPB) | Actual Generated T200 (PPB) | NO Response | $NO_2$ Response | $NO_x$ Response | Best Fit Line | Acceptable Criteria (± 2% from BFL) |
|---|---|---|---|---|---|---|
| Zero Air | 0 | 0.0 | 0.0 | 0.1 | -2.6 | PASS, 0 ± 5 |
| 100 | 100 | 98.3 | 1.1 | 101.3 | 101.3 | PASS, 1.9% |
| 200 | 200 | 197.4 | 6.4 | 203.8 | 205.1 | PASS, 0.7% |
| 300 | 300 | 298.8 | 9.4 | 308.0 | 309.0 | PASS, 0.3% |
| 400 | 399 | 401.7 | 10.0 | 412.0 | 411.8 | PASS, 0% |
| 500 | 499 | 503.3 | 13.7 | 517.1 | 515.7 | PASS, 0.3% |

Best Fit Line
(BFL)
Y = 1.0387x +- 2.5832
$R^2$ = 0.99992

*Transfer Standard:*

| Target (PPB) | Actual Generated T200 (PPB) | NO Response | $NO_2$ Response | $NO_x$ Response | Best Fit Line | Acceptable Criteria (± 2% from BFL) |
|---|---|---|---|---|---|---|
| Zero Air | | | | | | |
| 100 | | | | | | |
| 200 | | | | | | |
| 300 | | | | | | |
| 400 | | | | | | |
| 500 | | | | | | |

Best Fit Line (BFL)

**Operator comments/ observations: None**

**Operator Signature** 

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $O_3$ Monitoring Form

**Site Operator: R. Attridge** **Date: 10-09-2013**

| | | |
|---|---|---|
| **Sampler Make /Model** | | T400 |
| **Sampler SN** | | 224 |
| **Dilution Calibrator Model/SN** | **Primary** | T700/ 191 |
| | **Transfer** | N/A |

| | |
|---|---|
| **Instrument Check Start Time** | 1230 |
| **Instrument Check Stop Time** | 1700 |
| **Filter Replacement Y/N** | No |
| **Shelter Temp (5 to 40 °C)** | 24.5 |
| **Instrument Range** | 500 ppb |

### Level 1 Zero/Span (once every 2 weeks)

Check the Zero/ Span ppb with the T700 Dynamic Dilution Calibrator.

| Target Dilution (PPB) | $O_3$ Response (PPB) | Final $O_3$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.000 | 0.120 | ≤ ± 2% of Full Scale (± 10 PPB) | No |
| 100 | 100.000 | 101.900 | ≤ ± 7% (93 to 107 PPB) | No |

### Check the real time Analog vs. Digital Converter:

| Target Dilution (PPB) | T400 Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.100 | 0.630 | ± 2 | No |
| 100 | 101.900 | 102.100 | ± 2 | No |

### Verify Instrument Parameters:

| | | | |
|---|---|---|---|
| Sample Flow (550 ± 55 cc/ min) | 549 | Sample Temp. (10 - 50°C) | 37.7 |
| Photo Lamp (58 ± 1°C) | 58.0 | BOX Temp. (30 ± 20°C) | 25.1 |
| Slope (1 ± 0.15) | 0.900 | $O_3$ Measure (2500 – 4800 mV) | 3267.0 |
| Offset (0.0 ± 5 PPB) | 0.5 | $O_3$ Reference (2500 – 4800 mV) | 3268.0 |

**Operator comments/ observations: None**

## Multipoint Calibration (Quarterly, or as needed):

Check the analyzer response over 0 – 500 ppb range with the Dilution Calibrator.

***Primary Standard:***

| Target (PPB) | Actual Generated $O_3$ (PPB) | $O_3$ Response (PPB) | Best Fit Line (PPB) | Acceptable Criteria (± 2% from BFL) |
|---|---|---|---|---|
| Zero Air | 0.000 | 0.1 | 1.8 | PASS, < 2% FS |
| 100 | 100.0 | 98.2 | 97.6 | PASS, 0.6% |
| 200 | 201.0 | 196.4 | 193.3 | PASS, 1.6% |
| 300 | 302.0 | 293.4 | 289.0 | PASS, 1.5% |
| 400 | 401.0 | 384.7 | 384.8 | PASS, 0% |
| 500 | 502.0 | 477.9 | 480.5 | PASS, 0.5% |

Best Fit Line (BFL)
Y = 0.9573x + 1.8393
$R^2$ = 0.99978

***Target Standard:***

| Target (PPB) | Actual Generated $O_3$ (PPB) | $O_3$ Response (PPB) | Best Fit Line (PPB) | Acceptable Criteria (± 2% from BFL) |
|---|---|---|---|---|
| Zero Air | | | | |
| 100 | | | | |
| 200 | | | | |
| 300 | | | | |
| 400 | | | | |
| 500 | | | | |

Best Fit Line (BFL)

**Operator Comments / Observations: None.**

**Operator Signature:** 

AIR SCIENCES INC.

DENVER • PORTLAND

# Resolution EAST

## $SO_2$ Monitoring Form

**Site Operator: R. Attridge** **Date: 10-09-2013**

| | | |
|---|---|---|
| **Sampler Make /Model** | | T100 |
| **Sampler SN** | | 193 |
| **Dilution Calibrator Model/SN** | **Primary** | T700/ 191 |
| | **Transfer** | N/A |

| | |
|---|---|
| **Instrument Check Start Time** | 1110 |
| **Instrument Check Stop Time** | 1700 |
| **Filter Replacement Y/N** | NO |
| **Shelter Temp (5 to 40 °C)** | 23.3 |
| **Instrument Range** | 500 ppb |
| **Source Gas Conc.** | 40 ppm |

**Level 1 Zero/ Span (once every 2 weeks):**
**Check the Zero/ Span with the T700 Dynamic Dilution Calibrator:**

| Target Dilution (PPB) | $SO_2$ Response (PPB) | Final $SO_2$ Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.30 | 0.310 | ± 3% of Full Scale (-15 to 15 PPB) | N |
| 100 | 101.8 | 99.98 | ≤ ± 10% (360 to 110 PPB) | N |

**Check the real time Analog vs. Digital Converter:**

| Target Dilution (PPB) | $SO_2$ Response (PPB) | CR3000 Response (PPB) | Acceptance Criteria (PPB) | Adjustment Required? Y/N |
|---|---|---|---|---|
| Zero Air | 0.300 | 0.310 | ± 2 | N |
| 100 | 99.80 | 100.08 | ± 2 | N |

**Verify Instrument Parameters:**

| | | | |
|---|---|---|---|
| Sample Flow (450 ± 45 cc/ min) | 453 | Sample Press. (Ambient ± 2 in-Hg) | 25.6 |
| UV Lamp (1000 – 4800 mV) | 2708.3 | Lamp Ratio (30 – 120%) | 75 |
| Slope (1 ± 0.3) | 1.216 | BOX Temp. (Ambient ± 5°C) | 29.8 |
| Offset (< 250 mV) | 16.7 | HVPS (400 – 900 V) | 571 |

**Operator comments/ observations:** None

**Multipoint Calibration (Quarterly, or as needed):**

**Check the analyzer response over 0 – 500 ppb range with the Dilution Calibrator.**

*Primary Standard:*

| Target (PPB) | Actual Generated $SO_2$ (PPB) | $SO_2$ Response (PPB) | Best Fit Line (PPB) | Acceptable Criteria (± 2% from BFL) |
|---|---|---|---|---|
| Zero Air | 0.00 | 0.30 | -0.074 | PASS, <2%FS |
| 100 | 101 | 99.80 | 100.976 | PASS, 1.2% |
| 200 | 200 | 200.40 | 200.026 | PASS, 0.2% |
| 300 | 300 | 299.10 | 300.075 | PASS, 0.3% |
| 400 | 399 | 399.2 | 399.124 | PASS, 0% |
| 500 | 499 | 499.7 | 499.174 | PASS, 0.1% |

Best Fit Line (BFL)
$Y = 1.0005x + -0.0738$
$R^2 = 0.99999$

*Transfer Standard:*


| Target (PPB) | Actual Generated $SO_2$ (PPB) | $SO_2$ Response (PPB) | Best Fit Line (PPB) | Acceptable Criteria (± 2% from BFL) |
|---|---|---|---|---|
| Zero Air | | | | |
| 100 | | | | |
| 200 | | | | |
| 300 | | | | |
| 400 | | | | |
| 500 | | | | |


Best Fit Line (BFL)

**Operator Comments/ observations:**

**Discovered the T100 touch-screen interface inoperable due to a faulty control board. Replacement board ordered and covered under warranty- RPA**

**Operator Signature:**





# Air Quality Calibration Report West Plant Monitoring Station

PREPARED FOR:

RESOLUTION COPPER MINING

PREPARED BY:
RORY ATTRIDGE
AIR SCIENCES INC.

PROJECT 262-5
OCTOBER 2013

# CONTENTS

Page

INTRODUCTION ..... 1

SYSTEM DESCRIPTION ..... 3

CALIBRATION METHODOLOGY ..... 4

RESULTS AND RECOMMENDATIONS ..... 5

**Tables**

Table 1. Instruments and inlet heights ..... 3

**Figures**

Figure 1: Project Location Map – East Plant and West Plant Monitoring Station Locations 2

**Appendices**

Appendix A: Calibration Forms


SECTION 1

# INTRODUCTION

On October 8, 2013, the air quality instrumentation was calibrated at the Resolution Copper West Plant, near Superior, AZ. The West Plant monitoring station is operated by the Resolution Copper Mining company and is located approximately one quarter mile west of the administration buildings (see Figure 1). The Calibration was conducted in accordance with the following guideline documents:

- Quality Assurance Handbook for Air Pollution Measurement Systems, Volume II:Ambient Air Quality Monitoring Program (EPA-454/B-13-003, May 2013)
- Code of Federal Regulations (40 CFR Parts 50 and 58)

**Figure 1: Project Location Map – East Plant and West Plant Monitoring Station Locations**



SECTION 2

# SYSTEM DESCRIPTION

The parameters calibrated at the West monitoring site include particulate matter less than 10 and 2.5 microns in diameter ($PM_{10}$ & $PM_{2.5}$). The particulate instrumentation is housed in a climate controlled shelter. Inlet heights are listed in Table 1.

**Table 1. Instruments and inlet heights**

| Parameter | Approximate Height (meters) |
|---|---|
| $PM_{10}$ | 2 |
| $PM_{2.5}$ | 2 |

Monitored data parameters are recorded via analog inputs on two Campbell Scientific CR3000 dataloggers, each powered independently by either DC solar or by locally supplied AC line power.

SECTION 3

# CALIBRATION METHODOLOGY

The BAM 1020 $PM_{10}$ and BAM 1020 $PM_{2.5}$ monitors were assessed and Calibrationed by comparing and then adjusting the temperature, barometric pressure, and internal flow to a certified Delta-Cal Volumetric Air Flow Calibrator. All required maintenance was performed on the instrument to assure optimal operations. The temperature, barometric pressure and flow output readings from the Delta-Cal and the instrument were recorded on a standardized form.

Copies of the completed Calibration data forms for each parameter are attached.

SECTION 4

# RESULTS AND RECOMMENDATIONS

All calibrated instruments and calibrated sensors were within their recommended tolerance parameters.

ATTACHMENT

# Calibration Data Forms

# East Plant BAM-1020 $PM_{2.5}$ Audit Sheet

| | | | |
|---|---|---|---|
| **Model:** | **BAM-1020** | **Serial Number:** | M6646 |
| **Audit Date:** | 10/08/2013 | **Audited By:** | R. Attridge |
| **Audit Time:** | 1430hrs | | |

Firmware: 3236-06 V3.6.3

| **Flow Audits** | | | | | | |
|---|---|---|---|---|---|---|
| **Flow Reference Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Temperature Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Barometric Pressure Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |

| | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|
| **Leak Check Value:** | as found: | 0.4 LPM | Should Be: <1.0 | as left: | 0.4 LPM | Should Be: <1.0 | | | |
| | | **BAM** | **Ref. Std.** | | **BAM** | **Ref. Std.** | | | |
| **Ambient Temperature (°C):** | as found: | 24.8 | 25.6 | as left: | 25.4 | 25.8 | Adjusted | x | |
| **Barometric Pressure (mmHg):** | as found: | 652 | 652 | as left: | 652 | 652 | Adjusted | | |
| **Flow Rate (15.0 LPM):** | as found: | 15.0 | 15.27 | as left: | 15.0 | 15.18 | Adjusted | | |
| **Flow Rate (18.4 LPM):** | as found: | 18.4 | 18.57 | as left: | 18.4 | 18.50 | Adjusted | | |
| **Flow Rate (16.7 LPM):** | as found: | 16.7 | 16.77 | as left: | 16.7 | 16.69 | Adjusted | | |

**Audit Notes:** **Instrument found in a clean, serviceable condition.- RPA**

| **Mechanical Audits** | | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| Pump muffler unclogged: | As found | X | As left | X | PM10 particle trap clean: | As found | | As left | X | N/A | | |
| Sample nozzle clean: | As found | | As left | X | PM10 drip jar empty: | As found | X | As left | X | N/A | | |
| Tape support vane clean: | As found | X | As left | X | PM10 bug screen clear: | As found | X | As left | X | N/A | | |
| Capstan shaft clean: | As found | X | As left | X | PM2.5 particle trap clean: | As found | | As left | X | N/A | | |
| Rubber pinch rollers clean: | As found | X | As left | X | Inlet tube water-tight seal OK: | As found | X | As left | X | | | |
| on | As found | X | As left | X | Inlet tube perpendicular to BAM: | As found | X | As left | x | | | |

**Signature:** Rory Attridge

# East Plant BAM-1020 $PM_{10}$ Audit Sheet

| | | | |
|---|---|---|---|
| **Model:** | **BAM-1020** | **Serial Number:** | M8712 |
| **Audit Date:** | 10/08/2013 | **Audited By:** | R. Attridge |
| **Audit Time:** | 1505hrs | | |

Firmware: 3236-06 V3.6.3

| **Flow Audits** | | | | | | |
|---|---|---|---|---|---|---|
| **Flow Reference Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Temperature Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |
| **Barometric Pressure Standard Used:** | Model: | Delta Cal | Serial No: | 1103 | Calibration Date: | 4/13/2013 |

**Leak Check Value:** as found: 0.3 LPM — Should Be: <1.0 — as left: 0.3 LPM — Should Be: <1.0

| | | BAM | Ref. Std. | | BAM | Ref. Std. | | |
|---|---|---|---|---|---|---|---|---|
| **Ambient Temperature (°C):** | as found: | 25.7 | 24.5 | as left: | 24.9 | 25.22 | Adjusted | x |
| **Barometric Pressure (mmHg):** | as found: | 652 | 652 | as left: | 652 | 652 | Adjusted | |
| **Flow Rate (15.0 LPM):** | as found: | 15.0 | 14.90 | as left: | 15.0 | 14.95 | Adjusted | |
| **Flow Rate (18.4 LPM):** | as found: | 18.4 | 18.18 | as left: | 18.4 | 18.33 | Adjusted | x |
| **Flow Rate (16.7 LPM):** | as found: | 16.7 | 16.56 | as left: | 16.7 | 16.69 | Adjusted | |

**Audit Notes:** **Monitor found in a very clean, serviceable condition.**

**Mechanical Audits**

| | | | | | | | | | | | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| Pump muffler unclogged: | As found | X | As left | X | PM10 particle trap clean: | As found | | As left | X | N/A | |
| Sample nozzle clean: | As found | | As left | X | PM10 drip jar empty: | As found | | As left | X | N/A | |
| Tape support vane clean: | As found | | As left | X | PM10 bug screen clear: | As found | X | As left | X | N/A | |
| Capstan shaft clean: | As found | | As left | X | PM2.5 particle trap clean: | As found | | As left | | N/A | x |
| Rubber pinch rollers clean: | As found | | As left | X | Inlet tube water-tight seal OK: | As found | X | As left | X | | |
| Chassis ground wire installed: | As found | X | As left | X | Inlet tube perpendicular to BAM: | As found | X | As left | x | | |

**Signature:** Rory Attridge

# Appendix L: CD